

NOT Authored

1.B.1, 6/1 Lys & ?

P/P 12 days

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 02 March 2018

Third Party Insurer: AXA

Vehicle No: SLH2589X

Third Party Veh No: YP6477M

Model: TOYOTA AQUA HYBRID 1.5

Date of Accident: 28/02/18

Chassis: NHP10-2565643

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	By Shatter	\$820.00
1	REAR TAILGATE WINDSCREEN	Shatter	\$918.00
1	REAR TAILGATE SPOILER	wrap	\$1,346.15
1	REAR TAILGATE SPOILER 3D BRAKE LED LAMP	CM	\$257.80
1	REAR TAILGATE WIPER ARM	Ref	\$48.21
1	REAR TAILGATE WIPER ARM COVER	Ref	\$18.50
1	REAR TAILGATE WIPER ARM RUBBER SEAL	Ref	\$15.20
1	REAR TAILGATE WIPER BLADE	Ref	\$48.60
1	REAR TAILGATE WIPER MOTOR	Ref	\$650.10
1	REAR TAILGATE WIPER MOTOR COVER	Ref	\$25.70
3	REAR TAILGATE WIPER MOTOR COVER CLIP	\$7.21	Ref \$21.63
2	REAR TAILGATE DAMPER LH + RH	Ref	\$218.40
1	REAR TAILGATE OUTER GARNISH	wrap	\$201.60
2	REAR TAILGATE NUMBER PLATE LAMP LH + RH	\$42.10	Ref \$84.20
1	REAR TAILGATE OUTER LOCK HANDLE SWITCH	Shor	\$133.59
2	REAR TAILGATE HINGES LH + RH	\$48.90	Ref \$97.80
1	REAR TAILGATE INNER LOCK HANDLE	Ref	\$36.70
1	REAR TAILGATE INNER UPHOLSTERY BOARD	Ref	\$428.60
6	REAR TAILGATE INNER UPHOLSTERY BOARD CLIP	\$7.21	Ref \$43.26
1	REAR TAILGATE LOGO EMBLEM	Ref	\$45.90
1	REAR TAILGATE AQUA EMBLEM	Ref	\$48.60
1	REAR TAILGATE HYBRID SYNERGY DRIVE	Ref	\$70.50
1	REAR TAILGATE MECHANISM LOCK	Ref	\$452.71
1	REAR TAILGATE WEATHERSTRIP	Ref	\$291.80
2	REAR TAILLAMP LH + RH	\$528.80	Ref \$1,057.60
2	REAR TAILLAMP LOWER BRACKET LH + RH	\$42.57	Ref \$85.14
2	REAR TAILLAMP INNER PANEL LH + RH	\$142.70	Ref \$285.40
4	REAR TAILLAMP CLIP LH + RH	\$7.21	Ref \$28.84
1	REAR BUMPER	Ref	\$408.31
2	REAR BUMPER SIDE RETAINER LH + RH	\$68.28	Ref \$136.56
8	REAR BUMPER CLIP	\$5.78	Ref \$46.24
1	REAR BUMPER LOWER UNDER COVER	Ref	\$139.10
1	REAR BUMPER REINFORCEMENT	Ref	\$278.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before repair spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification allowed
- Supplementary damage must be observed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:

Date:

Head office : 6 Kung Chong Road Singapore 159143 Tel : +65 6472 1313 Fax : +65 6472 2112
Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Chassis: NHP10-2565643

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER		100.00
1	REAR TAILGATE NUMBER PLATE WITH CASING		50.00
1	REAR BUMPER REVERSE SENSOR		280.00
		S/N TOTAL	430.00

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date:	02 March 2018	Third Party Insurer:	AXA
Vehicle No:	SLH2589X	Third Party Veh No:	YP6477M
Model:	TOYOTA AQUA HYBRID 1.5	Date of Accident:	28/02/18
Chassis:	NHP10-2565643		

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,600.00	1400
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$1,400.00	1200
TO TUFF KOTE / ANTI-RUST	\$60.00	✓
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$60.00	500
TO REMOVE AND REINSTALL REAR WINDSCREEN PERFORM AND WATER LEAK TEST	\$150.00	1200
TO MOUNT VEHICLE ONTO 3D COMPUTERISE CAR 'O' LINER TO CALIBRATE SUB CHASSIS FRAME & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$280.00	✓
TO DISMANTLE & REINSTALL INTERIOR CARPET, FRONT/ REAR SEAT ASSY WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$250.00	1200

LABOUR TOTAL \$3,800.00

<u>WINSON</u>	<u>TOTAL</u>	<u>\$14,821.50</u>
---------------	--------------	--------------------