

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0295/2018/CCS  
**Date** : 7-Mar-18

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no: SLN 9032 H

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mdm Koh Kim Heok  
**Address** : Blk 105 Potong Pasir Ave 1  
#15-418  
Singapore 350105  
**Telephone** : HP +65 97361577 - Mr. Lim  
**Type of Claim** : Third Party Claims  
**Policy No.** : 2100031406-10000  
**Vehicle No** : **SDU 6060 D**  
**Model Code** : Audi TTC 2.0T FSI  
**Model / Year** : Jun-07  
**Engine No** : BWA141822  
**Chassis No** : TRUZZZ8J871035975  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 6-Mar-18  
**Place of Accident** : Blk 105 Potong Pasir Ave 1

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SDU 6060 D.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle front bumper, lhs front fender and lhs side member trim. Renew front bumper and lhs front fender, align to position. Reinstall all parts removed.	\$ <del>2,800.00</del>	<del>1000</del> 1250
3	To respray paint on front bumper and lhs front fender.	\$ <del>1,800.00</del>	1100
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>5,152.00</u>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SDU 6060 D.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Repair</i>	\$ 1,455.00	*
2	FRONT BUMPER GUIDE - LH <i>new</i>	\$ 33.00	*
3	FRONT FENDER - LH <i>Painted</i>	\$ 930.00	✓
4	FRONT FENDER ATTACHMENT PARTS ?	\$ 102.00	?
5	FRONT FENDER BRACE - LH ?	\$ 107.00	?
6	FRONT WHEEL HOUSING LINER - LH FRONT ? <i>new</i>	\$ 97.00	*
7	FRONT WHEEL HOUSING LINER - LH REAR	\$ 151.00	*.
8	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 102.00	*.
9	SUNDRIES	\$ 200.00	
TOTAL SPARE PARTS CHARGES		: \$ 3,177.00	
TOTAL LABOUR CHARGES		: \$ 5,152.00	
GRAND TOTAL		: \$ 8,329.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183


## Telefax

Name : Adrian Lij  
Surveyed Date : 14/03/18.  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not authorised, 05 days

## Please Note

: This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd



Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant