

ASS. REC. BY:

REF:

CS/FCI18004434/Grbⁿ²

Special Instruction:

Surveyor:

AWS

ASSIGNMENT (Office)

From (Person):

Suzanne Ler

of

FCI

Date/Time:

7/3/2018 @ 12:08pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 8814R

Insured:

SH 7989J

at Workshop m/s

CYS Automobile

Tel:

62192098

of

38 Woodlands Ind. Park East 1 # 07-17

Policy No:

Claim No:

D18001904 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/3/2018

08/03/2018

CA / REV / REP. / REV 24 HRS w/p

H.O.D. Endorsement:

Date/Time:

3:12pm @ 7/3/18

Person Contacted:

Hoay Sin

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SLD 8814R - x

SH 7989J - (C3/A16/16008662/H/wb3q2)

D.O.A: 8/5/16

Print thru email.

Subj: XKCR REF: FCI

ASSIGNMENT

(-2018)

From: _____ Date: 8/3/18

Estimated Cost: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLD 8844R

at Workshop no: CYS Automobile

at 38 woodlands Ind. Prk East 1# 07-17

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

Clients Record: _____

Make of Ven: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Salv or Market Value: _____

DAC Accident Report: _____ Consistent? : Yes or No

GA / PR / Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS lwp

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Date Time Action Instruction

Repaired \$6500 M's Tel.

Rd: \$5629.76, 46%.

RECEIVED 19 APR 2018

Date Time File Pass 107

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: _____

Date Time File Return 107

Report Form: _____

TP

Lum Sum: 6500

Add Fee:

☐ Stained \$
☐ Rep \$
☐ Tech \$
☐ Rep \$

Auto Fee

Insurance

Other Fee

Other Fee

Other Fee

Other Fee

Other Fee

2X15 = 30

170 + 30

50

59

309

SLD8844R Date: 21 Oct 2008

Time: _____ Mileage: _____

Truck Trail: _____

Make: Honda stream

1799

Color: Grey

Insured: Std N/A

So. Reading: 269457

Insured: Std N/A

Eng No: _____

Ch No: IHM RN-6840-85 205 747

Gen Cond: Good Fair Poor Burnt

Steering: In Good Jammed Leaked Burnt

Brake: In Good Jammed Leaked Burnt

Mod: N/A STD A/R

Tyre Size: 205/65 R16

R

11

BS / DUN / EXNOVA / G+ / FS / LIZA / MO / OHTS / PR / SUM

TOYO / YOKO

Front

Rear

R.Ba

6

mm

R.Ba

6

--

L.Ba

6

mm

L.Ba

6

--

D.D.A

D.D

08-03-18

Surveyed at: w/s

3pm

Des of Damages: Front Rear OS NS Good Roofed

0/5 ft

The V.C. Chassis frame Body Structure affected due to collision

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18004434/Gvd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7989J	Veh. Inspected	SLD 8844R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001904MFSH	Excess (\$)	0.00	
Assign From	CWS (SERENE LER)	Assign Date	07/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/03/2018	Inspection Date		
Survey held at	CYS AUTOMOBILE SERVICES PTE LTD 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Your Ref: D18001904MFSH

Our Ref: CS/FCI18004434/Grd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLD 8844R

Please be informed that we had conducted the inspection of the above mentioned vehicle on 08/03/2018 at the premises of M/s CYS AUTOMOBILE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 12,129.76 .
Revised Estimate Amount	: S\$ 8,116.80 .
"Check" Items Amount	: S\$.
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at o/s front portion. The undercarriage affected due to collision.



Yours faithfully
XING GUO QIANG
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	06-03-2018	Our Ref No. D18001904MFSH
Accident Date	05-03-2018	Claim Type. Third Party
Insured Vehicle	SH7989J	Third Party Vehicle. SLD8844R
Survey Location	38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK	
Contact Person.	MS TEE WEE SIN	
Contact No.	62192098/ 0	Fax No. 62192096
Survey Type	WITHOUT PREJUDICE: EST. COR - \$12,129.76	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYS AUTOMOBILE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235684)



PRI Documents



Close



PRI Header Details

Claim No	D18001904MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CYS AUTC
Workshop Name	CYS AUTOMOBILE SERVICES PTE LTD (Contact Person : MS TEE WEE SIN)	Survey Location & Contact Details	38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 AD Mobile: 0 , Phone: 62192098 , Fax: 62192096 EmailId: CYSAUTO@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: EST. COR - \$12,129.76		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH7989J	TP Vehicle No	SLD8844R
PRI Recieved Date	06-03-2018 10:37:25 PM	Surveyor Appointed Date	07-03-2018 12:07:40 PM	Surveyor Accept Date	07-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	07-03-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5697K
Vehicle Details	
Vehicle No.:	SLD8844R
Vehicle to be Exported:	No
Intended De-registration Date:	09 Mar 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8L A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	R18A12805755
Chassis No.:	JHMRN68408S205747
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$20,565.00
Original Registration Date:	21 Oct 2008
First Registration Date:	21 Oct 2008
Transfer Count:	3
Actual ARF Paid:	\$20,565.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Oct 2018
PARF Rebate Amount:	\$10,282.00
Intended COE Rebate Details	
COE Expiry Date:	20 Oct 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$14,400.00
COE Rebate Amount:	\$882.00
Total Rebate Amount:	\$11,164.00

The information contained herein is correct as at 09 Mar 2018

OK

▶ Stream Used Vehicle List (19 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Honda Stream 1.8A RSZ Sunroof (New 5-yr COE)	\$40,888	\$8,170 /yr	28-Jan-2008	1,799 cc	-	GV Credit Pte Ltd	Available
Office No. - 63443344 Mark Yong - 90078890 \$2800 Down Payment, Lowest Monthly From \$738 Onwards. Low Interest At 3.68% Per Annum By GV Cars Financing. 100% Loan Approval. 2 Years Warranty By GV In House Workshop. New Full Pure Leather Seats An...							
Honda Stream 1.8A X	\$11,800	-	25-Mar-2008	1,799 cc	-	GV Credit Pte Ltd	Available
Ideal To Renew COE. Cool, Stylist And Spacious Japanese MPV. Low Fuel Consumption Of 14.6Km / Litre. Regular Serviced / Well Maintained Throughout. Guaranteed Accident Free, Low Mileage, Original Stoc... Office No. - 63443344 Francis - 96665533							
Honda Stream 1.8A X	\$11,800	-	02-Apr-2008	1,799 cc	-	AA Trust Automotive	Available
AA Trust Certified Quality Pre-Owned Vehicle! Reliable And Low Maintenance Cost With Powerful I-VTEC Engine! Tip Top Conditions With Two Tone Leather Seats! Optional 10 Years COE Renewal As Well! Best... Office No. - 63450381 Ferris - 98624768 Dave - 98500051							
Honda Stream 1.8A X	\$12,700	-	25-Jul-2008	1,799 cc	160,000 km		Available
2 Owners, Good Condition, Transfer Of Ownership From Mid Mar 18 Onwards, Monthly Cost Of \$900. Suitable For Renewing For COE! Interested Parties, Please Email Me. Thanks. Office No. - - Spencer - 97931916							
Honda Stream 1.8A Sunroof	\$13,800	-	26-Mar-2008	1,799 cc	-		Available
Agent (Kah Motor) Unit. High OMM. No Repair Needed. All Wear And Tear Parts Replaced. Smooth Gearbox. Good To Renew COE As Current COE Price Is Low. Estimated Around \$21k COE For 5 Year After 22/3/18 ... Office No. - - William Lee - 98997788							
Honda Stream 1.8A X	\$14,000	\$10,250 /yr	25-Sep-2008	1,799 cc	180,000 km		Available
Best MPV In Town Now. Drives Smoothly And Beautifully. Powerful And Responsive Engine. Beautiful Interior And Exterior. Must View Model. Well Taken Care By Owner. Regularly Serviced And Maintained. 10... Office No. - - Win Chua - 94745535							
Honda Stream 1.8A	\$14,800	-	28-Mar-2008	1,799 cc	-	Dickson Automobile	Available
Excellent Choice For Either Short Term Usage Or Renewal Of COE! STA Evaluated Cars! Well Kept In Tip Top Condition, A Unit You Must View To Believe! Buy It From Us With A Peace Of Mind, A Company Accr... Office No. - 68447667 Steven Lee - 83832206 Jonathan Quah - 91901666 Ricky Eng - 91853390							
Honda Stream 1.8A	\$15,800	\$10,940 /yr	22-Sep-2008	1,799 cc	95,000 km		Available
1 Owner, Low Mileage, Well Maintained With Regular Servicing. Brand New Tyres. Accident Free. Best Value On The Market! Call Now For Viewing. Office No. - - Willie - 93202071							
Honda Stream 1.8A X	\$16,800	\$10,630 /yr	12-Dec-2008	1,799 cc	16,400 km		Available
A Family Car Well Maintained With Regular Servicing. Well Kept Interior And Exterior. An All Time Trustworthy And Beautiful Compact MPV In The Market. Price Negotiable. Pls Text Or Call To Arrange For... Office No. - - Lim - 91050433							
Honda Stream 1.8A	\$16,800	-	28-Jul-2008	1,799 cc	-	Dickson Automobile	Available
Ideal For Short Term Usage! \$0 Down-payment! High Trade-in! STA Certified Cars! Stylish MPV Designed To Give You Superb Handling, Well Maintained By Previous Owner. For You To View And Believe! Buy It... Office No. - 68447667 Jez Teo - 90044370 Jonathan Quah - 91901666 Eric Lee - 91827304							
Honda Stream 1.8A RSZ	\$16,800	-	03-Jul-2008	1,799 cc	118,000 km	A's Traders Pte Ltd	Available
Genuine Low Mileage Only 118 K K/m. Road Tax Up To COE Ends. New Paint. Ready For COE Extension. Superb Condition. Servicing Just Done. Message / Whatsapp For Viewing Appointment. Office No. - 69314967							



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR CYS CAR RENTAL PTE LTD
38 WOODLANDS INDUSTRIAL PARK E1
#07-10 SINGAPORE 757700

POLICY NO : THIRD PARTY CLAIMS
YOUR REF : SH 7989 J (FIRST CAPITAL)
OUR REF : TP 5878
VEHICLE NO : SLD 8844 R
MAKE/MODEL : HONDA STREAM
DATE OF ACCIDENT : 05.03.18

SURVEY BY

DATE : 06.03.18

1	PC	FRONT GRILLE	/ CRA			S\$	218.40	/
1	PC	FRONT GRILLE EMBLEM	/ MC				43.30	/
1	PC	FRONT GRILLE CHROME	/ CR				275.30	/
1	PC	FRONT BUMPER	/ TN				655.60	/
1	PC	FRONT BUMPER SIDE RETAINER RH	/ CR				31.90	/
1	PC	FRONT BUMPER FOG LAMP RH	/ CR				354.20	/
1	PC	FRONT BUMPER REINFORCEMENT	/ NN				228.80	X
1	PC	HEADLAMP ASSY RH (HID)	/ CR				690.80	/
1	PC	HEADLAMP LOWER BRACKET RH	/ CR				35.80	/
1	PC	FRONT SUPPORT PANEL	/ Repair	X			480.60	X
1	PC	RADIATOR	/ BR				1,512.80	/
1	PC	WHEEL HOUSING EXTENSION PANEL	/ BUC				161.50	/
1	PC	FRONT FENDER RH	/ BUC				486.50	/
1	PC	FRONT FENDER INNER SHIELD RH	/ CR				80.40	/
1	PC	FRONT FENDER LAMP RH	/ CR				35.80	/
1	PC	FRONT DOOR RH	/ BT				860.40	/
1	PC	FRONT DOOR SIDE MIRROR ASSY RH	/ X NN				474.40	X
2	PCS	FRONT DOOR HINGES RH	/ BT		40.10		80.20	/
1	PC	ROCKER PANEL SIDE GARNISH RH	/ CR				500.30	/
1	PC	FRONT SHOCK ABSORBER RH	/ BT				328.40	/
1	PC	FRONT KNUCKLE ARM RH	/ BT				328.40	/
1	PC	FRONT KNUCKLE ARM BEARING RH	/ MC photo				142.60	/
1	PC	FRONT LOWER ARM RH	/ BT				318.40	/
1	PC	STEERING RACK & PINION	/ X				1,605.50	X
1	PC	DRIVE SHAFT RH	/ X				996.90	X
						S\$	10,927.20	7141
						LESS 20%	2,185.44	
						S\$	8,741.76	5712.8
1	SET	FRONT BUMPER CLIPS	/ MC			S\$	28.00	/ S/NETT
1	SET	RIM	/ Repair				450.00	X "
1	PC	TYRE	/ SCR				160.00	96 "
						S\$	638.00	

----- P/G 2



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No : A05041/2001E

GST Reg. NO: 20-0105041-E

CON'T FROM PAGE-1	S\$	9,379.76
TO TOWING CHARGES	S\$	50.00 ✓
TO REMOVE AIR-CON CONDENSER, PIPE, DRIER AND TOP-UP AIR-CON GAS		120.00 ✓
TO TRANSFER DOOR FITTING		80.00 60.
TO DISMANTLE AND LOWER FRONT UNDERCARRIAGE		250.00 200.
TO CHECK AND ADJUST COMPUTER ALIGNMENT		120.00 60.
TO CHECK WIRING FUNCTION		30.00 ✓
TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL		100.00 60.
LABOUR CHARGES		1,000.00 800.
TO PUTTY AND SPRAY PAINTING CHARGES		1,000.00 900.
	<u>S\$</u>	<u>12,129.76</u> 2280

SIN DOLLARS: TWELVE THOUSAND ONE HUNDRED TWENTY-NINE AND CENTS SEVENTY-SIX ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

7 Days
Lumpsum Repair
After repair photos.
Guo Qiang - 82880282
Guo Qiang @ lkk auto. com
08/3/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18004434/Grd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7989J	Veh. Inspected	SLD 8844R	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001904MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	07/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JHMRN68408S205747	Colour	GREY	
Odometer	269457	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	TOYO	6 mm	
L/H Front Tyre	205/65 R16	TOYO	6 mm	
R/H Rear Tyre	205/65 R16	TOYO	6 mm	
L/H Rear Tyre	205/65 R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/03/2018	Inspection Date	08/03/2018	
Survey held at	CYS AUTOMOBILE SERVICES PTE LTD 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 8844R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT GRILLE	CRACKED	218.40	218.40
1	FRONT GRILLE EMBLEM	NECESSARY	43.30	43.30
1	FRONT GRILLE CHROME	BROKEN	275.30	275.30
1	FRONT BUMPER	TORN	655.60	655.60
1	FRONT BUMPER SIDE RETAINER RH	CUT	31.90	31.90
1	FRONT BUMPER FOG LAMP RH	CRACKED	354.20	354.20
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	228.80	-
1	HEADLAMP ASSY RH (HID)	CRACKED	690.80	690.80
1	HEADLAMP LOWER BRACKET RH	CRACKED	35.80	35.80
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	480.60	-
1	RADIATOR	BROKEN	1,512.80	1,512.80
1	WHEEL HOUSING EXTENSION PANEL	BUCKLED	161.50	161.50
1	FRONT FENDER RH	BUCKLED	486.50	486.50
1	FRONT FENDER INNER SHIELD RH	DEFORMED	80.40	80.40
1	FRONT FENDER LAMP RH	CUT	35.80	35.80
1	FRONT DOOR RH	BENT	860.40	860.40
1	FRONT DOOR SIDE MIRROR ASSY RH	NOT NECESSARY	474.40	-
2	FRONT DOOR HINGES RH @\$40.10	BENT	80.20	80.20
1	ROCKER PANEL SIDE GARNISH RH	DEFORMED	500.30	500.30
1	FRONT SHOCK ABSORBER RH	BENT	328.40	328.40
1	FRONT KNUCKLE ARM RH	BENT	328.40	328.40
1	FRONT KNUCKLE ARM BEARING RH	NECESSARY	142.60	142.60
1	FRONT LOWER ARM RH	BENT	318.40	318.40
1	STEERING RACK & PINION	NOT NECESSARY	1,605.50	-
1	DRIVE SHAFT RH	NOT NECESSARY	996.90	-
	LESS 20% DISCOUNT		-2,185.44	-1,428.20
			8,741.76	5,712.80
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	28.00	28.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET RIM (SN)	TO REPAIR SEE LABOUR	450.00	-
1	TYRE (SN)	SCRATCHED	160.00	96.00
			638.00	124.00
	LABOUR			
	TO TOWING CHARGES.		50.00	50.00
	TO REMOVE AIR-CON CONDENSER,PIPE,DRIER AND TOP-UP AIR-CON GAS.		120.00	120.00
	TO TRANSFER DOOR FITTING.		80.00	60.00
	TO DISMANTLE AND LOWER FRONT UNDERCARRIAGE.		250.00	200.00
	TO CHECK AND ADJUST COMPUTER ALIGNMENT.		120.00	60.00
	TO CHECK WIRING FUNCTION.		30.00	30.00
	TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL.		100.00	60.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL AND SET RIM.		1,000.00	800.00
	TO PUTTY AND SPRAY PAINTING CHARGES.		1,000.00	900.00
			2,750.00	2,280.00
GRAND TOTAL			12,129.76	8,116.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,500.00

Report Ref No. CS/FCI18004434/Grd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.