

Case Owner:

cc 4, Asm 1800 4440, Aua 3/11 LKK: 34031 IDAC:

Supervisor: **ADRIAN** Assignment: **113/18** Date/Time: **1/5/18 / 7/13/18** Registered in Merimen:

Pre-assign / CCU / FTE: **X02680T**
 Insured Vehicle No.: **SPON YONG METAL INDUSTRIES Pte** Claim No.: **SPM 009 T2**
 Name of Insured: **SPON YONG METAL INDUSTRIES Pte** Policy No.: **P0984415**
 Insured Tel No.: **HP:** Make / Model: **ISUZU CARRY**
 Excess Sec II :SS D.O.A.: **1/3/18** Place of Accident: **W7 Mang Swan Rd**
 Is driver the owner? (YES /) Nature of Accident:
 IF NO, Driver Name / Age: **CHIN SEOW BONE** OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
 Driver Tel No.: **91080648** (V/L: YES / NO) Insured Liability: % Final ? Yes / No



INSRS: **Hua Feng chris** INSR: **WSP:** INSR: **WSP:** INSR: **WSP:** INSR: **WSP:**
 Tel: **Liability:** Tel: **Liability:** Tel: **Liability:** Tel: **Liability:** Tel: **Liability:**
 RMKS: RMKS: RMKS: RMKS: RMKS:

Date/Time	STAGE	DATE / PIC
13/3 7/11	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
7/12/18	Call OI: > IHIN	
7/12/18	After call ltr to OI: PL/18	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOI:	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	S\$ () days	Reduction: %
FINAL SETTLEMENT	Date/Time: 27/9/18	Confirm with: CHRIS
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No.: NIL
Repair Cost:	S\$ 6200.00	
Loss of Rental (LOR):	S\$ 1000.00 (10 days) x 100	
Loss of Use (LOU):	S\$ (3 x days)	
Loss of Income (LOI):	S\$ (3 x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search:	S\$	
Medical:	S\$	
Disbursement:	S\$ (e.g. Tow/Independent)	
Legal Cost:	S\$	
Total:	S\$ 7200.00	Global Sum S\$:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	S\$ 7200.00	Name 1: HUA FENG AUTOMOTIVE ENGINEERING & RECONSTRUCTION
Payee 2: (Strike if N.A.)	S\$	Name 2:
Payee 3: (Strike if N.A.)	S\$	Name 3:

COPY SENT 3/10/18

RECEIVED 30 MAY 2018

RECEIVED 5 OCT 2018

7/12/18 to check validity of IO's PL. (1 attachee. Please check for excess.
 7/12/18 Pending Est & PA

19/6/18 OI'd roll back and collided onto P vehicle which was park along at the roadside.

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGH3611S Yr Regn: 2006, June
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Edix cc 1668
 Colour: Purple A/C: Insured / Std / NI / NA
 Sp. Reading: 237952 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: BE 11102187
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: 195/65R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 01/03/18
 Survey held at Hua Feiy
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AXA.
 & pls verify VID's driving licence.

MV: 53K LIS - \$6200+ (Red: \$9486.30/60.1.)
 PV: AOK.
 Nett: 13K.

Date/Time, File Pass to?

 : Prel. Report

Days Of Repair:

1)

 : Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee: : Site Insp (\$

) \$ + RS ___ \$

 : Interview (\$

) Photo

 : Tech. Invs (\$

) Other

 : Weekend (\$

) TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18004440/Aua3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 07-03-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 2680T	Veh. Inspected	SGH 3611S
Policy No.	P0954415	Coverage (\$)	0.00
Claim No.	S8M009T2	Excess (\$)	0.00
Assign From		Assign Date	07/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/03/2018	Inspection Date	01/03/2018
Survey held at	HUA FENG AUTOMOTIVE ENGINEERING & RECONSTRUCTION BLK 1 KAKI BUKIT AVE 6 #01-107 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Sheet 1
HUA FENG AUTOMOTIVE
ENGINEERING & RECONSTRUCTION
 BLOCK 1 KAKI BUKIT AVENUE 6 #01-107 AUTOBAY @ KB (S) 417883
 Tel : (65) 69664526 HP: 92712214 Fax: (65)67476918

TOK HONG GEE
 BLOCK 1 KAKI BUKIT AVE 6
 #01-107 AUTOBAY @ KB
 Singapore 417883

TPA 2A
 Thin Thin

01ST March 2018

Accident date: 1ST MARCH 2018
 Supplementary repair cost for vehicle no: SGH3611S HONDA EDIX

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Disorted</i>		\$1,077.00 ✓
2	2	Rear Boot Lid Hinges <i>sent</i>	\$86.10	\$172.20 ✓
3	1	Rear Boot Lid EDIX logo <i>new</i>		\$40.00 ✓
4	1	Rear boot lid center moulding <i>cracked</i>		\$130.60 ✓
5	6	Rear boot lid center moulding clips ✓	\$6.50	\$39.00 ✓
6	1	Rear boot lid emble logo <i>new</i>		\$95.00 ✓
7	1	Rear Boot Lid Number Plate <i>sent</i>		\$50.00 ✓
8	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$52.70	\$105.40 ✓
9	1	Rear Boot Lid wiper <i>lot</i>		\$65.00 ✓
10	1	Rear Boot Lid wiper arm <i>at</i>		\$125.00 ✓
11	1	Rear boot lid wiper motor <i>sent</i>		\$258.80 ✓
12	1	Rear Boot Lid Inner Lock <i>sent</i>		\$186.30 ✓
13	1	Rear boot lid inner rubber <i>lot</i>		\$128.10 ✓
14	1	Rear Boot Lid Inner Trim board <i>del</i>		\$296.70 ✓
15	2	Rear Boot Lid Inner side side cover <i>lot</i>	\$82.40	164.80 164.80 ✓
16	2	Rear boot lid shock absorber <i>sent</i>	\$145.90	\$291.80 ✓
17	1	Rear Boot Lid windscreen solar film <i>new</i>		\$200.00 ✓
18	1	Rear boot lid windscreen seal <i>new</i>		\$136.20 ✓
19	1	rear Boot Lid windscreen <i>shattered</i>		\$985.00 ✓
20	2	rear fender inner trim board (upper) <i>del</i>	\$210.40	\$420.80 ✓
21	2	rear speaker <i>new</i>	\$200.00	\$400.00 ✓
22	2	rear speaker LH side panel <i>new</i>	\$680.00	\$1,360.00 ✓
23	1	rear speaker top cover <i>new</i>		\$1,020.10 ✓
24	2	Rear tail lamp <i>cracked</i>	\$338.10	\$676.20 ✓

25	2	Rear tail lamp panel		\$128.40	\$256.80	✓
26	2	Rear tail lamp inner panel	2 parts	\$110.00	\$220.00	✓
27	4	Rear tail lamp clips	mc	\$6.50	\$26.00	✓
28	1	Rear Bumper	behind		\$853.00	✓
29	2	Rear Bumper Side Bracket	New	\$58.70	\$117.40	✓
30	8	Rear bumper clips	New	\$5.00	\$40.00	30
31	1	Rear Bumper reverse sensor	Damaged		\$350.00	200 (SN)
32	1	Rear End Panel	2 parts		\$492.90	✓
33	1	Rear End Panel Top Garnish	behind			
34	2	Rear fender inner trim board	22nd		\$110.10	✓
35	10	Rear fender inner trim board clips	~	\$386.10	\$772.20	✓
36	1	Rear spare tire panel top sponge	?	\$5.00	\$50.00	✓
37	1	Rear spare tire panel top cover			\$205.10	✓
38	1	Rear spare tire panel sealant	not		\$260.40	✓
39	1	Rear Exhaust	mc		\$250.00	✓
40	1	Rear Exhaust chome pipe			\$725.00	✓
					\$160.00	✓

7468.20
5974.56

SN. 200

Subtotal :- \$13,206.30

Labour charges

To remove & re-fix cushion	\$120.00	80
To remove & re-fix reverse sensor	\$100.00	40
To remove & re-fix rear windscreen	\$120.00	100
Gum	\$50.00	✓
To remove & re-fix rear exhaust	\$250.00	✓
To Check Wiring System	\$80.00	30
Tuff Kote	\$120.00	30
Towing charges	\$100.00	50
Panel beating	\$140.00	1000 6w
Spray painting	\$1,400.00	6w

1580

Subtotal :- \$2,480.00

Total:- \$15,686.30

Total 7754.56
H/S G2K
OPays

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices on request - confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary detail(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:



SERVICE REQUESTS

MESSAGES

CLAIMS



Service Request Details

Claim: SBM009T2

Reference: CC4/ASM18004440/Aua3

Loss Date: 1 March 2018

Request Date: 17 August 2018

Due Date: 7 March 2019

Vendor Name: LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss: Third Party Vehicle Damage

Services: Pending verification - Direct Settlement

Actions

Next Step: Finish the work

Complete Work

More

Vehicle Information

Incident: SGT36115

Vehicle Registration #

Make: TPVD TBC

Model: TBC

Service Address

2 CHIN BEE ROAD, . . 619818

Primary Contact/Insured

SOON YONG METAL INDUSTRIES PTE LTD
2 CHIN BEE ROAD, 619818, Singapore
62682668

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

New Message

TYPE	SENT	FROM	SUBJECT	BODY	
	27/8/18 10:08 AM	LOH Cynthia	Re:RE: Re:Request for Mandate	Mandate approved	
	10/8/18 3:56 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	RE: Re:Request for Mandate	Dear Cynthia, TP is claiming for Loss of rental. P...	
	25/7/18 7:04 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	RE: Re:Request for Mandate	Dear Cynthia, we apologize for error in our previo...	
	23/7/18 11:02 AM	LOH Cynthia	Re:Request for Mandate	Dear Thin Thin, Mandate approved \$6700 - \$6800 (1...	

TYPE	SENT	FROM	SUBJECT	BODY	
	27/6/18 6:55 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	Request for Mandate	Dear Sir / Madam, OID vehicle roll back and collid...	
	7/3/18 7:15 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	RE: FYA	Dear Cynthia, Noted with thanks. Regards, Mei Kwan	
	7/3/18 3:45 PM	LOH Cynthia	FYA	PLEASE CHECK VALIDITY OF ID'S D/L	



SERVICE REQUESTS

MESSAGES

CLAIMS



Re:Request for Mandate

Type

Question

Message

Dear Thin Thin, Mandate approved \$6700 - \$6800 (1) Proposed Nett Value \$6,200.00 (2) TP veh is < 1800cc, hence Loss of use should be only \$50 - \$60 per day --> 10 days LOU : \$ 500 - \$600

Reply



SERVICE REQUESTS

MESSAGES

CLAIMS



RE: Re:Request for Mandate

Type

Question

Message

Dear Cynthia, TP is claiming for Loss of rental. Proposed Nett Value \$6,200.00 Loss of rental \$1,000.00 no. of 10 days x \$ 100 Proposed Total \$7,200.00 Thanks. Best regards, Thin Thin

Reply

Thin Thin (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Monday, 16 April 2018 10:41 AM
To: chan pick yuen; Thin Thin (LKKAuto)
Cc: Admin A; Vivian Lau (LKKAuto)
Subject: RE: SGT3611S & XD2680T DOA 01.03.2018 *** LKK REF: CC4/ASM18004440/Aua3
Attachments: GIA.PDF; INVOICE.JPG; RENTAL.JPG

From: chan pick yuen [mailto:chris_chanhebe@hotmail.com]
Sent: Saturday, 14 April, 2018 10:56 PM
To: Admin A <admin-a@lkkauto.com>
Subject: Re: SGT3611S & XD2680T DOA 01.03.2018

Dear Sir / Mdm ,

Enclosed is GIA , RENTAL & INVOICE .

As request following :

1. RC \$6200 (AS AGREED)
2. LOR \$1200 (\$120 X 10 DAYS - 7 Days recommend + 2 days PRI + 1 DAYS weekend) \

@ 100%

total \$ 7400

Please let us have your offer soon . Thanks

Regards,
Chris Chan Pick Yuen
HP: 92712214



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

19 JUNE 2018

**SOON YONG METAL INDUSTRIES PTE LTD
2 CHIN BEE ROAD
SINGAPORE 619818**

Dear Sir/Madam,

OUR REF : CC4/ASM18004440/Aua3
YOUR REF : XD 2680T

**ACCIDENT INVOLVING XD 2680T AND SGH 3611S ALONG MENG SUAN ROAD ON
01/03/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s HUA FENG AUTOMOTIVE ENGINEERING & RECONSTRUCTION acting on behalf of the owner of SGH 3611S against your motor insurance policy.

Basing on the circumstances of the accident reported by both parties, we are of the opinion that we cannot be absolved from liability.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to thinthin@lkk.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damaged property (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filed a claim against any of the involved Third Party(s), you are to keep up to date and inform your legal representative(s) and the status of the claim



Auto
Consultants
Pte Ltd

51 UBI AVE #, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408722 TEL: (065) 6256310 FAX: (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity claim cost and/or settlement(s).

If you need any clarification, please do not hesitate to contact us at 6841 2360 or email us at thinthin@lkkauto.com

Please quote the claim reference when you contact us so that we can assist you more effectively.

Yours sincerely

THIN THIN HLAING
LKK Auto Consultants Pte Ltd
DID: 6841 2360
FAX: 6741 4100
Email: thinthin@lkkauto.com

Cc: AXA Insurance (Private)
(Motor Claims)

AUTHORISATION TO ACT

I/We, Tok HONG GEE of BK 269 Yishun St 22 #04-10
S 760269, owner of SGH 3611 S hereby

authorize Hua Feng Automotive Engineering & Reconstruction, ("The Workshop") to act for me/us with respect to my/our claim for the repair costs and/or rental and/or loss of use for my/our vehicle SGH 3611 S that was damaged pursuant to the accident occurred on 11/3/18 at MENG SUAN RD involving vehicle number SGH 3611 S.

I/We further authorize the Workshop to settle my/our above mentioned claim in a manner that they deem fit and The Workshop is further authorized to receive payment further to settlement of my/our claim with payment cheque being made in favor of Hua Feng Automotive Engineering & Reconstruction.

The settlement The Workshop may reach on my/our behalf is on without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Pursuant to Personal Data Protection Act 2012, I/We hereby agree that The Workshop may disclose or share my personal data to any authorized service providers whom The Workshop would necessarily need to cooperate, interact or work in one way or another in serving me or meeting my requests.

If I/we are not able to recover full amount for the repair cost from the third Party's Insurance Company in 6 (six) months' time from invoice date, Hua Feng Automotive Engineering & Reconstruction shall bill to you/your Company for the balance/full amount of the repair cost. The Workshop will close this case without prior notice if we are unable to recover within 2 years.

I/We Tok Hong Gee understand the above explanation by Hua Feng Automotive Engineering & Reconstruction.

Dated this 01 day of 03 (month) 18 (year)

Tok Hong Gee 

Claimant's Signature

(Company's stamp for company vehicle)



Hua Feng Automotive Engineering &
Reconstruction



redefining / insurance

WITHOUT PREJUDICE to:
Insurance Subrogated Claim and/or
(b) Any Personal Injury Claims
[Note: This Notice supersedes any inconsistencies
found in this Discharge Voucher]

CLAIM REF : S8M009T2
INSURED : SOON YONG METAL INDUSTRIES PTE LTD

DISCHARGE VOUCHER

We/I (TOK HONG GEE, S0166612F) hereby agree to accept the sum of dollars [Seven Thousand Two Hundreds Only] (S\$7,200.00) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. XD 2680T as a result of an accident along MENG SUAN ROAD on 01/03/2018 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SGH 3611S.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. XD 2680T in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. XD 2680T.

Dated this 27 day of 9 2018

Claimant's Signature : Tok Hong Gee 


NRIC no./ Company Stamp : S0166612F

Occupation/ Business : _____

Address : Blk 269 YISHUN ST 22 #104-10
S760269

Telephone No. : _____

Witness's Name : Chen Pak Yuen

Witness's Signature : 

Witness's NRIC No. : S7084264C

2017
HUA FENG AUTOMOTIVE
ENGINEERING & RECONSTRUCTION
BLOCK 1 KAKI BUKIT AVENUE 6 #01-107 AUTOBAY @ KB (S) 417883
Tel : (65) 69664526 HP: 92712214 Fax: (65)67476918

INVOICE

AXA INSURANCE PTE LTD
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Date: 13-Apr-18

Accident date: 1 Mar 2018
Final Bill For Vehicle No: SGH3611S HONDA EDIX

Descriptions	AMOUNT
Lump Sum repair cost as recommended by LKK AUTO CONSULTANTS PTE LTD Surveyor : Mr Adrian Ling	\$6,200.00
Total	\$6,200.00

S/DLRS: SIX THOUSAND AND TWO HUNDRED ONLY



福泉興汽車出租及貿易私人有限公司

HOCK CHUAN HENG CAR RENTAL & TRADING PTE LTD.

No. 4 Petain Road, Petain Court Singapore 208086 Tel: 6298 1936, 6294 0246, 6294 9170 Fax: 6298 3064

I/We _____
 HIRER'S PARTICULARS (If Different From Section ①) of _____ S _____ Tel: _____

hereinafter called "the Hirer" hereby confirm having agreed to hire this day from HOCK CHUAN HENG CAR RENTAL & TRADING PTE LTD hereinafter called "the Owner" the undermentioned Vehicle at the rental fees as shown below and I further agree that I shall be held responsible for:-

- a) **THIRD PARTY ONLY MOTOR VEHICLE COVERAGE**
 the Excess which is the maximum amount of \$1500 to cover for any third party damage or injury claims and also bear the full cost of any damage caused to the hired Vehicle resulting from any single accident including loss from inability to let the same Vehicle out on hire or loss resulting from theft and destruction of the Vehicle.
- b) **COMPREHENSIVE MOTOR VEHICLE COVERAGE**
 the Excess which is the maximum amount of \$2000 for any damage caused to the hired Vehicle from any single accident or any loss resulting from third party damage claims, injury claim, theft or destruction of the Vehicle.
- c) Only persons above 24 years of age with more than 2 years driving experience, authorised licensed and signing this agreement may drive the vehicle.

whether or not such damage or loss is by person/persons known or unknown to me or by negligence or any breach by me of the Terms and Conditions of Hire, hereinafter mentioned and printed at the back hereof.

Vehicle Regn No. 車輛註冊號碼 SJM 8639T		Rental Agreement 合同號碼 No. 11	
Section ① Hirer's And/Or Driver's Particulars 租車者/駕駛員個人記錄		租出日期及時間 Date & Time OUT 1/3/18 1:00PM	
姓名 Name TOK HONG GEE		交車日期及時間 Date & Time IN 10/3/18	
地址 Address Sik 209 # 04-10 Yisheng St 2		Chargable Rates Amount	
@ 760269		10	天 Days @ \$ 120
IC No./Passport No. 016662F		星期 Weeks @ \$	
駕駛執照號碼 Driving License No. 0166612F		月 Months @ \$	
IC 種類/護照種類 Type of IC/Passport Sport/Pass		Pass 日期 Past Date 19/09/1974	
出生日期 Date of Birth 29/11/1957		發出地 Place of Issue SPORE	
三號保險底金 \$1500/ or Third Party Only Policy Excess \$1500-		一號保險底金 \$2000/ or Comprehensive Policy Excess \$2000-	
車輛必須交還車主於 Vehicle Must Be Returned To Owner's Office By:		保險 Insurance	
備註與付款記錄 Remarks & Payment Records		總計 Total Charge \$1200	
IMPORTANT! For Singapore Use only.			
出車油箱 Fuel Tank OUT		出車油箱 Fuel Tank IN	
車牌號碼 Vehicle No. 1)		租費不包括汽油 Rates Do Not Include Fuel	
車牌號碼 Vehicle No. 2)		至 To	
工具 Tools		至 To	
車輛發出人 Vehicle Issued By:		加額費用 Total Additional Charges	
車輛收訖人 Vehicle Collected By:		租費不包括汽油 Rates Do Not Include Fuel	
NOTE: 12 租車者或司機必須付所有停車、違反交通及交通法例引起一切之責任。 HIRER AND/OR DRIVER IS LIABLE FOR ALL PARKING, TRAFFIC AND SMOKY EXHAUST VIOLATION.		超過小時 Extra Hours @ \$	
租車者不駕駛沙灘車及 HOCK CHUAN HENG CAR RENTAL AND TRADING PTE LTD HOCK CHUAN HENG CAR RENTAL AND TRADING PTE LTD		總計 Grand Total	

I/We have read and hereby agree to the terms and conditions on both sides of this rental agreement.

日期 Date _____ 租車者簽名 Signature of Hirer **[Signature]**

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	XD 2680T (Insd veh)	Model:	HONDA EDIX
	SGH 3611S (TP veh)		
Date of Accident:	01/03/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	15,792.90
Final Repair Cost	:	\$	6,200.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,000.00 10 days
LTA / GIA Search Fee	:	\$	0.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	7,200.00

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	HUA FENG AUTOMOTIVE ENGINEERING & RECONSTRUCTION	\$ 7,200.00

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

29/10/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

Service Request Details

Claim	SBR00972
Reference	CCA/ASM1800440/Aua3rd
Loss Date	1 March 2018
Request Date	17 August 2018
Due Date	
Vendor Name	LAX AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step: **Wait for Approve Invoice**

Add Expense

Vehicle Information	
Incident Vehicle Registration #	SGT3M115
Make	TPVO TBC
Model	TBC
Service Address	
2 CHIN BEE ROAD... 619818	
Primary Contact/Insured	
SOON YONG METAL INDUSTRIES PTE LTD 2 CHIN BEE ROAD, 619818, Singapore 62682668	
Claim Handler	
LOH Cynthia 656804843 cynthia.loh@axa.com.sg	

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
LAXInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LAX AUTO CONSULTANTS PTE LTD (TP)	29 October 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
payment Invalidehen SGH 36115.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 October 2018
LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 October 2018
DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	29 October 2018
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	29 October 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	29 October 2018
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	29 October 2018
INV RRT.pdf	Reports & Statement	Investigator / Adjuster Report	KUMAR Shaikendra	20 July 2018
TP video footage.mp4	Evidence	Videos	YU Dominic Yishan	12 July 2018
MANDATE AND IA.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 June 2018
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 June 2018
Insured driver driving licence.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 May 2018
PAIR COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 May 2018
Immediate Advice and Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 May 2018
TP GIA REPORT.pdf	Reports & Statement	GIA Report	LKK AUTO CONSULTANTS PTE LTD (TP)	8 March 2018
ACCIDENT PHOTO 2.jpeg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	7 March 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 ACCIDENT PHOTO 1.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	7 March 2018
 ACCIDENT PHOTO 3.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	7 March 2018
 EMAIL FROM WKSP TO AXA DD 01.03.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	7 March 2018
 P0954415_CL_00009_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	LOH Cynthia	7 March 2018
 P0954415_RN_00009_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	LOH Cynthia	7 March 2018

Assessment Details

[General & Workshop Details](#) |
 [Vehicle & Driver Details](#) |
 [Vehicle Condition](#) |
 [Taxes & Rate](#) |
 [Parts & Labour](#) |
 [Miscellaneous](#) |
 [Summary](#) |
 [Parts](#)

EDIT	SI NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIBT PRICE	DEP/L/ BTYENL	DISC COUTYS	SALY AGEN	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1			REAR BOOT LID			Damaged	1077		20		861.6	Approve	
	2	2			REAR BOOD LID HINGES			Bent	86.1		20		137.76	Approve	
	3	1			REAR BOOT LID EDX LOGO			Necessary	40		20		32	Approve	
	4	1			REAR BOOT LID CENTER MOULDING			Cracked	130.8		20		104.48	Approve	
	5	1			REAR BOOT LID CENTER MOULDING CLIPS			Necessary	10		20		8	Approve	
	6	1			REAR BOOT LID EMBLE LOGO			Necessary	95		20		76	Approve	
	7	1			REAR BOOT LID NUMBER PLATE			Bent	50		20		40	Approve	
	8	2			REAR BOOT LID NUMBER PLATE LAMP			Serviceable	0	0	0	0	0	Deny	
	9	1			REAR BOOT LID WIPER			Cut	65		20		52	Approve	
	10	1			REAR BOOT LID WIPER ARM			Cut	125		20		100	Approve	
	11	1			REAR BOOT LID WIPER MOTOR			Damaged	258.8		20		207.04	Approve	
	12	1			REAR BOOT LID INNER LOCK			Damaged	186.3		20		149.04	Approve	

EDIT	BR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEFR./ BITTS	DISC QUNTY	SALV AGES	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	13	1			REAR BOOT LID INNER RUBBER			Cut	128.1		20		102.48	Approve	
	14	1			REAR BOOT LID INNER TRIM BOARD			Deformed	268.7		20		237.36	Approve	
	15	2			REAR BOOT LID INNER SIDE COVER			Cut	62.4		20		131.84	Approve	
	16	2			REAR BOOT LID SHOCK ABSORBER			Bent	145.9		20		233.44	Approve	
	17	1			REAR BOOT LID WINDSCREEN SOLAR FILM			Necessary	200		20		160	Approve	
	18	1			REAR BOOT LID WINDSCREEN SEAL			Necessary	136.2		20		108.96	Approve	
	19	1			REAR BOOT LID WINDSCREEN			Damaged	865		20		756	Approve	
	20	2			REAR FENDER INNER TRIM BOARD (UPPER)			Deformed	210.4		20		336.04	Approve	
	21	2			REAR SPEAKER			Serviceable	0	0	0	0	0	Deny	
	22	2			REAR SPEAKER LH SIDE PANEL			Serviceable	0	0	0	0	0	Deny	
	23	1			REAR SPEAKER TOP COVER			Serviceable	0	0	0	0	0	Deny	
	24	2			REAR TAIL LAMP			Cracked	336.1		20		540.96	Approve	
	25	2			REAR TAIL LAMP PANEL			Repair	0	0	0	0	0	Deny	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTYRS	DISC QUNTYS	SALV AGES	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	26	2			REAR TAIL LAMP INNER PANEL			Repair	0	0	0	0	0	Deny	
	27	4			REAR TAIL LAMP CLIPS		Necessary	6.5			20		20.6	Approve	
	28	1			REAR BUMPER		Deformed	853			20		852.4	Approve	
	29	2			REAR BUMPER SIDE BRACKET		Necessary	36.7			20		93.92	Approve	
	30	8			REAR BUMPER CLIPS		Necessary	3.75			20		24	Approve	
	31	1			REAR END PANEL		Repair	0		0	0	0	0	Deny	
	32	1			REAR END PANEL TOP GARNISH		Deformed	110.1			20		88.08	Approve	
	33	2			REAR FENDER INNER TRIM BOARD		Deformed	306.1			20		617.76	Approve	
	34	10			REAR FENDER INNER TRIM BOARD CLIPS		Necessary	5			20		40	Approve	
	35	1			REAR SPARE TIRE PANEL TOP SPONGE		Serviceable	0		0	0	0	0	Deny	
	36	1			REAR SPARE TIRE PANEL TOP COVER		Serviceable	0		0	0	0	0	Deny	
	37	1			REAR SPARE TIRE PANEL SEALANT		Serviceable	0		0	0	0	0	Deny	
	38	1			REAR EXHAUST		Serviceable	0		0	0	0	0	Deny	

SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTRYS	DISC QUNT'S	SALV AGE'S	PART PRICE(NET)	ACTION (PARTS)	REMOVE
30	1			REAR EXHAUST CHROME PIPE			Serviceable	0	0	0	0	0	Deny	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR RER	LABOUR REPAIR	PART	ACTION (LABOUR)	COMMENT	REMOVE
	1		TO REMOVE & RE-FIX CUSHION	80	0	0	Approve		
	2		TO REMOVE & RE-FIX REVERSE SENSOR	40	0	0	Approve		
	3		TO REMOVE & RE-FIX REAR WINDSCREEN	100	0	0	Approve		
	4		GLUM	50	0	0	Approve		
	5		TO REMOVE & RE-FIX REAR EXHAUST	0	0	0	Deny		
	6		TO CHECK WIRING SYSTEM	30	0	0	Approve		
	7		TUFF NOTE	30	0	0	Approve		
	8		TOWING CHARGES	50	0	0	Approve		
	9		PANEL BEATING	600	0	0	Approve		
	10		SPRAY PAINTING	600	0	0	Approve		

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ptds Parts & Labour Miscellaneous Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR/7 DAYS	Approve			
	2	REAR BUMPER REVERSE SENSOR	Approve	200	DAMAGED	

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Claim Amount **\$7,754.56**

Claim Amount **\$7,754.56**

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$5,974.56	\$5,974.56
Labour	\$1,580.00	\$1,580.00
Miscellaneous	\$200.00	\$200.00

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Fees Parts & Labour Miscellaneous Summary Claim Amount \$6,200.00

Claim Amount \$6,200.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$6,200.00	\$6,200.00