

Jay Tan

CC 4, Asm/400 4441, T1 UA357

LKK: 33863  
IDAC: 33863

Surveyor:

MCW

DOI:

8/3/18

Date / Time:

7/3/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SCV 8186 T

Claim No. :

88M00A01

Name of Insured :

TEO SHEN TONG

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Bmw 520

Excess Sec II :SS

D.O.A.:

3/3/18

Place of Accident :

Pinkerton Rd

Is driver the owner? ( YES / NO )

( YES / NO )

Nature of Accident :

If NO, Driver Name / Age :

TEO TEO SHEN

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

90090777

(V/L: YES / NO)

Insured Liability :

% Final ? Yes / No

SJW 4142H



INSRS:

WSP:

Tel :

Liability :

RMKS:

TC Autoclinic



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time		STAGE	DATE / PIC
13/3/18	SJW 4142H - X; SCV 8186 T - X	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
16/3/18	called OI not available.	Call OI:	
		After call ltr to OI:	
26/3/18	called OI no response.	Documentation Check List:	
		Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA :	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

Based on footage while OI change lane, there is another oncoming vehicle, OI swerve back to the lane and collided onto front vehicle

RECEIVED 07 JUN 2018

RECEIVED 17 JUL 2018

**PRELIMINARY ADVICE** Date/Time: Sent By: Confirm with:

**FINALIZATION** Date/Time: Confirm with: Confirm by:

Repair Cost: SS ( days) Reduction: % Email  Call

**FINAL SETTLEMENT** Date/Time: 6/7/18 Confirm with: Shawn Email  Call

Final Liability: % 100. (Agreed / Assessed) BOLA S/N No. : NU

Repair Cost: SS 2316.76

Loss of Rental (LOR): SS ( days)

Loss of Use (LOU): SS 240.00 (\$80 x 3 days)

Loss of Income (LOI): SS (\$ x days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search SS

Medical: SS

Disbursement: SS (e.g. Tow/ Independent)

Legal Cost SS

Total: SS 2556.76 Global Sum SS:

**FINAL PAYMENT** Date/Time: Confirm with: Email  Call

Payee 1: SS 2556.76 Name 1: TC AUTOCLINIC PTE LTD

Payee 2: (Strike if N.A.) SS Name 2:

Payee 3: (Strike if N.A.) SS Name 3:

COPIED 12/7/18

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format:
- 3) Survey fee:



TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO : 67038511  
REFERENCE : 051/IC/TCAC/CCR/2018  
DATE : 05-MAR-2018

AXA INSURANCE S'PORE PTE LTD  
B SHENTON WAY  
#27-01 AXA TOWER  
S(068811)  
TEL : 68804741  
FAX : 68804838  
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : GIOVANNI RINALDI  
ADDRESS : 79 FARRER DRIVE  
#03-02  
S(259283)  
TELEPHONE NO : 97564612/97478748

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 2100470849-01000  
VEHICLE NO : SJW4142H  
MODEL CODE : FRLAR8ZJ11UEA--A--  
MODEL/YEAR : NISSAN QASHQAI 1.2  
ENGINE NO : HRA2284586A  
CHASSIS NO : SJNFEAJ11U1682485  
MILEAGE : 15974 KM  
DATE IN : 05/03/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : SHAWN CHUA CHU RONG  
ACCIDENT DATE : 03/03/2018

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjin 97495749  
-wp'  
8/3/18 @ 130pm  
3 days  
Shaw Chua  
Resurvey before paint

TC AUTOCLINIC PTE LTD  
 25 LENG KEE ROAD  
 SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJW4142H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	CON1	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	✓
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X
3	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	✓
4	SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
5	WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	X
6	ZZ/001	RENEW REAR BUMPER, LEFT TAIL LAMP, REAR UPPER PANEL, ENERGY ABSORBER, REINFORCEMENT, WEATHERSTRIP, REAR	1500.00	250.500
7	ZZ/002	LEFT FENDER & TRIM ETC PANELS & REPAIR	1500.00	
8	ZZ/003	REMOVE & INSTALL SEATS, CARPETING & HEADLINER TO FACILITATE REPAIR	120.00	X
9	ZZ/004	RENEW LEFT QUARTER GLASS TO FACILITATE REPAIR	150.00	X 600
10	ZZ/005	RESPRAY REAR BUMPER IN 2 COLORS, REAR UPPER PANEL, LEFT FENDER ETC	1000.00	300
11	ZZ/006	QC, RETUNE & CONSULT CHECK		
12	ZZ/007	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES			3525.00	

TC AUTOCLINIC PTE LTD  
 25 LENG KEE ROAD  
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJW4142H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 LEFT QUARTER GLASS	83313-4EAOA			380.00 x <i>nm</i>
2 LEFT FENDER TRIM	93829-4EAOA	483.00 x	} <i>x</i> <i>nm</i>	
3 WEATHERSTRIP	90830-4EAOB	158.70 x		
4 LEFT REINFORCEMENT STAY	H5211-4EAMA	126.00 ?		
5 REINFORCEMENT	H5030-4EAMA	619.20 ?		
6 ENERGY ABSORBER	85090-4EAOB	126.40 ?		
7 LEFT BUMPER BRACKET	85221-4EAOA	35.90 <i>del</i>		
8 LEFT BUMPER RETAINER	79185-4EAOA	23.80 <i>del</i>		
9 CLIP (\$1.20 EA X4)	01553-05933	4.80 <i>del</i>		
10 REAR BUMPER	85022-4EAOH	717.00 <i>del</i>		
11 REAR UPPER PANEL	G9110-4EAMA	482.60 <i>Ry</i>		
12 LEFT PROTECTOR	75749-4EAOA	186.40 x <i>nm</i>		
13 REAR LEFT FENDER	G8101-4EAMA	1169.40 x <i>nm</i>		
14 LEFT REFLECTOR	26565-JJ90A	55.00 <i>nm</i>		
15 LEFT TAIL LAMP (FENDER)	26555-4EAOA	323.70 <i>nm</i>		
SUB TOTAL		4511.90	0.00	380.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		902.38	0.00	0.00
GRAND TOTAL		3609.52	0.00	380.00
OVERALL TOTAL		3989.52		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJW4142H  
-----

TOTAL LABOUR CHARGES	3525.00
TOTAL SPARE PARTS CHARGES	3989.52
GRAND TOTAL	7514.52 *

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS  
-----

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO : 67038511  
REFERENCE : 051/IC/TCAC/CCR/2018  
DATE : 05-MAR-2018

AXA INSURANCE S'PORE PTE LTD  
8 SHENTON WAY  
#27-01 AXA TOWER  
S(068811)  
TEL : 68804741  
FAX : 68804838  
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : GIOVANNI RINALDI  
ADDRESS : 79 FARRER DRIVE  
#03-02  
S(259283)  
TELEPHONE NO : 97564612/97478748

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 2100470849-01000  
VEHICLE NO : SJW4142H  
MODEL CODE : FRLARBZJ11UEA--A--  
MODEL/YEAR : NISSAN QASHQAI 1.2  
ENGINE NO : HRA2284586A  
CHASSIS NO : SJNFEAJ11U1682485  
MILEAGE : 15974 KM  
DATE IN : 05/03/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : SHAWN CHUA CHU RONG  
ACCIDENT DATE : 03/03/2018

TC AUTOCLINIC PTE LTD  
 25 LENG KEE ROAD  
 SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJW4142H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	CONI	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	240.00 ✓
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	.00
3	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	55.00 ✓
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	.00
5	WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	.00
6	ZZ/001	RENEW REAR BUMPER, LEFT TAIL LAMP REPAIR REAR UPPER PANEL	1500.00	500.00 ?
7	ZZ/003	REMOVE & INSTALL SEATS, CARPETING & HEADLINER TO FACILITATE REPAIR	120.00	.00
8	ZZ/004	RENEW LEFT QUARTER GLASS TO FACILITATE REPAIR	150.00	.00
9	ZZ/005	RESPRAY REAR BUMPER IN 2 COLORS, REAR UPPER PANEL, MUDGUARD INNER PANEL	1000.00	600.00 ?
10	ZZ/006	QC, RETUNE & CONSULT CHECK		
11	ZZ/007	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES			3525.00	1395.00
ADDITIONAL DISCOUNT(5.00%)				69.75
FINAL LABOUR CHARGES				1325.25

TC AUTOCLINIC PTE LTD  
 25 LENG KEE ROAD  
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJW4142H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 LEFT QUARTER GLASS	83313-4EA0A			380.00	X
2 LEFT FENDER TRIM	93829-4EA0A	483.00			X
3 WEATHERSTRIP	90830-4EA0B	158.70			X
4 LEFT REINFORCEMENT STAY	H5211-4EAMA	126.00			X
5 REINFORCEMENT	H5030-4EAMA	619.20			X
6 ENERGY ABSORBER	85090-4EA0B	126.40			X
7 LEFT BUMPER BRACKET	85221-4EA0A	35.90			OK ✓
8 LEFT BUMPER RETAINER	79185-4EA0A	23.80			OK ✓
9 CLIP (\$1.20 EA X4)	01553-05933	4.80			OK ✓
10 REAR BUMPER	85022-4EA0H	717.00			OK ✓
11 REAR UPPER PANEL	69110-4EAMA	482.60			X
12 LEFT PROTECTOR	76749-4EA0A	186.40			X
13 REAR LEFT FENDER	68101-4EAMA	1169.40			X
14 LEFT REFLECTOR	26565-JJ90A	55.00			X
15 LEFT TAIL LAMP (FENDER)	26555-4EA0A	323.70			OK ✓
SUB TOTAL		1105.20	0.00	0.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		221.04	0.00	0.00	
GRAND TOTAL		884.16	0.00	0.00	
ADDITIONAL DISCOUNT (NETT-5.00%, LIST-5.00%, S/NETT-.00%)		44.21	0.00	0.00	
OVERALL TOTAL		839.95			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SJW4142H

-----

NETT ITEM	1105.20
LESS 20.00%)	-221.04
NETT AMOUNT	884.16
ADDITIONAL DISCOUNT(5.00%)	-44.21
FINAL AMOUNT	839.95

LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	0.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	0.00

TOTAL LABOUR CHARGES	1325.25
TOTAL SPARE PARTS CHARGES	839.95

TOTAL CHARGES	2165.20
ADD 7 % GST	151.56

GRAND TOTAL	2316.76
-------------	---------

-----

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO : 67038511  
REFERENCE : 051/IC/TCAC/CCR/2018  
DATE : 05-MAR-2018

AXA INSURANCE S'PORE PTE LTD  
B SHENTON WAY  
#27-01 AXA TOWER  
S(068B11)  
TEL : 68804741  
FAX : 68804838  
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : GIOVANNI RINALDI  
ADDRESS : 79 FARRER DRIVE  
#03-02  
S(259283)  
TELEPHONE NO : 97564612/97478748

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 2100470849-D1000  
VEHICLE NO : SJW4142H  
MODEL CODE : FRLARBZJ11UEA--A--  
MODEL/YEAR : NISSAN QASHQAI 1.2  
ENGINE NO : HRA2284586A  
CHASSIS NO : SJNFEAJ11U16B2485  
MILEAGE : 15974 KM  
DATE IN : 05/03/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : SHAWN CHUA CHU RONG  
ACCIDENT DATE : 03/03/2018

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Tanjin 97495749  
'WP'  
8/3/18 @ 1:30 pm  
3 days  
sure / meant to be  
Resurvey before paint

TC AUTOCLINIC PTE LTD  
 25 LENG KEE ROAD  
 SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJW4142H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	CONI	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	✓
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X
3	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	✓
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
5	WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	X
6	ZZ/001	RENEW REAR BUMPER, LEFT TAIL LAMP, REAR UPPER PANEL, ENERGY ABSORBER, REINFORCEMENT, WEATHERSTRIP, REAR	1500.00	250.
7	ZZ/002	LEFT FENDER & TRIM ETC PANELS & REPAIR	1500.00	
8	ZZ/003	REMOVE & INSTALL SEATS, CARPETING & HEADLINER TO FACILITATE REPAIR	120.00	X
9	ZZ/004	RENEW LEFT QUARTER GLASS TO FACILITATE REPAIR	150.00	X
10	ZZ/005	RESPRAY REAR BUMPER IN 2 COLORS, REAR UPPER PANEL, LEFT FENDER ETC	1000.00	300
11	ZZ/006	QC, RETUNE & CONSULT CHECK		
12	ZZ/007	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES			3525.00	

TC AUTOCLINIC PTE LTD  
 25 LENG KEE ROAD  
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJW4142H

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	LEFT QUARTER GLASS	83313-4EAOA			380.00	X
2	LEFT FENDER TRIM	93829-4EAOA	483.00			X
3	WEATHERSTRIP	90830-4EAOB	158.70			X
4	LEFT REINFORCEMENT STAY	H5211-4EAMA	126.00			?
5	REINFORCEMENT	H5030-4EAMA	619.20			?
6	ENERGY ABSORBER	85090-4EAOB	126.40			?
7	LEFT BUMPER BRACKET	85221-4EAOA	35.90			nei
8	LEFT BUMPER RETAINER	79185-4EAOA	23.80			nei
9	CLIP (\$1.20 EA X4)	01553-05933	4.80			nei
10	REAR BUMPER	85022-4EAOH	717.00			de
11	REAR UPPER PANEL	69110-4EAMA	482.60			Ay
12	LEFT PROTECTOR	76749-4EAOA	186.40			X
13	REAR LEFT FENDER	68101-4EAMA	1169.40			X
14	LEFT REFLECTOR	26565-JJ90A	55.00			?
15	LEFT TAIL LAMP (FENDER)	26555-4EAOA	323.70			qua
SUB TOTAL			4511.90	0.00	380.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			902.38	0.00	0.00	
GRAND TOTAL			3609.52	0.00	380.00	
OVERALL TOTAL			3989.52			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJW4142H  
-----

TOTAL LABOUR CHARGES	3525.00
TOTAL SPARE PARTS CHARGES	3989.52
GRAND TOTAL	7514.52 *

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS  
-----

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

## Service Request Details

Claim

S8M00A01

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Reference

None 

Loss Date

March 3, 2018

*07032018 @ 11:10am  
shawn veh not in*

Request Date

March 7, 2018

Due Date

March 14, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SJW4142H

Make

TPVD NISSAN

Service Address

---

...

Primary Contact/Insured

---

TEO SIEW TEONG  
81 BUKIT DRIVE, #01-06, 687850, Singapore  
90850886

Claim Handler

---

LOH Cynthia  
6568804843  
cynthia.loh@axa.com.sg

Additional Instructions

[Messages](#)   [Invoices](#)   [History](#)   [Documents](#)   [Assessment](#)   [Metrics](#)   [Notes](#)

---

New Message

# SATISFACTORY NOTE

TAN CHONG MOTOR SALES PTE LTD (TCMS)  
 AUTOLUTION INDUSTRIAL PTE LTD (AIPL)  
 TC AUTOCLINIC PTE LTD (TCAC)

DATE: 13-04-18  
 OWNER NAME: Giovanni Rinaldi  
 NRIC NO.: S2720690E  
 ADDRESS: 79 Farrer Rd  
#03-02 S259283

TYPE OF CLAIM:

OWN DAMAGE (OD)

OWN DAMAGE (OD) & UNINSURED LOSS (EXCESS & LOSS OF USAGE) VIA TCMS / AIPL / TCAC

THIRD PARTY THROUGH TCMS / AIPL / TCAC

THIRD PARTY - OWNER DIRECT CLAIM AGAINST THIRD PARTY INSURANCE

WINDSCREEN / GLASS (W/S)

VEHICLE MODEL: Nissan Qashqai 1.2  
 REGN. NO.: SJW 4142 H  
 CHASSIS NO.: SJNFEAJ11U1682485


INSURANCE CO.: AIG  
 CLAIM NO.: 051/IC/TCAC/CCR/2018  
 POLICY NO.: 2100470849-01000

DATE OF ACCIDENT: <u>03-03-18</u>	DATE RECEIVED: <u>11-04-18</u>	DATE COMPLETED: <u>13-04-18</u>
--------------------------------------	-----------------------------------	------------------------------------

We / I hereby confirmed that the accident repair carried out by Tan Chong Motor Sales Pte Ltd / Autolution Industrial Pte Ltd / TC AutoClinic Pte Ltd and that all necessary repairs as resulted of the accident of the above vehicle have been completed to our / my satisfaction and that We / I have no futher claim whatsoever against the above Company in repect thereof. Terms and Conditions as stipulated in the overleaf applies.

We / I have taken delivery of my car after all necessary repair carried out by Tan Chong Motor Sales Pte Ltd / Autolution Industrial Pte Ltd / TC AutoClinic Pte Ltd on\*

Note: In the event of an Own Damage Claim, your Insurance Company may under policy terms & conditions, or as standard Industrial Practice, increase the loading on your premium during Insurance Policy renewal. Your NCD [Non Claim Discount] may also be affected, subject to business policy of respective Insurance Company.

  
 (NAME / SIGNATURE OF INSURED)

**FOOTNOTE:**

<input type="checkbox"/> TCMS / AIPL / TCAC* WILL CLAIM ON BEHALF OF OWNER THROUGH TCMS'S LEGAL AID	<input type="checkbox"/> DEPOSIT PAID BY OWNER
<input type="checkbox"/> OWNER WILL MAKE CLAIM AGAINST THIRD PARTY INSURANCE COMPANY	<input type="checkbox"/> DOCUMENTS RETURNED TO OWNER
<input type="checkbox"/> TCMS / AIPL / TCAC* WILL CLAIM ON BEHALF OF OWNER UNINSURED LOSS. (EXCESS PAYMENT & LOSS OF USAGE)	

**INSURANCE CO. COPY**

\* Delete When Necessary



SERVICE REQUESTS

MESSAGES

CLAIMS



## Re:Request for Mandate approval

Type

Question

Message

hi, please proceed as proposed.

Reply



SERVICE REQUESTS

MESSAGES

CLAIMS



## Request for Mandate approval

Type

Question

Message

Dear Sir / Madam, Please be inform that we have spoken to OI. Informed TP callim and he agree to settle. He also aware the NCD issue. We seek your approval to offer to TP repairer as follow:  
Liability(TP) 100% Proposed Nett Value \$2,316.76 Loss of use \$240.00 no. of 3 days x \$ 80 Loss of rental \$- no. of days x \$ Loss of income \$- LTA search fees \$- Others - Proposed Total \$2,556.76

Reply

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SCV 8186T (Insd veh)	Model:	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
	SJW 4142H (TP veh)		
Date of Accident:	03/03/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	8,040.54
Final Repair Cost	:	\$	2,316.76
Loss of Use	:	\$	240.00
Rental (if any)	:	\$	3 days at \$80.00 per day
LTA / GIA Search Fee	:	\$	days

Others: : \$

Final Settlement Sum : \$ 2,556.76

Is Third Party Workshop GIA Registered?  YES  NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_(%)  
 B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_NIL\_  
 BOLA Liability: \_\_\_\_\_100\_\_\_\_\_(%) Assessed Liability (\*): \_\_\_\_\_(%)  
 \* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

<b>Payment Instruction: Payee's Breakdown</b>		
1)	TC AUTOCLINIC PTE. LTD.	\$ 2,556.76

NUR SHAQILAH BTE ABDOL  
WAHAB

18/07/2018  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

<< **Service Request Details**

Claim	S8M00A01
Reference	CC4/ASM18004441/Title3
Request Date	March 3, 2018
Due Date	March 7, 2018
Vendor Name	March 7, 2019
Type of Services	LKK AUTO CONSULTANTS PTE LOSS LTD (TP)
Third Party Vehicle Damage	Third Party Vehicle Services

Vehicle Information

**Actions**

Next Step    Finish the work    Complete Work    More

Incident Vehicle	SJW4142H
Registration #	TPVD NISSAN
Make	QASHQAI-1.2 DIG-T (J11) (A)
Model	TPVD NISSAN
Primary Contact/Insured	TEO SIEW TEONG 81 BUKIT DRIVE, #01-06, 687850, Singapore 90850886

Claim Handler

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
TP-SJW4142H ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	March 14, 2018
TP-SJW4142H Preliminary Advice.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	March 13, 2018
SCV8186T INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHIWAR Namrata	March 7, 2018
TP-SJW4142H EMAIL RECEIVED FROM WORKSHOP WITH ESTIMATE AND GIA REORT.msg	Other	Other	DHIWAR Namrata	March 7, 2018
TP GIA REPORT-SJW4142H.pdf	Reports & Statement	GIA Report	TAN Jas	March 6, 2018

## Service Request Details

Claim	S8M00A01	Vehicle Information	
Reference	CC4/ASM18004441/11003	Incident Vehicle	SJW4142H
Request Date	March 3, 2018	Registration #	TPVD NISSAN
Due Date	March 7, 2018	Make	NISSAN
Vendor Name	March 7, 2019	Model	QASHQAI-1.2 DIG-T (J11) (A)
Type of Loss	LKK AUTO CONSULTANTS PTE LTD (TP)	Primary Contact/Insured	TEO SIEW TEONG 81 BUKIT DRIVE, #01-06, 687850, Singapore 90850886
Services	Third Party Vehicle Damage	Claim Handler	

### Actions

- Next Step
- Finish the work
- Complete Work
- More

# Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

## Vehicle & Driver Details

Vehicle Registration# SJW4142H

Registration State SINGAPORE

Mileage 16020

Purchase Date mm/dd/yyyy

Registration Date \* 06/16/2016

Age of Vehicle 1

CATEGORY Manufacturing Year

POLICY INFORMAT...

ASSESSMENT INFO... 2016

CATEGORY Driver Name

FNOL INFORMATI... CAROLYN NATALIE BAVA

CATEGORY Make

POST SURVEY INF...

CATEGORY Engine No  
POLICY INFORMAT...  
ASSESSMENT INFO... HRA2284586A

CATEGORY Engine Capacity  
POLICY INFORMAT...  
ASSESSMENT INFO... 1197 cc

CATEGORY Sum Insured  
POLICY INFORMAT...  
ASSESSMENT INFO... 0

CATEGORY Market Value  
POLICY INFORMAT...  
ASSESSMENT INFO... 0

FNOL INFORMATI... 0  
POST SURVEY INF...  
CATEGORY Driver License #

FNOL INFORMATI...  
POST SURVEY INF...

CATEGORY License Type  
FNOL INFORMATI...  
POST SURVEY INF...

CATEGORY License Issue Date  
FNOL INFORMATI...  
POST SURVEY INF... mm/dd/yyyy

CATEGORY License Expiration Date  
FNOL INFORMATI...  
POST SURVEY INF... mm/dd/yyyy

CATEGORY Address





SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details    Vehicle & Driver Details    Vehicle Condition    Taxes & Ratio    Parts & Labour    Miscellaneous

Summary

Front left side

BRIDGESTONE 6mm

Front right side

BRIDGESTONE 6mm

Rear left side

BRIDGESTONE 6mm

Rear right side

BRIDGESTONE 6mm

SERVICE REQUESTS    MESSAGES    CLAIMS

### Assessment Details

General & Workshop Details    Vehicle & Driver Details    Vehicle Condition    Taxes & Ratio    Parts & Labour    Miscellaneous    Summary    Parts

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	1	1			LEFT FENDER TRIM			Serviceable	0		20		0
	2	1			WEATHERSTRIP			Serviceable	0		20		0
	3	1			LEFT REINFORCEMENT STAY			Serviceable	0		20		0
	4	1			REINFORCEMENT			Serviceable	0		20		0
	5	1			ENERGY ABSORBER			Serviceable	0		20		0
	6	1			LEFT BUMPER BRACKET			Necessary	35.9	5	20		27.28
	7	1			LEFT BUMPER RETAINER			Necessary	23.8	5	20		18.09
	8	4			CLIP			Necessary	1.2	5	20		3.65
	9	1			REAR BUMPER			Deformed	717	5	20		544.92
	10	1			REAR BUMPER PANEL			Repair	0		20		0

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>	7		REMOVE & INSTALL SEATS, CARPETING & HEADLINER TO FACILITATE REPAIR.	0	0	0	Reviewing	
<input type="checkbox"/>	8		RENEW LEFT QUARTER GLASS TO FACILITATE REPAIR.	0	0	0	Reviewing	
<input type="checkbox"/>	9		RESPRAY REAR BUMPER IN 2 COLOURS, REAR UPPER PANEL, LEFT FENDER ETC. (DISC 5%)	570	0	0	Reviewing	
<input type="checkbox"/>	10		QC, RETUNE & CONSULT CHECK. (NPA)	0	0	0	Reviewing	
<input type="checkbox"/>	11		COMPLIMENTARY WASH & VACUUM. (NPA)	0	0	0	Reviewing	

SERVICE REQUESTS    MESSAGES    CLAIMS

## Assessment Details

General & Workshop Details    Vehicle & Driver Details    Vehicle Condition    Taxes & Ratio    Parts & Labour    Miscellaneous

Summary    Add    Approve    Deny    Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
------	-------	------	--------	--------	---------	--------

<input type="checkbox"/>	1	DAYS OF REPAIR	Reviewing	0	3	
--------------------------	---	----------------	-----------	---	---	--

<input type="checkbox"/>	2	LEFT QUARTER GLASS	Reviewing	0	NOT NECESSARY	
--------------------------	---	--------------------	-----------	---	---------------	--

SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details    Vehicle & Driver Details    Vehicle Condition    Taxes & Ratio    Parts & Labour    Miscellaneous

Summary    Claim Amount    \$2,165.20    Claim Amount    \$2,165.20

CATEGORY    ESTIMATE    REVISED AMOUNT

Labour    \$1,325.25    \$1,325.25

Spare Parts    \$839.95    \$839.95

Submit for Review