



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:VALE OH		Ref: CC4/ASM18004442/Epa3q2 Date: 16/02/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	YP 6653X	Veh. Inspected	SG 5150E
Policy No.	P1969589	Coverage (\$)	0.00
Claim No.	S8M0097Y	Excess (\$)	0.00
Assign From		Assign Date	06/03/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	VOLVO B9TL	c.c	9364
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	YV3S4P925GA180611	Colour	GREEN
Odometer	94953 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
L/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
R/H Rear Tyre	275/70 R22.5	FIRENZA	6 mm
L/H Rear Tyre	275/70 R22.5	FIRENZA	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	14/02/2018	Inspection Date	07/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	