

INS. CASE OWNER:

CC 3, AIG 1800 4443, R1 ea3

LKR:

IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

7/3/18

Registered in Merimen:

7/3/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLE 5073M

Name of Insured:

DI SUN BINTA MOHD ISA

Insured Tel No.:

HP:

91370571

Excess Sec II :SS

D.O.A.:

7/3/2017

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SBD 73U



INSRS:

WSP:

Tel:

Liability:

RMKS:

pml



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

12/3/18

SBD 73U - X ; SLE 5073M - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

Email 23/3/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

FIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE Date/Time: -

Sent By: -

Post-Repair Photos:

Others:

FINALIZATION

Date/Time: 27/3/18

Confirm with: CHRONOS

Confirm by: MIB

Repair Cost:

P/P SS 4,941.35

(4 days)

Reduction:

93 %

Email

Call

FINAL SETTLEMENT

Date/Time: 17/4/18

Confirm with: CHRONOS

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.: 28

If NO or B 28, Ass. Lia: 0%

Repair Cost:

SS 5,293.66

3 VEH C-L ON 2ND

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 240.00

(\$ 60 x 4 days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 3.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 5,535.66

Global Sum SS:

FINAL PAYMENT

Date/Time: 17/4/18

Confirm with: CHRONOS

Email

Call

Payee 1:

SS 5,293.66

Name 1:

INSURANCE MOTOR LIMITED

Payee 2: (Strike if N.A.)

SS 240.00

Name 2:

GIM MAI NOI

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
18/4/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

*320 + *20

The U/C / Chassis frame / Body Structure affected due to collision

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	07/03/18	D.O.I.	12/03/18
Survey held at		PERFORMANCE	

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

[illegible]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18004443/ea3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 07-03-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLE 5073M	Veh. Inspected	SBD 73U	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	07/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/03/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Mon 12/03 @ 8am. SBD 73U
S&R (if liability clear)

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 187401339W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

289, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63465771

313, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190529 (AfterSales)
63190533/535 (Motorrad)
64796801 (AfterSales)
64796824 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

07 MAR 2018

Estimate No. : b1 46149
Date Estimated : 07/03/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Chan Mui Noi
Blk 768 Pasir Ris Street 71
#06-330

singapore 510768

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBD73U	NU80323	31/08/2017	318iA/4Dr	0

DESCRIPTION

To replace rear bumper & attachments including to knock out boot lid and dented area caused by the accident

1275 ~~2,125.00~~

To respray rear bumper and boot lid

1805 ~~2,005.00~~

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 ~~177.00~~

To check electrical wiring systems and lightings at the rear section for proper function.

150 ~~177.00~~

Sundries. *Nil*

80.00

Total Labour 1: 4,565.00

DESCRIPTION

REAR BUMPER CENTRE GUIDE
REAR BUMPER CARRIER (ECE)
INSERT FOR BUMPER REAR (M)
RR BUMPER BOTTOM REINFORCEMENT (M)
REAR BUMPER PANEL PRIMED (M)
RR FLAP TOWING EYE PRIMED (M)
SET MOUNTS PDC SENSOR RR (M)
LETTERING 318i
GROMMET
BADGE (BMW)
REAR SILENCER HEAT SHIELD
CLIP
PLUG BLACK D=5MM
REAR LH REFLECTOR (M)
REAR RH REFLECTOR (M)
DECOUPLING RING PDC TORQUE CONVERTER
ULTRASONIC SENSOR BLACK
(DG) ADHESIVE SET K6

QTY	PRICE
1	32.10
1	432.90
1	137.55
1	80.25
1	1,237.80
1	50.65
1	62.95
1	62.55
2	0.75
1	69.50
1	33.30
10	1.30
10	0.90
1	35.20
1	35.20
2	5.05
2	236.85
1	53.05

VALUE

32.10
432.90
137.55
80.25
1,237.80
50.65
62.95
62.55
1.50
69.50
33.30
13.00
9.00
35.20
35.20
10.10
473.70
53.05

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401159W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63390100 (Sales & Admin)
63390111 (AfterSales)
Fax. 64747770

380, Kembangan Road
East Coast Centre
Singapore 438180
Tel. 63388888 (AfterSales)
Fax. 63465772

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63390328 (AfterSales)
63390333/335 (Motorrad)
64796821 (AfterSales)
64796824 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46149
Date Estimated : 07/03/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBD73U	NU80323	31/08/2017	318iA/4Dr	0

Total Parts : 2,830.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claimed By / 3rd Party / Uninsured Losses / Direct Settlement

Repn No:

Claim To:

Date/Time: 12/03/18 P1130

Excess To:

Surveyor Name: RASUL

Sign:

Surveyor Tel: 90010068

Approved:

Valid To:

Approved Date:

Time:

RESURVEY PARTS PROVIDED BY SURVEYOR Yes/No No/Yes/No

Surveyor's Email:

No. of Working Days Recommended: 4-5 days

Labour 1	:	4,565.00
Parts	:	2,830.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	517.67
Grand Total	:	7,912.97

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sims Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46149
Date Estimated : 07/03/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Chan Mui Noi
Blk 768 Pasir Ris Street 71
#06-330

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

singapore 510768

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SBD73U	NU80323	31/08/2017	318iA/4Dr	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include making good the boot lid and knocking out dents caused by the accident	1275.00		1,275.00
To respray rear bumper and boot lid	1805.00		1,805.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED (M)	1,237.80	1.00		1,237.80
SET MOUNTS PDC SENSOR RR (M)	62.95	1.00		62.95
LETTERING 318i	62.55	1.00		62.55
GROMMET	0.75	2.00		1.50
BADGE (BMW)	69.50	1.00		69.50
(DG) ADHESIVE SET K6	53.05	1.00		53.05

SUPPLEMENTARY ITEMS

Total Labour :	3,460.00
Total Parts :	1,487.35
Total Labour & Parts :	4,947.35
Deduction for Excess :	
Total Repair Costs less Excess:	4,947.35
GST @7%:	346.31
Grand Total :	5,293.66

10 Sin Ming Drive Singapore 575701
Tel: 1800-CALL LTA (1800-2255 582) Fax: (65) 6553 5329

Our ref 2912170203N057012083

29 Dec 2017

CHAN MUI NOI
APT BLK 768 PASIR RIS STREET 71
#06-330
SINGAPORE 510768



Dear Sir/Madam

**NOTIFICATION ON SUCCESSFUL REPLACEMENT OF VEHICLE REGISTRATION NO.
SLR9627X WITH VEHICLE REGISTRATION NO. SBD73U**

You may be pleased to know that your application of 29 Dec 2017 for replacement of registration number is approved.

2. The details of the vehicle after the transaction are as follows:

Vehicle Registration No.	: SBD73U (Previously SLR9627X)
Vehicle Make	: B.M.W.
Vehicle Model	: 318i SEDAN LED NAV MSPT
Chassis No.	: WBA8E36030NU80323
Engine No./ Motor No.	: F1921718B38B15A / -

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Wednesday, 14 March 2018 11:03 AM
To: 'PBSP'; Mei Kwan (LKKAUTO)
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: REQ FOR DIRECT SETTLEMENT - SBD73U AND SLE5073M ON 07/03/2018 *** LKK REF: CC3/AIG18004443/ea3

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents for us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Monday, 12 March 2018 3:51 PM
To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: Re: REQ FOR DIRECT SETTLEMENT - SBD73U AND SLE5073M ON 07/03/2018 *** LKK REF: CC3/AIG18004443/ea3

Dear Asher,

Please let us have your reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Sent: Thursday, 8 March 2018 11:43:33 AM
To: PBSP; Asher Sng (LKKAUTO)
Cc: 甯珺 @; Vic (LKKAUTO)
Subject: RE: REQ FOR DIRECT SETTLEMENT - SBD73U AND SLE5073M ON 07/03/2018 *** LKK REF: CC3/AIG18004443/ea3

Dear Caroline,

Thank you for your email.

Please be informed that we are currently **pending for our insured's report.**

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 8 March, 2018 9:32 AM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: REQ FOR DIRECT SETTLEMENT - SBD73U AND SLE5073M ON 07/03/2018

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]

Sent: Wednesday, 7 March, 2018 6:07 PM

To: assignments <assignments@lkkauto.com>

Cc: Han Kwan Yong <han.kwan.yong@simedarby.com.sg>

Subject: Fw: REQ FOR DIRECT SETTLEMENT - SBD73U AND SLE5073M ON 07/03/2018

Dear Catherine

Please arrange survey on Monday morning, 12.03.2018.

Owner will leave the car in by 8am.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

From: PBSP

Sent: Wednesday, 7 March 2018 12:32 PM

To: 甯瑤 ©; CS A Team

Subject: REQ FOR DIRECT SETTLEMENT - SBD73U AND SLE5073M ON 07/03/2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

• Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SGD 734	Model:	
Date of Accident:	1-3-2018		

Global Sum Settlement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate			\$ 7912.97
Final Repair Cost			\$ 5293.66
Loss of Use			\$ 240.00
Rental (if any)			4 days at \$ 60 per day
LTA / GIA Search Fee			\$ 2.00
Others:			\$
			\$
Final Settlement Sum			\$ 5535.66

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Ltd	\$	5293.66
2)	Performance Motors Ltd	\$	2.00
3)	Chan Mui Noi	\$	240.00

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))



CERTIFICATE OF INSURANCE

■ Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) ■ Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 ■ Road Transport Act, 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VPA/P2046941 Account No. : 13854
Coverage : Comprehensive
Sum Insured : Market Value At The Time Of Loss
Name of Policy Holder : CHAN MUI NOI
Vehicle Registration No. : SLR9627X
Period of Insurance : From 21/12/2017 To 28/02/2019 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

- (a) The Policyholder
The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner
(b) Any other person who is driving on the Policyholder's order or with his permission
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Policyholder's business
The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

(01)

Basic Own Damage Excess : SGD 700.00

An Additional Excess is applicable as follows:
S\$500.00 for Unnamed Authorized Driver &/or Declared Young & Inexperienced Driver.
S\$5,000.00 for Undeclared Young and Inexperienced Driver.
(Please refer to your policy on the terms & conditions)

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD


Authorized Signature

Issued by - SGOVGBP2 on 28/12/2017

IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

10 Sui Ming Drive Singapore 575701
Tel: 1800-CALL LTA (1800-2255 582) Fax: (65) 6553 5329

Our ref: 2912170203N057012083

29 Dec 2017

CHAN MUI NOI
APT BLK 768 PASIR RIS STREET 71
#06-330
SINGAPORE 510768



Dear Sir/Madam

**NOTIFICATION ON SUCCESSFUL REPLACEMENT OF VEHICLE REGISTRATION NO.
SLR9627X WITH VEHICLE REGISTRATION NO. SBD73U**

You may be pleased to know that your application of 29 Dec 2017 for replacement of registration number is approved.

2. The details of the vehicle after the transaction are as follows:

Vehicle Registration No.	: SBD73U (Previously SLR9627X)
Vehicle Make	: B.M.W.
Vehicle Model	: 318i SEDAN LED NAV MSPT
Chassis No.	: WBA8E36030NU80323
Engine No./ Motor No.	: F1921718B38B15A / -

REPUBLIC OF SINGAPORE
IDENTITY CARD NO: S6923208F



CHAN MUI NOI

曾美蓮

CHINESE

Date of Birth

03-07-1969

Sex

F

Country of Birth

SINGAPORE

2118155



NRIC No: S6923208F



Motor Group Date of Issue

A+

11-06-1994

MR. BLK. TEE PAH HUI STREET 77 #01-200
SINGAPORE 110700

NRIC No:

S6923208F

Date:

07-07-1999

No: 2044906

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S6923208F

Name

CHAN MUI NOI

Birth Date: 03 Jul 1969

Issue Date: 24 Jul 2003



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(IES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

05 Jul 1999

NP 428A



Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Friday, 23 March 2018 11:32 AM
To: DI.ISLINA@GMAIL.COM
Subject: ACCIDENT INVOLVING SLE 5073M AND SBD 73U / OTHERS ON 07/03/2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/AIG18004443/R1ea3

23 MAR 2018

DI ISLIN BINTE MOHD ISA

Dear Sir/Madam,

ACCIDENT INVOLVING SLE 5073M AND SBD 73U / OTHERS ON 07/03/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Mr Chan Mui Nai (the third party claimant) of 768 Pao A Rea
St 71, Sipore 510768 (address), owner of 8B073U (vehicle no.)
hereby authorize PERFORMANCE MOTORS LTD ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. 8B073U that was damaged pursuant to the accident which occurred on 27/03/18
(date) along KPE TO ECP (location) involving vehicle no/s
9LE5073M ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 27 (day) of Mar (month) 20 18 (year)

x [Signature]

Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for \$5293.66 (Repair Cost), \$5240.00 (Loss of ~~rental~~/use), \$5200 (Disbursement), for vehicle no. S8D734 that was damaged pursuant to the accident which occurred on 7.3.18 (date) along KPE To ELP (location) involving vehicle no/s SLE5073MA. This is pursuant to the inspection conducted on 12.3.18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Chan Mei Noi ("the third party claimant") of vehicle no. S8D734 make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to S8D734 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 17 (day) of 04 (month) 2018 (year)



MRB

Signed by appointed surveyor

Signed by "the workshop" (with chop)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

180, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190828 (AfterSales)
63190833/330 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1250208

Date IN : 12/03/2018

Cust. Svc. Advisor: Han Kwan Yong

Page No. : 1 of 2

Invoice Number : 1953872 / WSB

Invoice Date : 11/04/2018

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Ms Chan Mui Noi
Blk 768 Pasir Ris Street 71
#06-330

singapore 510768

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.
SBD73U

CHASSIS NO.
NU80323

REGN. DATE
31/08/2017

MODEL
318IA/4DR

MILEAGE
4545

- - - - LABOUR 1 - - - -

To replace rear bumper and attachments including to make
good the rear boot lid and knock out dented area caused
by the accident. To remove
and install body parts in order to carry out painting job.

To respray rear bumper and rear boot lid.

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct checks for
proper function.

To check electrical wiring systems and lightings at the
rear section for proper function.

Sundries.

INS CLAIMS : ACCIDENT REPAIR, DIRECT SETTLEMENT.

DATE OF ACCIDENT : 7.3.2018. 3RD PARTY CAR : SLE5073M.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO
CONSULTANTS PTE LTD ON 12.2018 AT 11.30 AM.
AUTHORISED REPAIR BY MS ASHER SNG FROM LKK ON
14.3.2018 VIA E-MAIL.

PROPOSE LOSS OF USE = \$60X4. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

GIA SEARCH FEE = \$2.00.

NETT

1,275.00

1,805.00

150.00

150.00

80.00

0.00

0.00

0.00

Total Labour 1: 3,460.00

- - - - PARTS - - - -

SET MOUNTS PDC SENSOR RR (M)

(DG) ADHESIVE SET K6

LETTERING 318I

GROMMET

BADGE (BMW)

REAR BUMPER PANEL PRIMED (M)

Qty Retail
Price

1 62.95

1 53.05

1 62.55

2 0.75

1 69.50

1 1,237.80

NETT

62.95

53.05

62.55

1.50

69.50

1,237.80

Total Parts : 1,487.35



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 61190100 (Sales & Admin)
61190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 61190888 (AfterSales)
Fax. 63448773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 61190538 (AfterSales)
61190539/530 (Motorrad)
Fax. 64754601 (AfterSales)
64754604 (Motorrad)

SERVICE TAX INVOICERepair Order No. : **B1 1250208**Date IN : **12/03/2018**Cust. Svc. Advisor: **Han Kwan Yong**Page No. : **2 of 2**Invoice Number : **1953872 / WSB**Invoice Date : **11/04/2018**Payment Terms : **30 Days From Invoice**Invoice By : **Sharon Heng**

Labour Charges : **3,380.00**
Parts Charges : **1,487.35**
Lubricant/Misc : **80.00**

Total Labour & Parts Charges	: S\$	4,947.35
Less Insurance Excess	: S\$	0.00
Invoice Total Amount Exclude GST	: S\$	4,947.35
GST @ 7%	: S\$	346.31
Invoice Total Amount Include GST	: S\$	5,293.66

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 5,293.66**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-035211
Date of Request: 07/03/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 07/03/2018
Enquiry By: Han Kwan Yong
TP Vehicle No: SLE5073M
Accident Date: 07/03/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLE5073M	AIG Asia Pacific Insurance Pte. Ltd.	25/07/2017-24/07/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-035211
Date of Request: 07/03/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 07/03/2018
Enquiry By: Han Kwan Yong
TP Vehicle No: SLE5073M
Accident Date: 07/03/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ [X] GIRO ☐ [] Cash ☐ [] Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Mar 2018 Edit Reg		12 Mar 2018 00:00 Edit Adj Rpt	S\$4,947.35 Edit Estimates	S\$4,947.35 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Di Islin Binte Mohd Isa , ID: S6305331C								
Main Claimant:	CHAN MUI NOI , ID: S6923208F								
Vehicle Reg. No.:	SBD73U	Date of Loss:	07/03/2017 07:00 - :59 [5 Months and 330 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9010977502SG	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SLE5073M	Policy No. (Claimant):	VPA/P2046941						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 16/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SBD73U (9010977502SG)
[SLE5073M]
TP
CHAN MUI NOI
Mar 7 2017 7:00AM
[Di Islin Binte Mohd Isa]
Performance Motors Limited

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page 1	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown								Edit	
Assessment Reports										1 per page 1	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail		Print	
1	08/03/18 12:29	Accident Statement <small>From: SC - Reg. No: SLE5073M, Claimant: DI ISLIN BINTE MOHD ISA</small>								Load HTM	
2	08/03/18 12:30	Accident Statement <small>From: SC - Reg. No: SLE5073M, Claimant: DI ISLIN BINTE MOHD ISA</small>								Load HTM	
Photos/Images										3 per page 1	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	27/03/18 18:32	Odometer Reading								Load JPG <input checked="" type="checkbox"/>	
2	27/03/18 18:32	Chassis Number								Load JPG <input checked="" type="checkbox"/>	
3	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
4	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
5	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
6	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
7	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
8	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
9	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
10	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
11	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
12	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
13	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
14	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
15	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
16	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
17	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
18	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
19	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
20	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
21	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
22	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
23	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
24	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
25	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
26	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
27	27/03/18 18:32	General View								Load JPG <input checked="" type="checkbox"/>	
Documentation											

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/03/18 21:11	TP ESTIMATE	 Load TIF	
2	07/03/18 21:11	TP GIA REPORT	 Load PDF	
3	14/03/18 10:48	TP ESTIMATE - MARKED	 Load PDF	
4	23/03/18 11:46	LETTER TO OI	 Load PDF	
5	17/04/18 12:12	CLAIMANT NRIC	 Load PDF	
6	20/04/18 10:21	WORKSHOP INVOICE	 Load PDF	
7	20/04/18 10:21	AUTHORISATION TO ACT FORM	 Load PDF	
8	20/04/18 10:21	Release Voucher	 Load PDF	
9	20/04/18 10:21	GIA SEARCH	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLE5073M (Insd veh)	Model:	BMW 318i 1.5 SEDAN LED
	SBD73U (TP veh)		NAV (A)
Date of Accident:	07/03/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	7,912.97	
Final Repair Cost	:	\$	5,293.66	
Loss of Use	:	\$	240.00	4.00 days at \$60.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	2.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	5,535.66	
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)				
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ (%)		
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ 100 (%)		Assessed Liability (*): _____ 0 (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 5,295.66
2)	Chan Mui Noi	:	\$ 240.00
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

20 Apr
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18004443/R1EA3Q2

Date: 20/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SBD73U

Insured Vehicle No : SLE5073M

Date of Loss: 07/03/2017

Nature of Claim: TP

Claim No: 9010977502SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBD73U

Make & Model: BMW 318i, 1.5 SEDAN LED NAV (A)

Engine No: F1921718B38B15A

Reg. Date: 31/08/2017 (Man. Year: 2017)

Chassis No: WBA8E36030NU80323

Colour: Black

Odometer: 4545 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,910.30	1,567.35	1,342.95	46.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,485.00	3,380.00	1,105.00	24.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,395.30	4,947.35	2,447.95	33.10
+ GST 7.00/7.00% (S\$)	517.67	346.31	171.36	33.10
Nett Amount (S\$)	7,912.97	5,293.66	2,619.31	33.10
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,535.66		

INSPECTION

Date of Assignment: 12/03/2018

Date Inspected: 12/03/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDIES	Necessary	80.00 FS	*80.00 FS
2	1		*REAR BUMPER CENTRE GUIDE	Not Necessary	32.10 FS	*- FS
3	1		*REAR BUMPER CARRIER (ECE)	Not Necessary	432.90 FS	*- FS
4	1		*INSERT FOR BUMPER REAR (M)	Not Necessary	137.55 FS	*- FS
5	1		*RR BUMPER BOTTOM REINFORCEMENT (M)	Not Necessary	80.25 FS	*- FS
6	1		*REAR BUMPER PANEL PRIMED (M)	Deformed	1,237.80 FS	*1,237.80 FS
7	1		*RR FLAP TOWING EYE PRIMED (M)	Not Necessary	50.65 FS	*- FS
8	1		*SET MOUNTS PDC SENSOR RR (M)	Necessary	62.95 FS	*62.95 FS
9	1		*LETTERING 318I	Necessary	62.55 FS	*62.55 FS
10	2		*GROMMET	Necessary	1.50 FS	*1.50 FS
11	1		*BADGE (BMW)	Necessary	69.50 FS	*69.50 FS
12	1		*REAR SILENCER HEAT SHIELD	Not Necessary	33.30 FS	*- FS
13	10		*CLIP	Not Necessary	13.00 FS	*- FS
14	10		*PLUG BLACK D=5MM	Not Necessary	9.00 FS	*- FS
15	1		*REAR LH REFLECTOR (M)	Not Necessary	35.20 FS	*- FS
16	1		*REAR RH REFLECTOR (M)	Not Necessary	35.20 FS	*- FS
17	2		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	10.10 FS	*- FS
18	2		*ULTRASONIC SENSOR BLACK	Not Necessary	473.70 FS	*- FS
19	1		*(DG) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	2,910.30	1,567.35
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT BOOT LID AND DENTED AREA CAUSED BY THE ACCIDENT	New	2,125.00	1,275.00
2	TO RESPRAY REAR BUMPER AND BOOT LID	New	2,006.00	1,805.00
3	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			4,485.00	3,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >