

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

QBE Insurance (Singapore) Pte Ltd

Blk 60 , Anson Road # 11 - 01
 Maple Tree Anson
 Singapore 179914
 Tel : 6224 - 6633
 Fax : 6534 - 5356

Quotation

DATE : 08.03.2018
 VEH NO : SKV9826D
 MODEL : Toyota Altis
 D O A : 06.03.2018
 YR REF : SJN6994A

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKV9826D (TOYOTA ALTIS)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	List Items		
1	Front Bumper <i>Deformed</i>	1	585.90 ✓
2	Front Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Front Bumper Side Holder - LH & RH <i>m</i>	2	171.80 ✓
4	Front Bumper Reinforcement <i>Best</i>	1	330.90 ✓
5	Front Bumper Sponge <i>Deformed</i>	1	87.50 ✓
6	Front Bumper Lower Grille	1	155.40 x
7	Front Bumper Fog Lamp - LH & RH	2	492.40 x
8	Front Bumper Fog Lamp Cover - LH & RH	2	220.80 x
9	Front Grille <i>Cracked</i>	1	407.10 ✓
10	Front Grille Logo <i>new</i>	1	37.20 ✓
11	Front Grille Clips <i>new</i>	1 set	20.00 ✓
12	Headlamp - LH & RH <i>cracked</i>	2	3,797.60 ✓
13	Front Grille Top Cover <i>Deformed</i>	1	82.20 ✓
14	Front Grille Top Cover Clips <i>m</i>	1 set	15.00 ✓
15	Front Support Panel <i>Best</i>	1	974.50 ✓
16	Air Con Condenser <i>Best</i>	1	1,218.50 ✓
17	Radiator <i>Not new</i>	1	1,550.90 x
18	Radiator Top Cover <i>Deformed</i>	1	89.90 ✓
19	Front Fender - LH & RH <i>Repair</i>	2	1,590.00 x
20	Front Fender Emblem - LH & RH <i>new</i>	2	116.00 ✓
21	Front Brake Panel <i>Best</i>	1	139.10 ✓
22	Rear Bumper <i>Missing</i>	1	495.00 ✓
23	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
24	Rear Bumper Side Holder - LH & RH <i>m</i>	2	171.80 ✓
25	Rear Bumper Reflector - LH & RH <i>m</i>	2	136.00 ✓
26	Rear Bumper Reinforcement <i>Best</i>	1	395.10 ✓
27	Rear Bumper Reinforcement Bracket - LH & RH <i>RH Best</i>	2	156.00 x <i>78</i>

RE : ESTIMATE FOR ACCIDENT REPAIR SKV9826D (TOYOTA ALTIS)

28	Rear End Panel	Distorted	1	595.10	✓
29	Rear End Panel Top Garnish	Dehd	1	235.40	✓
30	Taillamp - LH & RH	RH cracked	2	772.80	386.40
31	Taillamp Lower Bracket - LH & RH	RH cracked	2	116.00	58.
32	Taillamp Panel - RH	Dehd	1	133.60	✓
33	Bootlid	Repis	1	896.10	798.50 X
34	Bootlid Lock	Nol m	1	349.60	X
35	Bootlid Weatherstripe	Nol m	1	175.10	X
36	Bootlid Reflector - LH & RH	RH at	2	690.00	345
37	Toyota Logo	?	1	68.60	✓
38	Corolla Wording	Nol m	1	55.10	✓
39	Altis Wording		1	55.40	✓
40	Rear Fender - RH	Buckled	1	1,070.10	✓
41	Rear Fender Inner Shield - RH	Dehd	1	68.10	✓
42	Rear Fender Inner Shield Clips - RH	m	1 set	20.00	✓
43	Rear Fender Inner Trim - RH	crumpled	1	398.10	✓
44	Rear Fender Inner Trim Clips - RH	m	1 set	30.00	✓
45	Rear Fender Wheelhouse - RH	Repis	1	581.30	X
46	Rear Exhaust Pipe	Best	1	963.60	✓
47	Rear Exhaust Mounting	Nol m	1	46.20	X
48	Rear Exhaust Heat Shield	Best	1	140.10	✓
49	Centre Exhaust Pipe	Best	1	1,150.60	✓
50	Spare Tyre Panel Top Cover	Deformed	1	298.10	✓
51	Rear Windscreen Moulding	Nol m	1	86.10	✓
52	Rear Wheel Rim - RH	at	1	1,645.30	680 (SN)
53	Rear Wheel Hub C/W Bearing - RH	Nol m	1	357.00	X

Less 25%

\$ 32,564.00
(8,141.00)
24,423.00

S/NET ITEMS

1	Front Number Plate	Best	1	30.00	✓
2	Front Number Plate Holder	Deformed	1	30.00	✓
3	Radiator Coolant	Nol m	1	60.00	40
4	Reverse Sensor	Damaged	1	280.00	200
5	Rear End Panel Sealant	?	1	60.00	✓
6	Rear Windscreen Sealant		1	60.00	✓

Total parts

\$ 24,943.00

LABOUR CHARGE

1	To knocking & pull out front & rear portion & renew above parts	\$ 2,800.00	1800
2	To putty & spray up paint works	\$ 2,400.00	1800
3	To check wiring system	\$ 150.00	60

RE : ESTIMATE FOR ACCIDENT REPAIR SKV9826D (TOYOTA ALTIS)

4	To underseal	\$	180.00 80
5	To remove upholstery	\$	150.00 80
6	To remove reverse sensor	\$	100.00 50
7	To remove rear and centre exhaust	\$	300.00 160
8	To remove fuel tank	\$	150.00 80
9	To remove rear windscreen	\$	180.00 120
10	To perform wheel alignment	\$	150.00 80
11	To remove condenser, radiator & to re-gas	\$	180.00 120
Total Labour		\$	6,740.00
Grand Total		\$	31,683.00

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN
THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 17204.87
h/s: 13750
13 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: