

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

Licence Number: **G5182579P**  
Name: **JESSICA LEIGH HENRY**  
Birth Date: **17 May 1972**  
Issue Date: **14 Jan 2013**  
Valid Till: **13 Jan 2018**

0021413768



**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

**EFFECTIVE DATE**

Class 3 Motor Cars  $\leq$  3000kg with  $\leq$  7 passengers, exclusive of the driver; and other motor vehicles  $\leq$  2500kg 14 Jan 2013

NP 428A







Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/02 Singapore Land Tower, Singapore 048628  
Tel: 6553 8888 / Fax: 6553 8392 / Website: www.sompo.com.sg  
Reg. No. 108691006 / UST Reg. No. M201703195

### Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Car No./Policy No. D18M11\*V01002148  
Insured HENRY JESSICA LEIGH  
Motor Car (Registration No.) SKD5852Z  
Cover Comprehensive - ExcelDrive FOCUS  
Policy Commencement Date 17 JANUARY 2018 12:17  
Policy Expiry Date 16 JANUARY 2019 23:59  
Maximum Liability (Section I) Market value at time of loss  
Excess\* \$800 - Section I  
(Waived up to 50% or maximum S\$600 whichever is lower if accident repair is done at ExcelDrive Workshops for the first claim per policy year)  
Voluntary Excess\* NA  
Windscreen Excess\* S\$100.00 - Waived if Repair at ExcelDrive Workshop  
Loss of Use NA  
\* Subject to GST wherever applicable

#### Persons or Classes of Persons entitled to drive\*

1. The Insured
2. Any other person who is driving on the Insured's order or with his permission
3. In the event of the death of the Insured,
  - a. any member of the Insured's family, or a paid driver who has been driving the Motor Car during the life of the Insured and permission to drive had not been withdrawn prior to the death of the Insured; and
  - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

#### Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

#### ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at [www.sompo.com.sg](http://www.sompo.com.sg) or call our Emergency Hotline: (65) 6226 3323.

I/WE HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act 1987 (Malaysia), and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP.27

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue: 17 JANUARY 2018 12:17

#### IMPORTANT NOTICE

- 1. Keep the Certificate in your Motor Car.
- 2. Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- 3. On the sale of this Motor Car or if for any reason the insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).
- 4. This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name: 11R05204 & RUEY AUTO - CI Code: 22A XNDBHQ4KTD0VKAU



PLEASE ARRANGE TO SURVEY  
VEHICLE AT 30 BUKIT BATOK  
CRESCENT (S 658075)

Lee Chen Sin  
CLAIM DEPARTMENT  
DID : 66547520  
FAX :

Date : 07/03/2018

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

**ESTIMATION**

Attn : Motor Claim Department

FAX :

Owner : JESSICA LEIGH HENRY

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPV01002148

Accident Date : 06/03/2018

Vehicle No : SKD-5852-Z

Make & Model : HYUNDAI CM SANTA FE 2.4L ABS D/AB 2WT

## ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY              | DESCRIPTION                  | REPAIRER AMT (\$) | SURVEYOR APP. |
|------------------|------------------------------|-------------------|---------------|
| <u>List Item</u> |                              |                   |               |
| 1                | FRONT BONNET                 | 520.00            | Bt/           |
| 1                | FRONT BONNET ABSORBER LH     | 40.00             | X SUC         |
| 1                | FRONT BONNET ABSORBER RH     | 40.00             | X SUC         |
| 10               | FRONT BONNET INSULATOR CLIPS | 30.00             | acc -         |
| 1                | FRONT BONNET LOCK            | 42.00             | Jan -         |
| 1                | FRONT FENDER LH              |                   | X SUC R       |
| 1                | FRONT FENDER RH              |                   | X SUC R       |
| 1                | HEADLAMP LH                  | 320.00            | ? CRA -       |
| 1                | HEADLAMP RH                  | 320.00            | ? CRA -       |

RESTORE

RESTORE

Date : 07/03/2018

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : JESSICA LEIGH HENRY

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPV01002148

Accident Date : 06/03/2018

Vehicle No : SKD-5852-Z

Make & Model : HYUNDAI CM SANTA FE 2.4L ABS D/AB 2WI

## ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION                    | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|--------------------------------|-------------------|---------------|
| 1   | HEADLAMP LOWER BRACKET LH      | 24.00             | ? ✓ RA -      |
| 1   | HEADLAMP LOWER BRACKET RH      | 24.00             | ? ✓ RA -      |
| 1   | FRONT GRILLE (BASE)            | 95.00             | DE ✓          |
| 1   | FRONT GRILLE (CHROME MOULDING) | 85.00             | CRA ✓         |
| 1   | FRONT GRILLE LOGO (BASE)       | 10.00             | rac ✓         |
| 1   | FRONT GRILLE LOGO              | 26.00             | rac ✓         |
| 10  | FRONT GRILLE CLIPS             | 30.00             | rac ✓         |
| 1   | FRONT BUMPER                   | 245.00            | TUR ✓         |
| 10  | FRONT BUMPER CLIPS             | 30.00             | rac ✓         |
| 1   | FRONT BUMPER SIDE RETAINER LH  | 24.00             | rac ✓         |

Date : 07/03/2018

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : JESSICA LEIGH HENRY

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPV01002148

Accident Date : 06/03/2018

Vehicle No : SKD-5852-Z

Make & Model : HYUNDAI CM SANTA FE 2.4L ABS D/AB 2WT

## ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION                        | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|------------------------------------|-------------------|---------------|
| 1   | FRONT BUMPER SIDE RETAINER RH      | 24.00             | NA ✓          |
| 1   | FRONT BUMPER LOWER GRILLE          | 45.00             | DE ✓          |
| 1   | FRONT BUMPER GARNISH               | 180.00            | TOR ✓         |
| 1   | FRONT NUMBER PLATE BASE            | 36.00             | CRA ✓         |
| 1   | FOG LAMP COVER LH                  | 28.00             | EX ✓          |
| 1   | FOG LAMP COVER RH                  | 28.00             | CRA ✓         |
| 1   | FOG LAMP LH                        | 95.00             | EX ✓          |
| 1   | FOG LAMP RH                        | 95.00             | ? ✓ CRA ✓     |
| 1   | FRONT BUMPER FOAM                  | 85.00             | CRA ✓         |
| 1   | FRONT BUMPER REINFORCEMENT (UPPER) | 220.00            | ? ✓ MT ✓      |

Date : 07/03/2018

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

**ESTIMATION**

Attn : Motor Claim Department

FAX :

Owner : JESSICA LEIGH HENRY

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPV01002148 Accident Date : 06/03/2018

Vehicle No : SKD-5852-Z Make & Model : HYUNDAI CM SANTA FE 2.4L ABS D/AB 2WI

## ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION              | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|--------------------------|-------------------|---------------|
| 1   | SUPPORT PANEL            | 380.00            | CRA ✓         |
| 1   | CONDENSER                | 260.00            | BA ✓          |
| 1   | RADIATOR                 | 380.00            | CRA ✓         |
| 1   | RADIATOR FAN ASSY        | 300.00            | ? ✓ CRA ✓     |
|     | <b>Sub Total</b>         | <b>4061.00</b>    |               |
|     | <b>Add 10% On Parts</b>  | <b>406.10</b>     |               |
|     | <b>Special Nett Item</b> |                   |               |
| 1   | FRONT NUMBER PLATE       | 35.00             | me ✓          |
| 1   | RADIATOR COOLANT         | 30.00             | me ✓          |



Date : 07/03/2018

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : JESSICA LEIGH HENRY

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPV01002148

Accident Date : 06/03/2018

Vehicle No : SKD-5852-Z

Make & Model : HYUNDAI CM SANTA FE 2.4L ABS D/AB 2WI

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

| QTY | DESCRIPTION                                                  | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|--------------------------------------------------------------|-------------------|---------------|
|     | Sub Total                                                    | 65.00             |               |
|     | <b>Labour &amp; Misc</b>                                     |                   |               |
|     | LABOUR TO CARRY OUT FRONT REPAIR                             | <del>700.00</del> | 600           |
|     | TO CHECK AND RECONNECT ALL NECESSARY WIRINGS                 | 35.00             |               |
|     | TO SPRAY PAINTING ON FRONT AFFECTED AREA                     | <del>700.00</del> | 600           |
|     | TO REMOVE & FIX AIRCON CONDENSER INCLUDING TOP UP AIRCON GAS | <del>150.00</del> | 100           |
|     | Sub Total                                                    | 1585.00           |               |

Remarks:

6 days - p/p / Repair by paint

SUB TOTAL 6,117.10

GST 7.0 % 428.20

TOTAL 6,545.30

Surveyor's name: Rasal - Hp 90010088

Principal's name: JESSICA LEIGH HENRY

Survey Date & Time: 08/03/18 @ 1710

EXCESS: 400

PERCENT

PAGE : 5

PLEASE ARRANGE TO SURVEY  
VEHICLE AT 30 BUKIT BATOK  
CRESCENT (S 658075)

Lee Chen Sin  
CLAIM DEPARTMENT  
DID : 66547520  
FAX :

Date : 27/03/2018

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

**SUPPLEMENTARY**

Attn : Motor Claim Department

FAX :

Owner : JESSICA LEIGH HENRY

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPV01002148

Accident Date : 06/03/2018

Vehicle No : SKD-5852-Z

Make & Model : HYUNDAI CM SANTA FE 2.4L ABS D/AB 2WL

## ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 400.00

| QTY | DESCRIPTION | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|-------------|-------------------|---------------|
|-----|-------------|-------------------|---------------|

### List Item

|   |                              |        |     |
|---|------------------------------|--------|-----|
| 1 | FRONT BONNET SEAL            | 30.00  | at- |
| 1 | POWER STEERING PIPE          | 160.00 | PA- |
| 1 | AIR DUCT                     | 36.00  | at- |
| 1 | WIPER TANK                   | 65.00  | DE- |
| 1 | FRONT BONNET HINGE LH        | 40.00  | PA- |
| 1 | FRONT BONNET HINGE RH        | 40.00  | at- |
| 1 | FRONT BUMPER GARNISH (OUTER) | 360.00 | at- |
| 1 | SUPPORT PANEL TOP GARNISH    | 45.00  | DE- |



Date : 27/03/2018

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

**SUPPLEMENTARY**

Attn : Motor Claim Department

FAX :

Owner : JESSICA LEIGH HENRY

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPV01002148

Accident Date : 06/03/2018

Vehicle No : SKD-5852-Z

Make & Model : HYUNDAI CM SANTA FE 2.4L ABS D/AB 2WT

## ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 400.00

| QTY | DESCRIPTION      | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|------------------|-------------------|---------------|
|     | Sub Total        | 776.00            |               |
|     | Add 10% On Parts | 77.60             |               |

Remarks:

|                  |        |
|------------------|--------|
| <b>SUB TOTAL</b> | 853.60 |
| <b>GST 7.0 %</b> | 59.75  |
| <b>TOTAL</b>     | 913.35 |

Surveyor's name: \_\_\_\_\_

Principal's name: JESSICA LEIGH HENRY

Survey Date & Time: \_\_\_\_\_

Date : 27/03/2018  
To : SOMPO INSURANCE SINGAPORE PTE. LTD.

Attn : Motor Claim Department FAX :

Owner : JESSICA LEIGH HENRY  
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.  
Certificate No : D18MTPV01002148 Accident Date : 06/03/2018  
Vehicle No : SKD-5852-Z Make & Model : HYUNDAI CM SANTA FE 2.4L ABS D/AB 2WD

FINAL ESTIMATED REPAIR COST DETAIL Excess : 0.00 Add Excess : 400.00

| QTY              | DESCRIPTION                  | REPAIRER AMT (\$) | SURVEYOR AMT (\$) |
|------------------|------------------------------|-------------------|-------------------|
| <u>List Item</u> |                              |                   |                   |
| 1                | FRONT BONNET SEAL            | 30.00             | 30.00             |
| 1                | POWER STEERING PIPE          | 160.00            | 160.00            |
| 1                | AIR DUCT                     | 36.00             | 36.00             |
| 1                | WIPER TANK                   | 65.00             | 65.00             |
| 1                | FRONT BONNET HINGE LH        | 40.00             | 40.00             |
| 1                | FRONT BONNET HINGE RH        | 40.00             | 40.00             |
| 1                | FRONT BUMPER GARNISH (OUTER) | 360.00            | 360.00            |
| 1                | SUPPORT PANEL TOP GARNISH    | 45.00             | 45.00             |
| 1                | FRONT BONNET                 | 520.00            | 520.00            |
| 1                | FRONT BONNET ABSORBER LH     | 40.00             | 0.00              |
| 1                | FRONT BONNET ABSORBER RH     | 40.00             | 0.00              |
| 10               | FRONT BONNET INSULATOR CLIPS | 30.00             | 30.00             |
| 1                | FRONT BONNET LOCK            | 42.00             | 42.00             |
| 1                | FRONT FENDER LH              | RESTORE 0.00      | 0.00              |

Supplementary item



Date : 27/03/2018  
To : SOMPO INSURANCE SINGAPORE PTE. LTD.

Attn : Motor Claim Department FAX :

Owner : JESSICA LEIGH HENRY  
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.  
Certificate No : D18MTPV01002148 Accident Date : 06/03/2018  
Vehicle No : SKD-5852-Z Make & Model : HYUNDAI CM SANTA FE 2.4L ABS D/AB 2WD

FINAL ESTIMATED REPAIR COST DETAIL Excess : 0.00 Add Excess : 400.00

| QTY | DESCRIPTION                    | REPAIRER AMT (\$) | SURVEYOR AMT (\$) |
|-----|--------------------------------|-------------------|-------------------|
| 1   | FRONT FENDER RH RESTORE        | 0.00              | 0.00              |
| 1   | HEADLAMP LH                    | 320.00            | 320.00            |
| 1   | HEADLAMP RH                    | 320.00            | 320.00            |
| 1   | HEADLAMP LOWER BRACKET LH      | 24.00             | 24.00             |
| 1   | HEADLAMP LOWER BRACKET RH      | 24.00             | 24.00             |
| 1   | FRONT GRILLE (BASE)            | 95.00             | 95.00             |
| 1   | FRONT GRILLE (CHROME MOULDING) | 85.00             | 85.00             |
| 1   | FRONT GRILLE LOGO (BASE)       | 10.00             | 10.00             |
| 1   | FRONT GRILLE LOGO              | 26.00             | 26.00             |
| 10  | FRONT GRILLE CLIPS             | 30.00             | 30.00             |
| 1   | FRONT BUMPER                   | 245.00            | 245.00            |
| 10  | FRONT BUMPER CLIPS             | 30.00             | 30.00             |
| 1   | FRONT BUMPER SIDE RETAINER LH  | 24.00             | 24.00             |
| 1   | FRONT BUMPER SIDE RETAINER RH  | 24.00             | 24.00             |
| 1   | FRONT BUMPER LOWER GRILLE      | 45.00             | 45.00             |

PAGE : 2





Date : 27/03/2018

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : JESSICA LEIGH HENRY

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPV01002148 Accident Date : 06/03/2018

Vehicle No : SKD-5852-Z Make & Model : HYUNDAI CM SANTA FE 2.4L ABS D/AB 2WD

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 400.00

| QTY | DESCRIPTION                                     | REPAIRER AMT (\$) | SURVEYOR AMT (\$) |
|-----|-------------------------------------------------|-------------------|-------------------|
| 1   | FRONT BUMPER GARNISH                            | 180.00            | 180.00            |
| 1   | FRONT NUMBER PLATE BASE                         | 36.00             | 36.00             |
| 1   | FOG LAMP COVER LH                               | 28.00             | 0.00              |
| 1   | FOG LAMP COVER RH                               | 28.00             | 28.00             |
| 1   | FOG LAMP LH                                     | 95.00             | 0.00              |
| 1   | FOG LAMP RH                                     | 95.00             | 95.00             |
| 1   | FRONT BUMPER FOAM                               | 85.00             | 85.00             |
| 1   | FRONT BUMPER REINFORCEMENT - Check item (UPPER) | 220.00            | 220.00            |
| 1   | SUPPORT PANEL                                   | 380.00            | 380.00            |
| 1   | CONDENSER                                       | 260.00            | 260.00            |
| 1   | RADIATOR                                        | 380.00            | 380.00            |
| 1   | RADIATOR FAN ASSY - Check item                  | 300.00            | 300.00            |

PAGE : 3



Date : 27/03/2018  
To : SOMPO INSURANCE SINGAPORE PTE. LTD.

Attn : Motor Claim Department FAX :

Owner : JESSICA LEIGH HENRY  
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.  
Certificate No : D18MTPV01002148 Accident Date : 06/03/2018  
Vehicle No : SKD-5852-Z Make & Model : HYUNDAI CM SANTA FE 2.4L ABS D/AB 2WD

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 400.00

| QTY | DESCRIPTION                                  | REPAIRER AMT (\$) | SURVEYOR AMT (\$) |
|-----|----------------------------------------------|-------------------|-------------------|
|     | Sub Total                                    | 4837.00           | 4634.00           |
|     | Add 10% On Parts                             | 0.00              | 483.70            |
|     |                                              |                   | 463.40            |
|     | <u>Special Nett Item</u>                     |                   |                   |
| 1   | FRONT NUMBER PLATE                           | 35.00             | 35.00             |
| 1   | RADIATOR COOLANT                             | 30.00             | 30.00             |
|     | Sub Total                                    | 65.00             | 65.00             |
|     | <u>Labour &amp; Misc</u>                     |                   |                   |
|     | LABOUR TO CARRY OUT FRONT REPAIR             | 700.00            | 600.00            |
|     | TO CHECK AND RECONNECT ALL NECESSARY WIRINGS | 35.00             | 35.00             |
|     | TO SPRAY PAINTING ON FRONT AFFECTED AREA     | 700.00            | 600.00            |
|     | TO REMOVE & FIX AIRCON CONDENSER             | 150.00            | 100.00            |

PAGE: 4



Date : 27/03/2018  
To : SOMPO INSURANCE SINGAPORE PTE. LTD.

Attn : Motor Claim Department FAX :

Owner : JESSICA LEIGH HENRY  
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.  
Certificate No : D18MTPV01002148 Accident Date : 06/03/2018  
Vehicle No : SKD-5852-Z Make & Model : HYUNDAI CM SANTA FE 2.4L ABS D/AB 2WD

FINAL ESTIMATED REPAIR COST DETAIL Excess : 0.00 Add Excess : 400.00

| QTY | DESCRIPTION                 | REPAIRER AMT (\$) | SURVEYOR AMT (\$) |
|-----|-----------------------------|-------------------|-------------------|
|     | INCLUDING TOP UP AIRCON GAS |                   |                   |
|     | Sub Total                   | 1585.00           | 1335.00           |

|           |          |          |
|-----------|----------|----------|
| Sub Total | 6,970.70 | 6,497.40 |
| GST 7.0 % | 487.95   | 454.82   |
| Total     | 7,458.65 | 6,952.22 |

COR: \$ 6,497.40 (PART BY PART)

6 DAYS REPAIR

EXCESS - \$ 400.00

PARTS - \$ 4634.00 + 10%

- \$ 509.40

S/N - \$ 65.00

LABOUR - \$ 1335.00

\$ 6497.40

Surveyor Name : RASUL - LKK

Date & Time : 08/03/2018 5:10:00 PM

Lee Chen Sin

CLAIM DEPARTMENT

DID : 66547520

FAX :

PAGE: 5



豐裕工業 (私營) 有限公司  
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)  
No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496958 Fax: 67495866/67495007  
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800. Tel: 6396 6369 / 6394 2235 Fax: 6394 2245  
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774  
Co. Reg. No.: 197602013M



lo.: M2-00252314

ECL1

IOZ PROTECT PTE LTD  
22 TAMPINES ST 92  
5852 Z(P/O:151980)  
IER BY:BRYAN

TAX INVOICE NO.: TL124878  
INVOICE DATE : 10/03/2018  
CREDIT TERMS : 30 DAYS  
SALES ORDER NO.:  
SALESMAN : TBS  
PAGE(S) : 1

AX INVOICE

| TS NO.        | DESCRIPTION                    | LOC. | QUANTITY | UNIT PRICE | AMOUNT |
|---------------|--------------------------------|------|----------|------------|--------|
|               |                                |      |          | (SIN)      | (SIN)  |
| 100-2B500     | PANEL ASSY-HOOD                |      | 1 ✓      | 520.000    | 520.00 |
| 101282        | CLIP, HOOD INSULATOR           |      | 10 ✓     | 3.000      | 30.00  |
| 130-2B300     | LATCH ASSY-HOOD                |      | 1 PCS    | 42.000     | 42.00  |
| 161-2B710     | GRILLE-RADIATOR                |      | 1 ✓      | 95.000     | 95.00  |
| 152-2B710 790 | CR PIECE 1-RADIATOR GRILLE     |      | 1 ✓      | 85.000     | 85.00  |
| 152-2B730 720 | GUARD-RADIATOR GRILLE          |      | 1 ✓      | 10.000     | 10.00  |
| 100-4A900     | EMBLEM-SYMBOL MARK             |      | 1 ✓      | 26.000     | 26.00  |
| 190-28000     | CLIP                           |      | 10 PCS   | 3.000      | 30.00  |
| 111-2B700     | COVER-FR BUMPER                |      | 1 PCS    | 245.000    | 245.00 |
| 190-28000     | CLIP                           |      | 10 PCS   | 3.000      | 30.00  |
| 115-2B700     | BRACKET-FR BUMPER SIDE MTG, LH |      | 1 ✓      | 24.000     | 24.00  |

DUSTRIAL (PTE) LIMITED

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

SIGNATURE

10:00

SIGNATURE

豐裕工業 (私營) 有限公司  
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)  
No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496958 Fax: 67495866/67495007  
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800. Tel: 6396 6369 / 6394 2235 Fax: 6394 2245  
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774  
Co. Reg. No.: 197602013M



lo.: M2-00252314

ECL1

IOZ PROTECT PTE LTD  
22 TAMPINES ST 92  
5852 Z(P/O:151980)  
IER BY:BRYAN

TAX INVOICE NO.: TL124878  
INVOICE DATE : 10/03/2018  
CREDIT TERMS : 30 DAYS  
SALES ORDER NO.:  
SALESMAN : TBS  
PAGE(S) : 2

AX INVOICE

| TS NO.    | DESCRIPTION                    | LOC. | QUANTITY | UNIT PRICE | AMOUNT |
|-----------|--------------------------------|------|----------|------------|--------|
|           |                                |      |          | (SIN)      | (SIN)  |
| 116-2B700 | BRACKET-FR BUMPER SIDE MTG, RH |      | 1 ✓      | 24.000     | 24.00  |
| 112-2B700 | MESH-FR BPR AIR INTAKE HOLE    |      | 1 ✓      | 45.000     | 45.00  |
| 125-2B700 | LIP-FR BPR (Return) (exchange) |      | 1 ✓      | 180.000    | 180.00 |
| 124-2B700 | COVER-BLANKING FR FOG RH       |      | 1 PCS    | 28.000     | 28.00  |
| 120-2B700 | ABSORBER-FR BUMPER ENERGY      |      | 1 ✓      | 85.000     | 85.00  |
| 101-2B800 | CARRIER ASSY-FR END MODULE     |      | 1 ✓      | 380.000    | 380.00 |
| 1021M540  | A/C CONDENSER(97606-1U100)     |      | 1 PCS    | 260.000    | 260.00 |
| 110-2B400 | RADIATOR ASSY                  |      | 1 ✓      | 380.000    | 380.00 |
| 119-2BAA0 | GARNISH, FR NUMBER PLATE       |      | 1 PCS    | 36.000     | 36.00  |

DUSTRIAL (PTE) LIMITED

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL



豐裕工業 (私營) 有限公司  
FONG EE INDUSTRIAL (PTE) LIMITED  
(AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496958 Fax: 67495866/67495007  
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800. Tel: 6396 6369 / 6384 2235 Fax: 6384 2245  
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774  
Co. Reg. No.: 197602013M

lo.: M2-00252314

ECLT

IOZ PROTECT PTE LTD  
22 TAMPINES ST 92  
I 5852 Z(P/O:151980)  
IER BY:BRYAN

AX INVOICE



TAX INVOICE NO.: TL124878  
INVOICE DATE : 10/03/2018  
CREDIT TERMS : 30 DAYS  
SALES ORDER NO.:  
SALESMAN : TBS  
PAGE(S) : 3

| TSNO. | DESCRIPTION | LOC. | QUANTITY | UNIT PRICE<br>(SIN) | AMOUNT<br>(SIN) |
|-------|-------------|------|----------|---------------------|-----------------|
|       |             |      |          |                     |                 |
|       |             |      |          | GST Excl Amount :   | 2555.00         |
|       |             |      |          | Special Discount :  |                 |
|       |             |      |          | GST @ 7 % :         | 178.85          |

DUSTRIAL (PTE) LIMITED

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

PRINT BY :  
TBS 10/03/2018 09:04:30



Lee Chen Sin

TOTAL

2733.85

SIGNATURE

SIGNATURE

豐裕工業 (私營) 有限公司  
FONG EE INDUSTRIAL (PTE) LIMITED  
(AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496958 Fax: 67495866/67495007  
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800. Tel: 6396 6369 / 6384 2235 Fax: 6384 2245  
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774  
Co. Reg. No.: 197602013M

lo.: M2-00252314

ECLT

IOZ PROTECT PTE LTD  
22 TAMPINES ST 92  
IGAPORE 528876  
I 5852 Z(P/O:151980)  
IER BY:BRYAN

AX INVOICE



TAX INVOICE NO.: TL124893  
INVOICE DATE : 12/03/2018  
CREDIT TERMS : 30 DAYS  
SALES ORDER NO.:  
SALESMAN : TBS  
PAGE(S) : 1

| TSNO     | DESCRIPTION                            | LOC. | QUANTITY | UNIT PRICE<br>(SIN) | AMOUNT<br>(SIN) |
|----------|----------------------------------------|------|----------|---------------------|-----------------|
| 65-2BAA0 | ORDER BY:BRYAN<br>SKID PLATE-FR BUMPER |      | 1 PCS    | 360.000             | 360.00          |
|          |                                        |      |          | GST Excl Amount :   | 360.00          |
|          |                                        |      |          | Special Discount :  |                 |
|          |                                        |      |          | GST @ 7 % :         | 25.20           |

DUSTRIAL (PTE) LIMITED

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

PRINT BY :  
TBS 12/03/2018 11:15:21

Lee Chen Sin



TOTAL

385.20



豐裕工業 (私營) 有限公司  
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)  
No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496958 Fax: 67495866/67495007  
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800. Tel: 6396 6369 / 6384 2235 Fax: 6384 2245  
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774  
Co. Reg. No.: 197602013M



o.: M2-00252314

ECL1

IOZ PROTECT PTE LTD  
22 TAMPINES ST 92  
SINGAPORE 528876  
5852 Z(P/O:151980)  
ORDER BY: BRYAN

TAX INVOICE NO.: TL124895  
INVOICE DATE : 12/03/2018  
CREDIT TERMS : 30 DAYS  
SALES ORDER NO.:  
SALESMAN : TBS  
PAGE(S) : 1

AX INVOICE

| TS NO.   | DESCRIPTION                  | LOC. | QUANTITY | UNIT PRICE | AMOUNT |
|----------|------------------------------|------|----------|------------|--------|
|          | ORDER BY: BRYAN              |      |          | (SIN)      | (SIN)  |
| 01-2B065 | LAMP ASSY-HEAD, LH           |      | 1        | 320.000    | 320.00 |
| 02-2B065 | LAMP ASSY-HEAD, RH           |      | 1        | 320.000    | 320.00 |
| 56-2B000 | BRKT-FR BUMPER SIDE SUPT, RH |      | 1        | 24.000     | 24.00  |
| 55-2B000 | BRKT-FR BUMPER SIDE SUPT, LH |      | 1 PCS    | 24.000     | 24.00  |
| 30-2B000 | REINFORCEMENT, FR BUMPER     |      | 1 PCS    | 220.000    | 220.00 |
| 80-1U100 | BLOWER ASSY-RADIATOR         |      | 1        | 300.000    | 300.00 |
| 55-2B000 | STRIP, HOOD                  |      | 1 PCS    | 30.000     | 30.00  |
| 40-2B100 | COOLER TUBE, P/S             |      | 1 PCS    | 160.000    | 160.00 |
| 20-2B600 | RESERVOIR ASSY-W/SHLD WASHER |      | 1        | 65.000     | 65.00  |
| 10-2B000 | HINGE ASSY-HOOD LH           |      | 1        | 40.000     | 40.00  |
| 20-2B000 | HINGE ASSY-HOOD RH           |      | 1        | 40.000     | 40.00  |

DUSTRIAL (PTE) LIMITED

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL


Lee Chen Sin

SIGNATURE

SIGNATURE

豐裕工業 (私營) 有限公司  
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)  
No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496958 Fax: 67495866/67495007  
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800. Tel: 6396 6369 / 6384 2235 Fax: 6384 2245  
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774  
Co. Reg. No.: 197602013M



o.: M2-00252314

ECL1

IOZ PROTECT PTE LTD  
22 TAMPINES ST 92  
SINGAPORE 528876  
5852 Z(P/O:151980)  
ORDER BY: BRYAN

TAX INVOICE NO.: TL124895  
INVOICE DATE : 12/03/2018  
CREDIT TERMS : 30 DAYS  
SALES ORDER NO.:  
SALESMAN : TBS  
PAGE(S) : 2

AX INVOICE

| TS NO.     | DESCRIPTION        | LOC. | QUANTITY | UNIT PRICE | AMOUNT  |
|------------|--------------------|------|----------|------------|---------|
|            | ORDER BY: BRYAN    |      |          | (SIN)      | (SIN)   |
| 1213-2B600 | AIR CUCT           |      | 1 PCS    | 36.000     | 36.00   |
|            | GST Excl Amount :  |      |          |            | 1579.00 |
|            | Special Discount : |      |          |            |         |
|            | GST @ 7 % :        |      |          |            | 110.53  |

DUSTRIAL (PTE) LIMITED

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

1689.53

PRINT BY :  
TBS 12/03/2018 11:53:43

Lee Chen Sin



豐裕工業 (私營) 有限公司  
FONG EE INDUSTRIAL (PTE) LIMITED  
(AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496958 Fax: 67495866/67495007  
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800. Tel: 6396 6369 / 6384 2235 Fax: 6384 2245  
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774  
Co. Reg. No.: 197602013M



No.: M2-00252314

ECLT

HOZ PROTECT PTE LTD  
.22 TAMPINES ST 92  
NGAPORE 528876  
D 5852 Z(P/O:151980)  
DER BY:BRYAN

TAX INVOICE NO.: TL124896  
INVOICE DATE : 12/03/2018  
CREDIT TERMS : 30 DAYS  
SALES ORDER NO.:  
SALESMAN : TBS  
PAGE(S) : 1

AX INVOICE

| RTS NO.   | DESCRIPTION                           | LOC. | QUANTITY | UNIT PRICE         | AMOUNT          |
|-----------|---------------------------------------|------|----------|--------------------|-----------------|
| 202-2B500 | ORDER BY:BRYAN<br>LAMP ASSY-FR FOG,RH |      | 1        | (SIN )<br>95.000   | (SIN )<br>95.00 |
|           |                                       |      |          | GST Excl Amount :  | 95.00           |
|           |                                       |      |          | Special Discount : |                 |
|           |                                       |      |          | GST @ 7 % :        | 6.65            |

INDUSTRIAL (PTE) LIMITED

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

101.65

PRINT BY :  
TBS 12/03/2018 12:23:52

Lee Chen Sin

SIGNATURE

SIGNATURE

豐裕工業 (私營) 有限公司  
FONG EE INDUSTRIAL (PTE) LIMITED  
(AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496958 Fax: 67495866/67495007  
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800. Tel: 6396 6369 / 6384 2235 Fax: 6384 2245  
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774  
Co. Reg. No.: 197602013M



No.: M2-00252314

ECLT

IOZ PROTECT PTE LTD  
22 TAMPINES ST 92  
IGAPORE 528876  
D 5852 Z(P/O:151980)  
DER BY:BRYAN

TAX INVOICE NO.: TL124908  
INVOICE DATE : 13/03/2018  
CREDIT TERMS : 30 DAYS  
SALES ORDER NO.:  
SALESMAN : TBS  
PAGE(S) : 1

AX INVOICE

| TS NO.    | DESCRIPTION                                 | LOC. | QUANTITY | UNIT PRICE         | AMOUNT          |
|-----------|---------------------------------------------|------|----------|--------------------|-----------------|
| 153-2B700 | ORDER BY:BRYAN<br>COVER RADIATOR GRILLE UPR |      | 1        | (SIN )<br>45.000   | (SIN )<br>45.00 |
|           |                                             |      |          | GST Excl Amount :  | 45.00           |
|           |                                             |      |          | Special Discount : |                 |
|           |                                             |      |          | GST @ 7 % :        | 3.15            |

INDUSTRIAL (PTE) LIMITED

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

48.15

PRINT BY :  
TBS 13/03/2018 09:06:32

Lee Chen Sin



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18004460/R1qbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 25-05-2018



Code : SMO

## 1. Policy Particulars :- OWN DAMAGE

|              |                 |                |            |
|--------------|-----------------|----------------|------------|
| Insured Veh. |                 | Veh. Inspected | SKD 5852Z  |
| Policy No.   | D18MTPV01002148 | Coverage (\$)  | 0.00       |
| Claim No.    | CMTD1801008/NSW | Excess (\$)    | 400.00     |
| Assign From  | MELVIN YE       | Assign Date    | 07/03/2018 |

## 2. Vehicle Particulars & Condition

|              |                  |              |            |
|--------------|------------------|--------------|------------|
| Make & Model | HYUNDAI SANTA FE | c.c          | 2359       |
| Engine No.   | HIDDEN           | Year of Reg. | 2011       |
| Chassis No.  | KMHS81BMCU854084 | Colour       | GREY       |
| Odometer     | 109668           | Steering     | IN ORDER   |
| Brakes       | IN ORDER         | Modification | SPORTS RIM |
| General      | FAIR             |              |            |

## 3. Conditions of Tyres

|                | Size       | Make     | Balance |
|----------------|------------|----------|---------|
| R/H Front Tyre | 235/65 R17 | MICHELIN | 6 mm    |
| L/H Front Tyre | 235/65 R17 | MICHELIN | 6 mm    |
| R/H Rear Tyre  | 235/65 R17 | MICHELIN | 6 mm    |
| L/H Rear Tyre  | 235/65 R17 | MICHELIN | 6 mm    |

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

## 5. General Information

|                |                                                                |                 |            |
|----------------|----------------------------------------------------------------|-----------------|------------|
| Accident Date  | 06/03/2018                                                     | Inspection Date | 08/03/2018 |
| Survey held at | ETHOZ GROUP LTD<br>30 BUKIT BATOK CRESCENT<br>SINGAPORE 658075 |                 |            |

## 5a. Remarks

- A)THE MARKET VALUE IS S\$57,000.00 (EST. AVERAGE)  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 6 Working Days |
|-------------------------------------|----------------|





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 5852Z

| Qty | Description of Parts                     | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>       |                      |                           |                   |
| 1   | FRONT BONNET (WCP)                       | BENT                 | 520.00                    | 520.00            |
| 1   | FRONT BONNET ABSORBER LH (WCP)           | SERVICEABLE          | 40.00                     | -                 |
| 1   | FRONT BONNET ABSORBER RH (WCP)           | SERVICEABLE          | 40.00                     | -                 |
| 10  | FRONT BONNET INSULATOR CLIPS (WCP)       | NECESSARY            | 30.00                     | 30.00             |
| 1   | FRONT BONNET LOCK (WCP)                  | JAMMED               | 42.00                     | 42.00             |
| 1   | FRONT FENDER LH (NPA) (WCP)              | TO REPAIR SEE LABOUR | -                         | -                 |
| 1   | FRONT FENDER RH (NPA) (WCP)              | TO REPAIR SEE LABOUR | -                         | -                 |
| 1   | HEADLAMP LH (WCP)                        | CRACKED              | 320.00                    | 320.00            |
| 1   | HEADLAMP RH (WCP)                        | CRACKED              | 320.00                    | 320.00            |
| 1   | HEADLAMP LOWER BRACKET LH (WCP)          | BENT                 | 24.00                     | 24.00             |
| 1   | HEADLAMP LOWER BRACKET RH (WCP)          | BENT                 | 24.00                     | 24.00             |
| 1   | FRONT GRILLE (BASE) (WCP)                | DEFORMED             | 95.00                     | 95.00             |
| 1   | FRONT GRILLE (CHROME MOULDING) (WCP)     | CRACKED              | 85.00                     | 85.00             |
| 1   | FRONT GRILLE LOGO (BASE) (WCP)           | NECESSARY            | 10.00                     | 10.00             |
| 1   | FRONT GRILLE LOGO (WCP)                  | NECESSARY            | 26.00                     | 26.00             |
| 10  | FRONT GRILLE CLIPS (WCP)                 | NECESSARY            | 30.00                     | 30.00             |
| 1   | FRONT BUMPER (WCP)                       | TORN                 | 245.00                    | 245.00            |
| 10  | FRONT BUMPER CLIPS (WCP)                 | NECESSARY            | 30.00                     | 30.00             |
| 1   | FRONT BUMPER SIDE RETAINER LH (WCP)      | NECESSARY            | 24.00                     | 24.00             |
| 1   | FRONT BUMPER SIDE RETAINER RH (WCP)      | NECESSARY            | 24.00                     | 24.00             |
| 1   | FRONT BUMPER LOWER GRILLE (WCP)          | DEFORMED             | 45.00                     | 45.00             |
| 1   | FRONT BUMPER GARNISH (WCP)               | TORN                 | 180.00                    | 180.00            |
| 1   | FRONT NUMBER PLATE BASE (WCP)            | CRACKED              | 36.00                     | 36.00             |
| 1   | FOG LAMP COVER LH (WCP)                  | SERVICEABLE          | 28.00                     | -                 |
| 1   | FOG LAMP COVER RH (WCP)                  | CRACKED              | 28.00                     | 28.00             |
| 1   | FOG LAMP LH (WCP)                        | SERVICEABLE          | 95.00                     | -                 |
| 1   | FOG LAMP RH (WCP)                        | CRACKED              | 95.00                     | 95.00             |
| 1   | FRONT BUMPER FOAM (WCP)                  | CRACKED              | 85.00                     | 85.00             |
| 1   | FRONT BUMPER REINFORCEMENT (UPPER) (WCP) | BENT                 | 220.00                    | 220.00            |
| 1   | SUPPORT PANEL (WCP)                      | CRACKED              | 380.00                    | 380.00            |
| 1   | CONDENSER (WCP)                          | BENT                 | 260.00                    | 260.00            |
| 1   | RADIATOR (WCP)                           | CRACKED              | 380.00                    | 380.00            |

Report Ref No. CS/SMO18004460/R1qbn2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts                                                                             | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
| 1   | RADIATOR FAN ASSY (WCP)                                                                          | CRACKED   | 300.00                    | 300.00            |
| 1   | FRONT BONNET SEAL (ADDITIONAL)(WCP)                                                              | CUT       | 30.00                     | 30.00             |
| 1   | POWER STEERING PIPE (ADDITIONAL)(WCP)                                                            | BENT      | 160.00                    | 160.00            |
| 1   | AIR DUCT (ADDITIONAL)(WCP)                                                                       | CUT       | 36.00                     | 36.00             |
| 1   | WIPER TANK (ADDITIONAL)(WCP)                                                                     | DEFORMED  | 65.00                     | 65.00             |
| 1   | FRONT BONNET HINGE LH (ADDITIONAL)(WCP)                                                          | BENT      | 40.00                     | 40.00             |
| 1   | FRONT BONNET HINGE RH (ADDITIONAL)(WCP)                                                          | BENT      | 40.00                     | 40.00             |
| 1   | FRONT BUMPER GARNISH (OUTER) (ADDITIONAL)(WCP)                                                   | CUT       | 360.00                    | 360.00            |
| 1   | SUPPORT PANEL TOP GARNISH (ADDITIONAL)(WCP)                                                      | DEFORMED  | 45.00                     | 45.00             |
|     | COST PLUS 10%                                                                                    |           | 483.70                    | 463.40            |
|     |                                                                                                  |           | 5,320.70                  | 5,097.40          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                                                                 |           |                           |                   |
| 1   | FRONT NUMBER PLATE (SN)                                                                          | MISSING   | 35.00                     | 35.00             |
| 1   | RADIATOR COOLANT (SN)                                                                            | NECESSARY | 30.00                     | 30.00             |
|     |                                                                                                  |           | 65.00                     | 65.00             |
|     | <b><u>LABOUR</u></b>                                                                             |           |                           |                   |
|     | LABOUR TO CARRY OUT FRONT REPAIR.INCLUSIVE OF THE REPAIR OF FRONT FENDER LH AND FRONT FENDER RH. |           | 700.00                    | 600.00            |
|     | TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.                                                    |           | 35.00                     | 35.00             |
|     | TO SPRAY PAINTING ON FRONT AFFECTED AREA.                                                        |           | 700.00                    | 600.00            |
|     | TO REMOVE & FIX AIRCON CONDENSER INCLUDING TOP UP AIR CON GAS.                                   |           | 150.00                    | 100.00            |
|     |                                                                                                  |           | 1,585.00                  | 1,335.00          |
|     | <b>GRAND TOTAL</b>                                                                               |           | <b>6,970.70</b>           | <b>6,497.40</b>   |
|     | <b>RECOMMENDED COST OF REPAIRS</b>                                                               |           |                           | <b>6,497.40</b>   |
|     | <b>LESS EXCESS</b>                                                                               |           |                           | <b>-400.00</b>    |
|     | <b>NETT LIABILITY</b>                                                                            |           |                           | <b>6,097.40</b>   |

Report Ref No. CS/SMO18004460/R1qbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.