

ASS. PEC. BY:

REF: CS/FCI18004478/GSD3

Special Instruction:

Surveyor:
CWS

ASSIGNMENT (Office)

From (Person): Joanne Yong

of FCI

Date/Time: 8/3/18 @ 9.12am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJC 833D

Insured: SHD 3897T

at Workshop m/s B L Garage

Tel: 6507/3848

of 25 Kaki Bkt Rd 4 Synergy #03-24

Policy No:

Claim No: D18001906MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 6/3/2018

09/03/2018

CA / REV / REP. / REV 24 HRS/wp

H.O.D. Endorsement:

Date/Time: 9.21am @ 8/3/18

Person Contacted: Ah loon

Vehicle IN/OUT

Date/Time	Action/Instruction (✓), Estimate
	SJC 833D - NA / CTI17010514/r3
	SHD 3897T - CS/FCI16011586/UVbd1
19/07/13	@ 17:26 p.m. revised PA to Joanne via email.

D.O.A: 30/5/17

D.O.A: 19/6/16

REF:

Surveyor

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SJC833D Yr Regn: Jan / 08
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Vios J c.c. 1497
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 135544 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR053HY9305040460
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 185 / 60 R 15
 R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$29k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. _____ D.O.I. 9/3/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>Evo Diang, pls fill in condition</u>
<u>02/09/18</u>	<u>Confirmed L/S \$3,400/- @ 5 days with X6A</u> <u>(\$ 3,938.59 Red - 64%)</u>
	RECEIVED 10 SEP 2018

Date/Time, File Pass to? : Preli. Report
10/09/18 : Final Report
 1) Typist
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: 5
 Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee.	<u>170</u>
Transportation.	<u>50</u>
S + RS. SI	<u>50</u>
Photos	<u>48</u>
Others	
TOTAL	<u>318</u>

Report Format : _____
 Lump Sum / I.B.I. : (\$ 3,400/- L/S)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001906MFSH

Date: 19 July 2018

Our Ref: CS/FCI18004478/Gsd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJC 833D.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 09/03/2018 at the premises of M/s B L Garage Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 9,338.59</u>
Revised Estimate Amount (Lump Sum)	: <u>S\$ 5,195.73</u>
"Check" Items Amount	: <u>S\$</u>
Market Value	: <u>S\$</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 5 Days

Yours faithfully,
Xing Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	06-03-2018	Our Ref No. D18001906MFSH
Accident Date	06-03-2018	Claim Type. Third Party
Insured Vehicle	SHD3897T	Third Party Vehicle. SJC833D
Survey Location	25 KAKI BUKIT ROAD 4SYNERGY @ KB #03-24	
Contact Person.	AMYLIA	
Contact No.	65073848/ 92406288	Fax No. 67023533
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	B L GARAGE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235686)



PRI Documents



Close



PRI Header Details

Claim No	D18001906MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & B L GARA
Workshop Name	B L GARAGE PTE LTD (Contact Person : AMYLIA)	Survey Location & Contact Details	25 KAKI BUKIT ROAD 4SYNERGY @ KB #03-24 Mobile: 92406288 , Phone: 65073848 , Fax: 6702353: EmailId: AMYLIA.BLGARAGE@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3897T	TP Vehicle No	SJC833D
PRI Recieved Date	07-03-2018 01:28:48 PM	Surveyor Appointed Date	08-03-2018 09:10:56 AM	Surveyor Accept Date	08-03-2018 1

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	08-03-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details	
Vehicle No.:	SJC833D
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS J AUTO
Chassis No.:	MR053HY9305040460
Propellant:	Petrol
Engine No.:	1NZX662811
Engine Capacity:	1497 cc
Maximum Power Output:	80.0 kW (107 bhp)
Maximum Laden Weight:	1505 kg
Unladen Weight:	1095 kg
Year Of Manufacture:	2007
Original Registration Date:	31 Jan 2008
Lifespan Expiry Date:	-
COE Category:	A - Car (1600cc & below)
PQP Paid:	\$21,485.00
COE Expiry Date:	30 Jan 2023
Road Tax Expiry Date:	30 Jul 2018
Inspection Due Date:	30 Jan 2019
Intended Transfer Date:	16 Jul 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 30 Jul 2018. You may renew the road tax from 30 Apr 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 30 Jul 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 31 Jul 2018 to 30 Jan 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	377.00	-	377.00
Total Amount Payable:			402.00
Amount Payable (From 31 Jul 2018 to 30 Jul 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 7 September 2018 3:31 PM
To: 'Amylia Wong'
Cc: sur@lkkauto.com
Subject: RE: Invoice for SJC833D - Accident Involving SJC833D & SHD3897T along Lorong 6 Toa Payoh Towards Braddell Road Intersection on 06.03.2018

Hi Amylia,

Please amend final invoice and all supporting documents and re-sent over to **First Capital Insurance Ltd.**

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Amylia Wong [mailto:amyliablgarage@gmail.com]

Sent: Friday, 7 September 2018 11:59 AM

To: ShirleyHiew@lkkauto.com

Subject: Re: Invoice for SJC833D - Accident Involving SJC833D & SHD3897T along Lorong 6 Toa Payoh Towards Braddell Road Intersection on 06.03.2018

Hi,

Confirm with the final fig.

On Fri, Sep 7, 2018 at 11:46 AM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Amylia,

Please re-confirmed final fig of \$3,400.00 (lump sum) @ 5 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Amylia Wong [mailto:amyliablgarage@gmail.com]

Sent: Wednesday, 5 September 2018 5:34 PM

To: sur@lkkauto.com

Subject: Re: Invoice for SJC833D - Accident Involving SJC833D & SHD3897T along Lorong 6 Toa Payoh Towards Braddell Road Intersection on 06.03.2018

Hi,

Attached estimation list for your reference.

On Wed, Sep 5, 2018 at 5:23 PM Amylia Wong <amyliablgarage@gmail.com> wrote:

Hi,

Please refer to the attached invoice as requested.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 19 July 2018 5:26 PM
To: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: 'LKK Assignments'; 'SUR'
Subject: RE: SURVEY ASSESSMENT - D18001906MFSH/1
Attachments: SJC 833D - Preli Advise.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SJC 833D.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Thursday, 8 March, 2018 9:24 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; "SUR" <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001906MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 8 March 2018 9:11 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001906MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5667J
Vehicle Details	
Vehicle No.:	SJC833D
Vehicle to be Exported:	No
Intended De-registration Date:	16 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS J AUTO
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	1NZX662811
Chassis No.:	MR053HY9305040460
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,074.00
Original Registration Date:	31 Jan 2008
First Registration Date:	31 Jan 2008
Transfer Count:	2
Actual ARF Paid:	\$9,478.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jan 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$21,485.00
COE Rebate Amount:	\$19,498.00
Total Rebate Amount:	\$19,498.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 16 Jul 2018

OK

B L GARAGE PTE LTD

BUS. REGN. NO. 201613916C
 25 KAKI BUKIT ROAD 4 #03-24 SYNERGY @KB SINGAPORE 417800
 TEL: 9240 6288 FAX: 6702 3577
 Email: amyliia.blgarage@gmail.com

THIRD PARTY CLAIM ESTIMATION

FIRST CAPITALINSURANCE LTD

36 Robinson, City House,
 #16-01 Singapore 068877

Vehicle Number	: SJC833D
Make / Model	: Toyota Vios J
Chassis Number	: MR053HY9305040460
Accident Date	: 06/03/2018
Reference	: SJC833D

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	Rear bumper ✓ <i>re</i>	\$ 451.25 /
2	Rear bumper retainer (short) RH/LH @ \$42.00 ✓ <i>re</i>	\$ 84.00 /
2	Rear bumper retainer (long) RH/LH @ \$98.00 ✓ <i>re</i>	\$ 196.00 /
2	Rear bumper bracket LH/RH @ \$75.10 ✗ <i>nn</i>	\$ 150.20 X
2	Rear bumper reflector LH/RH @ \$90.00 ✗ <i>nn</i>	\$ 180.00 X
1	Bootlid ✓ <i>BT</i>	\$ 585.00 /
1	Bootlid emblem logo ✓ <i>mc</i>	\$ 56.30 /
1	Bootlid emblem Vios ✓ <i>mc</i>	\$ 61.00 /
1	Bootlid handle ✗ <i>nn</i>	\$ 217.80 X
1	Bootlid handle clips ✗ <i>nn</i>	\$ 13.80 X
1	Bootlid lock ✓ <i>BT</i>	\$ 151.40 /
1	Bootlid lock catch ✗ <i>nn</i>	\$ 44.20 X
2	Bootlid hinge LH/RH @ \$79.00 ✗ <i>nn</i>	\$ 158.00 X
1	Bootlid rubber ✓ <i>cut</i>	\$ 212.49 /
1	Bootlid inner trim ✗ <i>nn</i>	\$ 251.16 X
2	Number plate lamp @ \$67.00 ✗ <i>nn</i>	\$ 134.00 X
1	End panel ✓ <i>BT</i>	\$ 539.13 645.00 /
1	End panel top garnish ✓ <i>re</i>	\$ 89.65 241.72 /
1	Rear exhaust silencer ✗ <i>nn</i>	\$ 881.63 X
2	Rear exhaust mounting @ \$36.00 ✗ <i>nn</i>	\$ 72.00 X
1	Rear exhaust heat shield ✗	\$ 186.00 X
2	Taillamp RH/LH @ \$324.60 ✓ <i>MA</i>	\$ 649.20 /
2	Taillamp panel RH/LH @ \$191.35 ✗ <i>nn</i>	\$ 382.70 X
2	Taillamp inner shield RH/LH @ \$31.60 ✗ <i>nn</i>	\$ 63.20 X
2	Taillamp clips @ \$7.90 ✓ <i>re</i>	\$ 15.80 /
1	Spare tyre top board ✓ <i>cut</i>	\$ 228.5 446.10 /
1	Spare tyre lock screw ✗ <i>nn</i>	\$ 53.40 X
1	Spare tyre panel ✗ <i>nn</i>	\$ 886.75 X
1	Spare tyre garnish ✗ <i>nn</i>	\$ 145.00 X
		\$ 7,615.10
		Less 10% Subtotal \$ (761.51)
		\$ 6,853.59

2319.72
25%: 2489.79

B L GARAGE PTE LTD
 BUS. REGN. NO. 201613916C
 25 KAKI BUKIT ROAD 4 #03-24 SYNERGY @KB SINGAPORE 417800
 TEL: 9240 6288 FAX: 6702 3577
 Email: amyliia.blgarage@gmail.com

THIRD PARTY CLAIM ESTIMATION

FIRST CAPITALINSURANCE LTD

36 Robinson, City House,
 #16-01 Singapore 068877

Vehicle Number	: SJC833D
Make / Model	: Toyota Vios J
Chassis Number	: MR053HY9305040460
Accident Date	: 06/03/2018
Reference	: SJC833D

Qty	Particulars	Unit Price - SGD \$
	<u>PARTS REPLACEMENT - LIST ITEMS</u>	
1	Rear bumper ✓	\$ 451.25
2	Rear bumper retainer (short) RH/LH @ \$42.00 ✓	\$ 84.00
2	Rear bumper retainer (long) RH/LH @ \$98.00 ✓	\$ 196.00
2	Rear bumper bracket LH/RH @ \$75.10 X	\$ 150.20
2	Rear bumper reflector LH/RH @ \$90.00 X ✓	\$ 180.00
1	Bootlid ✓	\$ 585.00
1	Bootlid emblem logo ✓	\$ 56.30
1	Bootlid emblem Vios ✓	\$ 61.00
1	Bootlid handle X	\$ 217.80
1	Bootlid handle clips X	\$ 13.80
1	Bootlid lock ✓	\$ 151.40
1	Bootlid lock catch X	\$ 44.20
2	Bootlid hinge LH/RH @ \$79.00 X	\$ 158.00
1	Bootlid rubber ✓	\$ 212.49
1	Bootlid inner trim ⊗	\$ 251.16
2	Number plate lamp @ \$67.00 X	\$ 134.00
1	End panel X ✓	\$ 645.00
1	End panel top garnish ✓	\$ 241.72
1	Rear exhaust silencer X	\$ 881.63
2	Rear exhaust mounting @ \$36.00 X	\$ 72.00
1	Rear exhaust heat shield X	\$ 186.00
2	Taillamp RH/LH @ \$324.60 LH - RH ✓	\$ 649.20
2	Taillamp panel RH/LH @ \$191.35 X	\$ 382.70
2	Taillamp inner shield RH/LH @ 31.60 X	\$ 63.20
2	Taillamp clips @ \$7.90 ✓	\$ 15.80
1	Spare tyre top board X ✓	\$ 446.10
1	Spare tyre lock screw X ✓	\$ 53.40
1	Spare tyre panel X	\$ 886.75
1	Spare tyre garnish X	\$ 145.00
		\$ 7,615.10
	Less 10%	\$ (761.51)
	Subtotal	\$ 6,853.59

<u>PARTS REPLACEMENT- SPECIAL NETT ITEMS</u>		
1	Rear number plate ✓	\$ 50.00
1	Bootlid inner trim clips ✗	\$ 25.00
1	End panel garnish clips ✓	\$ 12.00
1	End panel sealant ✓	\$ 60.00
1	Rear bumper clips ✓	\$ 38.00
1	Reverse sensor ✓	\$ 200.00
1	Spare tyre panel sealant ✗	\$ 80.00
	Subtotal	\$ 465.00
	Balance C/F	\$ 7,318.59
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	\$ 7,318.59
1.	To remove and transfer of bootlid component.	\$ 40 60.00
2.	To remove and refit inner trims and garnishes.	\$ 50 50.00
3.	To straighten and replace rear exhaust silencer.	\$ X 100.00
4.	To check wiring and lighting system.	\$ 30 50.00
5.	To remove and refit rear bumper sensor.	\$ 40 60.00
6.	To apply undercoating on affected area	\$ 60 100.00
7.	To spray paint on affected area.	\$ 600 800.00
8.	To straighten, repair, realign and replace damaged parts.	\$ 600 800.00
	Subtotal	\$ 2,020.00
	Grand total	\$ 9,338.59

SDany s.

lump sum repair 1

After repair photos.

Guo Guoy - 82880282

09/3/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18004478/Gsd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-09-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3897T	Veh. Inspected	SJC 833D
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18001906MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	08/03/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA VIOS J	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053HY9305040460	Colour	BLACK
Odometer	135544	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	MICHELIN	5 mm
L/H Front Tyre	185/60 R15	MICHELIN	5 mm
R/H Rear Tyre	185/60 R15	MICHELIN	5 mm
L/H Rear Tyre	185/60 R15	MICHELIN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/03/2018	Inspection Date	09/03/2018
Survey held at	B L GARAGE PTE LTD 25 KAKI BUKIT ROAD 4 #03-24 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJC 833D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	451.25	451.25
2	REAR BUMPER RETAINER (SHORT) RH/LH @\$42.00	DEFORMED	84.00	84.00
2	REAR BUMPER RETAINER (LONG) RH/LH @\$98.00	DEFORMED	196.00	196.00
2	REAR BUMPER BRACKET LH/RH @\$75.10	NOT NECESSARY	150.20	-
2	REAR BUMPER REFLECTOR LH/RH @\$90.00	NOT NECESSARY	180.00	-
1	BOOTLID	BENT	585.00	585.00
1	BOOTLID EMBLEM LOGO	NECESSARY	56.30	56.30
1	BOOTLID EMBLEM VIOS	NECESSARY	61.00	61.00
1	BOOTLID HANDLE	NOT NECESSARY	217.80	-
1	BOOTLID HANDLE CLIPS	NOT NECESSARY	13.80	-
1	BOOTLID LOCK	BENT	151.40	151.40
1	BOOTLID LOCK CATCH	NOT NECESSARY	44.20	-
2	BOOTLID HINGE LH/RH @\$79.00	NOT NECESSARY	158.00	-
1	BOOTLID RUBBER	CUT	212.49	212.49
1	BOOTLID INNER TRIM	NOT NECESSARY	251.16	-
2	NUMBER PLATE LAMP @\$67.00	NOT NECESSARY	134.00	-
1	END PANEL	BENT	645.00	539.13
1	END PANEL TOP GARNISH	DEFORMED	241.72	89.65
1	REAR EXHAUST SILENCER	NOT NECESSARY	881.63	-
2	REAR EXHAUST MOUNTING @\$36.00	NOT NECESSARY	72.00	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	186.00	-
2	TAILLAMP RH/LH @\$324.60	CRACKED	649.20	649.20
2	TAILLAMP PANEL RH/LH @\$191.35	NOT NECESSARY	382.70	-
2	TAILLAMP INNER SHIELD RH/LH @\$31.60	NOT NECESSARY	63.20	-
2	TAILLAMP CLIPS @\$7.90	NECESSARY	15.80	15.80
1	SPARE TYRE TOP BOARD	CUT	446.10	228.50
1	SPARE TYRE LOCK SCREW	NOT NECESSARY	53.40	-
1	SPARE TYRE PANEL	NOT NECESSARY	886.75	-
1	SPARE TYRE GARNISH	NOT NECESSARY	145.00	-
	LESS 10% DISCOUNT		-761.51	-

Report Ref No. CS/FCI18004478/Gsd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-	-829.93
			6,853.59	2,489.79
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	BENT	50.00	40.00
1	BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	25.00	-
1	END PANEL GARNISH CLIPS (SN)	NECESSARY	12.00	12.00
1	END PANEL SEALANT (SN)	NECESSARY	60.00	40.00
1	REAR BUMPER CLIPS (SN)	NECESSARY	38.00	38.00
1	REVERSE SENSOR (SN)	DAMAGED	200.00	200.00
1	SPARE TYRE PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
			465.00	330.00
	LABOUR			
	TO REMOVE AND TRANSFER OF BOOTLID COMPONENT.		60.00	40.00
	TO REMOVE AND REFIT INNER TRIMS AND GARNISHES.		50.00	50.00
	TO STRAIGHTEN AND REPLACE REAR EXHAUST SILENCER.	NOT NECESSARY	100.00	-
	TO CHECK WIRING AND LIGHTING SYSTEM.		50.00	30.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		60.00	40.00
	TO APPLY UNDERCOATING ON AFFECTED AREA.		100.00	60.00
	TO SPRAY PAINT ON AFFECTED AREA.		800.00	600.00
	TO STRAIGHTEN,REPAIR,REALIGN AND REPLACE DAMAGED PARTS.		800.00	600.00
			2,020.00	1,420.00
	GRAND TOTAL		9,338.59	4,239.79
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CS/FC18004478/Gsd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.