

CT AUTO PTE LTD

16 Sin Ming Industrial Estate Sector A, #01-83, Singapore 575674

Tel: 64563008 Fax: 64599942 Email: admin@ctauto.com.sg

Business Registration No. 201420132H

GST Registration No. 201420132H

Mr. Leong
9353 3333

ESTIMATE

Date: 5/3/2018

DOA: 25/2/2018

Vehicle No: SLC4931D

Make & Model: Volkswagen Passat 1.8 TSI

1	1	Rear R/H Door	Painted	\$ 2,568.00	✓
2	1	Rear R/H Door Top Window Glass Moulding	SVC	\$ 178.70	X
3	1	Rear R/H Door Bottom Window Glass Moulding	SVC	\$ 296.40	X ✓
4	1	Rear R/H Door Side Chrome Moulding	NT	\$ 160.50	✓
5	1	Rear R/H Door Outer Handle	NT	\$ 458.00	X
6	1	Rear R/H Door Lock Mechanism	2. Down	\$ 298.60	✓
7	1	Rear R/H Door Lock Catch	NT	\$ 48.20	X
8	1	Rear R/H Door Power Window with Regulator	2. NT	\$ 482.80	2 X
9	2	Rear R/H Door Hinges	2. SVC	\$ 329.60	2 ✓
10	1	Rear R/H Door Checker	2. SVC	\$ 129.40	X
11	1	Rear R/H Door Inner Trim Board	2. mounting grade	\$ 1,855.40	2 ✓
12	1	Rear R/H Door WeatherStrip	NT	\$ 316.80	✓
13	1	Rear R/H Door Lower Outer Garnish Protector	deformation	\$ 91.00	✓
14	1	Rear R/H Fender	Painted	\$ 1,613.60	✓
15	1	Rear R/H Fender Inner Shield	NT	\$ 232.20	2 ✓
16	1	Rear W/S Glass Moulding	NT	\$ 993.00	✓
17	1	R/H Side Skirt	NT	\$ 291.10	✓
18	1	R/H Side Skirt Corner Garnish	NT	\$ 103.80	✓
19	1	Rear R/H Lower Arm	2. distorted	\$ 406.60	2 ✓
20	1	Rear R/H Upper Arm	2. distorted	\$ 221.50	2 ✓
21	1	Rear R/H Control Arm	2. distorted	\$ 345.70	2 ✓
22	1	Rear R/H Knuckle Arm	2. distorted	\$ 748.00	2 ✓
23	1	Rear R/H Knuckle Bearing	2. NT	\$ 309.30	2 ✓
24	1	Rear Bumper	Painted	\$ 1,606.30	X
25	2	Rear Bumper Side Retainer (Upper)	SVC	\$ 190.90	X
26	2	Rear Bumper Side Retainer (Lower)	SVC	\$ 190.90	X
27	2	Rear Bumper Side Chrome	SVC	\$ 522.90	X ✓
				\$ 14,989.00	
		Less 10%		\$ 1,498.90	
				\$ 13,490.10	
		Special Net Items			
1		Sundries	NT	\$ 50.00	2 X
2	1 set	Rear R/H Door Top Window Glass Moulding Clips	NT	\$ 50.00	X
3	1 set	Rear R/H Door Bottom Window Glass Moulding Clips	NT	\$ 50.00	✓
4	1 set	Rear R/H Door Side Chrome Moulding Clips	NT	\$ 50.00	2 X
5	1 set	Rear R/H Door Inner Trim Board Clips	NT	\$ 301-80.00	2 ✓
6	1 set	Rear R/H Door Lower Outer Garnish Protector Clips	NT	\$ 50.00	X
7	1	Rear R/H Fender	NT	\$ 150.00	✓
8	1 set	Rear R/H Fender Inner Shield Clips	NT	\$ 50.00	X
9	1	Rear W/S Glass Moulding Sealant	NT	\$ 401-120.00	✓
10	1	Rear W/S Glass Moulding Damping Seal	NT	\$ 401-120.00	✓
11	1 set	R/H Side Skirt Clips	NT	\$ 301-50.00	✓
12	1 set	R/H Side Skirt Corner Garnish Clips	NT	\$ 301-50.00	✓
13	1 set	Rear Bumper Clips	NT	\$ 301-50.00	✓
				\$ 920.00	
		Total parts		\$ 14,410.10	
S/N	Labour Description			Amount	Amount
1	Labour for panel beating, cut, weld, straighten and replace rear damaged parts.			\$ 1,600.00	1000/-
2	To putty and spray painting rear portion.			\$ 1,200.00	800/-
3	To check rear lighting and wiring.			\$ 80.00	30/-
4	To remove and install rear door lock mechanism.			\$ 150.00	60/- NT

5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 350.00	100/-
6	To apply anti rust proofing to rear affected area.	\$ 250.00	80/-
7	To remove rear undercarriage to facilitate repairs	\$ 380.00	180/-
8	To remove and install rear windscreen.	\$ 150.00	120/-
9	To remove and install rear fuel tank.	\$ 250.00	110/-
10	To perform 4 wheel alignment and balancing.	\$ 120.00	80/-
11	To remove & refit door component to replace door, check & re-adjust the close gap and alignment and water seepage	\$ 120.00	60/-
	Total labour :	\$ 4,650.00	
	Total parts :	\$ 14,410.10	
	Total labour :	\$ 4,650.00	
	Total repair cost : (Before GST)	\$ 19,060.10	

08/03/2017 21630m

Not Antimal

45mm 5 days.

Ryan

97237799

LKK And

9

Check part prices.

LKK Auto Consultants hence notify the Repairs of the following:

- To receive telephone spray painting
- To display damaged parts during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary liability must be supervised and is subject to final approval from Insurance Company

Acknowledged by Repairs

Signature:

Date:

CT AUTO PTE LTD

16 Sin Ming Industrial Estate Sector A, #01-83, Singapore 575674

Tel: 64563008 Fax: 64599942 Email: admin@ctauto.com.sg

Business Registration No. 201420132H

GST Registration No. 201420132H

ESTIMATE

Date: 5/3/2018

DOA: 25/2/2018

Vehicle No: SLC4931D

Make & Model: Volkswagen Passat 1.8 TSI

S/N	Qty	Item Description	Parts Price	Surveyor
Supplementary Items				
1	1	Rear R/H Shock Absorber <i>distorted</i>	\$ 469.40	✓
2	1	Rear R/H Door Inner Trim Panel <i>st</i>	\$ 264.80	✓
			\$ 734.20	
		Less 10%	\$ 73.42	
			\$ 660.78	
Special Nett Items				
		Sundries <i>hnl</i>	\$ 50.00	X
1	1	Rear R/H Rim <i>cut</i>	\$ 650.00	✓
2	1	Rear R/H Tyre <i>abraded, depreciation.</i>	\$ 350.00	✓
			\$ 1,050.00	
		Total Parts	\$ 1,710.78	

09/03/2018

[Signature]

Chenck Partman.

2kk Anu

[Signature]