

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person):

Rachel Tan

of

GAI

Date/Time:

8/3/18 @ 10:31am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKC 5196P

Insured:

GBC 26424

at Workshop m/s

Kang Car Repairers

Tel:

6747 7636

of

1 Kaki Bkt Ave 6 #02-06 Autobay

Policy No:

Claim No:

KCR 03 2018 5196 GAI C

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

12:26pm 08/3/18

Person Contacted:

SharonVehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKC 5196P-XGBC 26424-NA/GAI 17023501/24D.O.A: 7/12/201709/3/18 @ 2:44pm Informed Rachel, we are pending estimate from repairer.18/3/18 @ 11:51am revised to Rachel Tan by email.US \$70000, 28 days. CRD \$23675.22, 542)

ASS. REC. BY: Adrian King

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 28 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKC5196P Yr Regn: 2011 / SeptType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis C.C: 1598.Colour: White A/C: Insured / Std / NI / NASp. Reading: 135246 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR053REE104121361Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16.R: 205/55R16.BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mmL/Bal. 06 mm

D.O.A.

Rear

R/Bal. 06 mmL/Bal. 06 mmD.O.I. 08/03/18Survey held at KangDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Great American

MV: 461K

PV: 261K

Nett: 201K.

RECEIVED 22 MAY 2018

Date/Time, File Pass to?

1) 21/5/18

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final ReportDays Of Repair: 28Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) \$ + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$Report Format: TPLump Sum / B.I. (\$) 20000

450




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY			Ref : CS/GAI18004481/Aqd3	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date : 08-03-2018	
			Code : GAI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBC 2642U	Veh. Inspected	SKC 5196P	
Policy No.		Coverage (\$)	0.00	
Claim No.	KCR0320185196GAIC	Excess (\$)	0.00	
Assign From	RACHEL TAN	Assign Date	08/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	04/03/2018	Inspection Date	08/03/2018	
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: KCR0320185196GAIC

Date: 18<sup>th</sup> May 2018

Our Ref: CS/GAI18004481/Aqd3

The Motor Claims Department  
Great American Insurance Company

Attn: Rachel

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. SKC 5196P**


We thank you for the instruction on 08/03/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/03/2018 at the premises of M/s KANG CAR REPAIRERS and have the following to report:-

Workshop Estimate Amount	: S\$ <u>43,625.22</u>
Revised Estimate Amount	: S\$ <u>20,000.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the front & rear portion.



Comments/ Present Status:

Damages consistent.

We have NOT authorise repair.

Yours faithfully

ADRIAN LING WAI PING  
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI  
Licensed Appraiser

## Nivitha (LKK Auto)

---

**From:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Sent:** Thursday, 8 March 2018 10:31 AM  
**To:** kangcar@singnet.com.sg  
**Cc:** Kang Car (yahoo); LKK Assignments  
**Subject:** RE: RE: NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR SKC5196P; ACCDT INVLG SKC5196P AND GBC2642U (GA) ON 04.03.2018  
**Attachments:** MRM33986273.pdf

Hi LKK

Please accept assignment, OI GIA report attached.  
Please review MV.

Regards  
Rachel Tan  
Executive, Motor Claims, Great American Insurance Company  
Tel: 6804 7846

-----Original Message-----

From: Kang Car Repairers Pte Ltd [mailto:kangcar@singnet.com.sg]  
Sent: Thursday, March 8, 2018 10:19 AM  
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>  
Cc: Kang Car (yahoo) <kangcar176@yahoo.com.sg>  
Subject: Re: RE: NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR SKC5196P; ACCDT INVLG SKC5196P AND GBC2642U (GA) ON 04.03.2018

WITHOUT PREJUDICE

Dear Rachel,

Please appoint LKK Auto Consultants to conduct the pre repair inspection on our client's vehicle .

Thank you & Regards,  
Sharon  
Kang Car Repairers Pte Ltd  
Tel: 6747 7636  
Fax: 6748 5071

-----Original Message-----

From : Rachel.Tan@sg.gaig.com  
Date : 07/03/2018 - 17:27 GMT+8  
To : kangcar@singnet.com.sg  
Subject : RE: NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR SKC5196P; ACCDT INVLG SKC5196P AND GBC2642U (GA) ON 04.03.2018

Without Prejudice

Dear Sharon

We append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. L.B.S. Automotive Appraisal Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants
6. JP KNIGHTS PTE LTD

Kindly let us know which SJE is selected and furnish the estimates for the survey to be carried out.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

-----Original Message-----

From: Kang Car Repairers Pte Ltd [mailto:kangcar@singnet.com.sg]

Sent: Wednesday, March 07, 2018 4:54 PM

To: General Claims <GeneralClaims@sg.gaig.com>; Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; Michael.Tay@sg.gaig.com

Cc: Customer Service <Customer.Service@sg.gaig.com>; Kang Car (yahoo) <kangcar176@yahoo.com.sg>

Subject: Fwd: NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR SKC5196P; ACCDT INVLG SKC5196P AND GBC2642U ON 04.03.2018

WITHOUT PREJUDICE

RESEND.

Thank you & Regards,

Sharon

Kang Car Repairers Pte Ltd

Tel: 6747 7636

Fax: 6748 5071

-----Original Message-----

From : kangcar@singnet.com.sg

Date : 07/03/2018 - 12:02 GMT+8

To : general.claims@sg.gaig.com

Cc : kangcar176@yahoo.com.sg

Subject : NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR SKC5196P; ACCDT INVLG SKC5196P AND GBC2642U ON 04.03.2018

WITHOUT PREJUDICE

Our Ref: KCR0320185196GAIC

Your Ref: GBC2642U

07.03.2018

Great American Insurance Company

3 Temasek Avenue

#16-01 Centennial Tower

Singapore 039190

Dear Sirs,

Our client's motor vehicle no: SKC5196P, which was damaged as a result of the above accident, is now lying at our premises/workshop, awaiting for repairs to be carried out.

As you are the insurers of motor vehicle GBC2642U, we hereby give you NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR VEHICLE at our premises/workshop. If your representative/surveyor does not inspect our client's damaged motor vehicle within the next two(2) days, we shall proceed to repair our client's damaged motor vehicle without any further notice and our client will thereafter look to you/your insured for the repair costs. This is without prejudice to our client's claim for damages, loss of use and incidental loss.

Please let us have your list of panel surveyors for our consideration.

We enclosed herewith our estimate cost of repairs and our client's accident report for your reference.

Thank you & Regards,  
Sharon  
Kang Car Repairers Pte Ltd  
Tel: 6747 7636  
Fax: 6748 5071

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

## Shiau Chan (LKKAUTO)

---

**From:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Sent:** Friday, 18 May 2018 1:20 PM  
**To:** Shiau Chan (LKKAUTO)  
**Subject:** CLMOMVC000002759 SKC5196P AND GBC2642U (GA) ON 04.03.2018

CLMOMVC000002759

-----Original Message-----

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>  
Sent: Friday, May 18, 2018 11:51 AM  
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>; assignments <assignments@lkkauto.com>  
Cc: SUR <sur@lkkauto.com>  
Subject: [External] RE: RE: NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR SKC5196P; ACCDT INVLG SKC5196P AND GBC2642U (GA) ON 04.03.2018

Dear Rachel,

Enclosed herewith preliminary advice of SKC 5196P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Shiau Chan (LKKAUTO)  
Sent: Friday, 9 March 2018 2:44 PM  
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; assignments <assignments@lkkauto.com>  
Cc: SUR <sur@lkkauto.com>  
Subject: RE: RE: NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR SKC5196P; ACCDT INVLG SKC5196P AND GBC2642U (GA) ON 04.03.2018

Dear Rachel,

Please be informed that we have inspected the vehicle SKC 5196P on 08/03/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)  
Sent: Thursday, 8 March 2018 12:28 PM  
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; assignments <assignments@lkkauto.com>  
Cc: SUR <sur@lkkauto.com>  
Subject: RE: RE: NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR SKC5196P; ACCDT INVLG SKC5196P AND GBC2642U (GA) ON 04.03.2018



## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 18 May 2018 11:51 AM  
**To:** 'Tan, Rachel'; assignments  
**Cc:** SUR  
**Subject:** RE: RE: NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR SKC5196P; ACCDT INVLG SKC5196P AND GBC2642U (GA) ON 04.03.2018  
**Attachments:** CSGAI18004481Aqd3.pdf

Dear Rachel,

Enclosed herewith preliminary advice of SKC 5196P.

Best Regards,  
Shiau Chan (Ms) | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Shiau Chan (LKKAUTO)  
Sent: Friday, 9 March 2018 2:44 PM  
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; assignments <assignments@lkkauto.com>  
Cc: SUR <sur@lkkauto.com>  
Subject: RE: RE: NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR SKC5196P; ACCDT INVLG SKC5196P AND GBC2642U (GA) ON 04.03.2018

Dear Rachel,

Please be informed that we have inspected the vehicle SKC 5196P on 08/03/2018.

We are pending for estimate from repairer.

Best Regards,  
Shiau Chan (Ms) | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)  
Sent: Thursday, 8 March 2018 12:28 PM  
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; assignments <assignments@lkkauto.com>  
Cc: SUR <sur@lkkauto.com>  
Subject: RE: RE: NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR SKC5196P; ACCDT INVLG SKC5196P AND GBC2642U (GA) ON 04.03.2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,  
G.Nivitha | Admin

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 9 March 2018 2:44 PM  
**To:** 'Tan, Rachel'; assignments  
**Cc:** SUR  
**Subject:** RE: RE: NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR SKC5196P; ACCDT INVLG SKC5196P AND GBC2642U (GA) ON 04.03.2018

Dear Rachel,

Please be informed that we have inspected the vehicle SKC 5196P on 08/03/2018.

We are pending for estimate from repairer.

Best Regards,  
Shiau Chan (Ms) | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)  
Sent: Thursday, 8 March 2018 12:28 PM  
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; assignments <assignments@lkkauto.com>  
Cc: SUR <sur@lkkauto.com>  
Subject: RE: RE: NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR SKC5196P; ACCDT INVLG SKC5196P AND GBC2642U (GA) ON 04.03.2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,  
G.Nivitha | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]  
Sent: Thursday, 8 March 2018 10:31 AM  
To: kangcar@singnet.com.sg  
Cc: Kang Car (yahoo) <kangcar176@yahoo.com.sg>; LKK Assignments <assignments@lkkauto.com>  
Subject: RE: RE: NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR SKC5196P; ACCDT INVLG SKC5196P AND GBC2642U (GA) ON 04.03.2018

Hi LKK

Please accept assignment, OI GIA report attached.  
Please review MV.

Regards



## CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


toyota altis

Price Range ▾

Depreciation ▾

2011 ▾

Vehicle Type ▾


[Advanced Search](#)

## Used Car Comparison

--- Comparing 3 Vehicles ---

Toyota Corolla Altis 1.6A


[Add to Shortlist](#)

Toyota Corolla Altis 1.6A


[Add to Shortlist](#)

Toyota Corolla Altis 1.6A


[Add to Shortlist](#)


Use search bar above to see to compare.

[Clear All](#)
[Add all to Shortlist](#)
[Back to search result](#)

### CAR DETAILS

Price	\$42,999	\$44,800	\$45,800	-
Instalment	\$888	\$882	\$862	-
Registration Date	29-Apr-2011	30-Jun-2011	25-Aug-2011	-
Manufactured	2011	2011	2011	-
Mileage	88,000 km	-	-	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,598 cc	1,598 cc	1,598 cc	-
Road Tax	\$742 /yr	\$742 /yr	\$742 /yr	-
Power	90.0 kW (120 bhp)	90.0 kW (120 bhp)	90.0 kW (120 bhp)	-
Curb Weight	1,195 kg	1,195 kg	1,195 kg	-
Features	1.6L VVTi DOHC Engine, SRS Airbags, ABS, Multi Function Steering Control, Knockdown Rear Seat, Auto Climatic Aircon Control.	Powerful Economical 1.6L DOHC VVT-i Engine Producing 120 Bhp, 4 Speed Auto Transmission. Dual Airbags, Auto Climatic Aircon, Multi Control Steering.	1.6L 16 Valves DOHC Dual VVT-i Engine, Automatic Transmission, Dual SRS Airbags, ABS, Multi Function Steering Controls, Digital/Auto Aircon Climate.	-
Accessories	Audio System, Sports Rims, Retractable Side Mirrors With Indicator, Leather Seats, Reverse Sensor.	Sports Rims, Factory Audio System, Remote Key With Immobiliser, Retractable Side Mirrors, Reverse Sensors, Fog Lamps, Solar Film.	Leather Seats, Sports Rims, Built In Audio System With Steering Controls, Retractable Side Mirrors, 3M Solar Film, Reverse Sensors, Fog Lights.	-
Description	No Regrets! Price Negotiable 2 Digit No. Plate, Low Mileage Done 88000KM, 100% Beautiful Condition, Low Depreciation, Low Interest Rate, Most Worthy Buy, Call Now For Viewing.	Very Well Maintained, Immaculate Condition, Fuel Efficient And Reliable, Well Maintained, Loan Available, Trade In Welcome, Price Negotiable, Call Or Visit Our Showroom For Viewing Now!	Well Maintained, Well Kept, Loan Available, Trade In Welcome, Price Negotiable, Call Or Visit Our Showroom For Viewing Now!	-
COE	\$47,604	\$43,813	\$55,989	-
OMV	\$15,510	\$15,263	\$14,797	-
ARF	\$15,510	\$15,263	\$14,797	-
Depreciation	\$11,220 /yr	\$11,220 /yr	\$11,080 /yr	-
No. of Owners	3	3	3	-
Type of Vehicle	Sedan	Sedan	Sedan	-
Category	PARF Car, Premium Ad Car	PARF Car	PARF Car	-
Availability	Available	Available	Available	-

### SELLER INFORMATION

Seller	99 Motor Trading	Mandal Motor Trading	Mandal Motor Trading	-
Address	7030 Ang Mo Kio Avenue 5 #01-53	31 West Coast Highway #01-08/09	31 West Coast Highway #01-08/09	-

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6178B
Vehicle Details	
Vehicle No.:	SKC5196P
Vehicle to be Exported:	Yes
Intended De-registration Date:	08 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	1ZRX116307
Chassis No.:	MR053REE104121361
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$14,797.00
Original Registration Date:	01 Sep 2011
First Registration Date:	01 Sep 2011
Transfer Count:	2
Actual ARF Paid:	\$14,797.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Aug 2021
PARF Rebate Amount:	\$9,618.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$46,989.00
COE Rebate Amount:	\$16,345.00
<b>Total Rebate Amount:</b>	<b>\$25,963.00</b>

The information contained herein is correct as at 08 Mar 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/03/2018 12:18
Date Of Accident	04/03/2018 11:05
Exact Location Of Accident	SIMEI AVE TWDS TAMPINES
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC5196P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WONG YEXIANG
NRIC No	S8306178B
Email Address	YEXIANG.ALVIN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98228349
Alternative Phone No	OFFICE-98228349

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093329657
Cover Note Number	DRIVO CLASSIC

### Driver

Name of Driver	WONG YEXIANG
NRIC No	S8306178B
Date Of Birth	17/02/1983
Occupation	INDOOR
Date Of Driving Pass	26/03/2003
Driving Experience	14 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98228349
Fax Number	
Contact Number	OFFICE-98228349
Email Address	YEXIANG.ALVIN@GMAIL.COM

Address	28 PEAKVILLE TERRACE
Postcode	487705
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : WONG YELIN
	GENDER: : FEMALE

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

ON SUNDAY, 4 MARCH 2018, MY SISTER, MY DOG AND I WERE TRAVELLING TOWARDS TAMPINES. DUE TO THE RED TRAFFIC LIGHT ALONG SIMEI AVE, I STOPPED MY CAR. SUDDENLY, VAN B CAME FROM BEHIND AND COULD NOT STOP IN TIME, THEREFORE COLLIDING INTO MY CAR'S REAR PORTION. DUE TO THE STRONG IMPACT, MY CAR WAS PUSHED FORWARD AND HIT THE CAR C IN FRONT. DUE TO THE ACCIDENT, MY CAR'S REAR PORTION WAS BADLY DAMAGED, REAR WINDSCREEN CRACKED AND MY FRONT PORTION WAS ALSO DAMAGED. MY SISTER AND I WERE INJURED. AFTER THE ACCIDENT, MY SISTER AND I WENT TO CHANGI-SIMEI CC TO FILE A POLICE REPORT BUT WAS INFORMED THAT THERE WAS NO NEED TO FILE ONE, THEREFORE, WE WENT TO RAFFLES MEDICAL TO GET OUR INJURIES LOOKED AT. THAT ALL.

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC2642U
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LIM BAK KIA
NRIC/Passport Number	S2031013H
Contact Number	96944212
Address	BLK 1 EUNOS CRESCENT #13-2533

Postcode 400001

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKS3372B  
Vehicle Make/Model/Colour  
Details Of Properties VEHICLE C  
Vehicle Category PRIVATE CAR  
Name of Driver CHARLES TAN  
NRIC/Passport Number  
Contact Number 91722115  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name WONG YEXIANG  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SKC5196P  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? NO  
Address 28 PEAKVILLE TERRACE  
Postcode 487705

#### DETAILS OF INJURED PERSON 2

Name WONG YELIN  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SKC5196P  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? NO  
Address 28 PEAKVILLE TERRACE  
Postcode 487705

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to my enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 05/03/2018.  
11.25 a.m.

Driver's Signature

(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature

Name:  
NRIC/FIN No.:



## Sketch Plan Pg. 2

### SKETCH PLAN

Tampines: ← Simei Ave



A: SKC 5196P

B: GBC 26424

C: SKS 3372B.

### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On Sunday 4 March 2018, my sister, my dog and I were travelling towards Tampines. Due to the red traffic light along Simei Avenue, I stopped my car. Suddenly, Van B came from behind and could not stop in time, therefore colliding into my car's rear portion. Due to the strong impact, my car was pushed forward and hit the Car C in front.

Due to the accident, my car's rear portion was badly damaged, rear windscreen cracked and my mini portion was also damaged. My sister and I were injured.

After the accident, my sister and I went to Changi Simei CC to file a Police report but was informed that there was no need to file one. Thereafter, we went to Raffles Medical to get our injuries looked at.

That's all.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 05/03/2018.

11.25 A.M.

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

M/S : GREAT AMERICAN INSURANCE COMPANY  
3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
SINGAPORE 039190

TEL: 6804 6003 FAX: 6235 2616  
ATTN: Motor Claim Department

Estimate No: EST1800062  
Date: 07 Mar 2018

Veh Reg No: SKC5196P  
Make/Model: TOYOTA COROLLA  
ALTIS

Chasis No: MR053REE104121361  
Reg. Date: 01/09/2011  
Your Ref No: GBC2642U

Claim Type: Third Party  
Accident Date: 04/03/2018  
TP Veh Reg No: GBC2642U

## Estimate Repair Cost to Vehicle No :SKC5196P

Quantity	Description	List Price SS	Amount SS
<b>List Price</b>			
1	1 PC BOOT LID <i>Distorted</i>	754.30	✓
2	1 PC BOOT LID LOGO <i>new</i>	52.20	✓
3	1 PC BOOT LID "DUAL" EMBLEM	42.20	✓
4	1 PC BOOT LID "1.6" EMBLEM	42.20	✓
5	1 PC BOOT LID "VVTI" EMBLEM	46.60	✓
6	1 PC BOOT LID "COROLLA" EMBLEM	58.20	✓
7	1 PC BOOT LID "ALTIS" EMBLEM	58.20	✓
8	1 PC BOOTLID "ELEGANCE" EMBLEM	52.00	✓
9	1 PC BOOT LID CHROME <i>cracked</i>	332.90	✓
10	1 PC BOOT LID LAMP LH <i>cracked</i>	146.60	✓
11	1 PC BOOT LID LAMP RH	146.60	✓
12	1 PC BOOT LID LOCK <i>damaged</i>	96.50	✓
13	1 PC BOOT LID KEY LOCK <i>key</i>	98.70	✓
14	1 PC BOOT LID LOCK CHECKER <i>Best</i>	28.40	✓
15	2 PCS BOOT LID HINGE <i>Best</i>	120.40	✓
16	2 PCS BOOTLID HINGE SPRING <i>new</i>	197.60	✗
17	1 PC BOOT LID RUBBER <i>cut</i>	175.40	✓
18	2 PCS BOOTLID STOPPER <i>new</i>	12.00	+
19	1 PC BOOT LID TRIM <i>crumpled</i>	174.10	✓
20	2 PCS REAR NUMBER PLATE LAMP <i>new</i>	139.60	✗
21	1 PC REAR FENDER LH <i>Distorted</i>	1,029.70	✓
22	1 PC REAR FENDER TRIM LH <i>crumpled</i>	334.30	✓
23	1 PC REAR FENDER MUDFLAP LH <i>ton</i>	49.70	✓
24	1 PC REAR FENDER VENTILATION GARNISH <i>new</i>	135.80	✓
25	1 PC REAR FENDER INNER PANEL LH <i>Reps</i>	225.80	✗
26	1 PC REAR FENDER OUTER PANEL LH <i>Reps</i>	266.30	✗
27	1 PC REAR END CHASSIS LH <i>Best</i>	453.80	✓
28	1 PC REAR FENDER LOWER INNER PANEL LH <i>Reps</i>	244.70	✗
29	1 PC REAR DOOR LH <i>Reps</i>	706.80	✗

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST 201300201N

M/S : GREAT AMERICAN INSURANCE COMPANY  
3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
SINGAPORE 039190

TEL: 6804 6003 FAX: 6235 2616  
ATTN: Motor Claim Department

Estimate No: EST1800062  
Date: 07 Mar 2018

Veh Reg No: SKC5196P  
Make/Model: TOYOTA COROLLA  
ALTIS

Chasis No: MR053REE104121361  
Reg. Date: 01/09/2011  
Your Ref No: GBC2642U

Claim Type: Third Party  
Accident Date: 04/03/2018  
TP Veh Reg No: GBC2642U

## Estimate Repair Cost to Vehicle No :SKC5196P

Quantity	Description	List Price	Amount
		SS	SS
30	1 PC REAR DOOR LOCK LH <i>Replaced</i>	374.20	<i>✓</i>
31	1 PC REAR DOOR RUBBER LH <i>Replaced</i>	175.90	<i>✓</i>
32	1 PC REAR DOOR OUTER MOULDING LH <i>Replaced</i>	113.20	<i>✓</i>
33	2 PCS REAR DOOR HINGE LH <i>Replaced</i>	152.60	<i>✓</i>
34	1 PC REAR DOOR PROTECTOR LH <i>Replaced</i>	66.20	<i>✓</i>
35	1 PC REAR DOOR PROTECTOR CHROME MOULDING LH <i>Replaced</i>	19.20	<i>✓</i>
36	1 PC REAR DOOR QUARTER GLASS RUBBER LH <i>Replaced</i>	74.20	<i>✓</i>
37	1 PC REAR DOOR BLACK STICKER LH <i>Replaced</i>	64.60	<i>✓</i>
38	1 PC REAR DOOR LOCK LH <i>Replaced</i>	437.30	<i>✓</i>
39	1 PC REAR DOOR PROTECTOR LH <i>Replaced</i>	112.70	<i>✓</i>
40	1 PC REAR DOOR PROTECTOR MOULDING LH <i>Replaced</i>	23.40	<i>✓</i>
41	1 PC REAR FENDER RH <i>Buckled</i>	1,029.70	<i>✓</i>
42	1 PC REAR FENDER TRIM RH <i>Replaced</i>	334.30	<i>✓</i>
43	1 PC REAR FENDER MUDFLAP RH <i>Replaced</i>	49.70	<i>✓</i>
44	1 PC REAR FENDER VENTILATION GARNISH RH <i>Replaced</i>	135.80	<i>✓</i>
45	1 PC REAR FENDER INNER PANEL RH <i>Replaced</i>	225.80	<i>✓</i>
46	1 PC REAR FENDER OUTER PANEL RH <i>Replaced</i>	266.30	<i>✓</i>
47	1 PC REAR END CHASSIS RH <i>Replaced</i>	453.80	<i>✓</i>
48	1 PC REAR FENDER LOWER INNER PANEL RH <i>Replaced</i>	244.70	<i>✓</i>
49	1 PC REAR DOOR RH <i>Replaced</i>	706.80	<i>✓</i>
50	1 PC REAR DOOR LOCK RH <i>Replaced</i>	374.20	<i>✓</i>
51	1 PC REAR DOOR RUBBER RH <i>Replaced</i>	175.40	<i>✓</i>
52	1 PC REAR DOOR OUTER MOULDING RH <i>Replaced</i>	113.20	<i>✓</i>
53	1 PC REAR DOOR GLASS CHANNEL RH <i>Replaced</i>	119.70	<i>✓</i>
54	1 PC REAR DOOR PROTECTOR RH <i>Replaced</i>	66.20	<i>✓</i>
55	1 PC REAR DOOR PROTECTOR MOULDING RH <i>Replaced</i>	19.20	<i>✓</i>
56	1 PC REAR DOOR QUARTER RUBBER RH <i>Replaced</i>	74.20	<i>✓</i>
57	1 PC REAR DOOR BLACK STICKER RH <i>Replaced</i>	64.40	<i>✓</i>
58	1 PC TAIL LAMP LH <i>Cracked</i>	281.90	<i>✓</i>
59	1 PC TAIL LAMP PANEL LH <i>Distorted</i>	79.30	<i>✓</i>

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST: 201300201N

M/S : GREAT AMERICAN INSURANCE COMPANY  
3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
SINGAPORE 039190

TEL: 6804 6003 FAX: 6235 2616  
ATTN: Motor Claim Department

Claim Type: Third Party  
Accident Date: 04/03/2018  
TP Veh Reg No: GBC2642U

Estimate No: EST1800062  
Date: 07 Mar 2018

Veh Reg No: SKC5196P  
Make/Model: TOYOTA COROLLA  
ALTIS  
Chasis No: MR053REE104121361  
Reg. Date: 01/09/2011  
Your Ref No: GBC2642U

## Estimate Repair Cost to Vehicle No :SKC5196P

Quantity	Description	List Price	Amount
		SS	SS
60	1 PC TAIL LAMP - RH <i>Cracked</i>	281.90 ✓	
61	1 PC TAIL LAMP PANEL RH <i>Distorted</i>	79.30 ✓	
62	1 PC SPARE TYRE PANEL <i>Distorted</i>	762.90 ✓	
63	1 PC SPARE TYRE RH SIDE PANEL <i>Distorted</i>	102.50 ✓	
64	1 PC SPARE TYRE LH SIDE PANEL <i>Distorted</i>	102.50 ✓	
65	1 PC SPARE TYRE COVER <i>to be</i>	348.10 ✓	
66	1 PC REAR PANEL <i>Distorted</i>	552.20 ✓	
67	1 PC REAR PANEL TRIM <i>Distorted</i>	185.30 ✓	
68	1 PC REAR BUMPER <i>Distorted</i>	482.00 ✓	
69	2 PCS REAR BUMPER BRACKET <i>Bent</i>	165.60 ✓	
70	1 PC REAR BUMPER SPONGE <i>Cracked</i>	117.50 ✓	
71	2 PCS REAR BUMPER SIDE RETAINER <i>2 pcs</i>	145.40 ✓	
72	2 PCS REAR BUMPER SMALL RETAINER	97.60 ✓	
73	1 PC REAR BUMPER REFLECTOR - LH <i>Cracked</i>	35.20 ✓	
74	1 PC REAR BUMPER REFLECTOR - RH <i>nt</i>	35.20 ✓	
75	1 PC REAR WINDSCREEN GLASS <i>Shattered</i>	1,259.20 ✓	
76	1 PC REAR WINDSCREEN BOTTOM PANEL <i>Repair</i>	905.50 ✓	
77	1 PC REAR SPEAKER BOARD <i>at</i>	691.10 ✓	
78	1 PC REAR WINDSCREEN RH SIDE GARNISH <i>2 pcs</i>	338.70 ✓	
79	1 PC REAR WINDSCREEN LH SIDE GARNISH <i>2 pcs</i>	338.70 ✓	
80	1 PC UPHOLSTERY <i>new</i>	1,667.40 ✓	
81	1 PC REAR FUEL LID <i>Bent</i>	107.30 ✓	
82	1 PC REAR FUEL TANK CAP <i>new</i>	61.40 ✓	
83	1 PC REAR FUEL NECK <i>2 pcs new</i>	216.70 ✓	
84	1 PC EXHAUST PIPE <i>Bent</i>	787.20 ✓	
85	1 PC REAR EXHAUST HEAT COVER <i>Cracked</i>	133.10 ✓	
86	1 PC CENTRE EXHAUST PIPE <i>Bent</i>	3,033.60 ✓	
87	4 PCS EXHAUST PIPE MOUNTING <i>new</i>	75.60 ✓	
88	1 PC REAR AXLE <i>Bent</i>	2,347.10 ✓	
89	2 PCS REAR SHOCK ABSORBER <i>Bent</i>	374.20 ✓	

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangear@singnet.com.sg  
GST: 201300201N

M/S : GREAT AMERICAN INSURANCE COMPANY  
3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
SINGAPORE 039190

TEL: 6804 6003 FAX: 6235 2616  
ATTN: Motor Claim Department

Claim Type: Third Party  
Accident Date: 04/03/2018  
TP Veh Reg No: GBC2642U

Estimate No: EST1800062  
Date: 07 Mar 2018

Veh Reg No: SKC5196P  
Make/Model: TOYOTA COROLLA  
ALTIS  
Chassis No: MR053REE104121361  
Reg. Date: 01/09/2011  
Your Ref No: GBC2642U

## Estimate Repair Cost to Vehicle No :SKC5196P

Quantity	Description	List Price	Amount
		<del>SS</del>	<del>SS</del>
90	1 PC REAR LH WHEEL HUB & BEARING <i>Damaged</i>	<del>637.40</del>	569.60
91	1 PC REAR RH WHEEL HUB & BEARING <i>Damaged</i>	<del>637.40</del>	569.60
92	1 PC FRT BUMPER <i>Repld</i>	459.80	✓
93	1 PC FRT BUMPER REINFORCEMENT <i>Best</i>	339.70	✓
94	2 PCS FRT BUMPER BRACKET <i>7H New</i>	100.40	✓
95	2 PCS FRT BUMPER SIDE RETAINER <i>new</i>	101.60	✓
96	1 PC FRT FOG LAMP RH <i>7H New</i>	278.20	✓
97	1 PC FRT FOG LAMP COVER RH <i>7H New</i>	51.50	✓
98	1 PC FRT FOG LAMP LH <i>7H New</i>	278.20	✓
99	1 PC FRT FOG LAMP COVER LH <i>7H New</i>	51.50	✓
100	1 PC FRT GRILLE <i>Replaced</i>	287.30	✓
101	1 PC FRT GRILLE EMBLEM <i>new</i>	60.20	✓
102	1 PC FRONT TOP GRILLE RUBBER <i>new</i>	98.20	✓
103	1 PC FRT BUMPER GRILLE <i>7H New</i>	139.80	✓
104	1 PC FRT SUPPORT PANEL <i>Buckled</i>	788.50	✓
105	1 PC BONNET LOCK <i>new</i>	147.60	✓
106	1 PC HEADLAMP LH <i>7H New</i>	525.40	✓
107	1 PC HEADLAMP RH <i>7H New</i>	525.40	✓
108	1 PC AIR CONDENSER <i>Best</i>	1,404.40	✓
109	1 PC AIR CONDENSER PIPE <i>new</i>	649.30	✓
110	1 PC RADIATOR <i>7H New</i>	1,769.20	✓
111	1 PC RADIATOR FAN MOTOR <i>2 new</i>	439.20	✓
112	1 PC RADIATOR COWLING	232.30	✓
113	1 PC RADIATOR LOWER GARNISH	153.80	✓
		38,636.00	
	Less 25%	9,659.00	28,977.00
	<b>Special Net</b>		
114	1 SET BOOT LID TRIM CLIPS <i>new</i>	<del>60.00</del>	30
115	1 PC REAR NUMBER PLATE <i>Best</i>	50.00	✓
116	1 PC REVERSE CAMERA <i>Damaged</i>	<del>500.00</del>	380

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

M/S : GREAT AMERICAN INSURANCE COMPANY  
3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
SINGAPORE 039190

TEL: 6804 6003 FAX: 6235 2616  
ATTN: Motor Claim Department

Estimate No: EST1800062  
Date: 07 Mar 2018

Veh Reg No: SKC5196P  
Make/Model: TOYOTA COROLLA  
ALTIS

Chasis No: MR053REE104121361  
Reg. Date: 01/09/2011  
Your Ref No: GBC2642U

Claim Type: Third Party  
Accident Date: 04/03/2018  
TP Veh Reg No: GBC2642U

## Estimate Repair Cost to Vehicle No :SKC5196P

Quantity	Description	List Price	Amount
		SS	SS
117	1 SET REVERSE SENSORS <i>Panged</i>	<del>250.00</del> 200	
118	1 SET REAR FENDER TRIM CLIPS LH <i>ru</i>	<del>58.00</del> 30	
119	1 SET REAR FENDER MUDFLAP CLIPS LH <i>ru</i>	<del>40.00</del> 10	
120	1 SET REAR FENDER TRIM CLIPS RH <i>ru</i>	<del>58.00</del> 30	
121	1 SET REAR FENDER MUDFLAP CLIPS RH <i>ru</i>	<del>40.00</del> 10	
122	1 SET REAR PANEL TRIM CLIPS <i>ru</i>	<del>40.00</del> 10	
123	1 SET REAR BUMPER CLIPS <i>ru</i>	<del>48.00</del> 30	
124	1 SET REAR WINDSCREEN TRIM CLIPS <i>ru</i>	<del>48.00</del> 30	
125	1 SET REAR WINDSCREEN RH SIDE GARNISH CLIPS <i>3ru</i>	<del>40.00</del> 15	
126	1 SET REAR WINDSCREEN LH SIDE GARNISH CLIPS <i>1ru</i>	<del>40.00</del> 15	
127	1 PC REAR SPORTS RIM LH <i>not ru</i>	600.00	
128	1 PC REAR TYRE LH <i>not ru</i>	380.00	
129	1 SET FRT BUMPER CLIPS <i>ru</i>	<del>48.00</del> 30	
130	1 PC FRT NUMBER PLATE <i>cached</i>	50.00	
131	1 SET FRT GRILLE CLIPS <i>ru</i>	<del>40.00</del> 15	
132	1 SET FRT BUMPER GRILLE CLIPS <i>7000</i>	40.00	
133	1 SET RADIATOR LOWER GARNISH CLIPS <i>2000</i>	<del>48.00</del> 20	
		2,478.00	2,478.00
	<b>Labour</b>		
134	1 TO CHECK WIRING	<del>100.00</del> 30	
135	1 TOWING	<del>100.00</del> 20	
136	1 (REAR) TO REMOVE AND REFIT WINDSCREEN GLASS	120.00	
137	1 TO REMOVE AND REFIT SEAT CUSHION	<del>200.00</del> 180	
138	1 TO REMOVE AND REFIT UNDERCARRIAGE	<del>550.00</del> 350	
139	1 TO REFIX UPHOLSTERY	<del>350.00</del> 60	
140	1 TO REMOVE AND REFIT PETROL TANK	<del>150.00</del> 80	
141	1 (REAR) TO CHECK WHEEL ALIGNMENT	<del>120.00</del> 20	
142	1 TO SPRAY UNDERSEAL	<del>300.00</del> 150	
143	1 (REAR) TO SPRAY PAINTING	<del>2,800.00</del> 1800	



# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

M/S: GREAT AMERICAN INSURANCE COMPANY  
3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
SINGAPORE 039190

TEL: 6804 6003 FAX: 6235 2616  
ATTN: Motor Claim Department

Estimate No: EST1800062  
Date: 07 Mar 2018

Veh Reg No: SKC5196P  
Make/Model: TOYOTA COROLLA  
ALTIS  
Chasis No: MR053REE104121361  
Reg. Date: 01/09/2011  
Your Ref No: GBC2642U

Claim Type: Third Party  
Accident Date: 04/03/2018  
TP Veh Reg No: GBC2642U

## Estimate Repair Cost to Vehicle No :SKC5196P

Quantity	Description	List Price	Amount
		SS	SS
144	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	<del>4,300.00</del>	2800
145	1 TO REMOVE AND REFIT DOOR GLASS	180.00	✓
146	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	<del>250.00</del>	160
147	1 TO CHECK WIRING	<del>50.00</del>	30
148	1 TO REFILL AIRCON GAS	120.00	✓
149	1 TO SPRAY UNDERSEAL	80.00	✓
150	1 (FRONT) TO SPRAY PAINTING	<del>1,200.00</del>	600
151	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	<del>1,200.00</del>	700
		12,170.00	12,170.00
	Total		SS 43,625.22
	Add GST @ 7%		3,053.77
	Total Amount Payable		SS 46,678.99

TOTAL: SINGAPORE DOLLAR FORTY SIX THOUSAND SIX HUNDRED SEVENTY EIGHT AND CENTS NINETY NINE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lg

08/03/18

28 days

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Total: 25883.62

h/s 2018



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18004481/Aqd3n2

3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
SINGAPORE 039190

Date : 25-05-2018



Code : GAI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 2642U	Veh. Inspected	SKC 5196P
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000002759	Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	08/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	MR053REE104121361	Colour	WHITE
Odometer	135246	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	04/03/2018	Inspection Date	08/03/2018
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	28 Working Days
-------------------------------------	-----------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 5196P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BOOT LID	DISTORTED	754.30	754.30
1	BOOT LID LOGO	NECESSARY	52.20	52.20
1	BOOT LID "DUAL" EMBLEM	NECESSARY	42.20	42.20
1	BOOT LID "1.6" EMBLEM	NECESSARY	42.20	42.20
1	BOOT LID "VVTI" EMBLEM	NECESSARY	46.60	46.60
1	BOOT LID "COROLLA" EMBLEM	NECESSARY	58.20	58.20
1	BOOT LID "ALTIS" EMBLEM	NECESSARY	58.20	58.20
1	BOOT LID "ELEGANCE" EMBLEM	NECESSARY	52.00	52.00
1	BOOT LID CHROME	CRACKED	332.90	332.90
1	BOOT LID LAMP LH	CRACKED	146.60	146.60
1	BOOT LID LAMP RH	CRACKED	146.60	146.60
1	BOOT LID LOCK	JAMMED	96.50	96.50
1	BOOT LID KEY LOCK	DAMAGED	98.70	98.70
1	BOOT LID LOCK CHECKER	BENT	28.40	28.40
2	BOOT LID HINGE	BENT	120.40	120.40
2	BOOT LID HINGE SPRING	NOT NECESSARY	197.60	-
1	BOOT LID RUBBER	CUT	175.40	175.40
2	BOOTLID STOPPER	NOT NECESSARY	12.00	-
1	BOOT LID TRIM	CRUMPLED	174.10	174.10
2	REAR NUMBER PLATE LAMP	NOT NECESSARY	139.60	-
1	REAR FENDER LH	DISTORTED	1,029.70	1,029.70
1	REAR FENDER TRIM LH	CRUMPLED	334.30	334.30
1	REAR FENDER MUDFLAP LH	TORN	49.70	49.70
1	REAR FENDER VENTILATION GARNISH	NOT NECESSARY	135.80	-
1	REAR FENDER INNER PANEL LH	TO REPAIR SEE LABOUR	225.80	-
1	REAR FENDER OUTER PANEL LH	TO REPAIR SEE LABOUR	266.30	-
1	REAR END CHASSIS LH	BENT	453.80	453.80
1	REAR FENDER LOWER INNER PANEL LH	TO REPAIR SEE LABOUR	244.70	-
1	REAR DOOR LH	TO REPAIR SEE LABOUR	706.80	-
1	REAR DOOR LOCK LH	DAMAGED	374.20	374.20
1	REAR DOOR RUBBER LH	NOT NECESSARY	175.90	-

Report Ref No. CS/GAI18004481/Aqd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR DOOR OUTER MOULDING LH	NOT NECESSARY	113.20	-
2	REAR DOOR HINGE LH	NOT NECESSARY	152.60	-
1	REAR DOOR PROTECTOR LH	NOT NECESSARY	66.20	-
1	REAR DOOR PROTECTOR CHROME MOULDING LH	NOT NECESSARY	19.20	-
1	REAR DOOR QUARTER GLASS RUBBER LH	NOT NECESSARY	74.20	-
1	REAR DOOR BLACK STICKER LH	NOT NECESSARY	64.60	-
1	REAR DOOR LOCK LH	REPEATED	437.30	-
1	REAR DOOR PROTECTOR LH	NOT NECESSARY	112.70	-
1	REAR DOOR PROTECTOR MOULDING LH	NOT NECESSARY	23.40	-
1	REAR FENDER RH	BUCKLED	1,029.70	1,029.70
1	REAR FENDER TRIM RH	CRUMPLED	334.30	334.30
1	REAR FENDER MUDFLAP RH	TORN	49.70	49.70
1	REAR FENDER VENTILATION GARNISH RH	NOT NECESSARY	135.80	-
1	REAR FENDER INNER PANEL RH	TO REPAIR SEE LABOUR	225.80	-
1	REAR FENDER OUTER PANEL RH	TO REPAIR SEE LABOUR	266.30	-
1	REAR END CHASSIS RH	TO REPAIR SEE LABOUR	453.80	-
1	REAR FENDER LOWER INNER PANEL RH	TO REPAIR SEE LABOUR	244.70	-
1	REAR DOOR RH	NOT NECESSARY	706.80	-
1	REAR DOOR LOCK RH	NOT NECESSARY	374.20	-
1	REAR DOOR RUBBER RH	NOT NECESSARY	175.40	-
1	REAR DOOR OUTER MOULDING RH	NOT NECESSARY	113.20	-
1	REAR DOOR GLASS CHANNEL RH	NOT NECESSARY	119.70	-
1	REAR DOOR PROTECTOR RH	NOT NECESSARY	66.20	-
1	REAR DOOR PROTECTOR MOULDING RH	NOT NECESSARY	19.20	-
1	REAR DOOR QUARTER RUBBER RH	NOT NECESSARY	74.20	-
1	REAR DOOR BLACK STICKER RH	NOT NECESSARY	64.40	-
1	TAIL LAMP LH	CRACKED	281.90	281.90
1	TAIL LAMP PANEL LH	DISTORTED	79.30	79.30
1	TAIL LAMP-RH	CRACKED	281.90	281.90
1	TAIL LAMP PANEL RH	DISTORTED	79.30	79.30
1	SPARE TYRE PANEL	DISTORTED	762.90	762.90
1	SPARE TYRE RH SIDE PANEL	DISTORTED	102.50	102.50
1	SPARE TYRE LH SIDE PANEL	DISTORTED	102.50	102.50

Report Ref No. CS/GAI18004481/Aqd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE COVER	TORN	348.10	348.10
1	REAR PANEL	DISTORTED	552.20	552.20
1	REAR PANEL TRIM	DISTORTED	185.30	185.30
1	REAR BUMPER	DISTORTED	482.00	482.00
2	REAR BUMPER BRACKET	BENT	165.60	165.60
1	REAR BUMPER SPONGE	CRACKED	117.50	117.50
2	REAR BUMPER SIDE RETAINER	NECESSARY	145.40	145.40
2	REAR BUMPER SMALL RETAINER	NECESSARY	97.60	97.60
1	REAR BUMPER REFLECTOR-LH	CRACKED	35.20	35.20
1	REAR BUMPER REFLECTOR-RH	CUT	35.20	35.20
1	REAR WINDSCREEN GLASS	SHATTERED	1,259.20	1,259.20
1	REAR WINDSCREEN BOTTOM PANEL	TO REPAIR SEE LABOUR	905.50	-
1	REAR SPEAKER BOARD	CUT	691.10	691.10
1	REAR WINDSCREEN RH SIDE GARNISH	NOT NECESSARY	338.70	-
1	REAR WINDSCREEN LH SIDE GARNISH	DEFORMED	338.70	338.70
1	UPHOLSTERY	NOT NECESSARY	1,667.40	-
1	REAR FUEL LID	BENT	107.30	107.30
1	REAR FUEL TANK CAP	NOT NECESSARY	61.40	-
1	REAR FUEL NECK	NOT NECESSARY	216.70	-
1	EXHAUST PIPE	BENT	787.20	787.20
1	REAR EXHAUST HEAT COVER	CRUMPLED	133.10	133.10
1	CENTRE EXHAUST PIPE	BENT	3,033.60	3,033.60
4	EXHAUST PIPE MOUNTING	NOT NECESSARY	75.60	-
1	REAR AXLE	BENT	2,347.10	2,347.10
2	REAR SHOCK ABSORBER	BENT	374.20	374.20
1	REAR LH WHEEL HUB & BEARING	DAMAGED	637.40	569.60
1	REAR RH WHEEL HUB & BEARING	DAMAGED	637.40	569.60
1	FRT BUMPER	DEFORMED	459.80	459.80
1	FRT BUMPER REINFORCEMENT	BENT	339.70	339.70
2	FRT BUMPER BRACKET	NOT NECESSARY	100.40	-
2	FRT BUMPER SIDE RETAINER	NECESSARY	101.60	101.60
1	FRT FOG LAMP RH	NOT NECESSARY	278.20	-
1	FRT FOG LAMP COVER RH	NOT NECESSARY	51.50	-
1	FRT FOG LAMP LH	NOT NECESSARY	278.20	-
1	FRT FOG LAMP COVER LH	NOT NECESSARY	51.50	-

Report Ref No. CS/GAI18004481/Aqd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT GRILLE	CRACKED	287.30	287.30
1	FRT GRILLE EMBLEM	NECESSARY	60.20	60.20
1	FRONT TOP GRILLE RUBBER	NOT NECESSARY	98.20	-
1	FRT BUMPER GRILLE	NOT NECESSARY	139.80	-
1	FRT SUPPORT PANEL	BUCKLED	788.50	788.50
1	BONNET LOCK	NOT NECESSARY	147.60	-
1	HEADLAMP LH	NOT NECESSARY	525.40	-
1	HEADLAMP RH	NOT NECESSARY	525.40	-
1	AIR CONDENSER	BENT	1,404.40	1,404.40
1	AIR CONDENSER PIPE	NOT NECESSARY	649.30	-
1	RADIATOR	NOT NECESSARY	1,769.20	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	439.20	-
1	RADIATOR COWLING	NOT NECESSARY	232.30	-
1	RADIATOR LOWER GARNISH	NOT NECESSARY	153.80	-
	LESS 25% DISCOUNT		-9,659.00	-5,896.88
			28,977.00	17,690.62
	<b>SPECIAL NETT ITEMS</b>			
1	SET BOOT LID TRIM CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR NUMBER PLATE (SN)	BENT	50.00	50.00
1	REVERSE CAMERA (SN)	DAMAGED	500.00	380.00
1	SET REVERSE SENSORS (SN)	DAMAGED	250.00	200.00
1	SET REAR FENDER TRIM CLIPS LH (SN)	NECESSARY	58.00	30.00
1	SET REAR FENDER MUDFLAP CLIPS LH (SN)	NECESSARY	40.00	10.00
1	SET REAR FENDER TRIM CLIPS RH (SN)	NECESSARY	58.00	30.00
1	SET REAR FENDER MUDFLAP CLIPS RH (SN)	NECESSARY	40.00	10.00
1	SET REAR PANEL TRIM CLIPS (SN)	NECESSARY	40.00	10.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	30.00
1	SET REAR WINDSCREEN TRIM CLIPS (SN)	NECESSARY	48.00	30.00
1	SET REAR WINDSCREEN RH SIDE GARNISH CLIPS (SN)	NECESSARY	40.00	15.00
1	SET REAR WINDSCREEN LH SIDE GARNISH CLIPS (SN)	NECESSARY	40.00	15.00
1	REAR SPORTS RIM LH (SN)	NOT NECESSARY	600.00	-
1	REAR TYRE LH (SN)	NOT NECESSARY	380.00	-
1	SET FRT BUMPER CLIPS (SN)	NECESSARY	48.00	30.00
1	FRT NUMBER PLATE (SN)	CRACKED	50.00	50.00
1	SET FRT GRILLE CLIPS (SN)	NECESSARY	40.00	15.00
1	SET FRT BUMPER GRILLE CLIPS (SN)	NOT NECESSARY	40.00	-

Report Ref No. CS/GAI18004481/Aqd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET RADIATOR LOWER GARNISH CLIPS (SN)	NOT NECESSARY	48.00	-
			2,478.00	935.00
	<b>LABOUR</b>			
	TO CHECK WIRING.		100.00	30.00
	TOWING.		100.00	100.00
	(REAR) TO REMOVE AND REFIT WINDSCREEN GLASS.		120.00	120.00
	TO REMOVE AND REFIT SEAT CUSHION.		200.00	180.00
	TO REMOVE AND REFIT UNDERCARRIAGE.		550.00	350.00
	TO REFIX UPHOLSTERY.		350.00	60.00
	TO REMOVE AND REFIT PETROL TANK.		150.00	80.00
	(REAR) TO CHECK WHEEL ALIGNMENT.		120.00	80.00
	TO SPRAY UNDERSEAL.		300.00	150.00
	(REAR) TO SPRAY PAINTING.		2,800.00	1,800.00
	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS,AND FOR CUTTING/WELDING WORKS.INCLUSIVE OF THE REPAIR OF REAR FENDER INNER PANEL LH,REAR FENDER OUTER PANEL LH,REAR FENDER LOWER INNER PANEL LH,REAR DOOR LH,REAR FENDER INNER PANEL RH,REAR FENDER OUTER PANEL RH,REAR END CHASSIS RH,REAR FENDER LOWER INNER PANEL RH AND REAR WINDSCREEN BOTTOM PANEL.		4,300.00	2,800.00
	TO REMOVE AND REFIT DOOR GLASS.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIX REAR EXHAUST PIPE.		250.00	160.00
	TO CHECK WIRING.		50.00	30.00
	TO REFILL AIRCON GAS.		120.00	120.00
	TO SPRAY UNDERSEAL.	NOT NECESSARY	80.00	-
	(FRONT) TO SPRAY PAINTING.		1,200.00	600.00
	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS,AND FOR CUTTING/WELDING WORKS.		1,200.00	700.00
	-		-	-
	-		-	-
	-		-	-
			12,170.00	7,360.00
	<b>GRAND TOTAL</b>		<b>43,625.00</b>	<b>25,985.62</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>20,000.00</b>

Report Ref No. CS/GAI18004481/Aqd3n2



Report Ref No. CS/GAI18004481/Aqd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.