

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

Arg Asia - CIP) IS

VEHICLE NO : SHC 1058S

DATE 7/3/2018

MAKE :

LEE - Kalvin

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ✓			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?			\$ 49.00	
	Rear Bumper Clips ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover ✓			\$ 225.00	
	Rear Bumper Reflector Lamp (LH/RH) X		\$ 32.00	\$ 64.00	
	<i>Rear End Panel -</i>				
	<i>Exhaust LH ✓</i>				
	SUB TOTAL			\$ 1,971.35	
	LESS 20%			\$ 394.27	
	DISCOUNTED TOTAL			\$ 1,577.08	
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
	Rear No. Plate ✓			\$ 25.00	Nett
	License Plate Cover ✓			\$ 100.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
				\$ 460.70	
	Labour Charge				
	Panel Beating			\$ 380.00	
	Spray Painting Charge			\$ 300.00 500.00	
	Wiring Charge			\$ 50.00 X	
	R/Refix Reverse Sensor			\$ 120.00 X 20	
	<i>Towling \$50 ✓</i>				
	TOTAL LABOUR			\$ 750.00	
	ESTIMATE TOTAL			\$ 2,787.78	
	<i>Kalvin IKKer</i>				
	<i>M 7/3/08 1535hr.</i>				
	<i>3 Days</i>				
	<i>PIP</i>				
	<i>Before Paint photo</i>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.