

ASS. REC. BY:

REF: CS/MSG18004486/Kvbe2 Special Instruction:

SUPERVISOR:

Kenneth

ASSIGNMENT (Office)

From (Person): Elaine Ngu of MSH Date/Time: 08/03/2018 206pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 2369T Insured: SKE 5680Y

at Workshop m/s Hui Yang Motor Tel: 6451 5752

of Blk 176 Sin Ming Dxe #04-02

Policy No: MSD/VPCP/17000414 Claim No: MSC/V/18-000347

Sum Insured: Excess:

Make of Veh: D.O.A. 05/03/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' 13-03-2018

H.O.D. Endorsement:

Date/Time: 08/03/2018 2:33pm Person Contacted: Bel Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLS 2369T - x
	SKE 5680Y - 003/MSG16018259/R16bn2 DUA: 21/08/2016
14/3/18	Send preli revised by merimen
19/4	@ 1738.75 email & confirm (Red 3076.75, 65%)

MSIG

ASSIGNMENT

Date 13/3/18

S/S 23397 09 17

Estimated Cost

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect vehicle No SLS 23397

at Workshop mis Hui Yang Motor

of Blk 176, Sin Ming Drive # 04-02

Insured

Policy No

Claims No

Sum Insured


Excess

Client's Record

Make of car

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value

DAD Accident Report Consistent? : Yes or No

GIA / PR Seen Consistent? : Yes or No

Est. Repairs 04 days Res: Yes or No

Lm Sum 1.3.1 % 3 Val: Yes or No

CA / REV / REP / 24 HRS lwp

Date Person Contacted

Vehicle IN / OUT

Type of Car / Truck / Bus / Van / Motor / Taxi / Prime Mover

Truck / Trailer

Make

Toy Prius

1787

Colour

M.D. Green

Insured Std N/A

Go Peeding

41701

Patio Insured Std N/A

Eng No

Chassis

ZVW40

0026323

Gen Cond Good Fair Poor Burnt

Steering In order Jammed Leaked Burnt or

Brake In order Jammed Leaked Burnt or

Mod N/A S/R - S/R - or

Tyre Size

205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / RIR / SUM

TOYO / YOKO or

Front

Rear

R/Sa

3

--

R/Sa

5

--

L/Sa

3

--

L/Sa

5

--

D/OA

5/3/18

D/O

13/3/18

Surveyed at

Des of Damages Fr Rear OS NS UO / Roofed or

Rec OS

The UO Chassis frame Body Structure affected due to collision

Date Time Action Instruction

14/3 File pass to Corrine

RECEIVED 19 APR 2018

Date Time File Pass to



Prel. Report



Final Report

Date Time File Return to

19/4 - typist

Days Of Repair

4

Resurvey No. of Trip

1

Survey Fee

200

Add Fee

Site fee

Fuel

Transport

Leave

10

210

Report Form

merimen

Lm Sum

Plp \$ 1738.75

Survey Department Check List (Case Handler)

Reference No. : CS / MSG / 8004486 / Kvb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 19/4/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18004486/Kvb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 08-03-2018

Code : MSG



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKE 5680Y	Veh. Inspected	SLS 2339T
Policy No.	MSD/VPCP/17-000414	Coverage (\$)	0.00
Claim No.	MSC/V/18-000347	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	08/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c
Engine No.	Year of Reg.
Chassis No.	Colour
Odometer	Steering
Brakes	Modification
General	

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/03/2018	Inspection Date
Survey held at		

5a. Remarks

--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING						Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd
Main	05 Mar 2018		08 Mar 2018 14:06 Assign			

[New Assignment](#)
[Cancel Case](#)

Main	Reference	Claim Details	Documents	Show All																				
<div style="text-align: right;">[Created by insurer]</div> CLAIM SUBFOLDER DETAILS Insured: TOKYO CENTURY LEASING (SINGAPORE) PTE LTD, Co. Reg. No.: 197901535G Main Claimant: MKM CAR LEASING PTE LTD, Co. Reg. No.: 201224734R Vehicle Reg. No.: SLS2339T Date of Loss: 05/03/2018 14:00 - :59 Claim Type: TP / MSC/V/18-000347 Policy/Cover Note No.: MSD/VPCP/17-000414 (Comprehensive) Vehicle Reg. No. (Insured): SKE5680Y Policy No. (Claimant): Coverage: 14/03/2017 - 13/03/2018 Excess: S\$300.00 Repairer: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752 Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540] Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/03/2018] Driver/Custodian (Insured): ARASHIMA SATOSHI (), NRIC: G5428707R, Tel: +6585223622 Adj Asg. Remarks: Please help to arrange surveyor on 13/03/2018 (Tuesday) and vehicle will be in our workshop on 12/03/2018 after 3pm. REQUEST BY TP.																								
<div style="text-align: right;"> View All Compose Case Mail </div>																								
ASSOCIATED MAIL RECEIVED There are no mail for this case.																								
<div style="text-align: right;"> View All Search Tasks Create New Task Complete </div>																								
ALL ASSOCIATED TASKS <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

3/14/2018

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Date: 14 Mar 2018	
Attn: Elaine Ngu Siau Mei	
<u>Preliminary Advice</u>	

Insured Vehicle No	: SKE5680Y	Accident Date	: 05/03/2018
TP Vehicle No	: SLS2339T	Assignment Date	: 08/03/2018
Make	: TOYOTA PRIUS ALPHA HYBRID	Est. Duration of Repair	: 4.00
Date of Inspection	: 13/03/2018		
Inspection At	: HUI YANG MOTOR PTE LTD (HQ) 176 SIN MING DRIVE #04-02, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,015.50
Revised Amount	:S\$	1,704.25
Check Items (Estimated)	:S\$	943.00
Total	:S\$	2,647.25

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/03/2018 12:46
Date Of Accident	05/03/2018 14:40
Exact Location Of Accident	ALONG CLEMENTI AVE 6 EXIT COMMONWEALTH AVE WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS2339T
Insured/Policyholder	
Name Of Registered Owner	MKM CAR LEASING PTE LTD
Co Reg No	201224734R
Email Address	RINA@MKMCARLEASING.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-67476880

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS ALPHA HYBRID 1.8S CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5087629360-01
Cover Note Number	

Driver

Name of Driver	LAI CHOONG HWEE
NRIC No	S7666200B
Date Of Birth	08/03/1976
Occupation	OUTDOOR
Date Of Driving Pass	23/06/2009
Driving Experience	8 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92282419
Fax Number	
Contact Number	
EMail Address	MATTCHLAI@YAHOO.COM.SG

SKETCH PLAN


IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

辉 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

MS19

13/03/18

(Tuesday)

05/03/2018

Owner: MKM CAR LEASING PTE LTD

Signature
5/3/18

Nett

Runny B4 part

4 days

81738.75

ESTIMATE TO REPAIR TOYOTA PRIUS ALPHA 18S - SLS2339T

1pc	rear tailgate
1pc	rear tailgate "PRIUS" emblem
1pc	rear tailgate "HYBRID" emblem
1pc	rear tailgate inner lock
1pc	rear tailgate inner rubber
1pc	rear bumper
2pcs	rear bumper side retainer @\$55.00
1pc	rear bumper RH side reflector
1pc	rear RH taillamp
2pcs	rear taillamp lower bracket @\$30.00
1pc	rear end panel
1pc	rear end panel inner garnish

<i>R</i>	\$	520.00	<i>X</i>
<i>ru</i>	\$	45.00	<i>✓</i>
<i>ru</i>	\$	45.00	<i>✓</i>
<i>R</i>	\$	155.00	<i>X</i>
<i>su</i>	\$	145.00	<i>X</i>
<i>B</i>	\$	350.00	<i>✓</i>
<i>ch on</i>	\$	110.00	<i>✓</i>
<i>Bu</i>	\$	45.00	<i>✓</i>
<i>su</i>	\$	380.00	<i>X</i>
<i>CR</i>	\$	60.00	<i>2+</i>
<i>RS</i>	\$	380.00	<i>X</i>
<i>su</i>	\$	135.00	<i>X</i>

\$ 2,370.00

cost + 15%

\$ 355.50

\$ 2,725.50

1set rear parking sensor

su s.nett \$ 280.00 *X*

wiring
tuffkote
spray painting
labour charges
Total

<i>su</i>	\$	80.00	<i>201</i>
<i>ru</i>	\$	80.00	<i>X</i>
	\$	950.00	<i>5501</i>
	\$	900.00	<i>4501</i>
	\$	5,015.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Mar 2018		08 Mar 2018 14:06 Edit Adj Rpt	S\$1,738.75 Edit Estimates	S\$1,738.75 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TOKYO CENTURY LEASING (SINGAPORE) PTE LTD, Co. Reg. No.: 197901535G									
Main Claimant: MKM CAR LEASING PTE LTD, Co. Reg. No.: 201224734R									
Vehicle Reg. No.: SLS2339T		Date of Loss: 05/03/2018 14:00 - :59 [5 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MSC/V/18-000347		Policy/Cover Note No.: MSD/VPCP/17-000414 (Comprehensive) Coverage: 14/03/2017 - 13/03/2018							
Vehicle Reg. No. (Insured): SKE5680Y		Policy No. (Claimant):							
		Excess: S\$300.00							
Repairer: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 07/04/2018]									
Driver/Custodian (Insured): ARASHIMA SATOSHI (), NRIC: G5428707R, Tel: +6585223622									
Adj Asg. Remarks: Please help to arrange surveyor on 13/03/2018 (Tuesday) and vehicle will be in our workshop on 12/03/2018 after 3pm. REQUEST BY TP.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS2339T (MSC/V/18-000347)
[SKE5680Y]

TP

MKM CAR LEASING PTE LTD

Mar 5 2018 2:00PM

[TOKYO CENTURY LEASING (SINGAPORE) PTE LTD]
Hui Yang Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	08/03/18 13:35	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement <small>From: SC - Reg. No: SKE5680Y, Claimant: TOKYO CENTURY LEASING (SINGAPORE) PTE LTD</small>		Load HTM	
No	Finalized On			Thumbnail	Print
1	14/03/18 17:50	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail	Print
1	14/03/18 10:13	LKK Auto Consultants Pte Ltd (HQ) General View		Load JPG	<input checked="" type="checkbox"/>
2	14/03/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
3	14/03/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
4	14/03/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
5	14/03/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
6	14/03/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
7	14/03/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
8	14/03/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
9	14/03/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
10	14/03/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
11	14/03/18 10:13	General View		Load JPG	<input checked="" type="checkbox"/>
12	19/04/18 11:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
13	19/04/18 11:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
14	19/04/18 11:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
15	19/04/18 11:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
16	19/04/18 11:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
17	19/04/18 11:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
18	19/04/18 11:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	08/03/18 13:32	MSIG Insurance (Singapore) Pte. Ltd. (HQ) TP SKW322U EST & GIA REPORT		Load PDF	
2	08/03/18 13:32	TP SLS2339T GIA REPORT.		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004486/KVBE2
Date: 24/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VPCP/17-000414
Claimant Vehicle No:	SLS2339T	Insured Vehicle No:	SKE5680Y
Date of Loss:	05/03/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000347

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS2339T	Engine No:	2ZR1996036
Make & Model:	TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A)	Chassis No:	ZVW400026325
Reg. Date:	14/09/2017 (Man. Year: 2017)	Odometer:	41701 km
Colour:	Metallic Dark Green		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 3 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 3 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,005.50	718.75	2,286.75	76.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	1,020.00	990.00	49.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,015.50	1,738.75	3,276.75	65.33
+ GST 7.00/7.00% (S\$)	351.09	121.71	229.38	65.33
Nett Amount (S\$)	5,366.59	1,860.46	3,506.13	65.33

INSPECTION

Date of Assignment:	08/03/2018	
Date Inspected:	13/03/2018 Inspected At:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2018)
Parts: 144	TOYOTA PRIUS ALPHA HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS2339T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE (WCP)	Repair	520.00 F	*- F
2	1		*REAR TAILGATE PRIUS EMBLEM (WCP)	Necessary	45.00 F	*45.00 F
3	1		*REAR TAILGATE HYBRID EMBLEM (WCP)	Necessary	45.00 F	*45.00 F
4	1		*REAR TAILGATE INNER LOCK (WCP)	Repair	155.00 F	*- F
5	1		*REAR TAILGATE INNER RUBBER (WCP)	Serviceable	145.00 F	*- F
6	1		*REAR BUMPER (WCP)	Bent	350.00 F	*350.00 F
7	2		*REAR BUMPER SIDE RETAINER (WCP)	Distorted	110.00 F	*110.00 F
8	1		*REAR BUMPER RH SIDE REFLECTOR (WCP)	Broken	45.00 F	*45.00 F
9	1		*REAR RH TAILLAMP (WCP)	Serviceable	380.00 F	*- F
10	1		*REAR TAILLAMP LOWER BRACKET (2 PCS)(WCP)	Cracked-Only 1 pc	60.00 F	*30.00 F
11	1		*REAR END PANEL (WCP)	Repair	380.00 F	*- F
12	1		*REAR END PANEL INNER GARNISH (WCP)	Serviceable	135.00 F	*- F
13	1		*SET REAR PARKING SENSOR	Serviceable	280.00 FS	*- FS
					Sub Total (\$\$)	2,650.00 625.00
					+ Margin on L,N Items 15.00/15.00% (\$\$)	355.50 93.75
					Total Parts (\$\$)	3,005.50 718.75

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRING	New	80.00	20.00
2	TUFF KOTE	New	80.00	0.00
3	SPRAY PAINTING	New	950.00	550.00
4	LABOUR CHARGES	New	900.00	450.00
Gross Labour Cost (S\$)			2,010.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >