

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD247P -**AAD1803-049***Not Authorized**Henry Bypaint 82926.19*

Vehicle No.:	SHD247P - JHOW
Chassis No.:	VF1ABL15AUC282384
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	05.03.2018
Third Party Insurer :	AXA

PART		LIST	
1	1	BUMPER COVER FRT	\$ <i>Bumper</i> 1,259.42 ✓
2	1	BUMPER ABSORBER FRT	\$ <i>SL</i> 394.68 X
3	1	BUMPER BEAM FRT	\$ <i>R</i> 914.08 X
4	1	BUMPER SPOILER FRT	\$ <i>SL</i> 181.75 X
5	1	BUMPER GRILLE LOWER FRT	\$ <i>SL</i> 266.80 X
6	1	BUMPER FOG LAMP GRILLE RH	\$ <i>SL</i> 207.22 X
7	1	BUMPER RETAINER FRT RH	\$ <i>D/S</i> 151.41 ✓
8	1	BUMPER SUPPORT FRT RH	\$ <i>SL</i> 123.88 X
9	1	BUMPER RETAINER FRT LH	\$ <i>SL</i> 151.41 X
10	1	BUMPER SUPPORT FRT LH	\$ <i>SL</i> 123.88 X
11	1	HEADLAMP RH	\$ <i>SL</i> 1,184.43 X
12	1	HEADLAMP PANEL FRT RH	\$ <i>R</i> 152.15 X
13	1	FENDER PANEL FRT RH	\$ <i>R</i> 783.83 ✓
14	1	FENDER INSULATOR RH	\$ <i>SL</i> 130.84
15	1	FENDER BRACKET FRT RH	\$ <i>R</i> 13.02
16	1	FENDER WHEELARCH FRT RH	\$ <i>SL</i> 278.84
17	1	FENDER PANEL BRACKET FRT RH	\$ <i>R</i> 177.41
18	1	WHEEL HOUSING PANEL FRT RH	\$ <i>R</i> 4,682.09
19	1	LOWER ARM FRT RH	\$ <i>SL</i> 685.76
20	1	KUNCKLE ARM FRT RH	\$ <i>SL</i> 846.98
21	1	ABSORBER FRT FRT RH	\$ <i>SL</i> 360.54
22	1	WIPER RESERVOIR	\$ <i>SL</i> 348.25 X
23	1	WIPER RESERVOIR NECK	\$ <i>SL</i> 136.11
24	1	WIPER RESERVOIR MOTOR	\$ <i>SL</i> 270.06
25	1	RADAITOR GRILLE	\$ <i>SL</i> 1,707.78
26	1	RADAITOR GRILLE BADGE 'RENAULT'	\$ <i>SL</i> 173.36
27	1	RADAITOR GRILLE FRAME	\$ <i>SL</i> 1,353.75
28	1	FRAME FULL SUPPORT PANEL	\$ <i>SL</i> 615.90
29	1	FRAME FULL SUPPORT BRACKET	\$ <i>R</i> 89.79
30	1	BONNET	\$ <i>R</i> 1,941.63
31	1	BONNET INSULATOR	\$ <i>SL</i> 405.73
32	1	DOOR MIRROR RH	\$ <i>SL</i> 1,483.40
33	1	DOOR MIRROR GLASS RH	\$ <i>SL</i> 242.33

TRANS-CAB AUTO SERVICES PTE LTD**AAD1803-049**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD247P -

34	1	DOOR MIRROR BACK COVER RH	\$	<i>sn</i> 218.46	X
35	1	DOOR MIRROR LAMP RH	\$	<i>sn</i> 194.18	X
36	1	DOOR PANEL FRT RH	\$	<i>sn</i> 2,844.66	X

TOTAL	\$	25,095.82
10%	\$	2,509.58
	\$	22,586.24

Special Nett

1	1SET	FRONT BUMPER CLIP	\$	<i>sn</i> 66.00	✓
2	1SET	WHEELARCH CLIP RH	\$	<i>sn</i> 66.00	} X
3	1	TOW COVER FRT	\$	<i>sn</i> 14.50	
4	1	CAP HUB RH FRT	\$	<i>sn</i> 35.00	
5	1	RIM RH FRT	\$	<i>sn</i> 385.00	
6	1	TYRE RH FRT	\$	<i>sn</i> 330.00	
7	1	DOOR SEAL CLIP FRT RH	\$	<i>sn</i> 4.68	
8	1	DOOR STICKER "Trans-cab"	\$	<i>sn</i> 80.00	
9	1	DOOR STICKER "Classic"	\$	<i>sn</i> 30.00	}
10	1SET	BUMPER SUPPORT FRT CLIP RH	\$	<i>sn</i> 9.80	
11	1SET	BUMPER RETAINER FRT CLIP RH	\$	<i>sn</i> 12.50	

TOTAL	\$	1,033.48
TOTAL PARTS	\$	23,619.72

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,200.00 *400*

To Check Electrical Lighting Concerned.

\$ 170.00 *150*

Putty and spray painting of the affected portion.

\$ 4,500.00 *4400*

To rust-proofing of the affected areas.

\$ 170.00 *300*

To check steering geometry and computer wheel alignment

\$ *sn* 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ *sn* 170.00 X

Towing fees

\$ *sn* 120.00 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-049

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD247P -

To transfer of door fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 170.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn 380.00 X

TOTAL	\$	10,820.00
Over All Total	\$	34,439.72

(PARTS BY PARTS) Repair Days15 Days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: