

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : Own Damage
 3rd Party
 Windscreen

Ins Company : India Int' ins
 Excess : _____
 Date of Accident : 12.02.2018
 Suggested Days of Repair : 8 day

Vehicle No. : YN6011J
 Make & Model : ISUZU / NJR85AUE6W
 Year of Manufacture : 2014
 Chassis No. : NJR857040449
4JJ11L2376
 Engine No. : 4JJ11L2376
 Policy No. : _____
 Time of Accident : 09.40 A.M

In-house Vehicle Assessor

Name : Wong Chee Wei
 Signature : _____
 Contact No : 68676919
HP : 97239882

Repair Estimates

Parts (a) Cost / List Price Items	<u>\$7,650.00</u>
Less 15 %	<u>\$(1,147.50)</u>
(b) Nett Price Items	_____
Less _____ %	_____
(c) Special Nett Items	<u>\$850.00</u>
Total Parts Cost (Appendix A)	<u>\$7,352.50</u>
Labour (Appendix B)	<u>\$1,810.00</u>
Total Repair Cost	<u>\$9,162.50</u>

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Name of Surveyor : RASUL
 Company : LKK
 Survey conducted on : 03/04/18 at 1530 1530

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.
 (b) Recommended Days of Repair : 4 days day(s)
 (c) Resurvey : Required / Not Required after repair Luytan
 (d) Excess : \$ _____
 (e) Signature of surveyor : [Signature] Date: 03/04/18

COMFORTDELGRO ENGINEERING PTE LTD

45 Pandna Road S (609286)

Tel: 68676919 Fax: 62626950

Appendix A

Spare Parts

Vehicle No. : YN6011J Submit By : Wong Chee Wei
 Make & Model : ISUZU NJR85AUE6W Year Manufacture : 2014
 Chassis No. : NJR857040449 Engine No. : 4JJ11L2376

TP

S/Order : _____

S/No	Part Description	Qty	Cost	Nett	List	S- Nett	Disposition By Surveyor
			Price	Price	Price	Price	
1	DOOR RHF	1 PC			\$2,400.00		R
2	DOOR SIGNAL LAMP RHF	1 PC			\$200.00		Pro ✓
3	SIDE LAMP RH	1 PC			\$325.00		Pro ✓
4	HEAD LAMP RH	1 PC			\$1,000.00		?
5	FR BUMPER	1 PC			\$1,400.00		scr -
6	FR BUMPER BRACKER RH	1 PC			\$375.00		?
7	FR BUMPER BRACKET LH	1 PC			\$375.00		X
8	CORNER GARNISH RH	1 PC			\$375.00		3 X
9	SIDE MIRROR	1 PC			\$200.00		X
10	SIDE MIRROR BRACKET RH	1 PC			\$1,000.00		X
11	DOOR STICKER - COMPANY DECAL	1 PC				\$850.00	ku ✓
12						300	
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

