

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

China Taiping CP/P) IS

VEHICLE NO : SHA 4073M

DATE 7/3/2018

MAKE :

LKK - kalvin

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,681.40
	Boot Lid Rubber ✕			\$ 115.80
	Boot Lid Lock Upper ✕			\$ 137.90
	Boot Lid Lock Lower ✕			\$ 31.70
	Boot Lid 'H' Emblem ✓			\$ 27.20
	Boot Lid CRDI Plate ✓			\$ 41.00
	Boot Lid Lamp (LH) ✓			\$ 556.80
	Bootlid Moulding ✕			\$ 85.00
	Bootlid i40 Emblem ✓			\$ 41.00
	Bootlid Lower Garnish ✕			\$ 398.00
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket, LH ?			\$ 49.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.00
	Rear Bumper Reflector Lamp (LH) ✓			\$ 32.00
	Tail Lamp (LH) ✓			\$ 565.60
	SUB TOTAL			\$ 5,620.75
	LESS 20%			\$ 1,124.15
	DISCOUNTED TOTAL			\$ 4,496.60
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00
	Rear Bumper Reverse Sensor ✕			\$ 135.70
	Labour Charge			
	Panel Beating- Repair Rear LH Fender			\$ 750.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,570.00
	ESTIMATE TOTAL			\$ 6,232.30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7/3/18 to 3-6-18

3 Pys

PIP

Before Paint to U