ASS. REC. BY:	REF: CS MS1G18004496 / 11 Vd 30 Special Instruction:
SUPVEVOY From (Person):	ASSIGNMENT (Office) Chhia Nyuk of MSIG Date/Time: 7/3/100/10-47cm
Estimated Cost:	Bill to:
OD TP WS	TP RES / OD RES / EVA / INV / MV 7 CS
To Inspect Veh	icle No: SLH 3178S Insured: SLV 445S /s Performance Motor Tel: 63190174
at Workshop m	terformance Motor, Tel: 63190174
of	303 Alexand M. Road
Policy No:_A	28795104MCX Claim No:
Sum Insured:_	Excess:
Make of Veh: (Client's Record)	D.O.A. 03/03/2018
CA / REV !	REP. / REV 24 HRS H.O.D. Endorsement:
	36pm 08 3 18 Person Contacted: Caroline Vehicle IN 16UT
Date/Time	Action/Instruction () Estimate
	16 1 SM85 X
	511.4458.x
15 3 8	Send preli revised by merimen
10 5 18	Final fig \$ 11,313.55 (Red 17,301.95, Gols confirmed by email

22/03/2002 -

GINNER Taufuls	REF: MSLA		
anton 1	ASSI	GNMENT	
From: Estimated Cost:	Date: 14081018	Veh No. SLH 31785 Type M.Car / M.Cycle / Bus / Van / Lorr Truck / Trailer or	Yr Regn: 2016 Oct y / Taxi / Prime Mover /
OD TP WS / TP RES / OD RES / E To Inspect Vehicle No:	SLH 3178S	Make: BMW X3	c.c 1997
7 11 11 11 11 11 11 11 11 11 11 11 11 11	leturnance	Colour Guy	A/C: Insured / Std / NI / NA
	s Alexandra Rd	Sp.Reading 26050	T/Radio: Insured / Std / NI / NA
Insured:	3 10000	Eng/No:	
Policy No.		C/No: WBAWY9	20400R99739
Claims No.		Gen. Cond: Good / Fair / Poor / Burnt	· ·
Sum Insured:	Excess:	Steering: Inorder / Jammed / Leaked / E	Burnt or
(Client's Record)		Brake: Inorder / Jammed / Leaked / E	Burnt or
Make of Veh:	nua.	Modi: Nil / S/Rhm / STD A/Rim or	1. 0.11
	r	Tyre Size: F: \(\frac{\fir}}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}\frac{\frac{\frac{\fracc}\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\fracc}\fr	5/40/219
(Policy Condition)		R:	<u></u>
Remark: The veh had commenced		BS / DUN / EXNOVA / GY / FS / LIZA	NJČ / OHTSU / PIR / SUMI /
repair at the time of inspe	ection.	TOYO / YOKO or	
Bal. or Market Value:		Front	Rear
IDAC Accident Rport: Co	onsistent? : Yes or No	R/Bal. 6 mm	R/Bal. mm
GIA / PR Seen:CC	onsistent? : Yes or No	L/Bal mm	L/Bal. mm
Est. Repairs: days	Res.: Yes or No	D.O.A.	D.O.I. 1 (/3//8/0/2) V
Lum Sum: %	3 Val.: Yes or No	Survey held at	
CA / REV / REP. / 24 HRS	VIII WAR	Des. of Damages : Frt Rear / O/S /	N/S / U/C / Rooftop or
Date: Person Conta	Vehicle: IN / OUT acted:	The U/C / Chassis frame / Body	Structure affected due to collision.
Date / Time Action / Instruction	1		
RECELY	4.73		
Date/Time. File Pass to? : Pre	eli. Report	Days Of Repair:	
	•	Resurvey No. of Trip:	Survey Fee: 300
Date/Time, File Return to?	•		Transportation.
2 Jols- typist	Add Fee	: Site Insp (\$)S + RSSI
. 7		: Interview (\$; Photos
Report Format :	eli men	Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$ 11, 3	(13.55	: Weekend (\$,



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Carrier Tolog 4	Affiliated to Federation Internation	onale Des Experts En Autor	nobile
MSIG INSURANCE (S	INGAPORE) PTE LTD	Ref: CS/MSG18004	1496/T1vd3
16 RAFFLES QUAY #24-01 HONG LEONG	BLDG SINGAPORE 048581	Date: 08-03-2018 Code: MSG	
1.4	Policy Particulars	:- THIRD PARTY CLA	IM TO A SECOND
Insured Veh.	SLV 445S	Veh. Inspected	SLH 3178S
Policy No.	A28795104MCX	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (CHHIA NYUK)	Assign Date	08/03/2018
2	Vehicle Parti	culars & Condition	· 北京國際。
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	· · · · · · · · · · · · · · · · · · ·
Odometer	-	Steering	
Brakes		Modification	
General			
3 type seems and	Conditi	ons of Tyres	
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre		·	mm
L/H Rear Tyre	Trend of the state		mm
4 .	Description	on of Damages	
5. /4[E	∰DD,N	Information	
Accident Date	03/03/2018	Inspection Date	AND THE RESIDENCE OF THE PROPERTY OF THE PROPE
Survey held at	PERFORMANCE MOTORS LTD		
	303 ALEXANDRA ROAD SINGAPORE 159941		
5a	Re	omarks	
A)THE INSPECTION	N WAS CONDUCTED ON A"WIT E TO YOUR INSTRUCTIONS, W	HOUT PREJUDICE" BAS	IS. SED REPAIRS.
	1 10(1)		

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Mar 2018		07 Mar 2018 10:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETA	ILS		[Created by insu	ırer]
Insured:	SKYWAY MOTOR PTE LTD,	Co. Reg. No.: 199904194N		
Main Claimant:		S8010605Z	• •	
Vehicle Reg. No.:	SLH3178S	Date of Loss:	03/03/2018 13:00	- :59
Claim Type:	TP	Policy/Cover Note No.:	A28795104MCX Coverage: 08/08/2	017 - 07/08/2018
Vehicle Reg. No. (Insured):	SLV445S	Policy No. (Claimant):		
		Excess:		
Repairer:	Performance Motors Limite Alexandra - Tel: 63190172/63	d (Alexandra) 303 Alexandra Roa 190174	d, Sime Darby Performan	ce Centre, 159941
Handling Insurer:	MSIG Insurance (Singapore 6594 2521)	e) Pte. Ltd. (HQ) - Tel: +65 6827	7888 [Handled by Chh	ia Nyuk Pui -
Adjuster:	LKK Auto Consultants Pte L	.td (HQ) - Tel: 6256-3561 [Imi	n.Advice due 08/03/	20181
Driver/Custodian (Insured):	CHAI JOON LUK (), NRIC: S			
ASSOCIATED MAIL RECEI	VED		View All	Compose Case Mail
ASSOCIATED MAIL RECEITHER There are no mail for this case			View All	Compose Case Mail
	e,	· View All	View All Control of Co	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Chhia Nyuk Pui

Date:

15 Mar 2018

Preliminary Advice

Insured Vehicle No : SLV445S

TP Vehicle No

: SLH3178S

Accident Date

: 03/03/2018

Make

: BMW X3 SDRIVE

Assignment Date

: 07/03/2018

Date of Inspection: 14/03/2018

Est. Duration of Repair

: 6.00

Inspection At

: PERFORMANCE MOTORS LIMITED (ALEXANDRA)

303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE

SINGAPORE 159941

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,345.80
Revised Amount	:S\$	9,668.90
Check Items (Estimated)	:S\$	10,328.30
Total	:S\$	19,997.20
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

0605Z

Vehicle Details

Vehicle No.:

SLH3178S

Vehicle to be Exported:

. .

Intended De-registration Date:

15 Mar 2018

Vehicle Make:

B.M.W.

Vehicle Model:

X3 SDRIVE 201 M SPORT HID SR NAV

Primary Colour:

Grey

Manufacturing Year:

2016

Engine No.:

A1321435N20B20A

Chassis No.:

WBAWY920400R99739

Maximum Power Output:

135.0 kW (181 bhp)

Open Market Value:

\$37,425.00

Original Registration Date:

31 Oct 2016

First Registration Date:

31 Oct 2016

Transfer Count:

0

Actual ARF Paid:

\$44,395.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

30 Oct 2026

PARF Rebate Amount:

\$33,296.00

Intended COE Rebate Details

COE Expiry Date:

30 Oct 2026

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$53,001.00

COE Rebate Amount:

\$45,706.00

Total Rebate Amount:

\$79,002.00

The information contained herein is correct as at 15 Mar 2018

SGCARMART.COM

Sign up Login

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

New Unregistered Honda Fit 1.3 GF, Ready Stocks!

Compare 10+ insurers **GET A CHEAPER QUOTE**

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Ways of Selling

Model



Manie P

\$3000 Drive Away, Low Monthly Installment! 3 Years Warranty Provided! Call Now! Apex Trading Pte Ltd - 54-544

(HIN LUNG AUTO One Stop Car Hub Finance, insurance, Workshop New and Used Cars

Browse by Category

Post an Ad

2 vehicles bmw x3

Advertiser Login

Sort by Date Posted

Advanced Search

20 result:

Stz

Price

Depreciation

Reg Date 2016 Eng Cap

Any

Search

Any

Search Selection

bmw x3

Any

Any

25,000 km

Any

BMW X3 sDrive20i

\$175,000

\$19,690 /vr

07-Mar-2016

1,997 cc

SUV

1 Owner, PML Unit With Full Service History And Agent Warranty. Immaculate Black On Black Unit With Low Mileage Of Just 25K KM. Regularly Groomed And Always Garaged At Owner's Home. Protected By 9H Gl...

Looking For A Status Upgrade? Or A Neat Family Car? Or Even A Long Drive With Your Friends? Look No Further! Get This Classy Suv For A All

Bavarian Marques Pte Ltd

Posted: 06-Mar-2018 Tags: 2016 BMW X3, BMW X3, BMW, X3, Used BMW



BMW X3 sDrive20i

\$180.800

\$18,770 /yr

27-Sep-2016

1,997 cc

10.875 km

SUV

Purpose Drive. 5 Years Extended PML Servicing, Full PML Servi... Prem Roy Motoring

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Depreciation

Reg Date

Eng Cap

Veh Type

For old advertisements, view Expired ads

20 results,

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, Lixury cars, s stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, bok up car bans, low mileage cars, car brands, carpark rates & car insurance. Find buy used b x3 Singapore, used brnw x3 Singapore, used brnw x3, used vehicles Singapore or even buy used brnw x3 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performan discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be gi information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum Tool & Tip
- © 2004-2018 sgCarMart. All rights reserved.

- · Terms of Service
- Privacy Policy
- Personal Data Protection

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the lodgement of this report to the insurers, you aforesaid.	ou hereby consent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	05/03/2018 11:01
Date Of Accident	03/03/2018 13:15
Exact Location Of Accident	ALONG PIE TWDS TUAS (ABOUT 1-2 KM AFTER PAYA LEBAR
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLH3178S
Insured/Policyholder	
Name Of Registered Owner	ANG HUI LIM JOSEPH
NRIC No	\$8010605Z
Email Address	ANG.JOSEPH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98587566
Alternative Phone No	OFFICE-98587566

Vehicle Particulars

Manufacturer **BMW** Model Х3

Exact Purpose for which vehicle was being used at

time of accident

NORMAL USAGE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number **NOTAVAIL**

Cover Note Number

Driver

Name of Driver ANG HUI LIM JOSEPH

NRIC No S8010605Z Date Of Birth 11/04/1980 Occupation **INDOOR** Date Of Driving Pass 01/10/2004

Driving Experience 13 YEARS AND 5 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98587566

Fax Number

Contact Number OFFICE-98587566

EMail Address ANG.JOSEPH@GMAIL.COM '. Address

NOTAVAIL

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

YES NO

Number of Passengers (Including Driver)

2

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?

YE\$

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLV445S

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE HIRE

Name of Driver

CHAI JOON LUK

NRIC/Passport Number

S7964439J

Contact Number

Address

Postcode

Insurance Company Name

MSIG INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of '
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Driver's Signature Reporting Centre Personnel's Signature

Page 3 of 35

· f

	SKETCH PLAN
	DESCRIBE CIRCUMSTANCES OF THE ACCIDENT
C	I was driving along PIE (towards Thiss). The incident implined along
(att	or Payor laber disposer). I was braking as the car intront had slowed
	down. Suddinly the carbehind me banged and my Car. I
	got down the car and immediately brought a per and paper
	to ask the counterpartit to sign and acknowledged that
	he banged into my car. As it was quite not and drustant
	the video and the video did not manage to apture the
	carplate of the counterparty. I wished to claim' against
	the 3rd party upon dong my own claim
	DECLARATION
	DECLARATION I/We degine the foregoing particulars are true in every respect.

2 aknowleged that I barged into SLH31785 EN PIE. on 3 Mas ch 2018

> chai JIDEN LUK JULO S 796 4439 J

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941

Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

Alexandra Road (Sime Darby Business Centre Singapore 159944 Tel. 63190528 (AfterSa: 63190533/530 (Motorrad: 64796601 (Motorrad: 64796604 (Motorrad: 6479604 (Motorrad: 64796604 (Motorrad:

(AfterSales) (AfterSales) (Motorrad)

Page No. : 1 of 3

GST REG. NO : M2 - 0020081 - X

ESTIMATE

0 5 MAR 2018

Estimate No.

: b1 46114

Date Estimated

: 05/03/2018

Prepared By

: Chua Kee Sin

ESTIMATE REPAIR FOR -

Ang Hui Lim Joseph (Hong WeiMing)

1 Pulasan Road

#02-06 1@Pulasan

Singapore

Singapore 424366

ACCOUNT

66

MSIG Insurance (S) Pte Ltd

4 Shenton Way

#21-01 SGX Centre 2 Singapore 068807

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SLH3178S

0R99739

31/10/2016

X3 sDrive20

0

DESCRIPTION

Replace tail end panel, rear boot lid, rear bumper and attac

hment etc include knock on accident

dent

Spray paint rear floor panel, tail panel, rear bumper, rear

boot lid and both side rear fender ?,

To remove and install boot compartment carpet and garnish to facilitate repairs.

To check electrical wiring systems and lightings at the rear section for proper function.

To replace exhaust manifold and gasket including checks for leak.

To replace rear windscreen glass

To supply and install rear windscreen solar film.

To carry out body cavity preservation. (For cut panel).

To supply rear emboss number plate.

Sundries.

2550 5,100.00

VALUE

271.00

5,782.00

150, 177.00

950.00

487 574.00

M x 451 531.00

4517

83.00

150.00

Total Labour 1:

14,149.00

QTY	PRIC	VALUE
10	1.10	<u>?</u> 11.00
30	2.95	7 88.50
2	1.10	? 2.20
3	33.65	? 100.95
1	60.60	7 60.60
	30	10 1.10 30 2.95 2 1.10 3 33.65

Performance Motors Limited A member of the Sime Darby Group CO. Reg. No. 197401559W GST Reg. No M2-0020081-x

303. Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

: b1 46114

Date Estimated

: 05/03/2018

Prepared By

: Chua Kee Sin

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

Page No. : 2 of 3

REGN. NO.	CHASSIS NO. REGN. DATE	MODEL		MILEAGE	
SLH3178S	0R99739 31/10/2016	X3 sDrive20		0	
	DESCRIPTION	QTY	PRIC	<u>VALUE</u> ✓ 1 220 00 ✓	
	REAR MUFFLER	1	1,220.90	61,220.90	
	TAILPIPE TIP CHROME	1	124.85	124.85 XA	
	BOOTLID	1	1,807.20	h) / 1,807.20 V	
	TAIL END PANEL	1	390.90	K ≥ 390.90 µ	-
r	OUTER PANEL TAIL TRIM	1	497.45	7497.45 V	A
	LEFT TRUNK L	1	74.60	à 14.00	
	RIGHT TRUNK	1	74.60	77.00	
	RR BUMPER CARRIER ECE	1	738.05	738.05	5
	RR LH BUMPER MIDDLE MOUNTING	1	142.55	(142.55	
	RR LH BUMPER MIDDLE MOUNTING	1	142.55	? 142.55X /	١
	RR RH BUMPER MIDDLE MOUNTING	1	142.55	142.55	
<u>.</u>	RR RH BUMPER MIDDLE MOUNTING	1	142.55	(142.55 🗶)	•
	RR BUMPER LH MOUNT	1	198.30	? 198.30	
	RR BUMPER LH MOUNT	1	198.30	198.30	
	RR BUMPER RH MOUNT	1	198.30	7,198.30	
	RR BUMPER RH MOUNT	1	198.30	198.30	_
	TRIM PANEL BUMPER RR BOTTOM (M)	1	251.70	de 251.70	
	COVERING LOWERM-PAKET / AHV	1	116.15	7 116.15	
	SET OF TRIM COVERS TOW FITTING (M)	1	91.15	m/3-91.15 × 91.15 ×	v
	SET OF TRIM COVERS TOW FITTING (M)	1	91.15	1. /	_
	RR BUMPER TRIM BUMPER PRIMED PDC (1	1,585.60 59.00 69.50		
	TRUNK LID BADGE	1	00.00		
	MODEL LETTERING X3	1	62.55	7 02.00	
	STRIKER BOOT LID	1	55.75	55.75	
	Holder upper section lock	1	17.60	7 17.60	
	LOCK TRUNK LID	1	211.85	211.85	١.
·	SPINDLE DRIVE DLI	1	414.30	ון טפידוד א	5
	SPINDLE DRIVE RH BUMP STOP	1	414.30	ام 414.30 كا م 414.30 كا م 48.00 كا	
	DRIP MOULDING LH	12	4.00 76.85	48.00	
	DRIP MOULDING RH	1	76.85 76.85	76.85	
	RR W/SCREEN	1	1,279.80	76.85	
	Velcro rear window	1 A	1.10		
	HOOK AND LOOP FASTENER (4PG)	6	2.80 il.⊃c	16.80 A	í
	LOADING SILL COVER	1	179.25	179.25	•
	HEAT INSULATOR REAR SILENCER	1	94.70	94.70	٨
	HEAT INSULATOR REAR SILENCER	1	94.70	, 7 94.70 }	
	BOOTLID GASKET	1	128.90	NUX 128.90	,
	DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	mi 20.20	
	BUMPER PDC SENSOR (A52 SPACEGRAU)	4	368.80	7 1,475.20	
	DUND DIVET AVIDVED	14 ?	· · · · · · · · · · · · · · · · · · ·	Ne 7.70%	
	BLIND RIVET AVIBULB 3.5c. pcs	14 g 24 j	⁴⁰ 0.55	al 13.20	
				1 10 17 5	,
	SCREW (SF PLUS M5X15) }	? ? ?)	0.55	7 1.10 13	
	(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	281.55	í
	(DG) BODYWORK ADHESIVE K5A (50ML)	· 1	118.35	7 118.35 VA	į.
	(DG) CLEANER R1 (100ML)	1	23.85	7 23.85	
	(DG) CLEANER R1 (100ML)	· 1	23.85	7. 23.85 X	
Į	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	NU 263.10 X	
	, , , , , , , , , , , , , , , , , , , ,	 			•

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel. 63190528 (AfterSal 63190533/530 (Motorrac Fax. 64796601 (AfterSal (Motorrac (AfterSales) (Motorrad) (AfterSales) (Motorrad)

GST REG. NO : M2 - 0020081 - X

STIMATE

Estimate No.

: b1 46114

Date Estimated

: 05/03/2018

Prepared By

: Chua Kee Sin

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE n

Page No. : 3 of 3

27

SLH3178S

0R99739

31/10/2016

X3 sDrive20

DESCRIPTION

HOPES **PUNCH RIVET N4**

(DG/SL) GLASS PRIMER 30ML (VP206)

OTY PRIC 0.55 24

1

VALUE 13.20

Total Parts

27.85

27.85 14,196.80

Χh

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is ai. wed
- Supplementary item(s) most the insurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Claims OD / 3rd Party / Uninquired losses / Direct Settlement Regn No. Claim No. Date&Time 1250 Surveyor's Name w Surveyor's Tel Yes / No **Authorised Date** RESURVEY PARTS PHOTO BY SURVEYOR PML Yes / No Surveyor's E-mail tau karbun No. of Working Days Recommend

28, 6,5.50

Labour 1 Parts

14,149.00 14,196.80

Labour 2 Excess

Total GST @ 7%

1,984.21

0.00

0.00

Grand Total

30,330.01

THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

^{**} PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No.

ы 46114

Date Estimated

05/03/2018

Prepared By

Chua Kee Sin

REPAIR FOR -

- ACCOUNT -

66

Page No. :

Ang Hui Lim Joseph (Hong WeiMing)

MSIG Insurance (S) Pte Ltd

1 Pulasan Road

4 Shenton Way

#02-06 1@Pulasan

#21-01 SGX Centre 2 Singapore 068807

Singapore

Singapore 424366

CHASSIS NO.

REGN DATE

MODEL

M LEACE

REGN NO **SLH3178S**

DESCRIPTION

0R99739

31/10/2016

X3 sDrive20

DISC. %

0

NETT

DESCRIPTION

UNIT PRICE

DISC. %

NETT

EXPANDING RIVET * # THIRD STOPLAMP *

1.35 233.60 10.00 1.00

QTY

ORIGINAL PRICE

13.50 المام 233.60

Total Labour:

Total Parts:

247.10

Total Labour & Parts:

247.10

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Thursday, 10 May 2018 11:41 AM

To:

PBSP

Cc:

SUR

Subject:

RE: FINAL REPORT / SLH3178S

Dear Caroline,

WITHOUT PREJUDICE

Confirmed \$11,313.55 before GST @ 6 working days.

Final invoice and all supporting documents sent over to MSIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]

Sent: Wednesday, 9 May 2018 12:18 PM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com>

Subject: FW: FINAL REPORT / SLH3178S

Dear Veron

As requested, please see attached photographs.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

From: Veron Chen (LKKAuto) [veronchen@lkkauto.com]

Sent: Monday, 7 May 2018 4:45 PM

To: PBSP; Taufikh (LKKAuto)

Cc: SUR

Subject: FW: FINAL REPORT / SLH3178S

Dear Caroline,

•
Best Regards,
Veron Chen Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 email :sur@lkkauto.com fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 S(408933)
Original Message
From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Monday, 7 May 2018 1:56 PM To: Taufikh (LKKAuto) <taufikh@lkkauto.com>; SUR <sur@lkkauto.com></sur@lkkauto.com></taufikh@lkkauto.com>
Subject: FINAL REPORT / SLH3178S
Dear Taufikh
We refer to the above and attached Final Report.
Please confirm COR as follows:
T-4-11-h 5 202 00
Total Labour : 5,392.00
Total Parts : 5,921.55
Total Labour & Parts: 11,313.55
Thank you.

Kindly provides us check items and supplementary photos.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Page No. :

Estimate No. : b1 46114

Date Estimated : 05/03/2018

Prepared By : Chua Kee Sin

REPAIR FOR -

- ACCOUNT -

66

Ang Hui Lim Joseph (Hong WeiMing)

MSIG Insurance (S) Pte Ltd

1 Pulasan Road

4 Shenton Way

#02-06 1@Pulasan

#21-01 SGX Centre 2 Singapore 068807

Singapore

Singapore 424366

REGN DATE	MODEL	M LEAG

regn no	CHASSIS NO	REGN DATE	MCCR.		M LEA 0	Œ
SLH3178S	0R99739	31/10/2016	x3 sDrive20		•	NETT
DESCRIPTION			ORIGINA	L PRICE	DISC. %	NETT
attachments, tail pulling and straig	oumper and attachme end panel, third stop phtening accident are d by the accident	lamp include		2550.00		2,550.00
To spray paint ta	iil end panel, rear bur	nper and boot lid		1374.00		1,374.00
To remove and i garnish to facilita	install boot compartm ate repairs	nent carpet and		230.00		230.00
To check electri rear section for p	cal wiring systems ar proper function.	nd lightings at the		150.00		150.00
	install rear windscree onducting water leak			487.00		487.00
* To carry out boo (For cut panel)	dy cavity preservation			451.00		451,00
Sundries				150.00		150,00
DESCRIPTION			UNIT PRICE	QTY	DISC. %	NETT
COVERING LO		✓	1,807.20 497.45 738.05 251.70 116.15 91.15	1.00 1.00 1.00 1.00 1.00 1.00		1,807.20 497.45 738.05 251.70 116.15 91.15

BOOTLID OUTER PANEL TAIL TRIM RR BUMPER CARRIER ECE TRIM PANEL BUMPER RR BOTTOM (M) COVERING LOWERM-PAKET / AHV SET OF TRIM COVERS TOW FITTING (M) RR BUMPER TRIM BUMPER PRIMED PDC (MODEL LETTERING X3 TRUNK LID BADGE HOOK AND LOOP FASTENER # EXPANDING RIVET * # THIRD STOPLAMP * BLIND RIVET AVIBVLB SCREW (SF PLUS M5X15)	1,807.20 497.45 738.05 251.70 116.15 91.15 1,585.60 62.55 69.50 2.80 1.35 233.60 0.55 0.55	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	1,807.20 497.45 738.05 251.70 116.15 91.15 1,585.60 62.55 69.50 11.20 13.50 233.60 16.50 5.50
	0.55	30.00	16.50
	0.55	10.00	5.50
(DG/SL) BODY ADHESIVE K5B (195ML)	281.55	1.00	281.55
PUNCH RIVET N4	0.55	40.00	22.00
(DG) BODYWORK ADHESIVE K5A (50ML)	118.35	1.00	118.35

SUPPLEMENTARY ITEMS

Total Labour:	5,392.00
Total Parts :	5,921.55
Total Labour & Parts :	11,313.55
Deduction for Excess:	
Total Repair Costs less Excess:	11,313.55
GST @7%:	791,95
Grand Total:	12,105.50

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	Status	
Main	05 Mar 2018		07 Mar 2018 10:47 Edit Adj Rpt	S\$11,313. Edit Estima		1,313.55 ew Rpt		Pending Report Cancel (for Survey
	Main	R	еfегепсе	Clai	m Details		Documents	-	Show All
CLAIM S	UBFOLDER DI					[Created	by insurer]		
Insured:	SKYWAY	MOTOR PTE LTD	, Co. Reg. No.: 1	99904194N					
Main Claimant:	Ang Hui I	im Joseph, ID	: \$8010605Z						
Vehicle Re No.:	SLH317	85			ate of Loss:	[16 Months	8 13:00 - :59 s and 3 Days From		e (Man Yr)]
Claim Typ	e: TP / 551	.525			licy/Cover te No.:		MCX (Comprehens 08/08/2017 - 07/0		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
Vehicle Re No. (Insured)	SLV445S			1	licy No. laimant):				
					cess:	S\$700.00			
Repairer:		nce Motors Limi /63190174	ted (Alexandra)	303 Alexandra F	load, Sime I	Darby Perfor	mance Centre, 159	941 Alexand	ra - Tel:
Handling Insurer:	MSIG Ins	urance (Singapo	ore) Pte. Ltd. (HC	2) - Tel: +65 68	27 7888	[Handled by	Chhia Nyuk Pui -	6594 2521]	
Adjuster:	LKK Auto 06/04/2		: Ltd (HQ) - Tel: (5256-3561 [H	andled by M	IOHD TAUF	IKH BIN HAMID]	[Final F	Rpt due
Driver/Cu dian (Insured)	CHAI JOOI	N LUK (), NRIC:	S7964439J						
ASSOCIA	TED MAIL RE	CEIVED					Viev	v All Con	npose Case Ma
There are	no mail for this	case.							
ALL ASS	OCIATED TAS	sks [©]				View All 5	Search Tasks Cr	eate New Tas	k Complet
Due Da	te Priority	Type Task	Group Subj	ect Handler	Assigr	ned By	Completed On	Created	On Done
No results	-		•		_	-	-		

Claim Documents

*SLH3178S (551525) [SLV445S] TP Ang Hui Lim Joseph Mar 3 2018 1:00PM [SKYWAY MOTOR PTE LTD] **Performance Motors Limited**

Vid	eo		1 per page 🗸 🗸
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail Prin
1	09/03/18 09:47	Video - Accident From:OD - Reg. No: SLV445S, Claimant: SKYWAY MOTOR PTE LTD	● Load MP4
Ass	essment Reports		1 per page
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Prin
1	15/03/18 14:41	Adjuster Immediate Advice	1 Load HTM
Pho	otos/Images		3 per page ✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Prin
1	15/03/18 10:44	General View	■ Load JPG ☑
2	15/03/18 10:44	General View	■ Load JPG ☑
3	15/03/18 10:44	General View	■ Load JPG ✓
4	15/03/18 10:44	General View	① Load JPG ✓
5	15/03/18 10:44	General View	1 Load JPG ✓
6	15/03/18 10:44	General View	■ Load JPG
7	15/03/18 10:44	General View	■ Load JPG ☑
8	15/03/18 10:44	General View	Load JPG
9	15/03/18 10:44	General View	■ Load JPG
10	15/03/18 10:44	General View	■ Load JPG ☑
11	15/03/18 10:44	General View	■ Load JPG
12	15/03/18 10:44	General View	■ Load JPG 🛂
13	15/03/18 10:44	General View	1 Load JPG ✓
14	15/03/18 10:44	General View	■ Load JPG ☑
15	15/03/18 10:44	General View	■ Load JPG
16	15/03/18 10:44	General View	■ Load JPG 🛂
17	15/03/18 10:44	General View	1 Load JPG ✓
18	15/03/18 10:44	General View	■ Load JPG
19	15/03/18 10:44	General View	1 Load JPG ✓
20	15/03/18 10:44	General View	■ Load JPG
21	15/03/18 10:44	General View	1 Load JPG ✓
22	15/03/18 10:44	General View	1 Load JPG ✓
23	15/03/18 10:44	General View	① Load JPG ☑
23 24	15/03/18 10:44	General View	① Load JPG ✓
25	15/03/18 10:44	General View	● Load JPG
25 26	15/03/18 10:44	General View	1 Load JPG ✓
27	15/03/18 10:44	General View	① Load JPG ✓
		General View	1 Load JPG
28	15/03/18 10:44	General View	1 Load JPG ✓
29 30	15/03/18 10:44 15/03/18 10:44	General View	1 Load JPG

Vide	90		1 per page
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail Prin
31	15/03/18 10:44	General View	1 Load JPG ✓
32	10/05/18 11:37	Reinspection Photo	■ Load JPG
33	10/05/18 11:37	Reinspection Photo	1 Load JPG ✓
34	10/05/18 11:37	Reinspection Photo	1 Load JPG ✓
35	10/05/18 11:37	Reinspection Photo	■ Load JPG
36	10/05/18 11:37	Reinspection Photo	1 Load JPG ✓
37	10/05/18 11:37	Reinspection Photo	⑤ Load JPG ✓
38	10/05/18 11:37	Reinspection Photo	1 Load JPG ✓
39	10/05/18 11:37	Reinspection Photo	⑤ Load JPG ✓
40	10/05/18 11:37	Reinspection Photo	1 Load JPG ✓
41	10/05/18 11:37	Reinspection Photo	1 Load JPG ✓
42	10/05/18 11:37	Reinspection Photo	■ Load JPG ✓
43	10/05/18 11:37	Reinspection Photo	1 Load JPG ✓
44	10/05/18 11:37	Reinspection Photo	1 Load JPG ✓
45	10/05/18 11:37	Reinspection Photo	1 Load JPG ✓
46	10/05/18 11:37	Reinspection Photo	1 Load JPG ✓
47	10/05/18 11:37	Reinspection Photo	1 Load JPG ✓
48	10/05/18 11:37	Reinspection Photo	1 Load JPG
49	10/05/18 11:37	Reinspection Photo	■ Load JPG ☑
50	10/05/18 11:37	Reinspection Photo	1 Load JPG ✓
51	10/05/18 11:37	Reinspection Photo	■ Load JPG ✓
Doc	cumentation		1 per page
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnall Prin
1	06/03/18 10:21	Estimate - CI - DL	1 Load PDF
2	06/03/18 10:21	SLH3178S E FILE REPORT.	1 Load PDF
3	07/03/18 10:51	OI SLV445S E FILE REPORT	1 Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG18004496/T1VD3E2

Date:

15/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A28795104MCX

Claimant Vehicle SLH3178S No:

Insured Vehicle No:

SLV445S

Date of Loss:

03/03/2018

Nature of Claim:

TP

Claim No: 551525

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLH3178S

Make & Model:

BMW X3 SDRIVE, 2.0 20I LED SR NAV (A)

Engine No:

A1321435N20B20A

Reg. Date: Colour:

31/10/2016 (Man. Year: 2016) Grey

Chassis No: Odometer:

WBAWY920400R99739 26050 km

Engine Capacity:

1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

275/40 R19

Rear Tyre Size:

275/40 R19

Front Tyre Size: Front Left Side:

Michelin 6 mm

Rear Left Side:

No

Michelin 6 mm

Front Right Side:

Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,616.50	6,071.55	8,544.95	58.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,999.00	5,242.00	8,757.00	62.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	28,615.50	11,313.55	17,301.95	60.46
+ GST 7.00/7.00% (S\$)	2,003.09	791.95	1,211.14	60.46
Nett Amount (S\$)	30,618.59	12,105.50	18,513.09	60.46

INSPECTION

Date of Assignment:

07/03/2018

Date Inspected:

14/03/2018 Inspected At:

Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre Singapore 159941

Estimated Period of Repair:

6.0 days

Adjuster:

MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 15 May 2018)

Parts:

M1-SUV

BMW X3 SDRIVE 2.0 20I LED SR NAV (A) (Catalogue:Merimen Singapore 1.0)

Repairer's Labour:

(Price-denominated Standard List) Print Code: (Unsubmitted, no print-code for SLH3178S)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	10		*BLIND RIVET	Not Necessary	11.00 FS	*-FS
3	1		*BLIND RIVET (30 PCS)	Not Necessary	88.50 FS	*-FS
4	2		*SCREW SELF TAPPPING	Not Necessary	2.20 FS	*-FS
5	3		*RUBBER MOUNTING	Not Necessary	100.95 FS	*-FS
6	1		*RR SILENCER CLAMPING BUSH	Not Necessary	60.60 FS	*-FS
7	1		*REAR MUFFLER	Not Necessary	1,220.90 FS	*-FS
8	1		*TAILPIPE TIP CHROME	Not Necessary	124.85 FS	*-FS
9	1		*BOOTLID	Bent	1,807.20 FS ¹	1,807.20 FS
10	1		*TAIL END PANEL	Repair	390.90 FS	*-FS
11	1		*OUTER PANEL TAIL TRIM	Deformed	497.45 FS	*497.45 FS
12	1		*LEFT TRUNK L	Not Necessary	74.60 FS	*-FS
13	1		*RIGHT TRUNK	Not Necessary	74.60 FS	*- FS
14	1		*RR BUMPER CARRIER ECE	Bent	738.05 FS	*738.05 FS
15	1		*RR LH BUMPER MIDDLE MOUNTING	Not Necessary	142.55 FS	*-FS
16	1		*RR LH BUMPER MIDDLE MOUNTING	Not Necessary	142.55 FS	*-FS
17	1		*RR RH BUMPER MIDDLE MOUNTING	Not Necessary	142.55 FS	*- FS
18	1		*RR RH BUMPER MIDDLE MOUNTING	Not Necessary	142.55 FS	*-FS
19	1		*RR BUMPER LH MOUNT	Not Necessary	198.30 FS	*-FS
20	1		*RR BUMPER LH MOUNT	Not Necessary	198.30 FS	*- FS
21	1		*RR BUMPER RH MOUNT	Not Necessary	198.30 FS	*- FS
22	1		*RR BUMPER RH MOUNT	Not Necessary	198.30 FS	*- FS
23	1		*TRIM PANEL BUMPER RR BOTTOM (M)	Deformed	251.70 FS	*251.70 FS
24	1		*COVERING LOWERM-PAKET / AHV	Deformed	116.15 FS	*116.15 FS
25	1		*SET OF TRIM COVERS TOW FITTING (M)0	Missing	91.15 FS	*91.15FS
26	1		*SET OF TRIM COVERS TOW FITTING (M)	Not Necessary	91.15 FS	*-FS
27	1		*RR BUMPER TRIM BUMPER PRIMED PDC (Deformed	1,585.60 FS [*]	1,585.60 FS
28	1		*TRUNK LID BADGE	Necessary	69.50 FS	*69.50 FS
29	1		*MODEL LETTERING X3	Necessary	62.55 FS	*62.55 FS
30	1 .		*STRIKER BOOT LID	Not Necessary	55.75 FS	*-FS
31	1		*HOLDER UPPER SECTION LOCK	Not Necessary	17.60 FS	*-FS
32	1		*LOCK TRUNK LID	Not Necessary	211.85 FS	*-FS
33	1		*SPINDLE DRIVE LH	Not Necessary	414.30 FS	*-FS
34	1		*SPINDLE DRIVE RH	Not Necessary	414.30 FS	*-FS
35	12		*BUMP STOP	Not Necessary	48.00 FS	*-FS
36	1		*DRIP MOULDING LH	Not Necessary	76.85 FS	*-FS
37	1		*DRIP MOULDING RH	Not Necessary	76.85 FS	*-FS
38	1		*RR W/SCREEN	Not Necessary	1,279.80 FS	*-FS
			Report was unsubmitted during	ng this print-out.		

No.	Qty	Part No.	Particular s	Condition	Repairer's	Amount
39	4		*VELCRO REAR WINDOW	Not Necessary	4.40 FS	*-FS
40	1		*HOOK AND LOOP FASTENER (6 PCS)	Necessary-4 PCS ONLY	16.80 FS	*11.20 FS
4 1	1		*LOADING SILL COVER	Not Necessary	179.25 FS	*- FS
42	1		*HEAT INSULATOR REAR SILENCER	Not Necessary	94.70 FS	*- FS
43	1		*HEAT INSULATOR REAR SILENCER	Not Necessary	94.70 FS	*-FS
44	1		*BOOTLID GASKET	Not Necessary	128.90 FS	*- FS
45	4		*DECOUPLLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*-FS
46	4		*BUMPER PDC SENSOR (A52 SPACEGRAU	Not Necessary	1,475.20 FS	*-FS
47	1		*BLIND RIVET AVIBVLB (40 PCS)	Necessary-30 PCS ONLY	20.90 FS	*16.50 FS
48	10		*SCREW (SF PLUS M5X15)	Necessary	5.50 FS	*5.50 FS
49	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	281.55 FS	*281.55 FS
50	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	118.35 FS	*118.35 FS
51	1		*(DG) CLEANER R1 (100ML)	Not Necessary	23.85 FS	*-FS
52	1		*(DG) CLEANER R1 (100ML)	Not Necessary	23.85 FS	*- FS
53	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	263.10 FS	*- FS
54	1		*PUNCH RIVET N4 (40 PCS)	Necessary	22.00 FS	*22.00 FS
55	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*- FS
56	10		*EXPANDING RIVET	Necessary	13.50 FS	*13.50 FS
57	1		*THIRD STOPLAMP	Necessary	233.60 FS	*233.60 FS
F=Fra	anchise	part. S=5	SpcNett.			
				Total Parts (S\$)	14,616.50	6,071.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REPLACE TAIL END PANEL, REAR BOOT LID, REAR BUMPER AND ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	5,100.00	2,550.00
2	SPRAY PAINT REAR FLOOR PANEL, TAIL PANEL, REAR BUMPER, REAR BOOT LID AND BOTH SIDE REAR FENDER	New	5,782.00	1,374.00
3	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
5	TO REPLACE EXHAUST MANIFOLD AND GASKET INCLUDING CHECKS FOR LEAK	New	950.00	0.00
6	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	487.00
7	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
8	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)	New	531.00	451.00
9	TO SUPPLY REAR EMBOSS NUMBER PLATE	New	83.00	0.00
	Gross Labou	r Cost (S\$)	13,999.00	5,242.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >