

ASS. REC. BY:

REF: CS/FCT/18004505 / R1 qd3ⁿ²

Special Instruction:

Surveyor:

Rosul

ASSIGNMENT (Office)

From (Person):

Serene Ler

of

FCT

Date/Time:

8/3/18 @ 3:14pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKJ 8553K

Insured:

SHC 2689P

at Workshop m/s

Performance

Tel:

63190174

of

303 Alexandra Road

Policy No:

Claim No:

D18061926MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

4/3/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

3:24pm 8/3/18

Person Contacted:

Caroline

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKJ 8553K-X
	SHC 2689P-X
12/3/18 @ 2:53pm	Revised to Serene by email.
07/3/18 @ 1:30pm	confirmed with Caroline final fee \$3160.30, 3 days. incl. \$1630.60, 34%



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FC18004505/R1qd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 08-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 2689P	Veh. Inspected	SKJ 8553K
Policy No.		Coverage (\$)	0.00
Claim No.	D18001926MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	08/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	04/03/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001926MFSH

Date: 13 March 2018

Our Ref: CS/FC118004505/R1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKJ 8553K.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/03/2018 at the premises of M/s PERFORMANCE MOTOR LIMITED, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 4,710.35</u>
Revised Estimate Amount	: <u>S\$ 2,999.75</u>
"Check" Items Amount	: <u>S\$ 1,154.60</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages at the front portion.



Yours faithfully

Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	07-03-2018	Our Ref No. D18001926MFSH
Accident Date	04-03-2018	Claim Type. Third Party
Insured Vehicle	SHC2689P	Third Party Vehicle. SKJ8553K
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63090174/ 0	Fax No. 64794601
Survey Type	DIRECT SETTLEMENT: EST. COR - \$5,040.07	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235708)



PRI Documents



Close



PRI Header Details

Claim No	D18001926MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PERFORM
Workshop Name	PERFORMANCE MOTORS LIMITED (Contact Person : CAROLINE)	Survey Location & Contact Details	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CEI Mobile: 0 , Phone: 63090174 , Fax: 64794601 EmailId: PML-PBSP@SIMEDARBY.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT: EST. COR - \$5,040.07		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC2689P	TP Vehicle No	SKJ8553K
PRI Recieved Date	07-03-2018 07:58:24 PM	Surveyor Appointed Date	08-03-2018 03:13:48 PM	Surveyor Accept Date	08-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	08-03-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 2 May 2018 2:30 PM
To: 'PBSP'; Rasul (LKKAuto); SUR
Subject: RE: FINAL REPORT / SKJ8553K

Dear Caroline,

Confirm final fig \$3,160.30 before GST and 3 repair days.

Kindly send the relevant documents to First Capital Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]

Sent: Friday, 13 April 2018 5:08 PM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: FINAL REPORT / SKJ8553K

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,097.00

Total Parts : 1,063.30

Total Labour & Parts : 3,160.30

Repair days: 3

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 13 March 2018 2:53 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001926MFSH/1
Attachments: CSFCI18004505R1qd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SKJ 8553K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 8 March 2018 3:28 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001926MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 8 March 2018 3:14 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001926MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8208613G



Name
CHEN JIANHAO

陈建豪

Race
CHINESE
Date of birth
14-03-1982
Country of birth
SINGAPORE

Sex
M

S8208613G

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S8208613G

Name
CHEN JIANHAO

Birth Date: 14 Mar 1982
Issue Date: 16 Jun 2004



001239261K



4891901

NRIC No. S8208613G



Date of issue
05-10-2012

ADDRESS
23 VERDE CRESCENT
SINGAPORE 688378

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars of unladen weight not exceeding 3000 kg with not more than 7 passengers, exclusive of the driver; and Motor Tractors and other Motor Vehicles of unladen weight not exceeding 2500 kg

PASS DATE
24 Nov 2001

NP 428A



Licence No: S8208613G

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64742770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)



repair sent in for service → ~~12/3/2018~~ 12/3/18
Sunday 8 repair

GST REG. NO : M2 - 0020081 - X

ESTIMATE

07 MAR 2018

Estimate No. : b1 46148	Page No. : 1 of 2
Date Estimated : 07/03/2018	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Chen Jianhao 23 Verde Crescent Singapore 688378	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ8553K	J720399	20/05/2013	316iA/4	0

DESCRIPTION	VALUE
Replace front bumper and remov e attachment etc include knock on accident dent	850 1,275.00
Spray painting front bumper	934 1,038.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
To supply front emboss number plate.	74 83.00
Sundries.	80 150.00
Total Labour 1:	2,723.00

DESCRIPTION	QTY	PRIC	VALUE
RIVET	10	0.50	5.00
FRT LH TOP SUPPORT SIDE PANEL	1	18.00	18.00
FRT RH TOP SUPPORT SIDE PANEL	1	18.00	18.00
FRONT SHOCK ABSORBER	1	41.15	41.15
FRT BUMPER TOP MOUNT	1	361.65	361.65
INSERT AIR INTAKE CENTER	1	97.90	97.90
FRT LH BOTTOM MOUNTING SIDE PANEL	1	18.00	18.00
FRT RH BOTTOM MOUNTING SIDE PANEL	1	18.00	18.00
FRT BUMPER PANEL TRIM (LINES SRA)	1	982.75	982.75
GRILLE FRONT LH (SPORT)	1	115.65	115.65
GRILLE FRONT RH (SPORT)	1	115.65	115.65
LICENCE PLATE BASE (ECE)	1	67.60	67.60
FRT BUMPER LOWER MOUNT	1	128.00	128.00
Total Parts :			1,987.35

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 46148**
Date Estimated : **07/03/2018**
Prepared By : **Chua Kee Sin**

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ8553K	J720399	20/05/2013	316iA/4	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date&Time 12/03/18 @ 11:50 Excess S\$ _____
Surveyor's Name Rafael Sign _____
Surveyor's Tel _____ Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No Yes / No
Surveyor's E-mail _____
No. of Working Days Recommend 3 days

[Handwritten Signature]
13/3/18

Labour 1	:	2,723.00
Parts	:	1,987.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	329.72
Grand Total	:	5,040.07

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

4,710.70

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46148
Date Estimated : 07/03/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Chen Jianhao
23 Verde Crescent

- ACCOUNT - 303
First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 688378

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKJ8553K	J720399	20/05/2013	316iA/4	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments include knocking out dents caused by the accident	850.00		850.00	
To spray paint front bumper	934.00		934.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights	150.00		150.00	
To supply front emboss number plate	83.00		83.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT BUMPER PANEL TRIM (LINES SRA)	982.75	1.00		982.75
# SUPPORT CENTRAL *	11.05	1.00		11.05
# PLAQUE 82MM *	69.50	1.00		69.50

SUPPLEMENTARY ITEMS

Total Labour :	2,097.00
Total Parts :	1,063.30
Total Labour & Parts :	3,160.30
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,160.30
GST @7%:	221.22
Grand Total :	3,381.52

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46148
Date Estimated : 07/03/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Chen Jianhao
23 Verde Crescent

- ACCOUNT - 303
First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 688378

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SKJ8553K	J720399	20/05/2013	316iA/4	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SUPPORT CENTRAL *	11.05	1.00		11.05 <i>na</i>
# PLAQUE 82MM *	69.50	1.00		69.50 <i>na</i>

Total Labour :	
Total Parts :	80.55
Total Labour & Parts :	80.55



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18004505/R1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-05-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 2689P	Veh. Inspected	SKJ 8553K
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18001926MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	08/03/2018
2. Vehicle Particulars & Condition			
Make & Model	BMW 316I 1.6 AT	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WBA3A12000J720399	Colour	WHITE
Odometer	93383	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/03/2018	Inspection Date	12/03/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKJ 8553K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
10	RIVET (SN)	SERVICEABLE	5.00	-
1	FRT LH TOP SUPPORT SIDE PANEL (SN)	SERVICEABLE	18.00	-
1	FRT RH TOP SUPPORT SIDE PANEL (SN)	SERVICEABLE	18.00	-
1	FRONT SHOCK ABSORBER (SN)	SERVICEABLE	41.15	-
1	FRT BUMPER TOP MOUNT (SN)	SERVICEABLE	361.65	-
1	INSERT AIR INTAKE CENTER (SN)	SERVICEABLE	97.90	-
1	FRT LH BOTTOM MOUNTING SIDE PANEL (SN)	SERVICEABLE	18.00	-
1	FRT RH BOTTOM MOUNTING SIDE PANEL (SN)	SERVICEABLE	18.00	-
1	FRT BUMPER PANEL TRIM (LINES SRA)(SN)	DEFORMED	982.75	982.75
1	GRILLE FRONT LH (SPORT)(SN)	SERVICEABLE	115.65	-
1	GRILLE FRONT RH (SPORT)(SN)	SERVICEABLE	115.65	-
1	LICENCE PLATE BASE (ECE)(SN)	SERVICEABLE	67.60	-
1	FRT BUMPER LOWER MOUNT (SN)	SERVICEABLE	128.00	-
1	SUPPORT CENTRAL (ADDITIONAL)(SN)	NECESSARY	11.05	11.05
1	PLAQUE 82MM (ADDITIONAL)(SN)	NECESSARY	69.50	69.50
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
1	FRONT EMBOSS NUMBER PLATE (SN)	BENT	83.00	83.00
			2,300.90	1,226.30
LABOUR				
REPLACE FRONT BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT.			1,275.00	850.00
SPRAY PAINTING FRONT BUMPER.			1,038.00	934.00
TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.			177.00	150.00
-			-	-
-			-	-
-			-	-
			2,490.00	1,934.00
GRAND TOTAL			4,790.90	3,160.30



RECOMMENDED COST OF REPAIRS			3,160.30
-----------------------------	--	--	-----------------

Report Ref No. CS/FCI18004505/R1qd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.