

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

7-Mar-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6495 E

1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00
1 pc	Rear bumper inner sponge	\$	114.00
1 pc	Rear bumper reinforcement	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00
1 pc	Rear bumper o/s reflector @ \$46.00	\$	46.00
			<hr/>
			\$ 1,905.00
Less 10%			\$ 190.50
			<hr/>
			\$ 1,714.50

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	Reverse sensor	\$	280.00 200
Sundry		\$	50.00 X
To dismantle / replace/test reverse sensor to new bumper and reset to the same		\$	120.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel		\$	700.00 200
To putty and spray painting on rear bumper, end panel		\$	400.00 180
To apply rustproofing on the repaired and replaced panels.		\$	200.00 X
			<hr/>
			\$ 3,692.50

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

- My Auto Consultants hence notify the Repairer of the following:
- To resurvey before after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Ka/lu/Uller
U 7/3/18 10:00am
2 Pgs.
PIP
Before Paint p/b