

3. myu Kohn

REF:

ASSIGNMENT

From: Date: 26/7/2

Estimated Cost:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect vehicle No:

At Workshop No:

IP:

Insured:

Policy No:

Claims No:

Sum insured: Excess:

(Claims Record)

Make of VEH:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NS	OS

Est. or Market Value:

DAC Accident Report Consistent? Yes or No

QA - PR Seen Consistent? Yes or No

Est. Repairs \$ days Res: Yes or No

Lump Sum: P/P % Eval: Yes or No

CA / REV / REP / 24 HRS

Date: Person Contacted:

Vehicle IN / OUT

Code / Title Action / Instruction

Van No: 5450557 ☒ PageType: M.Car / M.Cycle / ☒ Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour: Green AC Insured / Std / NI / NA

Sp. Reading: 70899 T.Radio Insured / Std / NI / NA

Eng No:

C.No:

Gen. Cond: Good / ☒ Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD / Rrim or

Tyre Size: F: 225/70 R15

R:

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / CHTSU / PIR / SUM /

TOYO / YOKO or

Front

R.Bal: 4 mm

Rear

R.Bal: 8-16 mm

L.Bal: 4 mm

L.Bal: 8-16 mm

D.O.A.

D.O.I: 26/2/2 12 hrs

Survey held at

Go Ahead

Des. of Damages: Frt / Rear / OS / NS / UIC / Rooftop or

Frt OS

The UIC / Chassis frame / Body Structure affected due to collision

AxA

1635.82 (Red. \$ 380 7.24 / 31.2)

On Time Return? ☐ Prel. Report☐ Final Report

See Time via Return?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transport:

Report Format:

Report Format:

Lump Sum: IB /

Add Fee: ☐ Site Insp \$☐ Interview \$☐ Tech. Insp \$☐ Weekend \$

2000-2000

2000-2000

2000-2000

2000-2000

2000-2000



Vehicle Accident Costing

Depot: Loyand Depot
Reg. No: SG 5055 Y
Fleet No:
Place of Accident:
Date:
Time:
Description of Damage:
Tyre Damage

Claim Number

- MTA Auto Insurance Co. (Singapore) Ltd.
No. of Pages: 1 of 1
• To be completed by the insured
• To be completed by the insurer
• Part of the insurance policy
• Part of the insurance policy
• Part of the insurance policy
• Part of the insurance policy
• Part of the insurance policy
• Part of the insurance policy

Approved by: Engineer

Signature:

Date:

LABOUR GAS

Name	Dept' Body/Elect/Mech'	Hours
NA		
Total of Hours		

MATERIALS USED

Bin No.	Description	\$
ATP-02796	BUMPER - CORNER FRONT O/S	276.62
ATP-02805	DEFLECTOR - CORNER FRONT O/S	102.18
ATP-02810	BEZEL LIGHT FRONT O/S	142.32
ATP-02961	DOME - EXTERIOR FRONT LOWER DECK	2024.28
A12-01966	PANEL - BATTERY ACCESS	576.36
C03-00370	BRACKET - FRONT FIBREGLASS CORNER O/S	25.00
C03-00409	BRACKET - BOTTOM BUMPER ATTACHMENT O/S	10.00
ELU-00312	LIGHT - FRONT HEAD LAMP - DIPPED BEAM	84.00
ELU-00313	LIGHT - FRONT HEAD LAMP - MAIN BEAM	76.00
ELU-00384	LIGHT - FRONT TURNING INDICATOR LED	117.72
	Spray Paint	1000.00
Total of Materials		4536.48

Hours and Materials correct

Engineering Supervisor

Summary		
Total Cost of Labour		4536.48
Total Cost of Material		4536.48
Recovery charge	Miles at	
Tyre Charge		
Other charges		
Loss of use days	days at \$ PER DAY	
Total		9273.96

total cost 6735.82 / 15 days
2/3/12

Print Received Message

This mail is associated with :

*SG5055Y (C0445418)
[SHB9666P]
TP
GO AHEAD LOYANG PTE LTD
Jul 19 2017 12:00AM
[TRANS-CAB SERVICES PTE LTD]

From: AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 03/01/2018 11:44 AM
To: vale.oh@axa.com.sg; LKK_HQ
CC: AXA_SG; thinthin@lkkauto.com; admin-a@lkkauto.com
Subject: Re: ACCIDENT ON 19/07/2017 INVOLVING VEHICLES SHB 9666P AND SG 5055Y

Hi Thin Thin

Perhaps, you may try to offer 50% towards TP claim.

Regards

Vale

<-- Original Message -->

From: LKK_HQ

To: vale.oh@axa.com.sg; AXA_SG

CC: thinthin@lkkauto.com; admin-a@lkkauto.com

Sent On: 02/01/2018 04:30 PM

Subject: Re: ACCIDENT ON 19/07/2017 INVOLVING VEHICLES SHB 9666P AND SG 5055Y

Dear Vale,

We refer to the below matter.

We have rejected TP claim as per instruction. However, TP did not accept our rejection and submit the footage for our reviewing. We have send via Accellion.

We have reviewed the footage submitted by TP. Based on footage, our insured vehicle was completely changing lane and stop due to another vehicle was try to change into our insured lane and TP unable to stop in time and collided onto our insured vehicle rear portion.

In view of the above, kindly let us have your further instruction.

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Bik 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: AXA_SG

To: vale.oh@axa.com.sg; LKK_HQ

CC: AXA_SG; thinthin@lkkauto.com; admin-a@lkkauto.com

Sent On: 22/10/2017 11:01 AM

Subject: Re: ACCIDENT ON 19/07/2017 INVOLVING VEHICLES SHB 9666P AND SG 5055Y



reaffirming / insurance



AXA INSURANCE PTE LTD
8 Shenton Way, #24-01 AXA Tower
Singapore 068812
Customer Centre 800-01
Tel: +65 6880 0888
Fax: +65 6338 3030
www.axa.com.sg
GST Reg No.: 1996030120
In. Reg No.: 1996030120

Hi Thin Thin

Pls proceed to reject TP claim unless they are able to proof otherwise, thanks.

Regards

Vale

<-- Original Message -->

From: LKK_HQ

To: vale.oh@axa.com.sg

CC: AXA_SG; thinthin@lkkauto.com; admin-a@lkkauto.com

Sent On: 16/10/2017 05:25 PM

Subject: ACCIDENT ON 19/07/2017 INVOLVING VEHICLES SHB 9666P AND SG 5055Y

Your Ref: **C0445418**

Our Ref: CC4/AXA17014460/K1ub3

Dear Sir / Madam,

ACCIDENT ON 19/07/2017 INVOLVING VEHICLES SHB 9666P AND SG 5055Y

We refer to the above matter.

TP reported that his front bumper right corner collided onto the rear bumper left corner of our insured vehicle.

OI reported that he was travelling straight at the 3rd lane along Sengkang East road towards Punggol when another vehicle which was on his right without signal swerved towards in his lane so he applied brake to avoid the collision. Subsequently, he felt an impact from behind.

We have reviewed both reports. Basing on available information, scenario from all involving parties, we are of the opinion that our insured is not liable for the accident as he was rear-ended by TP vehicle.

As such, we intend to reject the claim and kindly let us have your instruction / approval please.

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Bik 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

*SG5055Y (C0445418)
[SHB9666P]
TP
GO AHEAD LOYANG PTE LTD
Jul 19 2017 12:00AM
[TRANS-CAB SERVICES PTE LTD]

ReplyReply AllMark as UnreadPrint MessageDelete MessageForward

FromAXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 28/08/2018 15:51 PM.
ToLKK_HQ
SubjectAlert - Adj Mandate Approved (S\$4264.67) - SG5055Y - Claim Handler: Vale Oh

Approved:4264.67:Hi Thin Thin We are ok with 50%. However, labour is very high, pls re-negotiate on it, thanks. Vale

DOCUMENTS SUMMARY
There are no documents.

AXA Insurance

8 Shenton Way
#27-01/02 AXA Tower
Singapore 068811
Attn: Motor Claims Dept

Dear Sir/ Madam

**ACCIDENT INVOLVING VEHICLE NO SG5055Y & SHB9666P ALONG SENGKANG EAST RD B/4
PUNGGOL WEST FLYOVER ON 19/07/2017**

We are authorized by the owner of Go Ahead Singapore their above claims.

We therefore propose to claim as follows:

1.	Cost of Repairs	S\$	6779.33
2.	Loss of Use/ Rental (S\$ 350 x 5 days)	S\$	1750
3.	LTA Search Fee/GIA Reports	S\$	-
4.	Administration Charges	S\$	70.00
Total S\$			<u>8529.33</u>

Please let us have your reply soonest possible.

Thank you.

Yours faithfully,

Go Ahead Singapore
Accident Claim Specialist

Thin Thin (LKKAUTO)

From: Thin Thin (LKKAUTO)
Sent: Friday, 7 September 2018 4:42 PM
To: 'claims@transcab.com.sg'
Cc: CS A Team; 'carrisalee@ava-ins.com'; 'icewong@ava-ins.com'; 'ireneng@ava-ins.com'; 'foonghon@ava-ins.com'
Subject: ACCIDENT INVOLVING SHB 9666P AND SG 5055Y ALONG SENGKANG EAST ROAD ON 19/07/2017

07 SEPTEMBER 2018

Transcab Taxi
Singapore

Dear Sir/Mdm,

OUR REF : CC4/AXA17014460/K1ub3
YOUR REF : SHB 9666P

ACCIDENT INVOLVING SHB 9666P AND SG 5055Y ALONG SENGKANG EAST ROAD ON 19/07/2017

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **GO AHEAD LOYANG PTE LTD** acting on behalf of the owner of SG 5055Y against your motor insurance policy.

Basing on the circumstances of the accident reported by both parties, we are of the opinion that we cannot be absolved from liability.

We also wish to advise that there is an excess of S\$5,000.00 attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim. The applicability of the excess is as follows:

- (1) Any settlement equal to or above the excess, you shall be liable to make the payment of S\$5,000.00; or
- (2) Any settlement below the excess, you shall be liable for the amount settled.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by AXA for the above subject matter, AXA expressly reserves all their rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to thinthin@lkkauto.com within 7 days from the date of this letter if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA's Customer Care Centre.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2360 or email us at thinthin@lkkauto.com. Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

THIN THIN HLAING
LKK Auto Consultants Pte Ltd
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

This is a computer generated letter and no signature is required.

Cc Motor Claims Department
AXA Insurance Pte Ltd



redefining / insurance

CLAIM REF : C0445418
INSURED : TRANS-CAB SERVICES PTE LTD

DISCHARGE VOUCHER

We/I (**GO AHEAD LOYANG PTE LTD. 201541900C**) hereby agree to accept the sum of dollars [**Four Thousand Two Hundred and Sixty Only**] (**\$S\$4,260.00**) paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. **SHB 9666P** as a result of an accident along **SENGKANG EAST ROAD** on **19/07/2017** of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. **SG 5055Y**.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. **SHB 9666P** in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. **SHB 9666P**.

Dated this 10 day of September 2018

Claimant's Signature :  
NRIC no./ Company Stamp : 201541900C
Occupation/ Business : Go Ahead Loyang Pte Ltd
Address : 2 Loyang Way, S(508796)
Telephone No. : 6384 7169
Witness's Name : Chan Wei Tie
Witness's Signature : 
Witness's NRIC No. : 8123714Z

Final Repair Bill

M/S: AXA Insurance
8 Shenton Way
#27-01/02 AXA Tower
Singapore 068811

TEL: 6880 4888

Veh Reg No: SG5055Y

ATTN: Motor Claims Department

Make/Model: Volvo B9TL

Your Ref: -

Claim Type: Third Party

Accident Date: 19/07/2017

TP Veh Reg No: SHB9666P

Description	Quantity	List Price(S\$)	Amount(S\$)
TO SUPPLY PARTS, INSTALL AND LABOUR		6335.82	6335.82
		6335.82	6335.82
Total			S\$ 6335.82
Add GST @ 7%			S\$ 443.51
Total Amount Payable			S\$ 6779.33

For Go Ahead Loyang Pte Ltd

Reg No. 201541900C

Authorized Company Stamp



...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jul 2017		26 Jul 2017 13:13 Edit Adj Rpt	S\$6,335.82 Edit Estimates	S\$6,335.82 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K, Email: CLAIMS@TRANSCAB.COM.SG								
Main Claimant:	GO AHEAD LOYANG PTE LTD, Co. Reg. No.: 201541900C								
Vehicle Reg. No.:	SG5055Y	Date of Loss:	19/07/2017 00:00 - :59 [16 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0445418	Policy/Cover Note No.:	P1680520 (Third Party Only)						
Vehicle Reg. No. (Insured):	SHB9666P	Policy No. (Claimant):	D-16083754MFBP						
		Excess:	S\$5,000.00						
Reparer:	Go Ahead Loyang Pte. Ltd. (HQ) 2 Loyang Way, 508776 Loyang - Tel: 68126469								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Peter Wang Xiao]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 03/04/2018]								
Driver/Custodian (Insured):	ROGER KOH (59 / Male), NRIC: S1302990C, Tel: +6594502330								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AXA_SG (28/08/2018): Alert - Adj Mandate Approved (S\$4264.67) - SG5055Y - Claim Handler: Vale Oh - AXA_SG (30/03/2018): Alert - Adj Mandate Maintained - SG5055Y - Claim Handler: Vale Oh - AXA_SG (03/01/2018): Re: ACCIDENT ON 19/07/2017 INVOLVING VEHICLES SHB 9666P AND SG 5055Y - AXA_SG (22/10/2017): Re: ACCIDENT ON 19/07/2017 INVOLVING VEHICLES SHB 9666P AND SG 5055Y - AXA_SG (26/07/2017): New TP Assignment - C0445418/P1680520									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SG5055Y (C0445418)
[SHB9666P]
TP
GO AHEAD LOYANG PTE LTD
Jul 19 2017 12:00AM
[TRANS-CAB SERVICES PTE LTD]
Go Ahead Loyang Pte. Ltd.

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1 Edit	

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/08/17 15:44	Adjuster Immediate Advice	1 Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/07/17 18:03	General View	1 Load JPG	
2	26/07/17 18:03	General View	1 Load JPG	
3	26/07/17 18:03	General View	1 Load JPG	
4	26/07/17 18:03	General View	1 Load JPG	
5	26/07/17 18:03	General View	1 Load JPG	
6	26/07/17 18:03	General View	1 Load JPG	
7	26/07/17 18:03	General View	1 Load JPG	
8	26/07/17 18:03	General View	1 Load JPG	
9	26/07/17 18:03	General View	1 Load JPG	
10	26/07/17 18:03	General View	1 Load JPG	
11	26/07/17 18:03	General View	1 Load JPG	
12	26/07/17 18:03	General View	1 Load JPG	
13	26/07/17 18:03	General View	1 Load JPG	
14	26/07/17 18:03	General View	1 Load JPG	
15	26/07/17 18:03	General View	1 Load JPG	
16	26/07/17 18:03	General View	1 Load JPG	
17	26/07/17 18:03	General View	1 Load JPG	
18	26/07/17 18:03	General View	1 Load JPG	
19	26/07/17 18:03	General View	1 Load JPG	
20	26/07/17 18:03	General View	1 Load JPG	
21	26/07/17 18:03	General View	1 Load JPG	

Documentation

1 per page

No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	26/07/17 09:49	EMAIL_ABS	1 Load PDF	
2	26/07/17 09:49	GIA SHB9666P INSD_ABS	1 Load PDF	
3	26/07/17 09:49	CO-CLAIMANT TP_ABS	1 Load DOCX	
4	04/08/17 16:18	QUOTATION_ABS	1 Load DOCX	
5	04/08/17 16:18	SG5055Y TP GIA REPORT_ABS	1 Load PDF	
6	10/08/17 13:52	LOD_ABS	1 Load PDF	

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/07/17 10:41	TP GIA REPORT	1 Load PDF	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
2	03/08/17 15:41	TP ESTIMATE - MARKED		Load PDF
3	17/09/18 16:03	WORKSHOP INVOICE		Load PDF
4	17/09/18 16:03	DISCHARGE VOUCHER		Load PDF
5	17/09/18 16:03	LOD		Load PDF
6	17/09/18 16:03	LETTER TO OI		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHB9666P (Insd veh)	Model:	VOLVO B9TL 9.4 D (A)
	SG5055Y (TP veh)		
Date of Accident:	19/07/2017		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	: \$		9,868.67
Final Repair Cost	: \$		6,779.33
Loss of Use	: \$		1,750.00
Rental (if any)	: \$		0.00
@50%			4,264.67
LTA / GIA Search Fee	: \$		0.00
Others:	: \$		0.00
	: \$		
Final Settlement Sum (Global Sum)	: \$		4,260.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop:	Agreed Liability <u>50</u> (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown			
1)	Go-Ahead Loyang Pte Ltd	: \$	4,260.00
2)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

17 Sep
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17014460/K1UB3Q2-1
Date: 17/09/2018

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1680520
Claimant Vehicle No :	SG5055Y	Insured Vehicle No :	SHB9666P
Date of Loss:	19/07/2017	Nature of Claim:	TP
		Claim No:	C0445418

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG5055Y	Engine No:	D9194967
Make & Model:	VOLVO B9TL, 9.4 D (A)	Chassis No:	YV3S4P927GA176446
Reg. Date:	14/03/2016 (Man. Year: 2015)	Odometer:	70899 km
Colour:	Green		
Engine Capacity:	9364 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Giti 4 mm	Rear Left Side:	Giti 4/4 mm
Front Right Side:	Giti 4 mm	Rear Right Side:	Giti 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,536.46	835.82	2,700.64	76.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,686.60	5,500.00	186.60	3.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,223.06	6,335.82	2,887.24	31.30
+ GST 7.00/7.00% (S\$)	645.61	443.51	202.10	31.30
Nett Amount (S\$)	9,868.67	6,779.33	3,089.34	31.30
+ Loss of Use (5.0 x S\$350.00/day) (S\$)		1,750.00		
		(S\$) 8,529.33		
Liable Amount (50.00%) (S\$)		4,264.67		
Global Sum Settlement (S\$)		4,260.00		

INSPECTION

Date of Assignment:	26/07/2017		
Date Inspected:	26/07/2017	Inspected At:	GO-AHEAD SINGAPORE 2 LOYANG WAY SINGAPORE 508776

Estimated Period of Repair: 5.0 days

Adjuster: KALVIN ANG WEI KUN**Manager:** THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Nov 2017)	
Parts:	N/A	VOLVO B9TL 9.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SG5055Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER -CORNER FRONT O/S (CONSISTENT)	Cracked	276.62 F	*276.62 F
2	1		*DEFLECTOR -CORNER FRONT O/S (CONSISTENT)	Cracked	102.16 F	*102.16 F
3	1		*BEZEL LIGHT FRONT O/S (CONSISTENT)	Cracked	142.32 F	*142.32 F
4	1		*DOME-EXTERIOR FRONT LOWER DECK (CONSISTENT)	Repair	2,024.28 F	*- F
5	1		*PANEL -BATTERY ACCESS (CONSISTENT)	Repair	676.36 F	*- F
6	1		*BRACKET-FRONT FIBREGLASS CORNER O/S (CONSISTENT)	Cracked	25.00 F	*25.00 F
7	1		*BRACKET -BOTTOM BUMPER ATTACHMENT O/S (CONSISTENT)	Cracked	10.00 F	*10.00 F
8	1		*LIGHT -FRONT HEAD LAMP -DIPPED BEAM (CONSISTENT)	Cracked	84.00 F	*84.00 F
9	1		*LIGHT -FRONT HEAD LAMP -MAIN BEAM (CONSISTENT)	Cracked	78.00 F	*78.00 F
10	1		*LIGHT -FRONT TURNING INDICATOR LED (CONSISTENT)	Cracked	117.72 F	*117.72 F
Total Parts (S\$)						3,536.46 835.82

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINT	New	1,000.00	1,000.00
2	LABOUR	New	4,686.60	4,500.00
Gross Labour Cost (S\$)			5,686.60	5,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >