

ASS. REC. BY:

REF: CS/FCI18004533/R/vd3/

Special Instruction:

Surveyor:

Regul

CWS

ASSIGNMENT (Office)

Form (Person):

May chun

of

FCI

Date/Time:

9/3/11 @ 9.01 am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGX 9428G

Insured:

SHA 7820D

at Workshop m/s

Lei Huat (Meng Kee)

Tel:

6453 8110

of

160 Sin Ming Drive #04-01/02 and #07-03

Policy No:

Claim No:

D18001928MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 01/03/2011

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

9.05am @ 9/3/11

Person Contacted:

jenny

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SGX 9428G-x	
	SHA 7820D-NS/INCH1015656/Hlyln	D.O.A.: 02/08/2011
13/3/11	Email preli revised to FCI	
13/4/11	@4.52pm Jenny will email us finalise	
7/5/11	Final fig \$3493.86 (Red 500, 13/5)	confirmed by email

Estimate

CA / REV

REP.

24 HRS

'wp'

Survey Fee

Lei Huat

CA / REV

REP.

24 HRS

'wp'

Date of Damages

Rep

DS

NS

UC

Refused

Date

Person Contacted

Vehicle IN/OUT

The U.C.

Cross's frame

Body Structure affected

due to collision

Date/Time

Action/Instruction

RECEIVED 07 MAY 2011

Use Time File Pass

☐

Prel. Report

Days Of Rep

8

☐

Final Report

Res Under No. of Tr

1

Use Time File Pass

7/5 - typist

Add Fee:

She has

original

Tech

Add

Time Fee

Transport

Add Fee

Add

Add

Add

Record Format

CWS

Add Fee

P/p \$3493.86

291

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18001928MFSH
Our Ref: CS/FCI18004533/R1vd3

Date : 13/3/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGX 9428G


We thank you for your instruction on 9/3/2018

Please be informed that we had conducted the inspection of the above mentioned
9/3/2018 at the premises of M/s LAI HUAT (MENG KEE) MOTOR PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$3,993.89
Revised Estimate Amount	: S\$3,369.65
"Check" Items Amount	: S\$124.22
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6110Z
Vehicle Details	
Vehicle No.:	SGX9428G
Vehicle to be Exported:	No
Intended De-registration Date:	13 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	1NZX604074
Chassis No.:	MR053HY9305021566
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,466.00
Original Registration Date:	12 Sep 2007
First Registration Date:	12 Sep 2007
Transfer Count:	0
Actual ARF Paid:	\$13,713.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Sep 2027
COE Category:	E - Open Category

COE Period(Years):	10
PQP Paid:	\$44,081.00
COE Rebate Amount:	\$41,857.00
Total Rebate Amount:	\$41,857.00

The information contained herein is correct as at 13 Mar 2018

OK

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Teng Kuan Poh Andrew
 Period of Insurance : 12 Sep 2017 To 11 Sep 2018
 Engine No. : 1NZX604074
 Chassis No. : MR053HY9305021566

Vehicle No. : SGX9428G
 Policy No. : 2100040202-10
 Endorsement No. :
 Issued Date : 08 Sep 2017

ABOUT THE COVER

Make/Model : TOYOTA VIOS
 Engine Capacity/Tonnage : 1,497.00 CC
 Driver Restriction : NA

Sum Insured : Market Value
 Off Peak Car : Yes

First Year of Registration : 2007
 Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the stipulated age condition.

You have to pay an additional sum of \$2,000 as "Young and Inexperienced Driver Excess" ("YIDP") if you are or your Authorized Driver named or licensed is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, race-making, rallying trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1000cc Optional

* Limitations contained inoperative for Section 2 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 193) and Section 95 of the Road Transport Act, 1987 (Singapore) and will be included under their headings.

EXCESS

Section 1
 Fire - \$0, Own Damage - \$000, Theft - \$0, Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen - \$100

Named Driver and Excess (where applicable)

Teng Kuan Poh Andrew - \$000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ Approved Repairers (For claims related repairs)

Any accident repairs to the Vehicle must be carried out by one of our Approved Repairers. Within the first 3 years of the 1st registration of the Vehicle in Singapore, you have the option of having the accident repairs carried out at the Sole Agent's workshop.

For other Approved Reporting Centres/ Approved Repairers, please contact our 24-hour roadside emergency hotline at +65 4330 8290. Alternatively, you may refer to AIG website www.aig.com.sg or AIG 99 Mobile App. Simply search and download "AIG 99" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 193) Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 193) Part IV of the Road Transport Act, 1987 (Singapore).

9330210000

AIG ASIA PACIFIC INSURANCE P.L.
 78 SHENTON WAY #07-16 AIG BUILDING
 SINGAPORE 079120

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. J. Tan

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SHA782DD	04 Mar 2018 / 16:00:00	Successful	F03	FIRST CAPITAL INS LTD

[Previous](#) [OK](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/03/2018 17:33
Date Of Accident	04/03/2018 16:00
Exact Location Of Accident	BUKIT TIMAH ROAD TOWARDS SUNGEI ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGX9428G
Insured/Policyholder	
Name Of Registered Owner	TENG KUAN POH ANDREW
NRIC No	S1656110Z
Email Address	ANDREWTENG@HOTMAIL.CO.UK
Mobile Phone No	(LOCAL) +65-96327069
Alternative Phone No	OTHERS-96327069

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 E (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE, LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100040202-10
Cover Note Number	

Driver


Name of Driver	KONG WAI CHENG FLORENCE
NRIC No	S1611546J
Date Of Birth	22/05/1963
Occupation	INDOOR
Date Of Driving Pass	22/03/2005
Driving Experience	12 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96218168
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Nat
No.

Nat
No.

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The traffic light was red and the car I was driving SGX 9428G was stationary in front of the light in the second lane when it was hit from behind by Comfort Delgro taxi SHA 7820D driven by Mr Koh Teng Yaw NRIC: S1158870J. Mr Koh admitted that it was his fault. He was driving too fast and unable to stop in time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time: 7/3/2018


Driver's Signature
(If driver is not the policyholder)
Date & Time: 7/3/2018


Reporting Centre Personnel's Signature
Name: Jenny Lim
NRIC/FIN No.: S6927273H

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No. EST0018720
Teng Kuan Poh Andrew

Page 1 of 2
Your ref TP-SHA 7820D-FC
Job No 69300
Our ref 18.03.15
Payment
Date 8/3/2018

Attn

Vehicle No SGX 9428G
Vehicle Model Toyota Vios
Accident on 4/3/2018

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts:					
1.00	Pc	Rear bumper	427.50	25.00	320.63 <i>DE</i>
1.00	Pc	Rear bumper reflector LH	82.81	25.00	<i>CRA</i> 62.11 <i>?</i>
1.00	Pc	Rear bumper reflector RH	82.81	25.00	<i>CRA</i> 62.11 <i>?</i>
1.00	Pc	Rear tail lamp LH	277.62	25.00	208.22 <i>CRA</i>
1.00	Pc	Rear tail lamp RH	277.62	25.00	208.22 <i>CRA</i>
1.00	Pc	Rear tail lamp gasket LH	24.36	25.00	18.27 <i>nee</i>
1.00	Pc	Rear tail lamp gasket RH	24.36	25.00	18.27 <i>nee</i>
1.00	Pc	Rear boot lid lock	95.97	25.00	71.98 <i>PT</i>
1.00	Pc	Rear end panel	571.89	25.00	428.92 <i>PT</i>
1.00	Pc	Rear bumper side retainer LH (long)	89.39	25.00	67.04 <i>nee</i>
1.00	Pc	Rear bumper side retainer RH (long)	89.39	25.00	67.04 <i>nee</i>
1.00	Pc	Rear bumper side retainer LH (short)	31.22	25.00	23.42 <i>nee</i>
1.00	Pc	Rear bumper side retainer RH (short)	31.22	25.00	23.42 <i>nee</i>
1.00	Pc	Rear luggage tray centre	152.32	25.00	114.24 <i>CRA</i>
Special nett item:					
1.00	Set	Rear reversing sensor with installation	200.00		200.00 <i>Am</i>

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679. Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST No EST0018729
Teng Kuan Poh Andrew

Page 2 of 2
Your ref TP-SHA 7820D FC
Job No 5344938289306
Our ref 18.03.15
Payment
Date 8/3/2018

Attn

Vehicle No SGX 9428G
Vehicle Model Toyota Vios
Accident on 4/3/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
----------	------	-------------	------------	------------	--------

Labour & Misc

1.00		To straighten rear body including cutting and welding, to knock dents on floor panel and renew of parts	1,200.00		1,200.00
------	--	---	----------	--	----------

1.00		To spray paint	900.00		900.00
------	--	----------------	--------	--	--------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub-Total 3,993.89
GST 7.00% 279.57
Total S\$ 4,273.46

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-50/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCH No: 199407592C

ESTIMATE

EST No EST0018729
Teng Kuan Poh Andrew

Page 1 of 2
Your ref TP-SHA 7820D FG
Job No 69300
Our ref 18.03.15
Payment
Date 8/3/2018

Attn

Vehicle No SGX 9428G
Vehicle Model Toyota Vios
Accident on 4/3/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear bumper	427.50	25.00	320.63 ✓
1.00	Pc	Rear bumper reflector LH	82.81	25.00	62.11 ✓
1.00	Pc	Rear bumper reflector RH	82.81	25.00	62.11 ✓
1.00	Pc	Rear tail lamp LH	277.62	25.00	208.22 ✓
1.00	Pc	Rear tail lamp RH	277.62	25.00	208.22 ✓
1.00	Pc	Rear tail lamp gasket LH	24.36	25.00	18.27 ✓
1.00	Pc	Rear tail lamp gasket RH	24.36	25.00	18.27 ✓
1.00	Pc	Rear boot lid lock	95.97	25.00	71.98 ✓
1.00	Pc	Rear end panel	571.89	25.00	428.92 ✓
1.00	Pc	Rear bumper side retainer LH	89.39	25.00	67.04 ✓
1.00	Pc	Rear bumper side retainer RH	89.39	25.00	67.04 ✓
1.00	Pc	Rear bumper side retainer LH	31.22	25.00	23.42 ✓
1.00	Pc	Rear bumper side retainer RH (short)	31.22	25.00	23.42 ✓
1.00	Pc	Rear luggage tray centre	152.32	25.00	114.24 ✓
Special nett item:					
1.00	Set	Rear reversing sensor with installation	200.00		200.00 ✓

1693.89

200

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018729
Teng Kuan Poh Andrew

Page 2 of 2
Your ref. TP-SHA 7820D FC
Job No. 69300
Our ref. 18.03.15
Payment
Date 8/3/2018

Attn

Vehicle No SGX 9428G
Vehicle Model Toyota Vios
Accident on 4/3/2018

Quantity	Unit	Description	Unit price	Disc. pct	Amount
----------	------	-------------	------------	-----------	--------

Labour & Misc.

1.00		To straighten rear body including cutting and welding, to knock dents on floor panel and renew of parts	1,200.00		1,200.00 800
------	--	---	----------	--	-------------------------

1.00		To spray paint	900.00		900.00 800
------	--	----------------	--------	--	-----------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub-Total
GST 7.00%
Total

3,993.89
279.57
S\$ 4,273.46

Resur
Hp 900/100 68 1600

7 days

P/P

09/03/18 P1640

Resur 64 paint

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大伙修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support jolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO infra oven heater for re-spraying all motor vehicles."

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 7 May 2018 4:02 PM
To: 'Jenny Lim'; SUR
Cc: Rasul (LKKAuto)
Subject: RE: Finalisation - SGX 9428G / Toyota Vios

Dear Jenny,

WITHOUT PREJUDICE

Confirmed **\$3,493.86** instead of \$3493.89 @ 8 working days.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]
Sent: Thursday, 3 May 2018 4:06 PM
To: SUR <sur@lkkauto.com>
Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: Finalisation - SGX 9428G / Toyota Vios

Dear Sir

For your confirmation, please:

- Parts: \$1,693.89
 - SN: \$ 200.00
 - L&P: \$1,600.00
- Sub-total: \$3,493.89 / 12 days**

Supporting document and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18004533/R1vd3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-05-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7820D	Veh. Inspected	SGX 9428G	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001928MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	09/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	MR053HY9305021566	Colour	GREY	
Odometer	117176	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	MICHELIN	5 mm	
L/H Front Tyre	185/60 R15	MICHELIN	5 mm	
R/H Rear Tyre	185/60 R15	MICHELIN	5 mm	
L/H Rear Tyre	185/60 R15	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/03/2018	Inspection Date	09/03/2018	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGX 9428G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	427.50	427.50
1	REAR BUMPER REFLECTOR LH	CRACKED	82.81	82.81
1	REAR BUMPER REFLECTOR RH	CRACKED	82.81	82.81
1	REAR TAIL LAMP LH	CRACKED	277.62	277.62
1	REAR TAIL LAMP RH	CRACKED	277.62	277.62
1	REAR TAIL LAMP BRACKET LH	NECESSARY	24.36	24.36
1	REAR TAIL LAMP BRACKET RH	NECESSARY	24.36	24.36
1	REAR BOOT LID LOCK	BENT	95.97	95.97
1	REAR END PANEL	BENT	571.89	571.89
1	REAR BUMPER SIDE RETAINER LH (LONG)	NECESSARY	89.39	89.39
1	REAR BUMPER SIDE RETAINER RH (LONG)	NECESSARY	89.39	89.39
1	REAR BUMPER SIDE RETAINER LH (SHORT)	NECESSARY	31.22	31.22
1	REAR BUMPER SIDE RETAINER RH (SHORT)	NECESSARY	31.22	31.22
1	REAR LUGGAGE TRAY CENTRE	CRACKED	152.32	152.32
	LESS 25% DISCOUNT		-564.62	-564.62
			1,693.86	1,693.86
SPECIAL NETT ITEMS				
1	SET REAR REVERSING SENSOR WITH INSTALLATION (SN)	NOT WORKING	200.00	200.00
			200.00	200.00
LABOUR				
	TO STRAIGHTEN REAR BODY INCLUDING CUTTING AND WELDING ,TO KNOCK DENTS ON FLOOR PANEL AND RENEW OF PARTS.		1,200.00	800.00
	TO SPRAY PAINT.		900.00	800.00
			-	-
			-	-
			-	-
			2,100.00	1,600.00
GRAND TOTAL			3,993.86	3,493.86

Report Ref No. CS/FCI18004533/R1vd3q2



RECOMMENDED COST OF REPAIRS			3,493.86
-----------------------------	--	--	----------

Report Ref No. CS/FCI18004533/R1vd3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.