

Special Instruction:

L/S: \$ 5500.00

Third Parties:

Claimant:

Surveyor: Pro-Option Services

Workshop: HS 1 Auto

From (Person): Ching Nyuk Pui of msu Date/Time: 14052018
Estimated Cost: _____ Bill to: _____

OD/FP Re-inspection / Evaluation

To Inspect Vehicle No: SLT 541H Insured: GZ 7305E

at Workshop m/s HSL Auto Tel: 6634 2663

of Blk 1 Kaki Bukit Ave 6 #01-10

Policy No: _____ Claim No: 551775

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 03032018


(Client's Record)

Do Not Emulize,
H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 01/15/19 Confirmed with Final Fig , days (Red \$ / %; Original days)

Date/Time: 21/5/18 Submit Final Fig 4600, 6 days (Red \$ 900, 16 %; Original 5 days)

Date/Time	Action/Instruction
	SIT 5441 - x GZ 7305E - x
	LS 4600/2 Labour 5 days
	 22/5/2011

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 2 3 M.

Para(3) : Nett Value

pas + ps

Market Value :

Salvage Value :

Nett Value: _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

260

1) Date/Time 23 5 18 File Pass to Typist

2) Date/Time File Return to

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____

Catherine Chong (LKK Auto)

From: Chhia Nyuk Pui <NyukPui_Chhia@sg.msig-asia.com>
Sent: Monday, 14 May, 2018 1:35 PM
To: Veron Chen (LKKAuto); assignments
Subject: RE: Our ref: 551775 (OIV: GZ7305E). TPV: SLT541H

Dear Catherine

Please do a paper re and let us have your report soon.

Thanks

Chhia Nyuk Pui
Senior Executive, Claims Services
Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui_chhia@sg.msig-asia.com

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, April 24, 2018 1:47 PM
To: Chhia Nyuk Pui <NyukPui_Chhia@sg.msig-asia.com>; assignments <assignments@lkkauto.com>
Subject: RE: Our ref: 551775 (OIV: GZ7305E). TPV: SLT541H

Dear Nyuk Pui,

Thank you for the email.

Dear Catherine,

FYNA-CS3/MSG18004541/Gd3

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chhia Nyuk Pui [mailto:NyukPui_Chhia@sg.msig-asia.com]
Sent: Tuesday, 24 April 2018 1:33 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Our ref: 551775 (OIV: GZ7305E). TPV: SLT541H

Dear Veron

We have received TP lawyer claim.

Please let us have surveyor report.


Thank you.

Chhia Nyuk Pui

Senior Executive, Claims Services

Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui_chhia@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on  [@MSIG_SG](https://twitter.com/MSIG_SG)

A member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	0282F
Vehicle No.:	SLT541H
Vehicle to be Exported:	No
Intended De-registration Date:	21 May 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180 KOMPRESSOR
Primary Colour:	Blue
Manufacturing Year:	2011
Engine No.:	27191031346154
Chassis No.:	WDD2040452A580146
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$31,019.00
Original Registration Date:	01 Sep 2011
First Registration Date:	01 Sep 2011
Transfer Count:	2
Actual ARF Paid:	\$31,019.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Aug 2021
PARF Rebate Amount:	\$20,162.00
COE Expiry Date:	31 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$55,989.00
COE Rebate Amount:	\$18,346.00
Total Rebate Amount:	\$38,508.00

The information contained herein is correct as at 21 May 2018

OK

22/03/2002

ASS. REC. BY:

REF: CS3/MSG18004541/Gd3

Special Instruction:

Survivor:
Menmen

GQ

ASSIGNMENT (Office)

From (Person):

Chhia Nyuk

of

MSG

Date/Time:

8/3/18 @ 4:16pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV/CS

To Inspect Vehicle No:

SLT 541H

Insured:

GZ7305E

at Workshop m/s

HSL Auto Care

Tel:

66342663

of

1 Kaki Bkt Ave 6 # 01-02 Autobay

Policy No:

28989797 MKC

Claim No:

551775

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

3/3/2018

CA / REV / REP. / REV 24 HRS lwp'

H.O.D. Endorsement:

Date/Time:

9:27am @ 9/3/18

Person Contacted:

Mr. See

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLT 541H - x
	GZ7305E - x

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Mar 2018		08 Mar 2018 16:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]		
Insured:	YONG TAI LOONG PTE LTD, Co. Reg. No.: NA					
Main Claimant:	TAN KEANG LENG					
Vehicle Reg. No.:	SLT541H	Date of Loss:	03/03/2018 00:00 - :59			
Claim Type:	TP / 551775	Policy/Cover Note No.:	28989797MKC (TP, Fire & Theft) Coverage: 10/08/2017 - 09/08/2018			
Vehicle Reg. No. (Insured):	GZ7305E	Policy No. (Claimant):				
		Excess:				
Repairer:	Hsl Auto Service (HQ) A Kaki Bukit Avenue 6 Autobay #01-05, 417883 Kaki Bukit - Tel: 96601395					
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/03/2018]					
Adj Asg. Remarks:	Third Party Pre-Repair Survey					

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors Commissioner For Oaths Notary Public
UEN NO : 201523418E
(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16
MANHATTAN HOUSE
SINGAPORE 168876
TEL : (65) 6532 2455
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg;mdmling@tcmg.com.sg

Our Ref: TCMG/SLT541H/0318/HSL

Your Ref: **GZ 7305**

8 March 2018

BY FAX NO: 6225 7402 ONLY

M/s MSIG Insurance (Singapore) Pte Ltd
16 Raffles Quay
#24-01
Hong Leong Building
Singapore 048581

Attn: Motor Claims Department

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for **Tan Keang Leng**, the owner and/or driver of motor vehicle no. **SLT 541 H**, which was involved in an accident along Bedok North Street 4 Block 187 Carpark on **8 March 2018** at about 12:00 hours.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **GZ 7305** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at **M/s H.S.L. Auto Service**, (1 Kaki Bukit Avenue 6 #01-02 Autobay, S(417883)- Ah Seng @ 9660 1395/66342663).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully,


MR LING LEONG HUI

cc. **M/s H.S.L. Auto Service**
(Yref :SLT541H)

By FAX: 64814836 ONLY

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors Commissioner For Oaths Notary Public
UEN NO : 201523418E
(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16
MANHATTAN HOUSE
SINGAPORE 169876
TEL : (65) 6532 2455
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: thling@tcmg.com.sg

Our Ref : LLH/ing/1154/0418/HSL

Your Ref : GZ 7305 E

13 APR 2018

M/S YONG TAI LOONG PTE LTD

461 Macpherson Road
Singapore 368179

M/S MSIG INSURANCE (S) PTE LTD

16 Raffles Quay #24-01
Hong Leong Building
Singapore 048581

Attn: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING SLT 541 T AND GZ 7305 E ON 3 MARCH 2018 ALONG BEDOK NORTH STREET 4 BLOCK 187 CARPARK


We are instructed by **Tan Keang Leng**, to claim damages against you or your insured, the driver of motor vehicle no. **GZ 7305 E**, in connection with a road traffic accident on 3 of March 2018, at about 12:00 hours along Bedok North Street 4 Block 187 Carpark, involving our client's motor vehicle no. **SLT 541 T** and motor vehicle no. **GZ 7305 E** by you or your insured at the material time.

We are instructed that the accident was caused by your insured's negligence and/or management of his motor vehicle. As a result of the incident, our client's motor vehicle was damaged and our client had been put to loss and expenses, particulars of which are as follows:

1	Costs of Repair	\$ 5,500.00
2	Rental (\$200 x 9 days)	\$ 1,800.00
3	Survey Fees	\$ 590.00 /
4	Disbursement (at this stage)	\$ 93.00
5	Legal Cost (at this stage)	\$ 700.00
		<u>\$ 8,683.00</u>

DIRECTOR : LING LEONG HUI

CONSULTANTS : TOMMY CHOO TUCK SOON
POOTS LAURENCE JAMES



By Certificate of Posting
(For your attention: without enclosures)

BY PDX NO. 8173

PDX Intercompany Exchange Pte Ltd



010808336666

FROM TOMMY CHOO, MARK GO LLC
PDX Ref No. 8141

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors Commissioner For Oaths Notary Public

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16

MANHATTAN HOUSE

SINGAPORE 169876

TEL : (65) 6532 2455

FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

Email: lhling@tcmg.com.sg

A copy each of the following supporting documents is enclosed:

1. Copy of accident report and LTA search;
2. Copy of survey report and invoice and repair bill;
3. Colour photographs pertaining to our client's motor vehicle for your perusal.

Our client had on 8 March 2018 notified your insurer, M/s MSIG Insurance (S) Pte Ltd about the accident and to the best of our knowledge, your insurer had waived off the pre-repair inspection.

Please note that if you are insured and you wish to claim from your insurance policy, you should immediately pass this letter to your insurer.

Please note that you should send us an acknowledgment of receipt of this letter within fourteen (14) days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you or your insured.

Please note that if you have a counterclaim against our client arising out of the accident, you are also required to send us a letter giving full particulars of the counterclaim together with the relevant documents within 8 weeks of your receipt of this letter.

Yours faithfully,



Encs.

cc. client

Enquire Vehicle & Owner Information (Vehicle No. GZ7305E As At 03 Mar 2018 / 12:00:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: LLH.SLT541T.HSL

Current Owner Details

Owner ID Type: Company

Owner ID: 197201054D

Owner Name: YONG TAI LOONG PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 461

Registered Street Name: MACPHERSON ROAD

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 368179

Current Vehicle Details

Vehicle No.: GZ7305E

Make Description/Model: NISSAN / CABSTAR G

Insurance Company Name:MSIG INSURANCE (SINGAPORE) PTE LTD

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 06/03/2018 15:50
Date Of Accident 03/03/2018 12:00
Exact Location Of Accident BEDOK NORTH ST 4 BLK 187 CARPARK
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLT541H
Insured Policyholder
Name Of Registered Owner TAN KEANG LENG
NRIC No S7620282F
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-80251711
Alternative Phone No OFFICE-80251711

Vehicle Particulars

Manufacturer MERCEDES-BENZ
Model C180

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5088911782

Cover Note Number

Driver

Name of Driver PHUAH KOK WAY
NRIC No G2893395U
Date Of Birth 31/05/1983
Occupation INDOOR
Date Of Driving Pass 21/12/2017
Driving Experience 0 YEAR AND 2 MONTH
Gender MALE
Mobile Number (LOCAL) +65-91458829
Fax Number
Contact Number
Email Address NOEMAIL

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY
Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of Intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

WHILE ENTERING THE CARPARK, VEHICLE B REVERSED AND HIT ONTO MY VEHICLE. (REVERSING OF VEHICLE)

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GZ7305E

Vehicle Make/Model/Colour

Details Of Properties VEHICLE B

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

WHILE ENTERING CARPARK, VEHICLE B REVERSED AND HIT

OUT MY VEHICLE =

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

08/MAR/2018/THU 12:57

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/AN No.:

H.S.L Auto Service

1 Kaki Bukit Ave 6, #01-02 (Autobay) Singapore 417883

Mobile no: 96601395

INVOICE

Tan Keang Leng	<i>Invoice No:</i>	001/18
c/o 1 Kaki Bukit Ave 6	<i>Date:</i>	5 April 2018
#01-02	<i>Term:</i>	Cash
Singapore 417883	<i>Vehicle No:</i>	SLT541H
	<i>Make/Model:</i>	Mercedes Benz C180
	<i>Accident Date:</i>	3 March 2018

<u>Sr. No.</u>	<u>Description</u>	<u>Qty</u>	<u>Unit price (\$)</u>	<u>Amount (\$)</u>
1	Being labour and materials supplied for the restoration of the accident vehicle to its pre-accident condition.			\$5,500.00

Total Amount Payable: \$5,500.00

Sing Dollars: Five Thousand and Five Hundred only

HSL Auto Service



Authorized Signature



DAWN ENTERPRISES

21 Seletar West Farmway 1
Singapore 798125
Tel: 63832661 Fax: 64842836
Reg No.430058/00D

Nº 35456

RENTAL AGREEMENT

DATE 9/3/18

HIRER'S PARTICULARS

Name PHIAH KOE WAY

Address 8 Kim Keat Lane

I/C or Passport No. _____ Country _____

Occupation Sales

Date of Birth 1983-05-21 Age 34

Driving Licence No. 626925P6U Date Passed 2017-2017

Tel: (HP) 91458929 (Residence) 3pm 35 min

DRIVER'S PARTICULARS

Name _____

Address _____

I/C or Passport No. _____ Country _____

Occupation _____

Date of Birth _____ Age _____

Driving Licence No. _____ Date Passed _____

Tel: (Office) _____ (Residence) _____

IMPORTANT NOTES:

- 1 No Insurance Coverage if the driver is below 24yrs old or less than 2 years driving licence.
- 2 This vehicle is licenced to carry 2850 passengers only.
- 3 Hirer is liable to pay first \$ 2850 as excess all claims any accident plus loss of earning while damaged vehicle is under repair.
- 4 For usage to Malaysia subject to higher excess all claims of \$5,000.00 and different rental rate
- 5 Please notify our office should there be any accident involving this hired vehicle within 24 hrs
- 6 No refund will be given for vehicle returns early.
- 7 No refund will be given for petrol left in vehicle.
- 8 Hirer is liable to pay all parking fee and traffic summonses.
- 9 Vehicles to be return during office hour only.
- 10 No Service on Public Holiday and Sunday.

SCHEDULE

MODEL

<u>SFH 3989P</u>		
<u>T/Carry</u>		
Date	Time	Mileage
<u>9/3/18</u>	<u>10.35am</u>	
<u>17/3/18</u>	<u>6.00pm</u>	

CHARGES

Day at \$ <u>200.00</u> per days	\$ <u>1800.00</u>
Day at \$ _____ per week	
Day at \$ _____ per month	
TOTAL AMOUNT	\$ <u>1800.00</u>
AMOUNT PAID	\$ <u>1800.00</u>
BALANCE DUE	
Days Extension From _____ To _____	
Amount Deposit (refundable) \$	

FROM

9/3/18

TO

17/3/18

I/we have read and understood the terms and conditions above and hereby agreed to abide

Hirer's Signature

Driver/Gurantor's Signature

DAWN ENTERPRISES



DAWN ENTERPRISES

21 SELETAR WEST FARMWAY 1
SINGAPORE 798125
TEL: 6383 2661 FAX: 6484 2836
REG. NO. 430058/00D

H&L

No. 19137

Date, 17/8/18

OFFICIAL RECEIPT

Received from

Kok Wan

the sum of Dollars

One thousand eight hundred only

being Payment Of

SFH 39899

(9/8/18 - 17/8/18)

DAWN ENTERPRISES

\$

1800/-

Cash/Cheque No.

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Tel: 6315 1239, Fax: 6315 3298, Mobile: 9061 0543

INVOICE

Tan Keang Leng
c/o Blk 1 Kaki Bukit Ave 6
#01-02
Singapore 417883

Invoice no:	POS096/18
Date:	4 April 2018
Report no:	96M0318.HSL
Vehicle :	SLT541H

No	Item Description	Qty	Unit Price	Total Amount(\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			590.00
SGD(\$): Five hundred and ninety only			Grand Total:	590.00

"Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES



PRO-OPTION SERVICES

Mailing address: Blk 1898 Rivervale Drive, #04-1004, Singapore 542189

Tel: 6315 1239, Fax: 6315 3298, Mobile: 9061 0543

ACCIDENT VEHICLE INSPECTION REPORT

Report no : 96M0318.HSL

Vehicle no : SLT541H

1 REFERENCE

Date of inspection : 10 March 2018

Requested by : Tan Keang Leng
c/o Blk 1 Kaki Bukit Ave 6
#01-02

Singapore 417883

Type of survey : Independent

Repairster : HSL Auto Service

Blk 1 Kaki Bukit Ave 6, #01-02 Singapore 417883

Date of accident : 3 March 2018

2 VEHICLE DATA

Make/model : Mercedes Benz C 180 KOMPRESSOR

Chassis no : WDD2040452A580146

Engine no : 27191031346154

Date of registration : 01 September 2011

Engine capacity : 1597 cc

Colour : Blue

Odometer reading : 126459 km

3 STATIC CONDITION CHECK

Steering : Serviceable

Foot brakes : Serviceable

Hand brakes : Serviceable

Paintwork : Good

General Condition : Good

4 TIRE CONDITION CHECK

RH/MAKE

LH/MAKE

SIZE

Front tread : 6 mm/Continental

6 mm/Continental

225/45R17

Rear tread : 6 mm/Continental

6 mm/Continental

225/45R17

5 BRIEF DESCRIPTION OF DAMAGE

Rear bumper scraped/deformed, rear RH fender dented/scraped/distorted, RH taillamp casing broken, etc.
Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs : \$5,500.00 (lump sum)

No of days taken : Five (5)

8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 96M0318.HSL

Vehicle no: SLT541H

A SPARE PARTS

<u>Description</u>	<u>Qty</u>	<u>Assessed Condition</u>	<u>Repairer's Amount</u>	<u>Revised Amount</u>	
Rear bumper	1	scraped/deformed	1,390.00	1,390.00	982 ✓
Rear bumper side retainer RH	1	bent/tabs fractured	56.00	56.00	BR ✓
Rear bumper side chrome LH & RH	2	necessary	260.00	260.00	NEC ✓
Rear bumper centre chrome	1	necessary	204.00	204.00	NEC ✓
RH taillamp assy	1	casing broken	866.00	720 866.00	BR ✓
RH taillamp lower bracket	1	bent/fractured	54.00	54.00	BR ✓
RH rear fender	1	dented/scraped/distorted	2,030.00	2,030.00	BUC ✓
Rear windscreen moulding set	1	necessary	185.00	185.00	NEC
Subtotal of the above			5,045.00	5,045.00	4899.0
Discount 10%			504.50	504.50	489.90
Subtotal 1:			4,540.50	4,540.50	4409.1
(Special nett)					
Rear windscreen sealant	1	necessary	80.00	40 80.00	NEC
Rear parking sensor set	1	intact/serviceable	280.00	0.00	
Subtotal 2:			360.00	80.00	40/-
Total cost of parts:			4,900.50	4,620.50	4449.1

B LABOUR

To remove and refit rear windscreen	150.00	120.00	100/-
To check wiring and repair where necessary	40.00	30.00	✓
To reinstall rear parking sensors and check sensing range.	90.00	60.00	40/-
To remove and refit rear passenger seat, rear fender inner trim covers affected upholstery and car to facilitate the repairs	450.00	300.00	100/-
Panel beating charges to dismantle and remove damaged parts, renew and install new parts, to cut out the damaged rear fender, install new part and weld, to knock straighten and reshape surrounding body panels.	1,200.00	900.00	600
To putty and spray paint the rear bumper, rear fender, rear wheelhouse panel and affected areas.	1,000.00	750.00	400/-
To apply anti-rust undercoat.	150.00	90.00	60/-
Total cost of labour:	3,080.00	2,250.00	1230.
Total cost of repair:	7,980.50	6,870.50	5749.

L/S 4600/2

5 days labour

9 CONCLUSION

Report no: 96M0318.HSL
Vehicle no: SLT541H

The actual damage sustained by the vehicle was carefully inspected and assessed during the inspection and the assessment is appended in para. 8 of this report. The degree of damage sustained by individual part(s) is/are carefully assessed before the part(s) is/are recommended to be either replaced or repaired.

The revised or adjusted cost of repairs to restore the vehicle is \$6,870.50 .


However, considering the age and condition of the vehicle and the availability of good second parts in the market, the repairs are recommended to be undertaken on a contract lump sum basis of \$5,500.00 ; and the entire repairs had taken Five (5) days to complete.

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Note: By accepting to carry out the repairs on a contract lump sum basis, the repairer has has the discretion to replace the damaged part(s) with used, reconditioned or new part(s), or to repair the part(s) to a roadworthy condition.

We have not authorised any repairs and would like to revert the recommendations for your consideration and decision.

Yours faithfully



.....
Liaw Leong San
Licensed Automotive Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Mar 2018		08 Mar 2018 16:16 Edit Adj Rpt	\$4,600.00 Edit Estimates	\$4,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------





CLAIM SUBFOLDER DETAILS				[Created by insurer]		
Insured:	YONG TAI LOONG PTE LTD, Co. Reg. No.: NA					
Main Claimant:	TAN KEANG LENG					
Vehicle Reg. No.:	SLT541H	Date of Loss:	03/03/2018 00:00 - :59 [78 Months and 2 Days From LTA Reg Date (Man Yr)]			
Claim Type:	TP / 551775	Policy/Cover Note No.:	28989797MKC (TP, Fire & Theft) Coverage: 10/08/2017 - 09/08/2018			
Vehicle Reg. No. (Insured):	GZ7305E	Policy No. (Claimant):				
		Excess:				
Repairer:	Hsl Auto Service (HQ) A Kaki Bukit Avenue 6 Autobay #01-05, 417883 Kaki Bukit - Tel: 96601395					
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 09/03/2018]					
Adj Asg. Remarks:	Third Party Pre-Repair Survey					

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SLT541H (551775)**
[GZ7305E]
TP
TAN KEANG LENG
Mar 3 2018 12:00AM
[YONG TAI LOONG PTE LTD]
Hsl Auto Service

Upload Documents Upload Photos Compose New Letter			View View in Browser <input type="button" value="v"/>	
Documentation			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	08/03/18 15:57	MSIG Insurance (Singapore) Pte. Ltd. (HQ) TP PRI	 Load PDF	
2	08/03/18 16:05	EMAIL TP OUR LIST OF SJE & OUR REJECTION REPLY & NOMINATED LKK TO BE SJE	 Load PDF	
3	24/04/18 09:50	LOD, LTA Search, SLT541H GIA Rpt, Final Repair Bill, Rental Bill & Agreement, TP Survey Report	 Load PDF	
No	Relabel/Reorder		Thumbnail	Print
1	23/05/18 14:55	LKK Auto Consultants Pte Ltd (HQ) PHOTO	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18004541/GTD3E2

Date: 23/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 28989797MKC
Claimant Vehicle No : SLT541H	Insured Vehicle No : GZ7305E
Date of Loss: 03/03/2018	Nature of Claim: TP Claim No: 551775

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT541H	Engine No:	27191031346154
Make & Model:	MERCEDES-BENZ C180, 1.6 Kompressor (A)	Chassis No:	WDD2040452A580146
Reg. Date:	01/09/2011 (Man. Year: 2011)	Odometer:	126459 km
Colour:	Blue		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,900.50	4,449.10	451.40	9.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	1,330.00	1,750.00	56.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,980.50	5,779.10	2,201.40	27.58
Approved Total (Overridden) (\$\$)		4,600.00		
Nett Amount (\$\$)	7,980.50	4,600.00	3,380.50	42.36

INSPECTION

Date of Assignment:	08/03/2018	
Date Inspected:	09/03/2018	Inspected At: Blk 1 Kaki Bukit Ave 6 #01-02 Repairer : Hsl Auto Service (HQ)
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 May 2018)
Parts: 143 MERCEDES-BENZ C180 1.6 Kompressor (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLT541H)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Scraped / Deformed	1,390.00 FL	*1,390.00 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Broken	56.00 FL	*56.00 FL
3	2		*REAR BUMPER SIDE CHROME LH & RH	Necessary	260.00 FL	*260.00 FL
4	1		*REAR BUMPER CENTRE CHROME	Necessary	204.00 FL	*204.00 FL
5	1		*RH TAILLAMP ASSY	Broken	866.00 FL	*720.00 FL
6	1		*RH TAILLAMP LOWER BRACKET	Broken	54.00 FL	*54.00 FL
7	1		*RH REAR FENDER	Buckled	2,030.00 FL	*2,030.00 FL
8	1		*SET REAR WINDSCREEN MOULDING	Necessary	185.00 FL	*185.00 FL
9	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
10	1		*SET REAR PARKING SENSOR	Intact / Serviceable	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,405.00	4,939.00
- List Item Discount on L Items 10.00/10.00% (S\$)	504.50	489.90
Total Parts (S\$)	4,900.50	4,449.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR WINDSCREEN	New	150.00	100.00
2	TO CHECK WIRING AND REPAIR WHERE NECESSARY	New	40.00	30.00
3	TO REINSTALL REAR PARKING SENSORS AND CHECK SENSING RANGE	New	90.00	40.00
4	TO REMOVE AND REFIT REAR PASSENGER SEAT, REAR FENDER INNER TRIM COVERS AFFECTED UPHOLSTERY AND CAR TO FACILITATE THE REPAIRS	New	450.00	100.00
5	PANEL BEATING CHARGES TO DISMANTLE AND REMOVE DAMAGED PARTS, RENEW AND INSTALL NEW PARTS, TO CUT OUT THE DAMAGED REAR FENDER, INSTALL NEW PART AND WELD, TO KNOCK STRAIGHTEN AND RESHAPE SURROUNDING BODY PANELS	New	1,200.00	600.00
6	TO PUTTY AND SPRAY PAINT THE REAR BUMPER, REAR FENDER, REAR WHEELHOUSE PANEL AND AFFECTED AREAS	New	1,000.00	400.00
7	TO APPLY ANTI-RUST UNDERCOAT	New	150.00	60.00
Gross Labour Cost (S\$)			3,080.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >