

J8 M00ABC
CK131014

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2010 MAZDA 2 1.5 (SJV9719S)

Date of Loss

March 7, 2018

Time of Loss

15.05

Loss Description

SJV9719S (INSD) HIT SKJ7728E WHILE REVERSING INTO PARKING LOT

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

MOVA AUTOMOTIVE PTE LTD

Target Date of Completion *

03/13/2018



Days of work completion *

4



<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio **Parts & Labour** Miscellaneous Summary

Parts

Add

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISCOUNT%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			BOOT LID - REPAIR				0 R		0	Reviewing	
		2	1			BOOT LID EMBLEM - MAZDA				16 new ✓		16	Reviewing	
		3	1			BOOT LID EMBLEM - 2				12 new ✓		12	Reviewing	
		4	1			BOOT LID LOGO				24 new ✓		24	Reviewing	
		5	1			BOOT LID LOCK - CHECK				0 X		0	Reviewing	
		6	1			REAR BUMPER				570 DE ✓		570	Reviewing	
		7	1			REAR BUMPER RETAINER LH				28 new ✓		28	Reviewing	
		8	1			REAR BUMPER REFLECTOR LH - CHECK				0 ?		0	Reviewing	
		9	10			REAR BUMPER CLIPS				3.5 new ✓		35	Reviewing	
		10	1			REAR NUMBER PLATE LAMP GARNISH - CHECK				0 ?		0	Reviewing	
		11	1			REAR END PANEL - REPAIR				0 R		0	Reviewing	
		12	1			REAR END PANEL TOP COVER - CHECK				0 ?		0	Reviewing	
		13	1			REAR FENDER LH - REPAIR				0 R		0	Reviewing	
		14	1			TAILLAMP ASSY LH - CHECK				0 ?		0	Reviewing	

Labour

Add

EDIT SR NO REPAIR/REPLACE (LABOUR) PART NAME LABOUR R&R LABOUR REPAIR PAINT ACTION (LABOUR) COMMENT REMOVE

3/9/2018

Claim Portal

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
 	1		TO KNOCK AND STRAIGHTEN BOOT LID, REAR END PANEL, REAR FENDER LH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION	0	480 400	0	Reviewing		
 	2		SPRAY PAINT BOOT LID, REAR END PANEL, REAR BUMPER, REAR FENDER LH	0	0	550 600	Reviewing		
 	3		REMOVE & REPLACE LUGGAGE COMPARTMENT INNER TRIM, GARNISH, COVERING	0	50 40	0	Reviewing		
 	4		REMOVE & REPLACE REVERSE SENSOR AND CHECK FUNCTION	0	50 40	0	Reviewing		



« Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	REVERSE SENSOR	Reviewing	200	SPECIAL NET ?	
		2	REAR NUMBER PLATE	Reviewing	40 35	SPECIAL NET sw ✓	

Ram
Hp 90010068
4 days
p/p
13/03/18 @ 1100
EXCESS : TBA
Revert
Remy by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

« **Assessment Details**

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount
\$2,165.00

CATEGORY	Labour
ESTIMATE	\$590.00
REVISED AMOUNT	\$590.00
CATEGORY	Spare Parts
ESTIMATE	\$685.00
REVISED AMOUNT	\$685.00
CATEGORY	Paint
ESTIMATE	\$650.00
REVISED AMOUNT	\$650.00
CATEGORY	Miscellaneous
ESTIMATE	\$240.00
REVISED AMOUNT	\$240.00

Submit for Review