

DANIEL LEE  
BLK 48 #13-105  
TOA PAYOH LOR5  
SINGAPORE 310048

File No :  
Date : 08-March-2018

Estimated cost of repair for vehicle no: SDH8989E TOYOTA CAMRY  
Accident involving vehicle no: SDH8989E & XE877B on 03-March-2018

Description	Quantity	List Price
Rear bumper / <i>Cwt</i>	1	\$ 260.00
Rear bumper RH retainer / <i>ABC</i>	1	\$ 55.00
		\$ 315.00
	Add 15%	\$ 47.25
		\$ 362.25
To spray paint rear right portion and accident areas.	1	400 \$ <del>300</del> 450.00
Labour for rear RH fender, wheel arch panel, rear RH fender inner panel and adjust rear body alignment.	1	300 \$ 380.00
		\$ 1,192.25

*1062.25*  
*20%: 850*

T/Party: EQ INSURANCE COMPANY LTD

*4 Days.*  
*lump sum repair.*  
*After repair photos.*  
*Guo Qicq - 8288 0282*  
*09/3/18.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: