

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

Agribia - CP/P)

TS

VEHICLE NO : SHA 5618K

DATE 8/3/2018

MAKE :

LKK - Kalvin

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper X Repair			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips X			\$ 22.00
	Rear Bumper Sponge X			\$ 143.40
	Rear Bumper Under Cover X			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor X			\$ 135.70 Nett
	Rear Bumper Rubber Mat +			\$ 50.00 Nett
	Rear Bumper Advertisement Logo /			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH) /		\$ 100.00	\$ 200.00 Nett
				\$ 435.70
	Labour Charge			100
	Panel Beating			\$ 380.00
	Spray Painting Charge			\$ 200.00 180
	Wiring Charge			\$ 50.00 X
	R/Refix Reverse Sensor			\$ 120.00 X
	TOTAL LABOUR			\$ 750.00
	ESTIMATE TOTAL			\$ 2,711.58
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Kalvin / Uchi
 8/3/18 1525h2
 2 P.M.
 PIP
 After Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: