

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-036

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9771H - CHINA TAIPING

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD9771H - CANDY

VF1ABL15AUC277287

RENAULT

LATITUDE

03.03.2018

CHINA TAIPING**PART****LIST**

1	1	BUMPER COVER REAR <i>x repair</i>	\$	1,108.46
2	1	BUMPER LOWER REAR	\$	768.84
3	1	BUMPER BRACKET CTR REAR <i>x</i>	\$	113.47
4	1	BUMEP R BRACKET SIDE RH REAR <i>x</i>	\$	135.97
5	1	BUMEP R RETAINER RH REAR <i>x</i>	\$	44.99
6	1	BUMPER REFLECTOR RH <i>x</i>	\$	43.61
7	1	BUMEP R BRACKET SIDE LH REAR <i>x</i>	\$	135.97
8	1	BUMEP R RETAINER LH REAR <i>x</i>	\$	44.99
9	1	BUMPER REFLECTOR LH <i>x</i>	\$	43.61
10	1	BUMPER BEAM REAR <i>x</i>	\$	777.52
11	1	BUMPER BEAM BRACKET LH REAR <i>x</i>	\$	225.95
12	1	BUMPER BEAM BRACKET RH REAR <i>x</i>	\$	225.95
13	1	BOOT REAR <i>x</i>	\$	2,872.68
14	1	BOOT FINISHER <i>x</i>	\$	470.06
15	1	BOOT WHEATERSTRIP <i>x</i>	\$	323.05
16	1	BOOT REFLECTOR LAMP LH <i>x</i>	\$	493.35
17	1	BOOT REFLECTOR LAMP RH <i>x</i>	\$	493.35
18	1	BOOT BADGE 'RENAULT' <i>x</i>	\$	225.36
19	1	BOOT BADGE <i>x</i>	\$	225.36
20	1	BOOT SWITCH <i>x</i>	\$	168.13
21	1	BOOT LOCK <i>x</i>	\$	202.67
22	1	BOOT LOCK CATCH <i>x</i>	\$	74.40
23	2	LICENCE PLATE LAMP <i>x</i>	\$	50.52
24	2	BOOT RUBBER PLUG <i>x</i>	\$	221.81
25	1	FENDER PANEL REAR LH <i>x</i>	\$	3,299.13
26	1	WHEELARCH REAR LH <i>x</i>	\$	543.47
27	1	FENDER PANEL REAR RH <i>x</i>	\$	3,299.13
28	1	WHEELARCH REAR RH <i>x</i>	\$	543.47
29	1	TAILLAMP RH <i>x</i>	\$	552.55
30	1	TAILLAMP PANEL RH <i>x</i>	\$	986.70
31	1	TAILLAMP LH <i>x</i>	\$	552.55
32	1	TAILLAMP PANEL LH <i>x</i>	\$	986.70
33	1	OUTER PANEL REAR (End Panel) <i>x</i>	\$	1,471.77
34	1	OUTER PANEL REAR (End Panel) TRIM <i>x</i>	\$	404.56

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-036

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9771H - CHINA TAIPING

35	1	EXHAUST REAR	×	\$	7,489.05
36	1	EXHAUST CAP REAR	×	\$	230.49

TOTAL	\$	29,849.67
10%	\$	2,984.97
	\$	26,864.70

Specical Nett

1	1SET	PARKING AID	×	\$	700.00
2	1SET	REAR BUMPER CLIP	✓	\$	66.00
3	1SET	BUMPER BRACKET CTR CLIP	×	\$	33.00
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	×	\$	10.00
5	1SET	BUMEPR RETAINER RH CLIP RR	×	\$	20.00
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	×	\$	10.00
7	1SET	BUMEPR RETAINER CLIP LH RR	×	\$	20.00
8	1SET	BUMPER LOWER REAR RIVET	✓	\$	22.00
9	1SET	BUMPER LOWER REAR CLIP	✓	\$	66.00
10	1	EXHAUST MOUNTING REAR	×	\$	17.82
11	1SET	BOOT FINISHER CLIP	×	\$	24.20
12	1	BOOT STICKER "Trans-cab"	×	\$	30.00
13	1	BOOT STICKER "6555-3333"	×	\$	30.00
14	1SET	FENDER WHEELARCH REAR RH CLIP	×	\$	35.00
15	1SET	FENDER WHEELARCH REAR LH CLIP	×	\$	35.00
16	1	TAILLAMP CLIP RH	×	\$	5.00
17	1	TAILLAMP CLIP LH	×	\$	5.00
18	2	REAR WINDSCREEN SELANT	×	\$	80.00
19	1	WINDSCREEN MOULDING	×	\$	100.00
20	1	REAR WINDSCREEN INNER SPONGE SEAL	×	\$	100.00
21	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	×	\$	385.00
22	1	SPARE TYRE	×	\$	330.00

TOTAL	\$	2,124.02
TOTAL PARTS	\$	28,988.72

Putty And Spray Painting Of The Affected Portion.

\$	3,000.00	200
----	----------	----------------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	2,800.00	200
----	----------	----------------

To Rust-Proofing Of The Affected Areas.

\$	170.00	×
----	--------	---

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-036

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9771H - CHINA TAIPING

To reinstall rear bumper parking sensor.	\$	170.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 X
To repair and realign rear exhaust pipe.	\$	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 X
Towing Fees	\$	120.00 ?
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 X
To check steering geometry and computer wheel alignment	\$	220.00 X

TOTAL	\$	7,710.00
Over All Total	\$	36,698.72

(PARTS BY PARTS)**Repair Days****10Days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalin 16/1/14

8/3/18 1320hrs

2 Rps

Lumpsum Repair

After Repair photo