

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5633E**AAD1803-068***4/5 2100/202*

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC5633E - JHOW
VF1ABL15AUC280327
RENAULT
LATITUDE
06.03.2018
AXA

		PART			LIST
1	1	BUMPER COVER REAR <i>- Renault</i>	\$		1,108.46
2	1	BUMPER LOWER REAR <i>- cut</i>	\$		768.84
3	1	BUMPER BRACKET CTR REAR <i>X su</i>	\$		113.47
4	1	BUMEPR BRACKET SIDE RH REAR <i>X su</i>	\$		135.97
5	1	BUMEPR RETAINER RH REAR <i>X su</i>	\$		44.99
6	1	BUMPER REFLECTOR RH <i>X su</i>	\$		43.61
7	1	BUMEPR BRACKET SIDE LH REAR <i>X su</i>	\$		135.97
8	1	BUMEPR RETAINER LH REAR <i>X su</i>	\$		44.99
9	1	BUMPER REFLECTOR LH <i>X su</i>	\$		43.61
10	1	BUMPER BEAM REAR <i>X su</i>	\$		777.52
11	1	BUMPER BEAM BRACKET LH REAR <i>X su</i>	\$		225.95
12	1	BUMPER BEAM BRACKET RH REAR <i>X su</i>	\$		225.95
13	1	BOOT REAR <i>X su</i>	\$		2,872.68
14	1	BOOT FINISHER <i>X su</i>	\$		470.06
15	1	BOOT WHEATERSTRIP <i>X su</i>	\$		323.05
16	1	BOOT REFLECTOR LAMP LH <i>X su</i>	\$		493.35
17	1	BOOT REFLECTOR LAMP RH <i>X su</i>	\$		493.35
18	1	BOOT BADGE 'RENAULT' <i>X su</i>	\$		225.36
19	1	BOOT BADGE <i>X su</i>	\$		225.36
20	1	BOOT STRUT LH <i>X su</i>	\$		276.08
21	1	BOOT STRUT RH <i>X su</i>	\$		276.08
22	1	BOOT HINGE LH <i>X su</i>	\$		367.84
23	1	BOOT HINGE RH <i>X su</i>	\$		367.84
24	1	BOOT INNER TRIM <i>X su</i>	\$		586.45
25	1	BOOT SWITCH <i>X su</i>	\$		168.13
26	1	BOOT LOCK <i>X su</i>	\$		202.67
27	1	BOOT LOCK CATCH <i>X su</i>	\$		74.40
28	2	LICENCE PLATE LAMP <i>X su</i>	\$		50.52
29	2	BOOT RUBBER PLUG <i>X su</i>	\$		221.81
30	1	FENDER PANEL REAR LH <i>X su</i>	\$		3,299.13
31	1	WHEELARCH REAR LH <i>X su</i>	\$		543.47
32	1	FENDER PANEL REAR RH <i>X su</i>	\$		3,299.13
33	1	WHEELARCH REAR RH <i>X su</i>	\$		543.47
34	1	TAILLAMP RH <i>X su</i>	\$		552.55

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-068

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5633E

35	1	TAILLAMP PANEL RH	X <i>su</i>	\$	986.70
36	1	TAILLAMP LH	X <i>su</i>	\$	552.55
37	1	TAILLAMP PANEL LH	X <i>su</i>	\$	986.70
38	1	OUTER PANEL REAR (End Panel)	X <i>su</i>	\$	1,471.77
39	1	OUTER PANEL REAR (End Panel) TRIM	X <i>su</i>	\$	404.56
40	1	EXHAUST REAR	X <i>su</i>	\$	7,489.05
41	1	EXHAUST CAP REAR	X <i>su</i>	\$	230.49

TOTAL	\$	31,723.96
10%	\$	3,172.40
	\$	28,551.56

Specical Nett

1	1SET	PARKING AID	<i>shill</i>	\$	700.00
2	1SET	REAR BUMPER CLIP	<i>net</i>	\$	66.00
3	1SET	BUMPER BRACKET CTR CLIP	X <i>"</i>	\$	33.00
4	1SET	BUMEP R BRACKET SIDE CLIP RH RR	X <i>"</i>	\$	10.00
5	1SET	BUMEP R RETAINER RH CLIP RR	X <i>"</i>	\$	20.00
6	1SET	BUMEP R BRACKET SIDE CLIP LH RR	X <i>"</i>	\$	10.00
7	1SET	BUMEP R RETAINER CLIP LH RR	X <i>"</i>	\$	20.00
8	1SET	BUMPER LOWER REAR RIVET	<i>su</i>	\$	22.00
9	1SET	BUMPER LOWER REAR CLIP	<i>su</i>	\$	66.00
10	1	EXHAUST MOUNTING REAR	X <i>su</i>	\$	17.82
11	1SET	BOOT FINISHER CLIP	X <i>"</i>	\$	24.20
12	1	BOOT STICKER "Trans-cab"	X <i>su</i>	\$	30.00
13	1	BOOT STICKER "6555-3333"	X <i>su</i>	\$	30.00
14	1SET	FENDER WHEELARCH REAR RH CLIP	X <i>"</i>	\$	35.00
15	1SET	FENDER WHEELARCH REAR LH CLIP	X <i>"</i>	\$	35.00
16	1	TAILLAMP CLIP RH	X <i>"</i>	\$	5.00
17	1	TAILLAMP CLIP LH	X <i>"</i>	\$	5.00
18	2	REAR WINDSCREEN SELANT	X <i>"</i>	\$	80.00
19	1	WINDSCREEN MOULDING	X <i>"</i>	\$	100.00
20	1	REAR WINDSCREEN INNER SPONGE SEAL	X <i>"</i>	\$	100.00
21	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	X <i>su</i>	\$	385.00
22	1	SPARE TYRE	X <i>su</i>	\$	330.00

TOTAL	\$	2,124.02
TOTAL PARTS	\$	30,675.58

Putty And Spray Painting Of The Affected Portion.

\$

~~3,000.00~~

200

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5633E**AAD1803-068**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00 ²⁰⁰
To Rust-Proofing Of The Affected Areas.	\$	170.00 X 11
To reinstall rear bumper parking sensor.	\$	170.00 30
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 X 11
To repair and realign rear exhaust pipe.	\$	170.00 X 11
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 X 11
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 X 11
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 X 11
Towing Fees	\$	120.00 X 11
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 X 11
To check steering geometry and computer wheel alignment	\$	220.00 X 11

TOTAL \$ 7,710.00**Over All Total \$ 38,385.58****(PARTS BY PARTS)****Repair Days****10 Days**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s)
- Supplementary item(s) must be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Kahin (LKK)

9/3/18 1340h.

2 Days

Lump Sum Repair

After Repair photo.