

# VIN'S MOTOR PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722. Tel: 6453 2121 (4 Lines) Fax: 6459 9795

Our Ref : TP/022018/3532E  
 Accident date: 06/03/2018  
 Your Ref : YP226K

Tax Invoice:  
 Date : 08/03/2018

MOTOR CLAIM DEPARTMENT  
 AXA INSURANCE (S) PTE LTD  
 8 Shenton Way  
 #27-01 AXA Tower  
 Singapore 068811

ESTIMATE COST OF REPAIRS TO TOYOTA CHR SDP9119B

1 pc Rear tail gate	\$ 1,801.53	<i>Free</i>
1 pc Rear tail gate glass	\$ 1,329.10	<i>BPA</i>
1 pc Rear tail gate glass moulding	\$ 121.80	<i>neu</i>
1 pc Rear tail gate top spoiler	\$ 1,411.70	<i>?</i>
2 pcs Rear tail gate hinge @ \$99.26	\$ 198.52	<i>?</i>
<i>1 pc</i> pcs Rear tail gate shocker bracket @ \$286.20 <i>BT/LH</i>	\$ 572.40	<i>X RH X</i>
2 pcs Rear tail gate reflector @ \$386.53	\$ 773.06	<i>CRA</i>
2 pcs Rear tail gate no. plate lamp @ \$92.50	\$ 185.00	<i>X</i>
1 pc Rear tail gate garnish	\$ 756.20	<i>CRA</i>
1 pc Rear tail gate emblem	\$ 58.80	<i>neu</i>
1 pc Rear tail gate "CHR" emblem	\$ 59.90	<i>neu</i>
1 pc Rear tail gate lock	\$ 402.90	<i>BT</i>
1 pc Rear tail gate lock motor	\$ 711.30	<i>?</i>
2 pcs Rear tail gate stopper top @ \$17.50	\$ 35.00	<i>neu</i>
2 pcs Rear tail gate stopper lower @ \$31.50	\$ 63.00	<i>neu</i>
1 pc Rear tail gate wiper motor	\$ 650.50	<i>BT?</i>
1 pc Rear tail gate wiper arm	\$ 92.60	<i>X</i>
2 pcs Rear tail gate side garnish @ \$135.90	\$ 271.80	<i>DIS</i>
2 pcs Rear tail gate top corner rubber @ \$71.70	\$ 143.40	<i>neu</i>
1 pc Rear tail gate inner trim (top)	\$ 597.20	<i>DE</i>
1 pc Rear tail gate inner trim (lower)	\$ 511.40	<i>DE</i>
1 pc Rear tail gate no. plate garnish top cover	\$ 296.30	<i>CRA</i>
<i>1 pc</i> pcs Rear lamp @ \$466.60 <i>LH-PAO</i>	\$ 933.20	<i>BT-X</i>
1 pc Rear bumper	\$ 756.20	<i>DE</i>
<i>1 pc</i> pcs Rear bumper reflector @ \$75.20 <i>LH-CRA</i>	\$ 150.40	<i>RH-X</i>
<i>1 pc</i> pcs Rear bumper side cover @ \$110.20 <i>LH-DE</i>	\$ 220.40	<i>RHX</i>
1 pc Rear bumper lower pad	\$ 511.40	<i>DE</i>
1 pc Rear bumper center cover	\$ 104.20	<i>?</i>
2 pcs Rear bumper sensor @ \$120.00	\$ 240.00	<i>220 neu s/n</i>
<i>1 pc</i> pcs Rear bumper side retainer @ \$99.20 <i>neu LH</i>	\$ 198.40	<i>RH-X</i>
1 pc Rear bumper reinforcement	\$ 382.40	<i>BT</i>
1 pc Rear bumper under cover	\$ 193.60	<i>DE</i>
Balance c/f	\$ 14,733.61	

# VIN'S MOTOR PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722. Tel: 6453 2121 (4 Lines) Fax: 6459 9795

Our Ref: TP/032018/3532E

Page 2

Balance b/f		\$ 14,733.61
1 pc	Rear end panel	\$ 780.20 <i>PA-</i>
1 pc	Rear end panel inner trim	\$ 252.90 <i>DE-</i>
<i>1pc 2</i> pcs	Rear lamp panel @ \$130.90 <i>PA/LH</i>	\$ 261.80 <i>RH-X</i>
1 pc	Rear spare tyre panel	\$ 876.30 <i>R?</i>
1 pc	Rear spare tyre panel top cover	\$ 515.89 <i>TORA-</i>
1 pc	Rear center tool box	\$ 405.50 <i>DE-</i>
<i>1pc 2</i> pcs	Rear side tool box @ \$289.40 <i>LH-DE</i>	\$ 578.80 <i>RH-X</i>
1 pc	Rear LH fender	\$ 1,023.80 <i>PA-</i>
1 pc	Rear LH fender wheel arch	\$ 185.40 <i>DE-</i>
1 pc	Rear LH fender inner trim	\$ 691.20 <i>DE-</i>
1 pc	Rear speaker board	\$ 553.60 <i>DE-</i>
1 pc	Rear exhaust	\$ 1,452.60 <i>X</i>
1 pc	Rear exhaust top aluminium	\$ 487.20 <i>?</i>
		<hr/>
		\$ 22,798.80
	Less: 25%	\$ (5,699.70)
	Balance c/f	<hr/>
		\$ 17,099.10
1 pc	Rear tail gate glass gum	\$ 60.00 <i>N 40.00</i>
1 pc	Rear no. plate	\$ 40.00 <i>N 35.00</i>
	To towing	\$ 100.00 <i>70</i>
	To remove and renew rear glass	\$ 150.00 <i>120</i>
	To remove and refix rear seat cushion & roof lining	\$ 180.00 <i>100</i>
	To remove and refix rear petrol tank	\$ 80.00 <i>60</i>
	To repair rear damage	\$ 2,200.00 <i>1600</i>
	To spray painting	\$ 1,600.00 <i>1200</i>
		<hr/>
		\$ 21,509.10

VIN'S MOTOR PTE LTD

*[Handwritten signature]*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

*RASUL*  
*Hp 90010068*  
*14 days*  
*L/S*  
*09/03/18 @ 1530*  
*Resurvey after repair*