



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18004566/R1ua3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 09-03-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 362U	Veh. Inspected	SLT 731B	
Policy No.	Z17VP05014475	Coverage (\$)	0.00	
Claim No.	17/18/18/VP05020457	Excess (\$)	0.00	
Assign From		Assign Date	09/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/03/2018	Inspection Date	09/03/2018	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 17/18/18/VP05020457
Our ref: CC4/LPC18004566/R1ua3

Date: 14.03.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


SLT 731B

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09.03.2018 at the premises of M/s Wei Lee Motor Works - Sin Ming have the following to report:-

Workshop Estimate Amount	: S\$	4,758.58
Revised Estimate Amount	: S\$	4,037.13
"Check" Items Amount	: S\$	471.45
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Rear O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6.0 day

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Catherine Chong (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 8 March, 2018 5:33 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: ACCIDENT INVOLVING SJH362U & SLT731B ALONG BUANGKOK GREEN ON 7.3.2018
Attachments: 08032018172637.pdf

09032018 @ 1008am
Karen veh in.
Raul

Our Ref : 17/18/18/VP05020457

Dear Catherine,

We attached a copy of the estimate from Wei Lee Motor Works for your attention.

Kindly proceed to conduct a survey accordingly.

At the same time, kindly inform them that we are no longer at Shaw Towers.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

Mei Kwan (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Wednesday, 14 March, 2018 2:18 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; 'ERIC WOO JUN KIAT'; ONG LI LI; Thin Thin (LKKAUTO); Jas Khine (LKKAUTO); Admin A
Subject: RE: ACCIDENT INVOLVING SJH362U & SLT731B ALONG BUANGKOK GREEN ON 7.3.2018 *** LKK REF: CC4/LPC18004566/R1ua3
Attachments: Preliminary Advice.pdf; TP ESTIMATE - MARKED.pdf
Categories: HMK

EQI ref: 17/18/18/VP05020457
LKK REF: CC4/LPC18004566/R1ua3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SLT 731B

Date of survey: 09.03.2018

We have not authorized repairs.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: Tuesday, 13 March, 2018 2:36 PM
To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: ACCIDENT INVOLVING SJH362U & SLT731B ALONG BUANGKOK GREEN ON 7.3.2018 *** LKK REF: CC4/LPC18004566/R1ua3

Dear Mei Kwan,

We attached a copy of insured's GIA report for your attention

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd

Our Ref : 17/18/18/VP05020457

Dear Catherine,

We attached a copy of the estimate from Wei Lee Motor Works for your attention.

Kindly proceed to conduct a survey accordingly.

At the same time, kindly inform them that we are no longer at Shaw Towers.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: 455-3986

Business Regn No : 269436/00J

08, Mar 2018

Lonpac Insurance Bhd
100 Beach Road #19-00
Shaw Tower
S 189702

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle No: SJH362U

Accident involving vehicle No: SLT731B/SJH362U

DOA: 07/03/2018 AT Buangkok Dr Dlip Rd to Buangkok Green

Dear officer incharge

Re: Estimate cost of repair of repair for vehicle No: SLT731B

To supply—

****PLEASE arrange to survey the vehicle ASAP**
The Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Description	Qty	Amount
Lid	1	556.20 Pt ✓
Lid lock	1	102.00 Pt ✓
Lid-TOYOTA logo	1	50.20 nec ✓
Rear bumper	1	431.90 DE ✓
Bumper retainer, Rh-near fender	1	17.00 ne ✓
Bumper retainer, Rh-near taillamp	1	66.40 ne ✓
Bumper foglamp	1	82.70 CPA ✓
Taillamp, Rh	1	656.00 ERA ✓
End panel	1	673.60 Pt ✓
End panel top garnish	1	213.50 DE ✓
Boot weatherstrip	1	176.00 ne ✓
Bumper clip		38.00 ne ✓
Taillamp gasket	1	26.00 nec ✓
Exhaust tailpipe	1	628.60 T.R
	Parts	3,718.10
	Parts less 25%	929.52
		2,788.58

Reverse sensor

To remove damaged parts and attachments.

Cut n weld damaged panels.

Straighten rear chassis where necessary.

Replace/align all parts into position.

To spray paint.

RASUL

Hp 90010068

6 days

4/5

09/03/18 @ 1450

Resurvey after repair

220.00 ne ✓

850.00 700

900.00 800

4,758.58



Karen

6456 9830

6459 9830

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1813C
Vehicle Details	
Vehicle No.:	SLT731B
Vehicle to be Exported:	No
Intended De-registration Date:	12 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOSE AUTO
Primary Colour:	Beige
Manufacturing Year:	2008
Engine No.:	1NZX788606
Chassis No.:	MR053HY9305077290
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$11,834.00
Original Registration Date:	<u>11 Sep 2008</u>
First Registration Date:	11 Sep 2008
Transfer Count:	1
Actual ARF Paid:	\$11,834.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Sep 2018
PARF Rebate Amount:	\$5,917.00
Intended COE Rebate Details	

COE Expiry Date:	<u>10 Sep 2018</u>
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,101.00
COE Rebate Amount:	\$698.00
Total Rebate Amount:	\$6,615.00

The information contained herein is correct as at 12 Mar 2018

OK

12,000
6615

5,385

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18004566/R1ua3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSE SINGAPORE 199555

Date : 19-10-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 362U	Veh. Inspected	SLT 731B
Policy No.	Z17VP05014475	Coverage (\$)	0.00
Claim No.	17/18/18/VP05020457	Excess (\$)	0.00
Assign From	GERALD	Assign Date	08/03/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS E A	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053HY9305077290	Colour	GOLD
Odometer	247711	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	BRIDGESTONE	5 mm
L/H Front Tyre	185/60 R15	BRIDGESTONE	5 mm
R/H Rear Tyre	185/60 R15	BRIDGESTONE	5 mm
L/H Rear Tyre	185/60 R15	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	07/03/2018	Inspection Date	09/03/2018
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 731B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LID	BENT	556.20	556.20
1	LID LOCK	BENT	102.00	102.00
1	LID -TOYOTA LOGO	NECESSARY	50.20	50.20
1	REAR BUMPER	DEFORMED	431.90	431.90
1	BUMPER RETAINER ,RH -NEAR FENDER	NECESSARY	17.00	17.00
1	BUMPER RETAINER ,RH-NEAR TAILLAMP	NECESSARY	66.40	66.40
1	BUMPER FOGLAMP	CRACKED	82.70	82.70
1	TAILLAMP, RH	CRACKED	656.00	656.00
1	END PANEL	BENT	673.60	673.60
1	END PANEL TOP GARNISH	DEFORMED	213.50	213.50
1	BOOT WEATHERSTRIP	NECESSARY	176.00	176.00
1	BUMPER CLIP	NECESSARY	38.00	38.00
1	TAILLAMP GASKET	NECESSARY	26.00	26.00
1	EXHAUST TAILPIPE	TO REPAIR SEE LABOUR	628.60	-
	LESS 25% DISCOUNT		-929.52	-772.37
			2,788.58	2,317.13
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	NOT WORKING	220.00	220.00
			220.00	220.00
LABOUR				
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS .CUT N WELD DAMAGED PANELS,STRAIGHTEN REAR CHASSIS WHERE NECESSARY.REPLACE/ALIGN ALL PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF EXHAUST TAILPIPE .		850.00	700.00
	TO SPRAY PAINT.		900.00	800.00
			1,750.00	1,500.00
GRAND TOTAL			4,758.58	4,037.13

Report Ref No. CC4/LPC18004566/R1ua3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,200.00
---	--	--	----------

Report Ref No. CC4/LPC18004566/R1ua3n2

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.