

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-065

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5855G -

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5855G - JHOW

VF1ABL15AUC280382

RENAULT

LATITUDE

07.03.2018

China Taipei

PART**LIST**

1	1	BUMPER COVER REAR	—	\$	1,108.46
2	1	BUMPER LOWER REAR	—	\$	768.84
3	1	BUMPER BRACKET CTR REAR	—	\$	113.47
4	1	BUMEPR BRACKET SIDE RH REAR	X	\$	135.97
5	1	BUMEPR RETAINER RH REAR	X	\$	44.99
6	1	BUMPER REFLECTOR RH	X	\$	43.61
7	1	BUMEPR BRACKET SIDE LH REAR	X	\$	135.97
8	1	BUMEPR RETAINER LH REAR	X	\$	44.99
9	1	BUMPER REFLECTOR LH	—	\$	43.61
10	1	BUMPER BEAM REAR	—	\$	777.52
11	1	BUMPER BEAM BRACKET LH REAR	—	\$	225.95
12	1	BUMPER BEAM BRACKET RH REAR	—	\$	225.95
13	1	BOOT REAR	X Repair	\$	2,872.68
14	1	BOOT FINISHER	X	\$	470.06
15	1	BOOT WHEATERSTRIP	X	\$	323.05
16	1	BOOT REFLECTOR LAMP LH	X	\$	493.35
17	1	BOOT REFLECTOR LAMP RH	X	\$	493.35
18	1	BOOT BADGE 'RENAULT'	X	\$	225.36
19	1	BOOT BADGE	X	\$	225.36
20	1	BOOT STRUT LH	X	\$	276.08
21	1	BOOT STRUT RH	X	\$	276.08
22	1	BOOT HINGE LH	X	\$	367.84
23	1	BOOT HINGE RH	X	\$	367.84
24	1	BOOT INNER TRIM	X	\$	586.45
25	1	BOOT SWITCH	X	\$	168.13
26	1	BOOT LOCK	X	\$	202.67
27	1	BOOT LOCK CATCH	X	\$	74.40
28	2	LICENCE PLATE LAMP	X	\$	50.52
29	2	BOOT RUBBER PLUG	X	\$	221.81
30	1	FENDER PANEL INNER TRIM REAR LH	X	\$	671.45
31	1	FENDER PANEL REAR LH	X	\$	3,299.13
32	1	WHEELARCH REAR LH	X	\$	543.47
33	1	WHEELARCH REAR RH	X	\$	543.47
34	1	TAILLAMP RH	X	\$	552.55

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-065

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5855G -

35	1	TAILLAMP PANEL RH	X	\$	986.70
36	1	TAILLAMP LH	X	\$	552.55
37	1	TAILLAMP PANEL LH	X	\$	986.70
38	1	OUTER PANEL REAR (End Panel)	✓	\$	1,471.77
39	1	OUTER PANEL REAR (End Panel)TRIM	✓	\$	404.56
40	1	SPARE WHEEL PANEL (Luggage Floor Panel)	X	\$	2,189.88
41	1	SPARE WHEEL PANEL TRIM	X	\$	612.21
42	1	EXHAUST REAR	X	\$	7,489.05
43	1	EXHAUST CAP REAR	X	\$	230.49

TOTAL	\$	31,898.36
10%	\$	3,189.84
	\$	28,708.53

Specical Nett

1	1SET	PARKING AID	✓	\$	700.00 450
2	1SET	REAR BUMPER CLIP	✓	\$	66.00
3	1SET	BUMPER BRACKET CTR CLIP	✓	\$	33.00
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	✓	\$	10.00
5	1SET	BUMEPR RETAINER RH CLIP RR	X	\$	20.00
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	✓	\$	10.00
7	1SET	BUMEPR RETAINER CLIP LH RR	X	\$	20.00
8	1SET	BUMPER LOWER REAR RIVET	✓	\$	22.00
9	1SET	BUMPER LOWER REAR CLIP	✓	\$	66.00
10	1	EXHAUST MOUNTING REAR	X	\$	17.82
11	1SET	BOOT FINISHER CLIP	X	\$	24.20
12	1	BOOT STICKER "Trans-cab"	✓	\$	30.00
13	1	BOOT STICKER "6555-3333"	✓	\$	30.00
14	1	BOOT INNER TRIM CLIP	X	\$	45.00
15	1SET	FENDER WHEELARCH REAR LH CLIP	X	\$	35.00
16	1	FENDER INNER TRIM CLIP LH	X	\$	28.00
17	1	TAILLAMP CLIP RH	X	\$	5.00
18	1	TAILLAMP CLIP LH	X	\$	5.00
19	2	REAR WINDSCREEN SELANT	X	\$	80.00
20	1	WINDSCREEN MOULDING	X	\$	100.00
21	1	REAR WINDSCREEN INNER SPONGE SEAL	X	\$	100.00
22	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	X	\$	385.00
23	1	SPARE TYRE	X	\$	330.00

TOTAL	\$	2,162.02
TOTAL PARTS	\$	30,870.55

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-065

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5855G -

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 800
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 1000
To Rust-Proofing Of The Affected Areas.	\$	170.00 50
To reinstall rear bumper parking sensor.	\$	170.00 50
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 X
To repair and realign rear exhaust pipe.	\$	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 40
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 X
Towing Fees	\$	120.00 ?
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 X
To check steering geometry and computer wheel alignment.	\$	220.00 X

TOTAL \$ 11,160.00
Over All Total \$ 42,030.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without (PARTS BY PARTS) Repair Days"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Kalvin (LKK) **15 Days**
11/8/3/8 13x5h
5 Repairer *Atta Repair photo*