

TP China
Thin Thin.

FY27712 . 2004 August.
Yamaha T1102. III CC

STN 015997

Front Fenders	2 found	75	✓
Front LH Wing Mirror	Broken	36	✓
Front LH Footrest	cut	25	✓
Side Fairing LH.	cracked	110	✓
Rear LH Footrest	cut	28	✓
Rear LH Fairing.	Reqs	125	x
Rear Box	cut	280(SN)	200(SN)
Exhaust Pipe	xHM	205	x
Exhaust Heat Shield.	Dented	75	✓
Headlamp.	xHM	76	x
Balances LH.	cut	25	✓
Meter Assy	xHM	185	x
Front Fork Assy	Best	350	✓
Front Fork Bracket	Best	178	✓
Front Fork Oil	xm	20(SN)	✓

F427715.

Steering Core and Bearings ^{Ma} 55 ✓
Headlamp Cowling Lt 78. ✓

1626
300
200

2226.00

Panel Beating.
Spray Painting.
Wiring
Towing.

~~350~~ 200
~~350~~ 200
50 30
50. ✓

list: 1035
less 10%: 9315
S-N: 200

Labor: 480
total: 1411.50 1631.50
r/s: 900 (Nett Value)
04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: