



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : TP0023/03/18
THIRD PARTY CLAIM
M/S : TIMBER AUTO LEASING
BLK 349 HOUGANG AVE 7
#12-619
SINGAPORE 530349

Page : 1/2
Date : 09/03/2018

Attn :
Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SJG6065T - TOYOTA RUSH
INSURED : TIMBER AUTO LEASING
DATE OF ACCIDENT : 07/03/2018
POLICY NO : 5091994272

ENGINE# :
CHASSIS# :

*not Accident
near
1/6 #3650/-
4 day.
9/3/18
to be ph. After
repair*

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total	
		\$	\$	\$	
Replacement of Parts					
1 front headlamp assy RH <i>holder cno 1450.10</i>	10	1515.00	1515.00	1,515.00	✓
2 front grille <i>11</i>	10	625.00	625.00	625.00	X
3 front bumper <i>To 11</i>	10	1560.00	1560.00	1,560.00	✓
4 front bumper clips <i>ner</i>	60	10.00	10.00	60.00	✓
5 front bumper side retainer L&R <i>ner/ner</i>	20	50.00	50.00	100.00	✓
6 front bumper towing hook <i>m.s</i>	10	55.00	55.00	55.00	✓
7 front bumper reinforcement <i>2</i>	10	254.00	254.00	254.00	✓
8 front grille center logo <i>m-1</i>	10	75.00	75.00	75.00	X
9 front headlamp support panel <i>2</i>	10	365.40	365.40	365.40	X
10 front fender inner cowling RH <i>To 11</i>	10	254.00	254.00	254.00	✓
11 front fender RH <i>ner/ner</i>	10	787.00	787.00	787.00	✓
12 front fog lamp RH <i>11</i>	10	525.00	525.00	525.00	X
13 front bonnet <i>2</i>	10	1375.00	1375.00	1,375.00	X
14 front bonnet sponge clips <i>ner</i>	70	10.00	10.00	70.00	✓
15 front side mirror LH <i>11</i>	10	1269.70	1269.70	1,269.70	X
16 front side mirror cover <i>11</i>	10	115.00	115.00	115.00	X
Less 25%				9,005.10	
Total Material				-2,251.28	
Labour & Misc				\$6,753.82	

- 1 Remove & install f/grille, f/headlamp, f/bumper, f/fender, cut out & renew headlamp support panel, knock f/bonnet, wheel house panel RH and restraigthen body & chassis.
- 2 Spray painting.
- 3 Check wiring system.
- 4 Towing fee.

580 700.00

800 1,000.00

25.00 ✓

60 80.00



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref : Page : 2/2
Our Ref : TP0023/03/18 Date : 09/03/2018

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
5 Reset wheel camber alignment.				80.00
				1,885.00
Total Labour				\$1,885.00
Nett Total Before Gst				\$8,638.82

Your faithfully



NPH AUTO SERVICE
(Manager)

- LPH Auto Consultants hence notify the Follower of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: