

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

Big Asia - USUM
 DATE 8/3/2018

TS

VEHICLE NO : SHA 5075B

MAKE :

LKK - Kalvin

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>X repair</i>			\$ 1,349.50
	Boot Lid Rubber <i>X</i>			\$ 110.90
	Boot Lid Lock Upper <i>X</i>			\$ 132.10
	Boot Lid Lock Lower <i>X</i>			\$ 30.30
	Boot Lid Sonata Plate <i>-</i>			\$ 43.60
	Boot Lid Hyundai Plate <i>-</i>			\$ 24.20
	Boot Lid 'H' Emblem <i>-</i>			\$ 26.10
	Boot Lid CRDI Plate <i>-</i>			\$ 22.70
	Boot Lid Lamp (LH) <i>-</i>			\$ 230.20
	Rear Bumper <i>-</i>			\$ 578.40
	Rear Bumper Reinforcement <i>-</i>			\$ 483.30
	Rear Bumper Clip <i>-</i>			\$ 22.00
	Rear Bumper Sponge <i>-</i>			\$ 137.40
	Rear Bumper Under Cover <i>X</i>			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>X repair</i>		\$ 38.00	\$ 76.00
	Tail Lamp (LH) <i>-</i>			\$ 344.00
	Rear Panel <i>X repair</i>			\$ 391.80
	Rear Panel Garnish ?			\$ 95.80
	SUB TOTAL			\$ 4,284.10
	LESS 20%			\$ 856.82
	DISCOUNTED TOTAL			\$ 3,427.28
	Boot Lid Comfort Logo & Tel No. Sticker <i>-</i>			\$ 30.00
	Boot Lid Advertisement Logo <i>-</i>			\$ 100.00
	Rear Bumper Reverse Sensor <i>X</i>			\$ 135.70
	Rear Fender Advertisement Logo (LH/RH) <i>-</i>		\$ 100.00	\$ 200.00
	<i>Rear Bumper Plate (rubl) - \$50</i>			\$ 465.70
	Labour Charge			\$ 500
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
				\$ 50.00
				\$ 120.00
	TOTAL LABOUR			\$ 1,670.00
	ESTIMATE TOTAL			\$ 5,562.98

Auto Consultants hence notify the Repairer of the following:

- To resurvey before the repair starts
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance company

Ack: _____
 Date: _____

Kalvin 11/11/14
8/3/18 1035hrs.
3 Days
4/5
After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.