

22/03/2002

A.S. RECALLY:

REF: CS/AWA18004583/ Tig03ep

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Stella Goh

of

AWAC

Date/Time:

9/3/18 @ 4:12pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKK 343Y

Insured:

SYM 9522P

at Workshop m/s

Wee Wines Automotive

Tel:

9129 4556

of

249 Alexandra Road

Policy No:

AVHWSB 0009781806

Claim No:

NSV1800135 / SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/02/2018

CA / REV / REP. / REV 24 HRS

lwp

14/03/2018 @ 10am - 12pm

H.O.D. Endorsement:

Date/Time:

4:27pm @ 9/3/18

Person Contacted:

Michelle


Vehicle IN / OUT

Date/Time	Action/Instruction	
	() Estimate	
	SKK 343Y - CCG/AXA17004666/R/pa352	D.O.A. 28/2/17
	SYM 9522P - CS/RSI13000124/Hlan	D.O.A. 30/12/12
7/3/18 @	2:23pm confirmed with Christine from fig #12957.03, 8 days.	
	called @ 6579.32, 35%.	

Taufelt

HWAC

Right Date 14/3/18
Estimated Cost
OD ☒ PWS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV
To inspect/Vehicle No SKK 343 Y
at Workshop this Wearnes Automotive
of 249 Alexandra Rd
Insured
Policy No
Claims No
Sum Insured Excess
Onsite Record 10am-12pm
Make of car Michelle



Policy Condition
Remark: The veh had commenced its repair at the time of inspection.
Sal. or Market Value 978K.
DAD Accident Report Consistent? : Yes or No
G.A. FF Seen Consistent? : Yes or No
Est. Repairs 8 days Resn. Yes or No
Lim Sum % G.Val. Yes or No
CA ☐ REV ☐ REP. ☐ 24 HRS wp
Date Person Contacted Richmond Vehicle IN/OUT

SKK 343 Y 2013 March.
Type ☒ M/D ☐ Bus ☐ Van ☐ Light ☐ Taxi ☐ Prime Mover
Truck Trailer
Make Volvo S60 1596
Colour Red A.D. Insured Std. N/A
No. Plating 77654 T-Plate Insured Std. N/A
Eng No
Ch No YV1FS4.8 HBD2201569
Gen Cond ☒ Good ☐ Fair ☐ Poor ☐ Burnt
Steering ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt or
Brake ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt or
Mod ☒ V ☐ E ☐ STD ☐ A ☐ R ☐ H ☐ or
Tyre Size 215/50R17
BS ☒ DUN ☐ EXNOVA ☐ GY ☐ FS ☐ LIZA ☐ MID ☐ CHTSU ☐ PIR ☐ SUM
TOYO ☐ YOKO ☐
Front Rear
R.Ba 6 -- R.Ba 6 --
L.Ba 6 -- L.Ba 6 --
D.O.A. 14/3/18 21150
Surveyed at Wearnes Automotive
Des or Damages ☒ Fr ☐ R ☐ OS ☐ NS ☐ UC ☐ Roofed or

Date Time Action Instructor
Inform Richmond repair Unit 916K.
RECEIVED 2 MAY 2018

Date Time File Passed ☐ Prelim. Report ☐ Final Report
27/5 14:15
Date Time File Returned
Days Of Repair 8
Resurvey No. of Trip 1
Add Feet ☐ Shear ☐ S
☐ Twist ☐ S
☐ Torsion ☐ S
☐ Residual ☐ S
Report Format TP
12957.03
250
250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA18004583/T1qd3

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 09-03-2018



Code : AWA

1. Policy Particulars - THIRD PARTY CLAIM

Insured Veh.	SJM 9522P	Veh. Inspected	SKK 343Y
Policy No.	AVHWSB0009781806	Coverage (\$)	0.00
Claim No.	NSV1800135/SG	Excess (\$)	0.00
Assign From	STELLA GOH	Assign Date	09/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	28/02/2018	Inspection Date
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Nivitha (LKK Auto)

From: Goh, Stella <stella.goh@awac.com> on behalf of Motorsurvey
<Motorsurvey@awac.com>
Sent: Friday, 9 March 2018 4:12 PM
To: 'assignments'
Cc: 'SUR'; 'Michelle Ong Siew Bee'
Subject: TP Survey assignment for SKK 343Y - DOA: 28/02/2018 Our ref: NSV1800135/SG

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us do have consensus in the appointment of **Mr Mohamad Taufikh** as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SKK 343 Y
Insured Vehicle	:	SJM 9522 P
Policy Number	:	AVHWSB0009781806
Name of Workshop	:	Wearnes Automotive Pte. Ltd.
Contact Number	:	9129 4556
Person to Contact	:	Michelle Ong
Estimated Cost of repairs	:	\$ 21,045.50

Regards,
Claims Division

Copy to Wearnes Automotive Pte. Ltd. via Email

Note -

- (X)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards
Motor Claims
Claims Group

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 22 May 2018 1:23 PM
To: Christine Yow
Cc: Admin A; SUR
Subject: RE: AWAC TP SKK343Y / SJM9522P DOA:28/02/2018

Dear Christine,

Confirm final fig \$12,957.03 before GST and 8 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAUTO)
Sent: Tuesday, 8 May 2018 5:41 PM
To: Christine Yow <christine.yow@wearnes.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: FW: AWAC TP SKK343Y / SJM9522P DOA:28/02/2018

Dear Sir / Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/AWA18004583/T1qd3	Shiau Chan

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Christine Yow [<mailto:christine.yow@wearnes.com>]
Sent: Tuesday, 8 May 2018 3:10 PM
To: Admin A <admin-a@lkkauto.com>
Cc: stella.goh@awac.com
Subject: AWAC TP SKK343Y / SJM9522P DOA:28/02/2018

Hi

We hereby attach our LOD ,original mailed out to AWAC.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1413G

Vehicle Details

Vehicle No.: SKK343Y
Vehicle to be Exported: No
Intended De-registration Date: 15 Mar 2018
Vehicle Make: VOLVO
Vehicle Model: S60 T4
Primary Colour: Red
Manufacturing Year: 2012
Engine No.: B4164T1114682
Chassis No.: YV1F548HBD2201569
Maximum Power Output: 132.0 kW (177 bhp)
Open Market Value: \$31,981.00
Original Registration Date: 25 Mar 2013
First Registration Date: 25 Mar 2013
Transfer Count: 0
Actual ARF Paid: \$31,774.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Mar 2023
PARF Rebate Amount: \$23,830.00

Intended COE Rebate Details

COE Expiry Date: 24 Mar 2023
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$74,689.00
COE Rebate Amount: \$37,525.00
Total Rebate Amount: \$61,355.00

The information contained herein is correct as at 15 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/02/2018 12:17
Date Of Accident	28/02/2018 06:55
Exact Location Of Accident	ALONG ANG MO KIO AVE 5 TOWARDS CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK343Y
Insured/Policyholder	
Name Of Registered Owner	LAI WING HOE, THOMAS LUDWIG
NRIC No	S7931413G
Email Address	TLWH79@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-90082438
Alternative Phone No	OFFICE-90082438

Vehicle Particulars

Manufacturer	VOLVO
Model	S60
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10486908
Cover Note Number	

Driver

Name of Driver	LAI WING HOE, THOMAS LUDWIG
NRIC No	S7931413G
Date Of Birth	10/10/1979
Occupation	INDOOR
Date Of Driving Pass	19/02/1999
Driving Experience	19 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90082438
Fax Number	
Contact Number	OFFICE-90082438
Email Address	TLWH79@HOTMAIL.COM

Address NA
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1
 NAME: : CLARISSA BOO
 GENDER: : FEMALE
 Passenger 2
 NAME: : OSCAR LAI
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

My car SKK0343Y was stationary along Ang mo Kio ave 5 waiting the traffic light to turn green on the 1st lane, suddenly there was a impact from my rear vehicle. Find out that the other party SJM9522P had bang onto my vehicle. We manage to exchange particular. No injuries as for now.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJM9522P
 Vehicle Make/Model/Colour HONDA/STREAM 1.8L/WHITE
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver ONE YEW YOCK
 NRIC/Passport Number S1567435J
 Contact Number 92409616
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

[illegible]

SECRET

ACCIDENT STATEMENT (2000 characters)

My car SKK0343Y was stationary along Ang mo Kio ave 5 waiting the traffic light to turn green on the 1st lane, suddenly there was a impact from my rear vehicle. Find out that the other party SJM9522P had bang onto my vehicle. We manage to exchange particular. No injuries as for now.


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD SUMARDI BIN MOHD AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

28 February 2018 11:12 am

Date/Time:

28 February 2018 11:12 am

SERVICE ESTIMATE

73306 - C00001 SL: SERVICE SALES - PC

Mr Lai Wing Hoe, Thomas Ludwig
Blk 201A Compassvale Drive
#02-509

Singapore 541201

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 01/03/2018

WIP No. . : 47825

Veh.In/Out:

*Tel.No. . : Mobile: 90082438

Reg.No. . : SKK343Y

Reg.date . : 25/03/2013

Mileage ... : 0

Chassis No: YV1FS48HBD2201569

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Lai Wing Hoe, Tho

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
						3200 ✓	
802	TO REPLACE REAR BOOT LID, REAR EMBLEM, REAR BUMPER, REAR BRACKET, REAR LOWER SPOILER, REAR SENSOR, REAR END PANEL, ETC	0	4000.00	0		4,000.00 S	
800	TO PUTTY SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR END PANEL, ETC	0	2800.00	0		2,800.00 S	
802	TO TRANSFER REAR BOOT LID PART	0	250.00	0		250.00 S ✓	
802	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS	0	1600.00	0		1,600.00 S 1200 ✓	
R06	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER	0	60.00	0		60.00 S X M	
280	TO CHECK WIRING INCLUDE RESETING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00 S ✓	
	BUMPER COVER REAR S6	1.0 EA	1428.70	1285.83		1,428.70 S de	
	TOW COVER REAR S60 1	1.0 EA	73.90	66.51		73.90 S de	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Tan Jia 77195749
wp
14/3/18 @ 1150
Resurvey before paint
8 days.
sun @ lkkauto.com.
15/3/18

SERVICE ESTIMATE

73306 - C00001 SL: SERVICE SALES - PC

Mr Lai Wing Hoe, Thomas Ludwig

Blk 201A Compassvale Drive

#02-509

Singapore 541201

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 01/03/2018

WIP No. . : 47825

Veh.In/Out:

*Tel.No. . : Mobile: 90082438

Reg.No. . : SKK343Y

Reg.date. : 25/03/2013

Mileage . : 0

Chassis No: YV1FS48HBD2201569

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Lai Wing Hoe, Tho

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER BRACKET CTR R	1.0 EA	88.70	79.83		88.70	S nei
	BUMPER SPOILER REAR	1.0 EA	486.40	437.76		486.40	S de
	BUMPER SPOILER BRACK	2.0 EA	16.60	29.88		33.20	S nei
	BUMPER BRACKET LHR S	1.0 EA	54.30	48.87		54.30	S nei
	BUMPER BRACKET RHR S	1.0 EA	54.30	48.87		54.30	S nei
	BUMPER BRACKET LHR S	1.0 EA	54.30	48.87		54.30	S nei
	BUMPER BRACKET RHR S	1.0 EA	54.30	48.87		54.30	S nei
	BUMPER RAIL (BEAM) R	1.0 EA	1277.20			1,277.20	S ? X mm
	REAR BOOT S60 11-	1.0 EA	2300.80	2070.72		2,300.80	S bt
	BOOT HINGE LH S60 11	1.0 EA	185.50			185.50	S ? 3 mm
	BOOT HINGE RH S60 11	1.0 EA	185.50			185.50	S ? 3 mm
	BOOT SILL MOULDING S	1.0 EA	283.90	255.51		283.90	S cut
	BOOT HINGE COVER OUT	1.0 EA	51.20			51.20	S X
	BOOT HINGE COVER OUT	1.0 EA	51.20			51.20	S X
	BOOT HINGE COVER INN	1.0 EA	51.20			51.20	S X
	BOOT HINGE COVER INN	1.0 EA	51.20			51.20	S X
	CLIP LUGG COMP S80 0	10.0 EA	4.80	43.70		48.00	S nei

SERVICE ESTIMATE

73306 - C00001 SL: SERVICE SALES - PC

Mr Lai Wing Hoe, Thomas Ludwig

Blk 201A Compassvale Drive

#02-509

Singapore 541201

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 3

Inv.date. : 01/03/2018

WIP No. . : 47825

Veh.In/Out:

*Tel.No. . : Mobile: 90082438

Reg.No. . : SKK343Y

Reg.date. : 25/03/2013

Mileage . : 0

Chassis No: YV1FS48HBD2201569

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Lai Wing Hoe, Tho

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	BOOT LOCK COVER S60	1.0 EA	3.20	2.88 /		3.20	Sant
	BOOT LOCK S60 CH -20	1.0 EA	430.70			430.70	S ? Xnn
	EMBLEM 'VOLVO' REAR	1.0 EA	92.00	82.80 /		92.00	Sue
	EMBLEM 'S60' CH 1700	1.0 EA	84.00	75.60 /		84.00	Sue
	EMBLEM 'T4' S80 S60	1.0 EA	84.00	75.60 /		84.00	Sue
	TAILLAMP LH S60 11-	1.0 EA	387.40			387.40	S ? } pny
	TAILLAMP RH S60 11-	1.0 EA	387.40			387.40	S ? }
	BLIND RIVET 4.0*21MM	10.0 EA	3.00	27 /		30.00	Sue
	BUMPER CLIP	10.0 EA	4.80	43.20 /		48.00	Sue
	BUMPER EXPANSION PLU	10.0 EA	3.30	29.70 /		33.00	Sue
	BUMPER INSTALLING MT	1.0 EA	83.40	75.60 /		83.40	Sue
	D PAINT SEALANT	1.0 EA	500.20	450.18 /		500.20	Sue
	D ADHESIVE CHEMICA	1.0 EA	303.20	272.88 /		303.20	Sue
	PARKING AID KIT S60	1.0 EA	1228.40			1,228.40	S ? Xma

Gross Total. 19,668.70

Labour Total	9,160.00
Parts Total	10,508.70
Package Total	0.00

Net.....	19,668.70
GST @ 7.0%	1,376.81
Total.....	21,045.50
Paid.....	0.00
Please Pay..	21,045.50

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

19,836.25

19,826.11

Supplementary List

SERVICE ESTIMATE

0 - R00003 SL: ALLIED WORLD ASSURANCE COMPANY LTD
ALLIED WORLD ASSURANCE COMPANY LTD GST Reg.No:M28920628X
60 ANSON ROAD #09-01 Inv.No. : B&P 0 Page 1
MAPLETREE ANSON Inv.date. : 22/03/2018
SINGAPORE 079914 WIP No. : 47825
Veh.In/Out: 14/03/2018 22/03/2018

Closed by : Michelle Ong Siew Be
Svc Consultant : ACC *Tel.No. : 64230888
Remarks : Mr Lai Wing Hoe, Tho Reg.No. : SKK343Y
Reg.date. : 25/03/2013
Mileage .. : 77,654
Chassis No: YV1FS48HBD2201569

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BOOT SEAL S60 11-	1.0 EA	72.50	10		65.25	S
	BOOT HINGE COVER OUT	1.0 EA	51.20	46.68		51.20	S
	BOOT HINGE COVER INN	1.0 EA	51.20	46.68		51.20	S

		Gross Total.	167.65
Labour Total	0.00	Net.....	167.65
Parts Total	167.65	GST @ 7.0%	11.74
Package Total	0.00	Total.....	179.39
		Paid.....	0.00
		Please Pay..	179.39

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - R00003 SL: ALLIED WORLD ASSURANCE COMPANY LTD
 ALLIED WORLD ASSURANCE COMPANY LTD GST Reg.No:M28920628X
 60 ANSON ROAD #09-01 Inv.No. . : B&P 0 Page 1
 MAPLETREE ANSON Inv.date. : 22/03/2018
 SINGAPORE 079914 WIP No. . : 47825
 Veh.In/Out: 14/03/2018 22/03/2018
 *Tel.No. . : 64230888
 Reg.No. . : SKK343Y
 Closed by : Michelle Ong Siew Be Reg.date .: 25/03/2013
 Svc Consultant : ACC Mileage ..: 77,654
 Remarks : Mr Lai Wing Hoe, Tho Chassis No: YV1FS48HBD2201569

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BOOT LID,REAR EMBLEM,REAR BUMPER,REAR BRACKET, REAR LOWER SPOILER,REAR SENSOR, REAR END PANEL,ETC	0	3200.00	0		3,200.00	S
800	TO PUTTY SPRAY PAINT ON REAR BOOT LID,REAR BUMPER,REAR END PANEL,ETC	0	2100.00	0		2,100.00	S
802	TO TRANSFER REAR BOOT LID PART	0	250.00	0		250.00	S
802	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS	0	1200.00	0		1,200.00	S
280	TO CHECK WIRING INCLUDE RESETTNG OF ALL ELECTRICAL MODULES	0	450.00	0		450.00	S
①	BUMPER COVER REAR S6	1.0 EA	1428.70	10		1,285.83	S
②	TOW COVER REAR S60 1	1.0 EA	73.90	10		66.51	S
③	BUMPER BRACKET CTR R	1.0 EA	88.70	10		79.83	S
④	BUMPER SPOILER REAR	1.0 EA	486.40	10		437.76	S



LKK

SERVICE TAX INVOICE

O - R00003 SL: ALLIED WORLD ASSURANCE COMPANY LTD
ALLIED WORLD ASSURANCE COMPANY LTD GST Reg.No:M28920628X
60 ANSON ROAD #09-01 Inv.No. : B&P 7013377 Page 2
MAPLETREE ANSON Inv.date. : 26/04/2018
SINGAPORE 079914 WIP No. : 47825
Veh.In/Out: 14/03/2018 22/03/2018

Closed by : Michelle Ong Siew Be
Svc Consultant : ACC
Remarks : Mr Lai Wing Hoe, Tho

*Tel.No. : 64230888
Reg.No. : SKK343Y
Reg.date. : 25/03/2013
Mileage : 77,654
Chassis No: YV1FS48HBD2201569

Parts/Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
030657220	BUMPER SPOILER BRACK	2.0	EA	16.60	10		29.88	S
030795054	BUMPER BRACKET LHR S	1.0	EA	54.30	10		48.87	S
030795055	BUMPER BRACKET RHR S	1.0	EA	54.30	10		48.87	S
031407892	BUMPER BRACKET LHR S	1.0	EA	54.30	10		48.87	S
031407893	BUMPER BRACKET RHR S	1.0	EA	54.30	10		48.87	S
031395582	REAR BOOT S60 11-	1.0	EA	2300.80	10		2,070.72	S
031307102	BOOT SILL MOULDING S	1.0	EA	283.90	10		255.51	S
030715711	CLIP LUGG COMP S80 O	10.0	EA	4.80	10		43.20	S
031391243	BOOT LOCK COVER S60	1.0	EA	3.20	10		2.88	S
030796589	EMBLEM 'VOLVO' REAR	1.0	EA	92.00	10		82.80	S
031333641	EMBLEM 'S60' CH 1700	1.0	EA	84.00	10		75.60	S
031333648	EMBLEM 'T4' S80 S60	1.0	EA	84.00	10		75.60	S
000979878	BLIND RIVET 4.0*21MM	10.0	EA	3.00	10		27.00	S
003541113	BUMPER CLIP	10.0	EA	4.80	10		43.20	S
003533394	BUMPER EXPANSION PLU	10.0	EA	3.30	10		29.70	S
031335404	BOOT SEAL S60 11-	1.0	EA	72.50	10		65.25	S
031306890	BOOT HINGE COVER OUT	1.0	EA	51.20	10		46.08	S



SERVICE TAX INVOICE

0 - R00003 SL: ALLIED WORLD ASSURANCE COMPANY LTD
ALLIED WORLD ASSURANCE COMPANY LTD GST Reg.No:M28920628X
60 ANSON ROAD #09-01 Inv.No. : B&P 7013377 Page 3
MAPLETREE ANSON Inv.date. : 26/04/2018
SINGAPORE 079914 WIP No. : 47825
Veh.In/Out: 14/03/2018 22/03/2018

Closed by : Michelle Ong Siew Be
Svc Consultant : ACC
Remarks : Mr Lai Wing Hoe, Tho

*Tel.No. : 64230888
Reg.No. : SKK343Y
Reg.date. : 25/03/2013
Mileage : 77,654
Chassis No: YV1FS48HBD2201569

Parts/Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
031306891	BOOT HINGE COVER INN	1.0	EA	51.20	10		46.08	S
031335993	*D* PAINT SEALANT	1.0	EA	500.20	10		450.18	S
V31670171	ADHESIVE TUBE CHEMIC	4.0	EA	75.80	10		272.88	S
009154605	BUMPER INSTALLING MT	1.0	EA	83.40	10		75.06	S

				Gross Total.	12,957.03
Labour Total	7,200.00	Net.....		12,957.03	
Parts Total	5,757.03	GST @ 7.0%		906.99	
Package Total	0.00	Total.....		13,864.02	
				Paid.....	0.00
				Please Pay..	13,864.02

GST: S=StdRated; O=OutOfScope; Z=ZeroRated
Enquiries must be lodged within 14 days from the invoice date
This is a computer generated invoice. No signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA18004583/T1qd3e2

(SINGAPORE BRANCH)

60 ANSON ROAD #08-01 (8th FLOOR)

MAPLETREE ANSON

SINGAPORE 079914

Date : 25-05-2018



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJM 9522P	Veh. Inspected	SKK 343Y
Policy No.	AVHWSB0009781806	Coverage (\$)	0.00
Claim No.	NSV1800135/SG	Excess (\$)	0.00
Assign From	STELLA GOH	Assign Date	09/03/2018

2. Vehicle Particulars & Condition

Make & Model	VOLVO S60	c.c	1596
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	YV1FS48HBD2201569	Colour	RED
Odometer	77654	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/50 R17	TOYO	6 mm
L/H Front Tyre	215/50 R17	TOYO	6 mm
R/H Rear Tyre	215/50 R17	TOYO	6 mm
L/H Rear Tyre	215/50 R17	TOYO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/02/2018	Inspection Date	14/03/2018
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 343Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR S6 (SN)	DEFORMED	1,428.70	1,285.83
1	TOW COVER REAR S60 1 (SN)	DEFORMED	73.90	66.51
1	BUMPER BRACKET CTR R (SN)	NECESSARY	88.70	79.83
1	BUMPER SPOILER REAR (SN)	DEFORMED	486.40	437.76
2	REAR BUMPER SPOILER BRACK @\$16.60 (SN)	NECESSARY	33.20	29.88
1	BUMPER BRACKET LHR S (SN)	NECESSARY	54.30	48.87
1	BUMPER BRACKET RHR S (SN)	NECESSARY	54.30	48.87
1	BUMPER BRACKET LHR S (SN)	NECESSARY	54.30	48.87
1	BUMPER BRACKET RHR S (SN)	NECESSARY	54.30	48.87
1	BUMPER RAIL (BEAM) R (SN)	NOT NECESSARY	1,277.20	-
1	REAR BOOT S60 11- (SN)	BENT	2,300.80	2,070.72
1	BOOT HINGE LH S60 11 (SN)	NOT NECESSARY	185.50	-
1	BOOT HINGE RH S60 11 (SN)	NOT NECESSARY	185.50	-
1	BOOT SILL MOULDING S (SN)	CUT	283.90	255.51
1	BOOT HINGE COVER OUT (SN)	NOT NECESSARY	51.20	-
1	BOOT HINGE COVER OUT (SN)	NOT NECESSARY	51.20	-
1	BOOT HINGE COVER INN (SN)	NOT NECESSARY	51.20	-
1	BOOT HINGE COVER INN (SN)	NOT NECESSARY	51.20	-
10	CLIP LUGG COMP S80 0 @\$4.80 (SN)	NECESSARY	48.00	43.20
1	BOOT LOCK COVER S60 (SN)	CUT	3.20	2.88
1	BOOT LOCK S60 CH -20 (SN)	NOT NECESSARY	430.70	-
1	EMBLEM 'VOLVO' REAR (SN)	NECESSARY	92.00	82.80
1	EMBLEM 'S60' CH 1700 (SN)	NECESSARY	84.00	75.60
1	EMBLEM 'T4' S80 S60 (SN)	NECESSARY	84.00	75.60
1	TAILLAMP LH S60 11- (SN)	NOT NECESSARY	387.40	-
1	TAILLAMP RH S60 11- (SN)	NOT NECESSARY	387.40	-
10	BLIND RIVET 4.0*21MM @\$3.00 (SN)	NECESSARY	30.00	27.00
10	BUMPER CLIP @\$4.80 (SN)	NECESSARY	48.00	43.20
10	BUMPER EXPANSION PLU @\$3.30 (SN)	NECESSARY	33.00	29.70
1	BUMPER INSTALLING MT (SN)	NECESSARY	83.40	75.06
1	*D* PAINT SEALANT (SN)	NECESSARY	500.20	450.18
1	*D* ADHESIVE CHEMICA (SN)	NECESSARY	303.20	272.88
1	PARKING AID KIT S60 (SN)	NOT NECESSARY	1,228.40	-
1	BOOT SEAL S60 11- (SN) (ADDITIONAL)	CUT	65.25	65.25

Report Ref No. CS/AWA18004583/T1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT HINGE COVER OUT (SN) (ADDITIONAL)	CUT	46.08	46.08
1	BOOT HINGE COVER INN (SN) (ADDITIONAL)	CUT	46.08	46.08
			10,666.11	5,757.03
	LABOUR			
	TO REPLACE REAR BOOT LID, REAR EMBLEM, REAR BUMPER, REAR BRACKET, REAR LOWER SPOILER, REAR SENSOR, REAR END PANEL, ETC.		4,000.00	3,200.00
	TO PUTTY AND SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR END PANEL, ETC.		2,800.00	2,100.00
	TO TRANSFER REAR BOOT LID PART.		250.00	250.00
	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS.		1,600.00	1,200.00
	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER.	NOT NECESSARY	60.00	-
	TO CHECK WIRING INCLUDE RESETING OF ALL ELECTRICAL MODULES.		450.00	450.00
			9,160.00	7,200.00
	GRAND TOTAL		19,826.11	12,957.03

RECOMMENDED COST OF REPAIRS			12,957.03
------------------------------------	--	--	------------------

Report Ref No. CS/AWA18004583/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appralser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.