

AxA

$$T_z$$

DATE 3/10/2018 9:51

MAKE :

MODEL : HYUNDAI i40

LEFT FRONT

PP

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door (LH) X repair			\$ 1,403.05
	Front Door Mirror (LH) —			\$ 980.50
	Front and Rear Wheel Hup-Cap (LH/RH) —		\$ 150.70	\$ 301.40
	Front Fender (LH) —			\$ 618.95
	Front Fender Shield (LH) X			\$ 89.80
	Rear Door (LH) X repair			
	Rear Fender (LH) X repair			
	Rear Bumper (LH) X repair			
	SUB TOTAL			\$ 3,393.70
	LESS 20%			\$ 678.74
	DISCOUNTED TOTAL			\$ 2,714.96
	Rear Bumper Rubber Mat X			\$ 50.00
	Rear Door Tel No. Sticker (LH/RH) —			\$ 10.00
	Front Door Coloured Comfort Logo (LH) —			\$ 75.00
	Front Door Advertisement Logo (LH) —			\$ 100.00
				\$ 235.00
	Labour Charge			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 1,200.00
	Wiring Charge			\$ 30.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Transfer of Door			\$ 120.00
	Four Wheel Alignment			\$ 120.00
	TOTAL LABOUR			\$ 2,840.00
	ESTIMATE TOTAL			\$ 5,789.96
	Kokila CKK 12/3/8 145hrs 3 Dgs PIP Before Paint & Lh			
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				