

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
 SINGAPORE 486443
 TEL: 65446676 / 65446689 FAX: 62141511
 CO. REG:200707743D GST REG:200707743D

9-Mar-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8895 B

1 pc	Front n/s fender X	\$	384.00
1 pc	Front n/s door glass /	\$	322.00
1 pc	Front n/s door /	\$	765.00
2 pcs	Front n/s door hinges @ \$34.00 X	\$	68.00
1 pc	Front n/s door outer moulding /	\$	73.00
1 pc	n/s mirror assy /	\$	590.00
		\$	<u>2,202.00</u>
	Less 10%	\$	220.20
		\$	<u>1,981.80</u>

S/NETT

1 pc	Front n/s fender sticker	\$	30.00 X
1 set	n/s door sticker	\$	100.00 /
	Sundry	\$	50.00 20
	To dismantle and refit new n/s door window glass to front n/s door	\$	150.00 20
	To dismantle and refit the inner component of front n/s door into new shell door	\$	150.00 50
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same	\$	800.00 200
	To putty and spray painting on front n/s fender, front n/s door, n/s side mirror X	\$	600.00 250
	To apply rustproofing on the repaired and replaced panels.	\$	200.00 50
		\$	<u>4,061.80</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin 2/11/18
9/3/18 @ 1500
2 Day
4/5
After Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modifications is allowed
- Sup: every item must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____