

22/03/2002

ASS. REC. BY:

REF: CS/MSG1800-1624 / Utd3ⁿ²

Special Instruction:

Surveyor:
Mentmen

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSG

Date/Time:

12/3/18 @ 11:40am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJL 2070C

Insured:

SGL 5903R

at Workshop m/s

Abwin Service

Tel:

6713 9400

of

No. 8 Kaki Bkt Ave 4 #07-18 premier

Policy No:

27767071 QMX

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/3/2018

13/03/2018

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

11:51am 12/3/18

Person Contacted:

Linda

Vehicle IN / OUT

Date/Time

Action/Instruction

(Estimate

SJL 2070C - CC6 / ALG 15013319 / Uha3s2

D.O.A: 5/8/15

SGL 5903R - CS3 / MSG 17006069 / Sqbe2-1

D.O.A: 26/3/17

Date: 13/3/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJL 2070C

at Workshop/mis: Abwin Service

at: No. 8 kaki Bkt Ave 4 # 07-48

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

Client's Record:

Make of car:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NS	O/S

Salvage/Market Value: \$16500

DAC Accident Report: Consistent? : Yes or No

PP Seen: 2 Consistent? : Yes or No

Est. Repairs: 5 days Repair: Yes or No

Lift Sum: 20 % 3 Val: Yes or No

CA / REV / REP / 24 HRS: up

Date: Person Contacted: Vehicle IN / OUT

SJL 2070C

11 08

Truck Trailer: CA /

Make: Honda Civic

Year: 1998

Colour: Grey

Engine No: 112 422

Chassis No: JHMFD264085201504

Gen. Con: Good Fair Poor Burnt

Steering: Good Limited Leaked Burnt

Brake: Good Limited Leaked Burnt

Mod: Nil

Type Size: 205/55R16

BS / DUN / EXNOVA / GY / RS / LIZA / MIC / OHTSU / PIR / SUM / TOYO / YOKO or: Continental

Front: 6 Rear: 6

LBa: 6

D.O.A: 10/3/18

Surveyed at: 13/3/18

Des of Damages: Frt. Rear: Rear

The U.C. Chassis frame Body Structure affected due to collision

174 11963 net 4537

27/3/18 Confirmed L/S \$2900 w/le 1 ven. (Red: 1805.66 : 3872)

RECEIVED 27 MAR 2018

Date/Time File/Pass id:

24/3 Typist

Date/Time File/Pass id:

TP

Sum: 2900/-

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

200

10

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt.	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018		12 Mar 2018 11:40 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Lim Pang Guan @ Seet Lin Nguan, ID: S12060001		
Main Claimant:	Sundar Veeramani, ID: G6004501T		
Vehicle Reg. No.:	SJL2070C	Date of Loss:	10/03/2018 07:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	27767071QMX Coverage: 22/09/2017 - 21/09/2018
Vehicle Reg. No. (Insured):	SGL5903R	Policy No. (Claimant):	
		Excess:	
Repairer:	Abwin Service Pte Ltd (HQ) No. 8 Kaki Bukit Avenue 4, #07-48 Premier@Kaki Bukit Gate 2, 415875 Kaki Bukit - Tel: 6713 9400		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/03/2018]		
Adj Asg. Remarks:	Car in, please survey. Thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nabilah Rasol

From: Monica Chung
Sent: Monday, 12 March, 2018 9:01 AM
To: Nabilah Rasol
Cc: ivanteo@abwin.com.sg; Katherine Wong
Subject: FW: ARRANGE FOR 3RD PARTY SURVEY SJL2070C AGAINST SGL5903R DOA 10/03/2018
Attachments: Estimation.pdf; InvoiceSEARCH.pdf; SAS2371897.PDF
Follow Up Flag: Follow up
Flag Status: Flagged

Dear Nabilah,

FYA.

Regards,

Monica Chung
Assistant Executive, Claims Services (Motor)
Direct line +65 6594 2552 | Direct fax +65 6225 7402 | monica_chung@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on



A member of **MS&AD** INSURANCE GROUP

From: Ivan Teo [mailto:ivanteo@abwin.com.sg]
Sent: Monday, March 12, 2018 8:43 AM
To: Claims <claims@sg.msig-asia.com>; Monica Chung <Monica_Chung@sg.msig-asia.com>
Subject: ARRANGE FOR 3RD PARTY SURVEY SJL2070C AGAINST SGL5903R DOA 10/03/2018

Dear Monica,

Kindly arrange for 3rd party survey.
My client : SJL2070C
Your insured : SGL5903R
Vehicle In

Thank you.

Best Regards,

ABWIN 安穩

Abwin Service Pte Ltd
No. 8 Kaki Bukit Avenue 4
#07-48 Premier@Kaki Bukit Gate 2
Singapore 415875

Ivan Teo

Motor Claim Executive

DID +65 6713 9416 / 86680608

T +65 6713 9400 | F +65 6713 9415

[Website](#) | [Facebook](#) | [LinkedIn](#)

Looking to start a new business soon? Find out how we can provide you with a complete vehicle ownership solution and much more!

Click [here](#) to view our listing >>



CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18004624/Utd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 12-03-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGL 5903R	Veh. Inspected	SJL 2070C
Policy No.	27767071QMX	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	12/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/03/2018	Inspection Date
Survey held at	ABWIN SERVICE PTE LTD No. 8 KAKI BUKIT AVENUE 4 #07-48 PREMIER@KAKI BUKIT GATE SINGAPORE 415875	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

not found
2/5 to 2900/2
SGL
13/3/18
Liang Ph. Atherayon.

ABWIN 諭輝

IVAN TEO
ABWIN SERVICE PTE LTD
DID: 67139416
Fax: 67139415
HP: 86680608

Date : 12/03/2018
TP Vehicle No. : SGL-5903-R
To : **MSIG INSURANCE (SINGAPORE) PTE LTD**
Attn : **Motor Claim Department**
Owner : SUNDAR VEERAMANI
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5088162337
Vehicle No. : SJL-2070-C
Make & Model : HONDA CIVIC SI 2.0 (A)

Accident Date: 10/03/2018

PARF/COE Rebate Enquiry

Page 1 of 2

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	4501T
Vehicle Details	
Vehicle No.:	SJL2070C
Vehicle to be Exported:	No
Intended De-registration Date:	13 Mar 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 2.0L A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	K20Z23501505
Chassis No.:	JHMF26408S201504
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$22,802.00
Original Registration Date:	18 Nov 2008
First Registration Date:	18 Nov 2008
Transfer Count:	2
Actual ARF Paid:	\$22,802.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Nov 2018
PARF Rebate Amount:	\$11,401.00
Intended COE Rebate Details	

IVAN TEO
ABWIN SERVICE PTE LTD
DID: 67139416
Fax: 67139415
HP: 86680608

Date : 12/03/2018
TP Vehicle No. : SGL-5903-R
To : **MSIG INSURANCE (SINGAPORE) PTE LTD**
Attn : **Motor Claim Department**

Owner : SUNDAR VEERAMANI
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5088162337
Vehicle No. : SJL-2070-C
Make & Model : HONDA CIVIC SI 2.0 (A)

Accident Date: 10/03/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	Sub Total	\$4,705.68	3643.76
	GST 7%	\$329.40	
	Total	\$5,035.08	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental work(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004624/UTD3N2

Date: 28/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27767071QMX
Claimant Vehicle No :	SJL2070C	Insured Vehicle No :	SGL5903R
Date of Loss:	10/03/2018	Nature of Claim:	TP
		Claim No:	552065

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL2070C	Engine No:	K20Z23501505
Make & Model:	HONDA CIVIC, 2.0 L (A)	Chassis No:	JHMF26408S201504
Reg. Date:	18/11/2008 (Man. Year: 2008)	Odometer:	112422 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,405.68	1,963.76	441.92	18.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,680.00	620.00	26.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,705.68	3,643.76	1,061.92	22.57
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	4,705.68	2,900.00	1,805.68	38.37
+ GST 7.00/7.00% (S\$)	329.40	203.00	126.40	38.37
Nett Amount (S\$)	5,035.08	3,103.00	1,932.08	38.37

INSPECTION

Date of Assignment: 12/03/2018
Date Inspected: 13/03/2018 Inspected At:

Abwin Service Pte Ltd (HQ)
No. 8 Kaki Bukit Avenue 4, #07-48
Premier@Kaki Bukit Gate 2
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Mar 2018)
Parts:	143	HONDA CIVIC 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL2070C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented/Buckled	610.70 FL	*610.70 FL
2	1		*BOOTLID LOCK	Twisted	194.50 FL	*194.50 FL
3	1		*EMBLEM LOGO	Necessary	25.70 FL	*25.70 FL
4	1		*EMBLEM CIVIC	Necessary	29.10 FL	*29.10 FL
5	1		*EMBLEM 2.0	Necessary	29.50 FL	*29.50 FL
6	1		*EMBLEM I-VTEC	Necessary	34.10 FL	*34.10 FL
7	1		*WEATHER STRIP	Twisted	97.60 FL	*97.60 FL
8	1		*REAR BUMPER	Dented	638.00 FL	*638.00 FL
9	1		*REAR BUMPER SIDE RETAINER RH	Bent	25.00 FL	*25.00 FL
10	1		*REAR BUMPER SIDE RETAINER LH	Bent	25.00 FL	*25.00 FL
11	1		*END PANEL	Badly Dented	300.50 FL	*300.50 FL
12	1		*END PANEL TOP GARNISH	Twisted	85.00 FL	*85.00 FL
13	1		*TAILLAMP RH	Not Necessary	226.20 FL	*- FL
14	1		*TAILLAMP LH	Not Necessary	226.20 FL	*- FL
15	10		*REAR BUMPER CLIPS	Necessary	38.00 FS	*38.00 FS
16	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
17	1		*END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,915.10	2,382.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	509.42	418.94
Total Parts (\$\$)	2,405.68	1,963.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO FACILITATE REPAIR	New	1,200.00	700.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	900.00
3	TO RUST PROOF AFFECTED AREA	New	100.00	80.00
Gross Labour Cost (\$\$)			2,300.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >