

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 4346X

DATE 8/3/2018 14:45

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X repair</i>			\$ 562.30
	Front Bumper Bracket Top (LH) <i>X</i>			\$ 22.40
	Front Bumper Retainer Mounting <i>X</i>			\$ 9.20
	<i>Front Fender (LH) X repair</i>			
	SUB TOTAL			\$ 593.90
	LESS 20%			\$ 118.78
	DISCOUNTED TOTAL			\$ 475.12
	Labour Charge			
	Panel Beating			\$ 550.00 <i>300</i>
	Spray Painting Charge			\$ 400.00 <i>360</i>
	Tuff Kote			\$ 50.00 <i>X</i>
	TOTAL LABOUR			\$ 1,000.00
	ESTIMATE TOTAL			\$ 1,475.12
	<i>Kahz (11/11/18)</i>			
	<i>1/3/18 10.10 AM</i>			
	<i>2 R-7s</i>			
	<i>4s</i>			
	<i>After Repair p/h</i>			

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey if required spray painting
- To display damaged area during resurvey
- Parts prices subject to quotation
- Third party surveys on a "Without Prejudice" basis
- To illegal modification and
- Supplementary work to be surveyed and
- Subject to final approval by insurance Company

Acknowledged by Repairer

Signature:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.