

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 7075M

DATE 9/3/2018 16:26

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid / <i>Pat</i>			\$ 1,349.50
	Boot Lid Rubber <i>X see</i>			\$ 110.90
	Boot Lid Lock Upper <i>X see</i>			\$ 132.10
	Boot Lid Lock Lower <i>X see</i>			\$ 30.30
	Boot Lid Sonata Plate <i>- see</i>			\$ 43.60
	Boot Lid Hyundai Plate <i>- see</i>			\$ 24.20
	Boot Lid 'H' Emblem <i>- see</i>			\$ 26.10
	Boot Lid CRDI Plate <i>- see</i>			\$ 22.70
	Boot Lid Trimboard <i>X see</i>			\$ 165.40
	Boot Lid Trimboard Clips (10pcs) <i>X see</i>			\$ 10.00
	Rear Bumper <i>- Pat</i>			\$ 578.40
	Rear Bumper Reinforcement <i>- see</i>			\$ 483.30
	Rear Bumper Clip <i>- see</i>			\$ 22.00
	Rear Bumper Sponge <i>- see</i>			\$ 137.40
	Rear Bumper Under Cover <i>X see</i>			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>X see</i>	\$	38.00	\$ 76.00
	Tail Lamp (LH/RH) <i>X see</i>	\$	344.00	\$ 688.00
	Rear Panel <i>X repair</i>			\$ 391.80
	Rear Panel Garnish <i>X see</i>			\$ 95.80
<b>SUB TOTAL</b>				<b>\$ 4,573.30</b>
<b>LESS 20%</b>				<b>\$ 914.66</b>
<b>DISCOUNTED TOTAL</b>				<b>\$ 3,658.64</b>
	Boot Lid Comfort Logo & Tel No. Sticker <i>- see</i>			\$ 30.00 <b>Nett</b>
	Boot Lid Advertisement Logo <i>- see</i>			\$ 100.00 <b>Nett</b>
	Rear Bumper Reverse Sensor <i>- still</i>			\$ 135.70 <b>Nett</b>
	Rear Bumper Advertisement Logo <i>- see</i>			\$ 50.00 <b>Nett</b>
	Rear Fender Advertisement Logo (LH/RH) <i>- see</i>	\$	100.00	\$ 200.00 <b>Nett</b>
				<b>\$ 515.70</b>
	<b>Labour Charge</b>			
	Panel Beating <i>Kalin 11/10/18</i>			\$ <del>850.00</del> <i>500</i>
	Spray Painting Charge <i>9/3/18 16:40hr</i>			\$ <del>600.00</del> <i>540</i>
	Wiring Charge <i>3 days</i>			\$ <del>50.00</del> <i>X 20</i>
				\$ <del>50.00</del> <i>20</i>
				\$ <del>120.00</del> <i>20</i>
<b>TOTAL LABOUR</b>				<b>\$ 1,670.00</b>
<b>ESTIMATE TOTAL</b>				<b>\$ 5,844.34</b>

**Diff Koto consultants** hence notify the Repairer of the following:  
 • Remove/Refix Reverse Sensor  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

*Kalin 11/10/18*  
*9/3/18 16:40hr*  
*3 days*  
*4/5*  
*After Repair photo*