

**Hoe Heng RICAS Private Limited**

50 Gul Crescent Singapore 629543

Tel: 6352 5566

Fax: 6352 6565

Website: www.hoeheng.com.sg

Biz Reg: 201626658W
GST Reg No: 201626658W

PAGE : 1 of 1

ESTIMATE : HHRACQT18-000006**DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD**

88 SOUTH BRIDGE ROAD

SINGAPORE 058716

Contact No : 6665 5555

Fax :

Attn :

Date : 23/02/2018

Validity :

Terms : C.O.D.

Vehicle No. : SBT5H

Model / Make : LEXUS GS350-3.5 (A)

Subject : Repair Quotation

S/N	Descriptions	Unit Price	Qty	Disc	Amount
1.	Front Left Hand Door	770.0000	1	Rp	770.00
2.	Rear Left Hand Door	770.0000	1	btw	770.00
3.	Wheel Hub (Rear Tyre Rim)	336.0000	1	etc	336.00
4.	Labour: - To remove all the damaged parts and attachment - To welding and panel beating left hand side body, realignment and make good the condition - To transfer all the accessories to the new door	650.0000	1	500	650.00
5.	To Re-Connect And Check Wiring	180.0000	1	40	180.00
6.	Spray Painting On Affected Areas	750.0000	1	7650	750.00

SINGAPORE DOLLAR THREE THOUSAND SIX HUNDRED NINETY SEVEN AND CENTS
NINETY TWO ONLY

Sub-Total : S\$ 3,456.00

GST 7% : S\$ 241.92

Grand Total : S\$ 3,697.92

Remarks :

The above estimates was from a visual inspection only and it is possible that further labor, parts replacement and materials may be required once we commence repair. However, should this happens, we will advise you accordingly.

Thank you.

Jeslyn Chew
Group Procurement**Notes:**

Schedule / Estimated Repair Duration may be advised upon order confirmation.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be approved and is subject to final approval E & O. Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorised Signatory / Company's Stamp / Date

Tanpin 27495744
-wp
12/3/18 @ 1450
5 days
Lumpsum
Resurvey after repair.
sur @ (Kuantan) on