

**Hoe Heng RICAS Private Limited**

50 Gul Crescent Singapore 629543

Tel: 6352 5566

Fax: 6352 6565

Website: www.hoeheng.com.sg

Biz Reg: 201626658W**GST Reg No: 201626658W**

PAGE : 1 of 1

ESTIMATE : HHRACQT18-000006**DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD**

88 SOUTH BRIDGE ROAD

SINGAPORE 058716

Date : 23/02/2018

Validity :

Terms : C.O.D.

Vehicle No. : SBT5H

Model / Make : LEXUS GS350-3.5 (A)

Contact No : 6665 5555

Fax :

Attn :

Subject : Repair Quotation

S/N	Descriptions	Unit Price	Qty	Disc	Amount
1.	Front Left Hand Door	770.0000	1		770.00
2.	Rear Left Hand Door	770.0000	1		770.00
3.	Wheel Hub (Rear Tyre Rim)	336.0000	1		336.00
4.	Labour: - To remove all the damaged parts and attachment - To welding and panel beating left hand side body, realignment and make good the condition - To transfer all the accessories to the new door	650.0000	1		650.00
5.	To Re-Connect And Check Wiring	180.0000	1		180.00
6.	Spray Painting On Affected Areas	750.0000	1		750.00

**SINGAPORE DOLLAR THREE THOUSAND SIX HUNDRED NINETY SEVEN AND CENTS
NINETY TWO ONLY****Sub-Total : S\$ 3,456.00****GST 7% : S\$ 241.92****Grand Total : S\$ 3,697.92****Remarks :**

The above estimates was from a visual inspection only and it is possible that further labor, parts replacement and materials may be required once we commence repair.
However, should this happens, we will advise you accordingly.

Thank you.

Jeslyn Chew
Group Procurement**Authorised Signatory / Company's Stamp / Date****Notes:**

Schedule / Estimated Repair Duration may be advised upon order confirmation.

E & O.E