

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0154/18

DATE : 08-MAR-2018

AXA INSURANCE S'PORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

S(068811)

TEL : 68804741

FAX : 68804838

ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : LIM TIONG SAN

ADDRESS : BLK 620 ANG MO KIO AVE 9

#12-14

S(560620)

TELEPHONE NO : 90225755

TYPE OF CLAIM : THIRD PARTY CLAIM

POLICY NO : *

VEHICLE NO : SL01199Y

MODEL CODE : JDRNRRZT32EWA-----

MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4X4I

ENGINE NO : MR20934332B

CHASSIS NO : JN1JANT32Z0002863

MILEAGE : 17057 KM

DATE IN : 08/03/2018

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : HAMZAH

ACCIDENT DATE : 07/03/2018

-96450079

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLO1199Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR FRONT BUMPER AND RENEW FRONT OVERRIDER.	600.00	
2	ZZ/002	CHARGES TO SPORAY PAINTING SAME.	600.00	
3	ZZ/003	RENEW FRONT LICENCE PLATE.		
		TOTAL LABOUR CHARGES	1200.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLQ1199Y

		DAMAGED PARTS & PRICES			REMARKS
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	
1	SUNDRIES	NPN			70.00
2	FRT LICENCE PLATE	FLP			80.00
3	FRONT BUMPER OVERRIDER	F2060-4CE0A			1107.30
SUB TOTAL			0.00	0.00	1257.30
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			0.00	0.00	0.00
GRAND TOTAL			0.00	0.00	1257.30
OVERALL TOTAL			1257.30		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLQ1199Y

TOTAL LABOUR CHARGES	1200.00
TOTAL SPARE PARTS CHARGES	1257.30

GRAND TOTAL	2457.30 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.