

Signature: Tanpin

REF: ALH

h

ASSIGNMENT

From: _____ Date: 14/03/2018
Estimated Cost: _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SBL9P
at Workshop m/s Performance
of 303 Alexandra Rd
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: Han

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 7 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SBL9P Yr Regn: 2013, June
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: BMW 520I cc. 1997
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 60400 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WBAHG12090DX53156
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/50R17
R: 1 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 14/3/18 @ 1pm
Survey held at pml

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PIP \$ 19588.80 (Red \$ 6079.70 / 24%)

(Red: \$ 6,087.95 / 23%)

MV: \$ 4104,000.00 (est)

LTA: \$ 68,780.00 (est)

NETT: \$ 35,720.00 (est)

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

) \$ + RS \$

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18004649/hb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 12-03-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 9516C	Veh. Inspected	SBL 9P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/03/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

09 MAR 2018

E S T I M A T E

@ 6pm.

Estimate No. : b1 46165
Date Estimated : 08/03/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 3

- ESTIMATE REPAIR FOR -Foo Kuang Teck
7A Jalan Ulu Siglap

Singapore 457129

- ACCOUNT - 40000Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBL9P	DX53156	11/06/2013	520iA	0

DESCRIPTION

To replace rear bumper & attachments, boot lid, tail panel including to pull & straighten both rear chassis, to knock out trunk floor panel and dent ed area caused by the accident

solid day.

5525 ~~3400~~ 6,800.00

To respray rear bumper, boot lid, tail panel, rear right fender, rear left fender and boot compartment?

4608 ~~2255~~ 5,120.00To carry out body cavity preservation.
(Per panel).

100 118.00

To carry out body cavity preservation.
(For cut panel).451 ~~451~~ 531.00

To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.

561? 661.00

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

451 531.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 271.00

To remove and install fuse box at the rear section to facilitate repairs.

451 ~~451~~ 531.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To supply rear emboss number plate.

del 83.00

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampung Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46165
Date Estimated : 08/03/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBL9P	DX53156	11/06/2013	520ia	0

DESCRIPTION

Sundries.

VALUE

150.00

Total Labour 1: 15,150.00

DESCRIPTION

BODY NUT
TAIL END PANEL
BOOTLID
RR BUMPER BOTTOM CENTRE GUIDE
RR BUMPER CTR GUIDE
RR BUMPER LH MOUNT
RR BUMPER RH MOUNT
RR BUMPER CARRIER
RR BUMPER PANEL PRIMED (PDC)
RR BUMPER TOW HOOK COVER PRIMED
RR BUMPER ADAPTER
EMBLEM GROMMET
MODEL LETTERING 520i
BMW EMBLEM
STRIKER BOOT LID
STOP BUFFER
TRUNK LID LOCK TOP
PLUG
REAR LH BUMPER HEAT INSULATOR
LH GUTTER STRIP
RH GUTTER STRIP
REAR RIGHT COVERING
BOOTLID SEALING
(D/G) REPAIR KIT CRASH ACTIV
PLUG BLACK D=5MM
EXPANDING NUT
REAR LH REFLECTOR
REAR RH REFLECTOR
REAR LH LIGHT IN TRUNK LID
REAR RH LIGHT IN TRUNK LID
REAR LH LIGHT IN THE SIDE PANEL
REAR RH LIGHT IN THE SIDE PANEL
DECOUPLING RING PDC TORQUE CONVERTE
BUMPER PDC SENSOR (SCHWARZ)
BLIND RIVET AVIBVLB
SCREW (SF PLUS M5X15)
(DG/SL) BODY ADHESIVE K5B (195ML)
(DG) CLEANER R1 (100ML)
PUNCH RIVET N4
(S/L) SEAM SEAL 300ML

QTY

PRIC

VALUE

10	0.90	9.00
1	817.30	817.30
1	1,602.40	1,602.40
1	58.95	58.95
1	67.35	67.35
1	142.55	142.55
1	142.55	142.55
1	714.25	714.25
1	1,467.20	1,467.20
1	46.45	46.45
1	48.00	48.00
2	0.80	1.60
1	62.55	62.55
1	69.50	69.50
1	52.25	52.25
2	27.90	55.80
1	425.35	425.35
10	1.05	10.50
1	32.10	32.10
1	16.80	16.80
1	16.80	16.80
1	84.20	84.20
1	115.25	115.25
2	159.80	319.60
3	0.90	2.70
10	0.55	5.50
1	35.20	35.20
1	35.20	35.20
1	338.00	338.00
1	338.00	338.00
1	572.25	572.25
1	572.25	572.25
2	5.05	10.10
2	236.85	473.70
50	0.55	27.50
10	0.55	5.50
1	281.55	281.55
1	23.85	23.85
20	0.55	11.00
2	33.80	67.60

Total Parts : 9,210.05

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46165
Date Estimated : 08/03/2018
Prepared By : Han Kwan Yong

Page No. : 3 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBL9P	DX53156	11/06/2013	520iA	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 14/3/18 / pm Claim No. _____

Date & Time 14/3/18 / pm Excess \$S _____

Surveyor's Name Tan Jie Sign Tan Jie

Surveyor's Tel 92495449 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PLS Yes / No _____

Surveyor's E-mail Tan Jie @ lkk.com

No. of Working Days Recommended 7 days

2476A.30

Labour 1	:	15,150.00
Parts	:	9,210.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,705.20
Grand Total	:	26,065.25

25 626.25

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46165
Date Estimated : 08/03/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Foo Kuang Teck
7A Jalan Ulu Siglap

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 457129

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SBL9P	DX53156	11/06/2013	520iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	1.25	6.00		7.50 <i>re</i>
# BLIND RIVET *	1.25	4.00		5.00 <i>re</i>
# EXPANDING NUT	1.00	4.00		4.00 <i>re</i>
# EXPANDING NUT	1.10	4.00		4.40 <i>re</i>
# TRUNK LID POWER LOCK DRIVE *	586.65	1.00		586.65 <i>bt</i>
# TRIM PANEL TRUNK LID *	121.15	1.00		121.15 <i>de</i>
# PLUG BLACK D=5MM *	0.90	7.00		6.30 <i>re</i>
# SENSOR WIRE FOR SMART OPENER TOP *	42.10	1.00		42.10 <i>dis</i>
# SENSOR WIRE FOR SMART OPENER BOTTOM *	40.50	1.00		40.50 <i>de</i>
# CONTROL UNIT SMART OPENER *	468.85	1.00		468.85 <i>dis</i>
# BLIND RIVET AVIBVLB *	0.55	20.00		11.00 <i>re</i>
# BLIND RIVET AVIBVLB *	0.55	20.00		11.00 <i>re</i>

Total Labour :

Total Parts : 1,308.45

Total Labour & Parts : 1,308.45

25660.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46165
Date Estimated : 08/03/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Foo Kuang Teck
7A Jalan Ulu Siglap

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 457129

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE	
SBL9P	DX53156	11/06/2013	520iA	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
* To replace rear bumper and attachments, boot lid and attachments, tail end panel, rear RH covering include making good the rear LH/RH fenders, trunk floor plate and knocking out dents caused by the accident	850 day 5525.00		5,525.00	✓	
* To respray rear bumper, boot lid, tail end panel, rear RH fender, rear LH fender and trunk floor plate	4608.00		4,608.00	✓	
To carry out body cavity preservation. (Per panel).	100.00		100.00	✓	
To carry out body cavity preservation. (For cut panel).	451.00		451.00	✓	
* To replace bootlid smart opener top and bottom sensor lines include programming and conducting checks for proper function	561.00		561.00	✓	
To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00	✓	
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00	✓	
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00	✓	
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00	✓	
To supply rear emboss number plate.	83.00		83.00	✓	
Sundries.	150.00		150.00	✓	

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	1.25	6.00		7.50 <i>rec</i>
# BLIND RIVET *	1.25	4.00		5.00 <i>rec</i>
TAIL END PANEL	817.30	1.00		817.30 <i>bt</i> ✓
BOOTLID	1,602.40	1.00		1,602.40 ✓
# EXPANDING NUT	1.00	4.00		4.00 <i>rec</i> ✓
# EXPANDING NUT	1.10	4.00		4.40 <i>rec</i> ✓
RR BUMPER BOTTOM CENTRE GUIDE	58.95	1.00		58.95 ✓
RR BUMPER CTR GUIDE	67.35	1.00		67.35 ✓
RR BUMPER CARRIER	714.25	1.00		714.25 ✓
RR BUMPER PANEL PRIMED (PDC)	1,467.20	1.00		1,467.20 ✓
RR BUMPER ADAPTER	48.00	1.00		48.00 ✓
EMBLEM GROMMET	0.80	2.00		1.60 ✓
MODEL LETTERING 520I	62.55	1.00		62.55 ✓
BMW EMBLEM	69.50	1.00		69.50 ✓
TRUNK LID LOCK TOP	425.35	1.00		425.35 ✓
# TRUNK LID POWER LOCK DRIVE *	586.65	1.00		586.65 <i>bt</i> ✓
PLUG	1.05	10.00		10.50 ✓
# TRIM PANEL TRUNK LID *	121.15	1.00		121.15 <i>de</i> ✓
REAR RIGHT COVERING	84.20	1.00		84.20 ✓
PLUG BLACK D=5MM	0.90	3.00		2.70 ✓
# PLUG BLACK D=5MM *	0.90	7.00		6.30 <i>rec</i> ✓
# SENSOR WIRE FOR SMART OPENER TOP *	42.10	1.00		42.10 <i>dis</i> ✓
# SENSOR WIRE FOR SMART OPENER BOTTOM *	40.50	1.00		40.50 <i>de</i> ✓
# CONTROL UNIT SMART OPENER *	468.85	1.00		468.85 <i>dis</i> ✓
# BLIND RIVET AVIBVLB *	0.55	20.00		11.00 <i>rec</i> ✓
# BLIND RIVET AVIBVLB *	0.55	20.00		11.00 <i>rec</i> ✓
SCREW (SF PLUS M5X15)	0.55	10.00		5.50 ✓
(DG/SL) BODY ADHESIVE K5B (195ML)	281.55	1.00		281.55 ✓
PUNCH RIVET N4	0.55	20.00		11.00 ✓
(DG) CLEANER R1 (100ML)	23.85	1.00		23.85 ✓
(S/L) SEAM SEAL 300ML	33.80	2.00		67.60 ✓

SUPPLEMENTARY ITEMS

Total Labour :	12,459.00
Total Parts :	7,129.80
Total Labour & Parts :	19,588.80
Deduction for Excess :	
Total Repair Costs less Excess:	19,588.80
GST @7%:	1,371.22
Grand Total :	20,960.02

Vic (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Wednesday, 27 June, 2018 4:43 PM
To: PBSP; Taufikh (LKKAUTO); Vic (LKKAUTO)
Subject: RE: FINAL REPORT / SBL9P
Attachments: Final Report SBL9P.PDF; Final Report SBL9P_2.pdf

Without Prejudice

Hi Caroline,

We refer to the email below.

The case handler for this case is Vic.

Hi Vic,

Please kindly assist. - CC3/AIG18004649/T1hb3

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Friday, 22 June 2018 7:43 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Subject: Re: FINAL REPORT / SBL9P

Dear Taufikh and Asher

Please assist to confirm COR.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Monday, 2 April 2018 5:24:22 PM

To: taufikh@lkkauto.com; Asher Sng (LKK Auto)

Subject: FINAL REPORT / SBL9P

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 12,459.00

Total Parts : 7,129.80

Total Labour & Parts : 19,588.80

Repair days: 7

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours: Monday to Friday, 09:00 – 17:00
LEN: S66550020G / GST Reg. No.: M409017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MBHH18032307 Vehicle Registration No: SKZ9516C
Name (as shown in NRIC) : LINA HARTANTO NRIC/FIN/Passport No : S22004371
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore()
Contact (Tel) : _____ Mobile No : 96192189
Email Address : LINAHARTANTO@GMAIL.COM
Date of Accident : 07/03/2018 Time of Accident : 14:45
Place of Accident : JUNCTION OF LOWER DELTA RD AND JALAN BUKIT MERAH
Insurance Company : AIG ASIA PACIFIC INSURANCE PTE. LTD.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amend from was there any video captured by Car Camera from YES to NO

Policyholder / Driver's Signature
Date: _____

Xian Chern
Reporting Centre Personnel's Signature
Name: Chin Xian Chern
NRIC/FIN No.: G8577824U
Date: 9 MAR 2018

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 19 September 2018 8:49 AM
To: 'PBSP'
Cc: Taufikh (LKKAuto); Vic (LKKAuto); Admin A
Subject: FINAL REPORT / SBL9P *LKK REF: CC3/AIG18004649/T1hb3

Without Prejudice

Hi,

We refer to the above matter.

For COR, recommended amount at P/P **\$19,588.80(before GST) with 7 repair days.**

*** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Please note that all the finalisation subject to insurer approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SBL9P (2494491266SG)**
[SKZ9516C]

TP

FOO KUANG TECK

Mar 7 2018 12:00AM

[Daimler Fleet Management]

Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 19/10/2018 11:44 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$21867.47) - SBL9P - Claim Handler: Loh, Chee-Heng

Approved:21867.47.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018 Edit Reg		14 Mar 2018 00:00 Edit Adj Rpt	S\$19,588.80 Edit Estimates	S\$19,588.80 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Daimler Fleet Management Singapore Pte Ltd , Co. Reg. No.: NA		
Main Claimant:	FOO KUANG TECK , ID: S0338412H		
Vehicle Reg. No.:	SBL9P	Date of Loss:	07/03/2018 00:00 - :59 [56 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2494491266SG	Policy/Cover Note No.:	0999994742
Vehicle Reg. No. (Insured):	SKZ9516C	Policy No. (Claimant):	D17MTVP01008721
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 21/03/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (19/10/2018): Alert - Adj Mandate Approved (S\$21867.47) - SBL9P - Claim Handler: Loh, Chee-Hen...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SBL9P (2494491266SG)**
[SKZ9516C]

TP

FOO KUANG TECK

Mar 7 2018 12:00AM

[Daimler Fleet Management Singapore Pte Ltd]
Performance Motors Limited

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Letters/Correspondences

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	☒

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/09/18 08:46	Odometer Reading	 Load JPG ☒	☒
2	19/09/18 08:46	Chassis Number	 Load JPG ☒	☒
3	19/09/18 08:46	General View	 Load JPG ☒	☒
4	19/09/18 08:46	General View	 Load JPG ☒	☒
5	19/09/18 08:46	General View	 Load JPG ☒	☒
6	19/09/18 08:46	General View	 Load JPG ☒	☒
7	19/09/18 08:46	General View	 Load JPG ☒	☒
8	19/09/18 08:46	General View	 Load JPG ☒	☒
9	19/09/18 08:46	General View	 Load JPG ☒	☒
10	19/09/18 08:46	General View	 Load JPG ☒	☒
11	19/09/18 08:46	General View	 Load JPG ☒	☒
12	19/09/18 08:46	General View	 Load JPG ☒	☒
13	19/09/18 08:46	General View	 Load JPG ☒	☒
14	19/09/18 08:46	General View	 Load JPG ☒	☒
15	19/09/18 08:46	General View	 Load JPG ☒	☒
16	19/09/18 08:46	General View	 Load JPG ☒	☒
17	19/09/18 08:46	General View	 Load JPG ☒	☒
18	19/09/18 08:46	General View	 Load JPG ☒	☒
19	19/09/18 08:46	General View	 Load JPG ☒	☒
20	19/09/18 08:46	General View	 Load JPG ☒	☒
21	19/09/18 08:46	General View	 Load JPG ☒	☒
22	19/09/18 08:46	General View	 Load JPG ☒	☒
23	19/09/18 08:46	General View	 Load JPG ☒	☒
24	19/09/18 08:46	General View	 Load JPG ☒	☒
25	19/09/18 08:46	General View	 Load JPG ☒	☒
26	19/09/18 08:46	General View	 Load JPG ☒	☒
27	19/09/18 08:46	General View	 Load JPG ☒	☒
28	19/09/18 08:46	General View	 Load JPG ☒	☒
29	19/09/18 08:46	General View	 Load JPG ☒	☒
30	19/09/18 08:46	General View	 Load JPG ☒	☒
31	19/09/18 08:46	General View	 Load JPG ☒	☒
32	19/09/18 08:46	General View	 Load JPG ☒	☒

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	19/09/18 08:46	General View	 Load JPG	☒
34	19/09/18 08:46	General View	 Load JPG	☒
35	19/09/18 08:46	General View	 Load JPG	☒
36	19/09/18 08:46	General View	 Load JPG	☒
37	19/09/18 08:46	General View	 Load JPG	☒
38	19/09/18 08:46	General View	 Load JPG	☒
39	19/09/18 08:46	General View	 Load JPG	☒
40	19/09/18 08:46	General View	 Load JPG	☒
41	19/09/18 08:46	General View	 Load JPG	☒
42	19/09/18 08:46	General View	 Load JPG	☒
43	19/09/18 08:46	General View	 Load JPG	☒
44	19/09/18 08:46	General View	 Load JPG	☒
45	19/09/18 08:46	General View	 Load JPG	☒
46	19/09/18 08:46	General View	 Load JPG	☒
47	19/09/18 08:46	General View	 Load JPG	☒
48	19/09/18 08:46	General View	 Load JPG	☒
49	19/09/18 08:46	General View	 Load JPG	☒
50	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
51	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
52	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
53	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
54	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
55	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
56	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
57	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
58	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
59	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
60	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
61	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
62	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
63	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
64	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
65	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
66	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
67	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
68	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
69	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
70	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
71	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
72	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
73	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
74	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
75	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
76	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
77	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
78	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
79	19/09/18 08:47	Reinspection Photo	 Load JPG	☒
80	19/09/18 08:47	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
82	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
83	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
84	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
85	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
86	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
87	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
88	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
89	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
90	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
91	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
92	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
93	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
94	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
95	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
96	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
97	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
98	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
99	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
100	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
101	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
102	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
103	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
104	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
105	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
106	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
107	19/09/18 08:47	Reinspection Photo	 Load JPG	✓
108	19/09/18 08:47	Reinspection Photo	 Load JPG	✓

Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/03/18 16:19	TP ESTIMATE	 Load TIF	
2	12/03/18 16:19	TP GIA REPORT	 Load PDF	
3	15/03/18 17:49	TP ESTIMATE- MARKED	 Load PDF	
4	19/03/18 11:43	LETTER TO OI	 Load PDF	
5	19/03/18 11:43	EMAIL TO OI	 Load PDF	
6	17/10/18 16:17	AUTHORIZATION TO ACT LETTER	 Load PDF	
7	17/10/18 16:17	REPAIR INVOICE	 Load PDF	
8	17/10/18 16:17	LTA SEARCH FEE	 Load PDF	
9	25/10/18 09:59	RELEASE VOUCHER	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/03/18 10:01	OI GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKZ9516C (Insd veh)	Model:	BMW 520I 2.0 (A)
	SBL9P (TP veh)		
Date of Accident:	07/03/2018		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$				27,474.12
Final Repair Cost	:	\$				20,960.02
Loss of Use	:	\$				900.00
Rental (if any)	:	\$				9.00 days at \$100.00 per day
LTA / GIA Search Fee	:	\$				7.45
Others:	:	\$				days
	:	\$				
Final Settlement Sum	:	\$				21,867.47

Is Third Party Workshop GIA Registered?		[X]	YES	[]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ (%)				
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: <u>27</u>				
BOLA Liability: <u>100</u> _____ (%)		Assessed Liability (*): _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.						
Remarks _____						

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	: \$	20,967.47
2)	FOO KUANG TECK	: \$	900.00
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

25 Oct
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18004649/T1HB3S2

Date: 25/10/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994742
Claimant Vehicle No :	SBL9P	Insured Vehicle No :	SKZ9516C
Date of Loss:	07/03/2018	Nature of Claim:	TP
		Claim No:	2494491266SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBL9P	Engine No:	A3980435N20B20B
Make & Model:	BMW 520I, 2.0 (A)	Chassis No:	WBAXG12090DX53156
Reg. Date:	11/06/2013 (Man. Year: 2013)	Odometer:	60400 km
Colour:	Black		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,759.75	7,362.80	3,396.95	31.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,917.00	12,226.00	2,691.00	18.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,676.75	19,588.80	6,087.95	23.71
+ GST 7.00/7.00% (S\$)	1,797.37	1,371.22	426.15	23.71
Nett Amount (S\$)	27,474.12	20,960.02	6,514.10	23.71
+ Loss of Use (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		21,867.47		

INSPECTION

Date of Assignment:	14/03/2018	
Date Inspected:	14/03/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*BODY NUT	Not Necessary	9.00 FS	*-FS
2	1		*TAIL END PANEL	Bent	817.30 FS	*817.30 FS
3	1		*BOOTLID	Bent	1,602.40 FS	*1,602.40 FS
4	1		*RR BUMPER BOTTOM CENTRE GUIDE	Deformed	58.95 FS	*58.95 FS
5	1		*RR BUMPER CTR GUIDE	Necessary	67.35 FS	*67.35 FS
6	1		*RR BUMPER LH MOUNT	Not Necessary	142.55 FS	*-FS
7	1		*RR BUMPER RH MOUNT	Not Necessary	142.55 FS	*-FS
8	1		*RR BUMPER CARRIER	Bent	714.25 FS	*714.25 FS
9	1		*RR BUMPER PANEL PRIMED (PDC)	Deformed	1,467.20 FS	*1,467.20 FS
10	1		*RR BUMPER TOW HOOK COVER PRIMED	Not Necessary	46.45 FS	*-FS
11	1		*RR BUMPER ADAPTER	Deformed	48.00 FS	*48.00 FS
12	2		*EMBLEM GROMMET	Necessary	1.60 FS	*1.60 FS
13	1		*MODEL LETTERING 520I	Necessary	62.55 FS	*62.55 FS
14	1		*BMW EMBLEM	Necessary	69.50 FS	*69.50 FS
15	1		*STRIKER BOOT LID	Not Necessary	52.25 FS	*-FS
16	2		*STOP BUFFER	Not Necessary	55.80 FS	*-FS
17	1		*TRUNK LID LOCK TOP	Bent	425.35 FS	*425.35 FS
18	10		*PLUG	Necessary	10.50 FS	*10.50 FS
19	1		*REAR LH BUMPER HEAT INSULATOR	Not Necessary	32.10 FS	*-FS
20	1		*LH GUTTER STRIP	Not Necessary	16.80 FS	*-FS
21	1		*RH GUTTER STRIP	Not Necessary	16.80 FS	*-FS
22	1		*REAR LIGHT COVERING	Deformed	84.20 FS	*84.20 FS
23	1		*BOOTLID SEALING	Not Necessary	115.25 FS	*-FS
24	2		*(D/G) REPAIR KIT CRASH ACTIV	Not Necessary	319.60 FS	*-FS
25	10		*PLUG BLACK D=5MM	Necessary 3pcs Only	9.00 FS	*2.70 FS
26	10		*EXPANDING NUT	Not Necessary	5.50 FS	*-FS
27	1		*REAR LH REFLECTOR	Not Necessary	35.20 FS	*-FS
28	1		*REAR RH REFLECTOR	Not Necessary	35.20 FS	*-FS
29	1		*REAR LH LIGHT IN TRUNK LID	Not Necessary	338.00 FS	*-FS
30	1		*REAR RH LIGHT IN TRUNK LID	Not Necessary	338.00 FS	*-FS
31	1		*REAR LH LIGHT IN THE SIDE PANEL	Not Necessary	572.25 FS	*-FS
32	1		*REAR RH LIGHT IN THE SIDE PANEL	Not Necessary	572.25 FS	*-FS
33	2		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	10.10 FS	*-FS
34	2		*BUMPER PDC SENSOR (SCHWARZ)	Not Necessary	473.70 FS	*-FS
35	1		*BLIND RIVET AVIBVLB	Not Necessary	27.50 FS	*-FS
36	10		*SCREW (SF PLUS M5X5)	Necessary	5.50 FS	*5.50 FS
37	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	281.55 FS	*281.55 FS
38	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
39	20		*PUNCH RIVET N4	Necessary	11.00 FS	*11.00 FS
40	1		*(S/L) SEAM SEAL 300ML	Necessary 2pcs Only	101.40 FS	*67.60 FS
41	1		*REAR EMBOSS NUMBER PLATE	Dented	83.00 FS	*83.00 FS
42	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
43	6		*BLIND RIVET	Necessary	7.50 FS	*7.50 FS
44	4		*BLIND RIVET	Necessary	5.00 FS	*5.00 FS
45	4		*EXPANDING NUT	Necessary	4.00 FS	*4.00 FS
46	4		*EXPANDING NUT	Necessary	4.40 FS	*4.40 FS
47	1		*TRUNK LID POWER LOCK DRIVE	Bent	586.65 FS	*586.65 FS
48	1		*TRIM PANEL TRUNK LID	Deformed	121.15 FS	*121.15 FS
49	7		*PLUG BLACK D=5MM	Necessary	6.30 FS	*6.30 FS
50	1		*SENSOR WIRE FOR SMART OPENER TOP	Distorted	42.10 FS	*42.10 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*SENSOR WIRE FOR SMART OPENER BOTTOM	Deformed	40.50 FS	*40.50 FS
52	1		*CONTROL UNIT SMART OPENER	Distorted	468.85 FS	*468.85 FS
53	20		*BLIND RIVET AVIBVLB	Necessary	11.00 FS	*11.00 FS
54	20		*BLIND RIVET AVIBVLB	Necessary	11.00 FS	*11.00 FS
Total Parts (\$)						10,759.75 7,362.80

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER & ATTACHMENTS, BOOT LID, TAIL PANEL INCLUDING TO PULL & STRAIGHTEN BOTH REAR CHASSIS, TO KNOCK OUT TRUNK FLOOR PANEL AND DENTED AREAS CAUSED BY THE ACCIDENT.	New	6,800.00	5,525.00
2	TO RESPRAY REAR BUMPER, BOOT LID, TAIL PANEL, REAR RIGHT FENDER, REAR LEFT FENDER AND BOOT COMPARTMENT.	New	5,120.00	4,608.00
3	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)	New	118.00	100.00
4	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)	New	531.00	451.00
5	TO REPLACE BOOTLID SMART OPENER TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION.	New	661.00	561.00
6	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION.	New	531.00	451.00
7	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.	New	177.00	150.00
8	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.	New	271.00	230.00
9	TO REMOVE AND INSTALL FUSE BOX AT THE REAR SECTION TO FACILITATE REPAIRS.	New	531.00	0.00
10	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION.	New	177.00	150.00
Gross Labour Cost (\$\$)			14,917.00	12,226.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >