

INS. CASE OWNER

CC 6 ^{LK2} / AIG 1800 4657, TWB3 9

LKK:
IDAC:

Surveyor: 7unfika. DOI: 14/7/18 Date / Time: 12/7/18
Registered in Merimen: 12/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.: SLE 7414A
Name of Insured: LRF
Insured Tel No.: _____ HP: _____
Excess Sec II :SS _____ D.O.A.: 11/7/18
Is driver the owner? (YES / NO) _____ Nature of Accident: _____
If NO, Driver Name / Age: GWEE KIM GUAN
Driver Tel No.: 90106679 (V/L: YES / NO)

Claim No.: 379906904756
Policy No.: 999995059
Make / Model: TOYOTA
Place of Accident: ELP TWS LTY.

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
Insured Liability: % Final ? Yes / No

SEV 6087P



INSRS: _____
WSP: Charn's
Tel: customer
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

Date/Time	STAGE	DATE / PIC
14/7/18 vinitan	SEV 6087P - X	SLE 7414A - 7
5/12/18	Email + letter to O2. TP visits to claim \$7.45	
	Notification ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: <u>14.3.18</u> After call ltr to OE:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OE	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA:	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

RECEIVED 05 DEC 2018

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS _____ (_____ days) Reduction: _____ %		Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: <u>4/12/18</u>	Confirm with: <u>Sharon</u>	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% <u>100</u> (Agreed / Assessed) BOLA S/N No.: <u>15</u>		If NO or B 28, Ass. Lia:
Repair Cost:	SS <u>4887.25</u>		
Loss of Rental (LOR):	SS <u>1028.00</u> (<u>4</u> days) <u>X100 + 657</u>		<u>GID CHANGED LANE.</u>
Loss of Use (LOU):	SS _____ (<u>5</u> x days)		<u>COPY SENT</u>
Loss of Income (LOI):	SS _____ (<u>5</u> x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	<input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search:	SS <u>7.45</u>		
Medical:	SS _____		1) Claim status: Normal/Reject/Private Settle
Disbursement:	SS _____ (e.g. Tow/Independent.)		2) Report Format:
Legal Cost:	SS _____		3) Survey fee:
Total:	SS <u>5216.70</u>	Global Sum SS:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS <u>5316.70</u>	Name 1: <u>Charn's Customcraft</u>	
Payee 2: (Strike if N.A.)	SS _____	Name 2:	
Payee 3: (Strike if N.A.)	SS _____	Name 3:	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/LCR18004651/wb3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 12-03-2018



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 7414A	Veh. Inspected	SKV 6087P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/03/2018	Inspection Date	
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724

BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723

TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charn@charn.com.sg

Bus. Reg. No. 251513/00M

FWD/AIG(SLE7414A)
DOA: 11/03/2018@1330

AIG ASIA PACIFIC INSURANCE PTE LTD

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SKV 6087 P - TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

CHASSIS NO: MR053REH104538055 (2015)

Insurance consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1 pc	Rear boot	\$ 753.80	bt ✓
1 pc	Rear boot logo	\$ 52.20	nr ✓
1 pc	Rear boot 'COROLLA' emblem	\$ 48.30	nr ✓
1 pc	Rear boot 'ALTIS' emblem	\$ 52.20	nr ✓
1 pc	Rear boot lock	\$ 379.20	bt ✓
1 pc	Rear bumper	\$ 522.40	de ✓
1 pc	Rear bumper retainer LH	\$ 103.20	X in ✓
1 pc	Rear bumper retainer RH	\$ 103.20	de ✓
1 pc	Rear bumper reinforcement	\$ 395.50	bt ✓
1 pc	Rear bumper side bracket LH	\$ 68.10	nr ✓
1 pc	Rear bumper side bracket RH	\$ 68.10	nr ✓
1 pc	Rear bumper reflector RH	\$ 80.70	nr ✓
1 pc	Rear taillamp RH	\$ 355.60	nr ✓
1 pc	Rear end panel	\$ 587.20	nr ✓
1 pc	Rear end panel top garnish	\$ 287.50	X in ✓
		<u>\$ 3,857.20</u>	3466.50
	LESS 25%	\$ 964.30	
		<u>\$ 2,892.90</u>	2599.87
1 pc	Rear No.plate (S/NETT)	\$ 35.00	X in ✓
2 pcs	Reverse Sensor (S/NETT) @ \$220.20	\$ 440.40	nr ✓ 220.20

Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, rear end panel, rear boot, rear fenders LH/RH, rear bumper and spare tyre compartment, rear RH chassis and rear door RH.

Putty and respray rear inner panel, rear end panel, rear boot, rear fenders LH/RH, rear bumper, spare tyre compartment, rear RH chassis and rear RH door.

ADD 7% GST

\$ 1,100.00

\$ 1,200.00

\$ 5,668.30

\$ 396.78

\$ 6,065.08

Tan Kim 97495789
15/5/18 @ 1430
- w/p
sur@ikkauto.com

800.
900 800
6 days
*Bouway before print

4520.07

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

FWD/AIG(SLE7414A)
DOA: 11/03/2018@1330

12/3/2018

AIG ASIA PACIFIC INSURANCE PTE LTD

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SKV 6087 P - TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

CHASSIS NO: MR053REH104538055 (2015)

Supplementary

1 pc	Rear seal RH	\$ 55.80	<i>dev</i>
	LESS 25%	\$ 13.95	
		<u>\$ 41.85</u>	
	ADD 7% GST	\$ 2.93	
		<u>\$ 44.78</u>	

CHARN'S CUSTOMCRAFT

Parts - 2599.87
 Supp - 41.85
 S/N - 220.00
 Lab - 1700.00

 4562.12 #
 4561.92 #
 6 days

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	0218E

Vehicle Details

Vehicle No.:	SKV6087P
Vehicle to be Exported:	Yes
Intended De-registration Date:	31 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1ZR529081
Chassis No.:	MR053REH104538055
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,804.00
Original Registration Date:	25 Sep 2015
First Registration Date:	25 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$17,804.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Sep 2025
PARF Rebate Amount:	\$13,353.00

Intended COE Rebate Details

COE Expiry Date:	24 Sep 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,089.00
COE Rebate Amount:	\$42,721.00
Total Rebate Amount:	\$56,074.00

The information contained herein is correct as at 12 Mar 2018

OK

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Wednesday, 14 March 2018 3:26 PM
To: 'Eileen, May Hwee Yap'
Cc: Vivian Lau (LKKAuto); Hsiao Tong (LKKAuto); Admin A
Subject: ACCIDENT INVOLVING SLE 7414A(LCRF/AIG) & SKV 6087P ALONG ECP TOWARDS CITY ON 11/03/2018, 1320HRS

14 March 2018

LION CITY RENTALS PTE LTD

Policy Holder

Your Ref: **SLE 7414A**

Our Ref: CC3/LCR18004651/wb3

Dear Sir/Madam,

ACCIDENT INVOLVING SLE 7414A(LCRF/AIG) & SKV 6087P ALONG ECP TOWARDS CITY ON 11/03/2018, 1320HRS

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SKV 6087P against your insurance policy.

Based on the information on hand, we are of the opinion that liability is not in our favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

RELEASE VOUCHER
(AIG ASIA PACIFIC-EXPRESS THIRD PARTY CLAIM)

"We/I, Charn's Customcraft (the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 4,881.25 (repair cost), S\$ 428.00 (loss of rental/use), S\$ 7.45 (disbursement), for vehicle no. SKV 6087P that was damaged pursuant to the accident which occurred on 11/03/2018 (date) along ECP TWDS CITY (location) involving vehicle no/s SLE 7414A.

This is pursuant to the inspection conducted on 15/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LEE HOW CHENG (the third party claimant") of vehicle no. SKV 6087P make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKV 6087P (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 4 (day) of 12 (month) 2018 (year)

M711



Signed by AIG appointed surveyor

[Handwritten Signature]



Chopped & Signed by "the workshop"



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
 Spray-Painting, Mechanical Repair And Customizing of Cars
 BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
 BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
 TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg
 Bus. Reg. No. 25151300M GST Reg. No. M90967863L

TAX INVOICE

M1 AIG ASIA PACIFIC INSURANCE PTE LTD
 ATTN: THE MOTOR CLAIMS DEPT

No. 2018115861
 TERM:
 YOUR ORDER No.
 OUR D/O No.
 DATE: 19/11/2018

QUANTITY	DESCRIPTION	AMOUNT \$ CTS.
----------	-------------	-------------------

Vehicle No.	Make/Model	DOA	Reg. No.
SKV6087P	TOYOTA COROLLA ALTIS CLASSIC 1	11/03/2018@1330	41973

1.00 pc	Rear Boot	753.80
1.00 pc	Rear Boot Emblem Logo	52.20
1.00 pc	Rear Boot Emblem 'COROLLA'	48.30
1.00 pc	Rear Boot Emblem 'ALTIS'	52.20
1.00 pc	Rear Boot Inner Lock	379.20
1.00 pc	Rear Bumper	522.40
1.00 pc	Rear Bumper Retainer RH	103.20
1.00 pc	Rear Bumper Reinforcement	395.50
1.00 pc	Rear Bumper Side Bracket LH	68.10
1.00 pc	Rear Bumper Side Bracket RH	68.10
1.00 pc	Rear Bumper Reflector RH	80.70
1.00 pc	Rear Taillamp RH	355.60
1.00 pc	Rear End Panel	587.20
1.00 pc	Rear Seal RH	55.80
	Subtotal	3,522.30
	Discount 25%	-880.58
1.00 pc	Reverse Sensor @ \$220	220.20

CHARN'S CUSTOMCRAFT

Subtotal

GST 7%

Total



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
 Spray-Painting, Mechanical Repair And Customizing of Cars
 BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
 BLOCK 1009, BUKIT MERAH LANE 3, #01-B2, SINGAPORE 159723
 TEL: 6271 7054, 6273 3304 FAX: 6273 6876 EMAIL: charns@singnet.com.sg
 Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

TAX INVOICE

M1 AIG ASIA PACIFIC INSURANCE PTE LTD
 ATTN: THE MOTOR CLAIMS DEPT

2018115861

No.

TERM:

YOUR ORDER No.

OUR D/O No. T9/11/2018

DATE:

QUANTITY	DESCRIPTION	AMOUNT \$ CTS.
----------	-------------	-------------------

Vehicle No.	Make/Model	DOA	Reg. No.
SKV6087P	TOYOTA COROLLA ALTIS CLASSIC I	11/03/2018@1330	41973

Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, rear end panel, rear boot, rear fenders LH/RH, rear bumper and spare tyre compartment, rear RH chassis and rear door RH. 800.00

Putty and respray rear inner panel, rear end panel, rear boot, rear fenders LH/RH, rear bumper, spare tyre compartment, rear RH chassis and rear RH door. 900.00

CHARN'S CUSTOMCRAFT



Subtotal \$4,561.92

GST 7% \$319.33

Total \$4,881.25



TAX INVOICE

GST REG. NO.: 200106276D

INVOICE TO
LEE HOW CHENG BLK 7 KIM TIAN PLACE #06-65 SINGAPORE 160007

DATE	INVOICE NO.
27-Mar-2018	A 37475

VHA NO.	DUE DATE	VEH. NO.
A 37475	27-Mar-2018	SKT 6344 H

DESCRIPTION	NO. OF DAYS	RATE	AMOUNT
RENTAL FROM 15 MARCH 2018 TO 19 MARCH 2018 YOUR REF: SKV 6087 P	4	150.00	600.00
GST @ 7%			\$42.00
TOTAL			\$642.00

All cheques must be made payable to BKW Rent A Car Pte Ltd.
Please write the vehicle and invoice number on the reserve.

BKW Rent-A-Car Pte Ltd

120 Lower Delta Road #02-15 Cendex Centre (S) 169208 Tel: 6738 7777 Fax: 6738 6666

ACRA No: 200106276D GST Reg. No: 20-0106276-D Website: www.bkw.sg
A subsidiary of BKW Automobile Pte Ltd



bizSAFE



BKW RENT A CAR PTE LTD

120 Lower Delta Road #02-15 Condamine Centre Singapore 169208 Tel: 6738 7777 Fax: 6738 6666

ACRA No: 20-0106276-D GST Reg. No: 20-0106276-D

24 HOURS HELPLINE : 6223 1122

VHA No: **A 37475**

Workshop: *Cherry Garden*

VEHICLE HIRING AGREEMENT

HIRER'S PARTICULARS

Name (as in IC): *Lee Hui Cherry*
 NRIC/Passport No: *S1230218E* Date of Birth: *24/06/1957*
 Address: *51k 7 Kim Tian Place* Age: *160007*
 # *06-65*
 Name & Address of Employer: *HP*
 Occupation: *13 YEARS* Driving Exp: *11/4/2007*
 Driving Licence No: *S1230218E* Passed Date:
 DL Type: Local/Int/Other: *8298N88*
 Tel(O): (R) HP

DRIVER'S PARTICULARS

Name (as in IC): *LI Weimeng*
 NRIC/Passport No: *S891293H* Date of Birth: *20/4/1989*
 Occupation: *Local* Driving Exp: *Yes*
 Driving Licence No: *Local* Passed / Expiry Date:
 DL Type: Local/Int/Other: *Local* Contact No:

Hirer's Own Vehicle No: *SKV6087P* Replace Veh No:
 Loan Vehicle No: *SKT CB4TH* VR No:
 Make & Model: *1.1115* (Auto/Manual Group):
 CHARGES \$ cts
 Daily *4* day @ \$ *150* Per day *\$600* ✓
 Weekly/Monthly week @ \$ Per week/Monthly
 Others
 CDW/PAI @ \$ Per day/Monthly
 Delivery/Collection Svc
 GST *7%* *42* ✓
 CR No: (A) SUB-TOTAL *\$642* ✓
 Acc/Less: QLT ✓
 Surcharge: IN ✓
 Excess mileage: \$ *FREE* per day
 Excess mileage: \$ *unavailable* per km
 TOTAL CHARGES

Security Deposit: \$ *14000* Bank:
 CASH/NETS/VISA/MC/AMEX/CHK No:
 Expiry Date: Card ID No:
 Name as in Card:
 NON-WAIVER/EXCESS (Subject to GST): \$ *14000*
 ACCESSORIES CHECK
 Date Cards Camera Systems High Cab Radio / CD Cartridge
 Jigs Tire Chains Patrol Cap Spare Tyre
 Hirer's Signature: *[Signature]* Additional Driver's Signature:

SINGAPORE Use Only

I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have been given by BKW Rent A Car Pte Ltd in connection with this agreement is true.

- IMPORTANT**
- The Hirer must be authorized driver, must be over 23 years of age and under 65 years old, be holding valid driving licenses and have a minimum of 2 years regular and qualified driving experience. Failure to observe stipulations may result in damages payable to the Rental Company by the Hirer/Authorized Driver.
 - All vehicles are supplied with petrol and should be returned with petrol level likewise. A service charge of \$5 on top of a petrol surcharge is payable by the Hirer should he fail to return the vehicle at the appropriate petrol level.
 - No refund for early return of vehicle. The hirer shall be liable for additional charges for any late return at the rate shown per hour per day, inclusive of CDW and/or PAI where applicable. Any return after our operation hours will be charged as a full day rental.
 - Use of the vehicle for illegal purpose (For instance in connection with theft, drug peddling or trafficking, smuggling), is strictly prohibited.
 - Vehicle strictly for Singapore use only and may not be driven out of Singapore without prior written consent of BKW Rent A Car Pte Ltd. The hirer is liable for a penalty fee of \$200 in addition to the appropriate insurance top up in the case of non-disclosure of Malaysia usage.
 - The Hirer and/or driver shall be responsible for all damages or losses howsoever caused, all traffic violations, fines and penalties imposed on the vehicle for whatsoever reason in respect of or in connection with its use or operation.
 - The Hirer and/or driver shall be responsible for all claims, damages, losses, increased insurance premiums, non-waiver excess and cost expense (including

- legal costs on a full indemnity basis), whatsoever and howsoever brought against, suffered or incurred by you in respect of the vehicle or the use or the operation of the vehicle. Full excess amounts have to be paid immediately in the event of an accident. The owner reserves the right not to replace an equipment unless an accident occurred. Any damage to the car will be repair at BKW authorized workshop.
- Smoke or permit smoking and transport of pets in the vehicle are not allowed. Any offensive smell e.g. cigarette, deodorant or pet's smell, the Hirer and/or driver shall bear the cost of removing the offensive smell (or out of hire) between \$200 - \$400.
- The Hirer agrees that a punctured tyre, empty petrol tank, loss of vehicle's key or locked keys inside of vehicle, by itself, does not constitute a breakdown and that in the event the driver's 24-Hours Emergency Service is called upon to respond to such occurrences, the Hirer shall bear the cost of such replacement of \$50/100 per trip.
- In case of accident, the Hirer shall report to rental office immediately. An accident report must be made within 24 hours. Failure to comply, the Hirer will have to liaise with liability from all parties claim. Full excess amount have to be paid immediately in the event of an accident.
- The Hirer/Driver shall have the responsibility to ensure that the radiator water level in the car is sufficient and do not drive when the vehicle is stall and does not have sufficient water. Any damage to the engine will be bear by the Hirer/Driver.
- All customers' data will be kept strictly confidential and is solely used for the purpose of conducting the sales transactions and other related matters.
- I understand and agree to the personal data collection statement stated on the Terms and Conditions Page.

Date Out	Time Out	Mileage	Check By	Remarks
15/3/18	1400	55697	Arnell	
19/3/18	1604	55848	NIK	20/03/18 @ 1020

Hirer/Driver Signature: *[Signature]*
 Hirer's/Driver Signature: *[Signature]*

Return Of Vehicle: The Hirer/Driver is Required to Sign in The Column "Signature Of Hirer/Driver Falling Which The Day And Time Inserted Below Shall Be Deemed To Be The Day And Time The Vehicle is Returned To BKW Rent A Car Pte Ltd And The Same Shall Be Accepted As Conclusive Evidence Of The Same And Shall Not Be Challenged Or Questioned On Any Account Whatsoever. And I had cleared my Belonging Items from the rental vehicle (dashboard, parking coupons, etc)?



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. M4-0006529-2

Print Date/Time : 12 Mar 2018 / 11:24:41

Receipt Date/Time : 12 Mar 2018 / 11:24:41

Tax Invoice/Receipt

Receipt No. : ITNET-00000-160312-000763

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLE7414A As at 12 Mar 2018/11:23:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLE7414A Enquiry Fee 20180312112347647038	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx8513		Credit Card: Visa/MasterCard	7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018 Edit Reg		15 Mar 2018 00:00 Edit Adj Rpt	S\$4,561.92 Edit Estimates	S\$4,561.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF Pte Ltd, Co. Reg. No.: NA								
Main Claimant:	LEE HOW CHENG, ID: S1230218E								
Vehicle Reg. No.:	SKV6087P	Date of Loss:	11/03/2018 13:00 - :59 [29 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3799069047SG	Policy/Cover Note No.:	0999994764						
Vehicle Reg. No. (Insured):	SLE7414A	Policy No. (Claimant):	PNPV2017-00007078						
Repairer:	Charm's Customcraft (HQ) Block 1010 Bukit Merah Lane 3, #01-105, 159724 Bukit Merah - Tel: 62717054								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Gan, Angie-GL] Angiegeokling.Gan@aig.com								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 21/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKV6087P (3799069047SG)
 [SLE7414A]
 TP
LEE HOW CHENG
 Mar 11 2018 1:00PM
 [LCRF Pte Ltd]
 Charn's Customcraft

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View	View in Browser
Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
2	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
3	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
4	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
5	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
6	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
7	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
8	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
9	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
10	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
11	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
12	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
13	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
14	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
15	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
16	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
17	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
18	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
19	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
20	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
21	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
22	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
23	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
24	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
25	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
26	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
27	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
28	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
29	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
30	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
31	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
32	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
33	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
34	04/12/18 15:00	General View	Load JPG	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
36	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
37	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
38	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
39	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
40	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
41	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
42	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
43	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
44	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
45	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
46	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
47	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
48	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
49	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
50	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
51	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
52	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
53	04/12/18 15:00	General View	Load JPG	<input checked="" type="checkbox"/>
54	04/12/18 15:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	04/12/18 15:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	04/12/18 15:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	04/12/18 15:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	04/12/18 15:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	04/12/18 15:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	04/12/18 15:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	04/12/18 15:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/03/18 16:25	TP ESTIMATE	Load PDF	
2	12/03/18 16:25	TP GIA REPORT	Load PDF	
3	14/03/18 15:29	LETTER TO LCRF	Load PDF	
4	16/03/18 17:44	TP ESTIMATE- MARKED	Load PDF	
5	17/12/18 08:20	WORKSHOP INVOICE	Load PDF	
6	17/12/18 08:20	AUTHORISATION TO ACT FORM	Load PDF	
7	17/12/18 08:20	Release Voucher	Load PDF	
8	17/12/18 08:20	RENTAL RECEIPT	Load PDF	
9	17/12/18 08:20	LTA SEARCH	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/03/18 09:20	OI GIA	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLE7414A (Insd veh)	Model:	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A)
	SKV6087P (TP veh)		
Date of Accident:	11/03/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	6,109.86
Final Repair Cost	:	\$	4,881.25
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	428.00 4 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	5,316.70
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____100____(%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Charn's Customcraft	:	5,316.70
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

17 Dec
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18004651/T1WB3Q2

Date: 17/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994764
Claimant Vehicle No : SKV6087P	Insured Vehicle No :	SLE7414A
Date of Loss: 11/03/2018	Nature of Claim:	TP Claim No: 3799069047SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV6087P	Engine No:	1ZR529081
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Chassis No:	MR053REH104538055
Reg. Date:	25/09/2015 (Man. Year: 2015)	Odometer:	38882 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,410.15	2,861.92	548.23	16.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,700.00	600.00	26.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,710.15	4,561.92	1,148.23	20.11
+ GST 7.00/7.00% (S\$)	399.71	319.33	80.38	20.11
Nett Amount (S\$)	6,109.86	4,881.25	1,228.61	20.11
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,316.70		

INSPECTION

Date of Assignment:	15/03/2018	
Date Inspected:	15/03/2018	Inspected At: Charn's Customcraft (HQ) Block 1010 Bukit Merah Lane 3, #01-105 Singapore 159724
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	753.80 FL	*753.80 FL
2	1		*REAR BOOT LOGO	Necessary	52.20 FL	*52.20 FL
3	1		*REAR BOOT COROLLA EMBLEM	Necessary	48.30 FL	*48.30 FL
4	1		*REAR BOOT ALTIS EMBLEM	Necessary	52.20 FL	*52.20 FL
5	1		*REAR BOOT LOCK	Bent	379.20 FL	*379.20 FL
6	1		*REAR BUMPER	Deformed	522.40 FL	*522.40 FL
7	1		*REAR BUMPER RETAINER LH	Not Necessary	103.20 FL	*- FL
8	1		*REAR BUMPER RETAINER RH	Deformed	103.20 FL	*103.20 FL
9	1		*REAR BUMPER REINFORCEMENT	Bent	395.50 FL	*395.50 FL
10	1		*REAR BUMPER SIDE BRACKET LH	Necessary	68.10 FL	*68.10 FL
11	1		*REAR BUMPER SIDE BRACKET RH	Necessary	68.10 FL	*68.10 FL
12	1		*REAR BUMPER REFLECTOR RH	Cracked	80.70 FL	*80.70 FL
13	1		*REAR TAILLAMP RH	Cracked	355.60 FL	*355.60 FL
14	1		*REAR END PANEL	Bent	587.20 FL	*587.20 FL
15	1		*REAR END PANEL TOP GARNISH	Not Necessary	287.50 FL	*- FL
16	1		*REAR NO.PLATE	Not Necessary	35.00 FS	*- FS
17	1		*REVERSE SENSOR	N/SNot Necessary/O/S Distorted	440.40 FS	*220.20 FS
18	1		*REAR SEAL RH	Deformed	55.80 FL	*55.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,388.40	3,742.50
- List Item Discount on L Items 25.00/25.00% (S\$)	978.25	880.58
Total Parts (S\$)	3,410.15	2,861.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE NECESSARY ,PARTS ,JACKING ,PANEL BEATING ,REPAIR AND STRAIGHTEN REAR INNER PANEL ,REAR END PANEL ,REAR BOOT ,REAR FENDER RH/LH ,REAR BUMPER AND SPARE TYRE COMPARTMENT ,REAR RH CHASSIS AND REAR DOOR RH	New	1,100.00	800.00
2	PUTTY AND RESPRAY REAR INNER PANEL ,REAR END PANEL,REAR BOOT ,REAR FENDER RH/LH ,REAR BUMPER,SPARE TYRE COMPARTMENT ,REAR RH CHASSIS AND REAR RH DOOR	New	1,200.00	900.00
Gross Labour Cost (S\$)			2,300.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >