



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
 Spray-Painting, Mechanical Repair And Customizing of Cars
 BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
 BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
 TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charn@single.com.sg
 Bus. Reg. No. 251513/00M

FWD/AIG(SLE7414A)
 DOA: 11/03/2018@1330

AIG ASIA PACIFIC INSURANCE PTE LTD
 ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
 ESTIMATE COST OF REPAIR FOR VEHICLE NO:
 SKV 6087 P - TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT
 CHASSIS NO: MR053REH104538055 (2015)

Insurance Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To resurvey damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

1 pc	Rear boot	\$ 753.80	bt ✓
1 pc	Rear boot logo	\$ 52.20	not ✓
1 pc	Rear boot 'COROLLA' emblem	\$ 48.30	not ✓
1 pc	Rear boot 'ALTIS' emblem	\$ 52.20	not ✓
1 pc	Rear boot lock	\$ 379.20	?
1 pc	Rear bumper	\$ 522.40	de ✓
1 pc	Rear bumper retainer LH	\$ 103.20	? ✓
1 pc	Rear bumper retainer RH	\$ 103.20	de ✓
1 pc	Rear bumper reinforcement	\$ 395.50	bt ✓
1 pc	Rear bumper side bracket LH	\$ 68.10	? ✓
1 pc	Rear bumper side bracket RH	\$ 68.10	not ✓
1 pc	Rear bumper reflector RH	\$ 80.70	not ✓
1 pc	Rear taillamp RH	\$ 355.60	not ✓
1 pc	Rear end panel	\$ 587.20	bt ✓
1 pc	Rear end panel top garnish	\$ 287.50	? ✓
		<hr/>	
		\$ 3,857.20	
	LESS 25%	\$ 964.30	
		<hr/>	
		\$ 2,892.90	

1 pc	Rear No.plate (S/NETT)	\$ 35.00	X
2 pcs	Reverse Sensor (S/NETT) @ \$220.20	\$ 440.40	LH-X, RH-dis

Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, rear end panel, rear boot, rear fenders LH/RH, rear bumper and spare tyre compartment, rear RH chassis and rear door RH.

800.
 \$ 1,100.00

Tan Jiah 97495749
 15/3/18 @ 1430
 - WSP
 sur@ikkauto.com

Putty and respray rear inner panel, rear end panel, rear boot, rear fenders LH/RH, rear bumper, spare tyre compartment, rear RH chassis and rear RH door.

900 800
 \$ 1,200.00

6 days.
 *Resurvey before paint

ADD 7% GST

\$ 5,668.30
 \$ 396.78
 \$ 6,065.08

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.
 All parts are subject to availability.

CHARN'S CUSTOMCRAFT