



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

FWD/AIG(SLE7414A)
DOA: 11/03/2018@1330

12/3/2018

AIG ASIA PACIFIC INSURANCE PTE LTD

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SKV 6087 P - TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

CHASSIS NO: MR053REH104538055 (2015)

1 pc	Rear boot	\$ 753.80
1 pc	Rear boot logo	\$ 52.20
1 pc	Rear boot 'COROLLA' emblem	\$ 48.30
1 pc	Rear boot 'ALTIS' emblem	\$ 52.20
1 pc	Rear boot lock	\$ 379.20
1 pc	Rear bumper	\$ 522.40
1 pc	Rear bumper retainer LH	\$ 103.20
1 pc	Rear bumper retainer RH	\$ 103.20
1 pc	Rear bumper reinforcement	\$ 395.50
1 pc	Rear bumper side bracket LH	\$ 68.10
1 pc	Rear bumper side bracket RH	\$ 68.10
1 pc	Rear bumper reflector RH	\$ 80.70
1 pc	Rear taillamp RH	\$ 355.60
1 pc	Rear end panel	\$ 587.20
1 pc	Rear end panel top garnish	\$ 287.50
		<u>\$ 3,857.20</u>
	LESS 25%	\$ 964.30
		<u>\$ 2,892.90</u>
	Rear No.plate (S/NETT)	\$ 35.00
	Reverse Sensor (S/NETT)	\$ 200.00
	Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, rear end panel, rear boot, rear fenders LH/RH, rear bumper and spare tyre compartment	\$ 800.00
	Putty and respray rear inner panel, rear end panel, rear boot, rear fenders LH/RH, rear bumper, spare tyre compartment and affected areas.	\$ 900.00
		<u>\$ 4,827.90</u>
	ADD 7% GST	\$ 337.95
		<u>\$ 4,489.95</u>

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....