

Tanala Automotive Consultancy

My Mail Box 883230

Singapore 919191

ROB: 53240124K

Swee Seng Leasing Pte Ltd

21 Toh Guan Road East

#03-02 Toh Guan Centre

Singapore 608609

Attn: Motor Claims Department

Estimate No : ES2018/0089

Date : 13/03/2018

Vehicle No : SLJ6285K

Make/Model : Toyota / Esquire

Date of Accident : 29/01/2018

S/N	Description	Qty	Unit Amount	Amount
List Items				
1	Rear Bumper	1	894.60	894.60
2	Reflector RH/LH, RR	2	158.85	317.70
3	Bumper Lower, RR	1	495.50	495.50
4	Bumper Chrome RH/LH, RR	2	195.50	391.00
5	Tail Boot	1	1,790.09	1,790.09
6	Inner Lock	1	368.40	368.40
7	Rear Body Weatherstrip	1	398.20	398.20
8	Esquire Logo	1	115.20	115.20
				<hr/>
				4,770.69
Less: 25%				<hr/>
				(1,192.67)
				<hr/>
				3,578.02
Nett Items				
1	Reverse Sensor	1 Set	250.00	250.00
2	Rear Windscreen Sealant	1	60.00	60.00
				<hr/>
				310.00
Labour charges				
To dismantle/refit rear windscreen				150.00
To panel beat/repair rear body				} 850.00
To dismantle/replace above-mentioned parts				} }
To spray painting on affected areas				750.00
To apply tuff kote				150.00
To check wiring				100.00
				<hr/>
				2,000.00

Days of Repair: 7 days @ S\$150/day

TOTAL 5,888.02

Cheryl

Tanala Automotive Consultancy