

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : 065/IC/TC/HO/2018

DATE : 12-MAR-2018

AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MR LOH SUI SHONG
ADDRESS : BLK 508C WELLINGTON CIRCLE
#06-15
S(753508)
TELEPHONE NO : 96987198

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : GA124822
VEHICLE NO : SKW1689E (29/9/2015)
MODEL CODE : BDRAREZL33EYA---D-
MODEL/YEAR : TEANA 2.0XL CVT
ENGINE NO : MR20038932R
CHASSIS NO : MNTBBAL33Z0003617
MILEAGE : ~~65654~~ KM 65833
DATE IN : 12/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 200.00
ESTIMATE BY : HO YUE MENG
ACCIDENT DATE : 02/03/2018

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jiah 97495709
Ex \$200
Authorised.
14/3/18 @ 1445.
5 days.
Resurvey before paint
Sun@lkkauto.com

TC AUTOCLINIC PTE LTD
 1 SIXTH LOK YANG ROAD
 SINGAPORE 628099

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKW1689E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ACI	VACUUM AIRCOND SYSTEM, TOP UP GAS TO SPECIFICATION & MACHINE LEAKAGE TEST	120.00	?
2	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	✓
3	PTS	SUPPLY & INSTALL FRONT TURNING SENSOR	200.00	?
4	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS-FRONT	60.00	cut ✓
			250.	750.
5	ZZ/001	REMOVE/INSTALL FRONT BUMPER, RADIATOR SUPPORT PANEL & AFFECTED PORTION. REPAIR BONNET, RH & LHF FENDER	1000.00	
				500.
6	ZZ/002	RESPRAY PAINT FRONT BUMPER, RADIATOR SUPPORT PANEL, BONNET, RH FRONT FENDER AND LH FRONT FENDER	1200.00	
TOTAL LABOUR CHARGES			2628.00	

TC AUTOCLINIC PTE LTD
 1 SIXTH LOK YANG ROAD
 SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKW1689E

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1	SEAL-CONDENSER, SIDE RH	92184-3TU0A			32.00 ?
2	CLIP-RH FRONT FENDER PROTECTOR @\$1.20EACH X6PCS	01553-05933	7.20	?	
3	CANOE RIVET-RH FRONT FENDER PROTECTOR @\$6.50EAX3PC	76882-0M000	19.50	?	
4	PROTECTOR-FRONT FENDER, RH	63840-3TS0A	81.60	?	
5	MALE ASSY-HOOD LOCK	65601-3TU0D	93.20	?	
6	TANK ASSY-LIQUID	92131-1DA1A			140.30 ?
7	CONDENSER ASSY	92110-3TU0A			752.30 ?
8	SUPPORT-RADIATOR CORE, UPPER RH	F2512-3TSMA	142.10	?	
9	SUPPORT ASSY-RADIATOR CORE	62500-3TU0A	1647.20	?	
10	NOZZLE ASSY-HEADLAMP CLEANER, RH	28641-3TS0A			106.30 ?
11	COVER-HEADLAMP CLEANER MOTOR, RH	28658-3TU0B			68.80 ?
12	EMBLEM-FRONT	62889-3TS0A	73.60	?	
13	GRILLE-RADIATOR, FRONT	62310-3TS0A	341.20	?	
14	CLIP-UPPER FRONT BUMPER MOULDING @\$1.30EACH X8PCS	01553-09321	10.40	?	
15	MOULDING-FRONT BUMPER, UPPER	62078-3TS0A	168.00	?	
16	LH FRONT BUMPER STAY	62211-3TS0A	86.60	?	
17	RH FRONT BUMPER STAY	62210-3TS0A	86.60	?	
18	FRONT BUMPER REINFORCEMENT	62032-3TS0A	533.80	?	
19	ABSORBER-FRONT BUMPER, RH	62092-3TS0A	50.40	?	
20	FRONT BUMPER ENERGY ABSORBER	62090-3TS0A	265.10	?	
21	RETAINER-FRONT BUMPER, LOWER CENTER	62299-3TS0A	180.00	?	
22	RETAINER-FRONT BUMPER, LOWER	62242-3TS0A	42.00	?	
23	RETAINER-FRONT FASCIA, LH	62245-3TS0A	42.00	?	
24	RETAINER-FRONT BUMPER	62240-3TS0A	252.00	?	
25	RETAINER-FRONT BUMPER	62240-3TS0B	84.00	?	

TC AUTOCLINIC PTE LTD
 1 SIXTH LOK YANG ROAD
 SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKW1689E

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
26 RETAINER-FRONT FASCIA,RH	62244-3TS0A	42.00	na	
27 BRACKET-FRONT BUMPER SIDE,RH FRONT	62226-3TS0A	20.90	na	
28 RH FRONT BUMPER SIDE BRACKET	62220-3TS0A	20.90	na	
29 STIFFENER-FRONT BUMPER SIDE,LH	62059-3TS0A	60.00	?	
30 STIFFENER-FRONT BUMPER SIDE,RH	62058-3TS0A	60.00	?	
31 BRACKET-LICENCE PLATE	96210-3TU0A	126.70	X	
32 FRONT BUMPER CLIP @\$1.20EACH X2PCS	01553-05933	2.40	na	
33 COVER-BUMPER BRACKET	622A0-3TS0H	19.30		
34 FRONT BUMPER FASCIA	62022-3TD6H	766.10	na	
35 RH FOG LAMP FINISHER	62256-3TU0B	67.90	?	
36 LAMP-FOG,RH	26150-8994A			321.60 ?
37 TURN SIGNAL LAMP ASSY-FRONT,RH	26130-3TD0A	151.10	?	
38 LAMP ASSY-RH	26010-3TD3A	419.20	ant	
39 LAMP ASSY-LH	26060-3TD3A	419.20	?	
SUB TOTAL		6382.20	0.00	1421.30
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1276.44	0.00	0.00
GRAND TOTAL		5105.76	0.00	1421.30
OVERALL TOTAL		6527.06		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKW1689E

TOTAL LABOUR CHARGES	2628.00
TOTAL SPARE PARTS CHARGES	6527.06

GRAND TOTAL	9155.06 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	200.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.