



scene photos




scene photos



scene photos



scene photos



scene photos



scene photos



Status of Driving Licence

QUALIFIED DRIVING LICENCE

Qualified Driving Licence No. :	S18131108
Status of Qualified Driving Licence :	Valid
Class of Qualified Driving Licence :	2B,3,4
Expiry Date :	Valid for life unless revoked, suspended or disqualified.

PROVISIONAL DRIVING LICENCE

Provisional Driving Licence No. :	S18131108
Status of Provisional Driving Licence :	No Licence
Class of Provisional Driving Licence :	
Expiry Date :	

The above information is accurate as at 13/03/2018 12:01 AM.



Twin Wheels Auto Trading Enterprise

18th January 2017

Attn : MOTOR CLAIMS DEPARTMENT

India International Insurance Pte Ltd

64 Cecil Street

#04-#05 IOB Building

Singapore 049711

Dear Sirs / Madam,

Quotation 3rd Party Claims for your insured vehicle no. SHD 4203 P with our Vehicle No.

SKL 107 H, Accident on 17.01.2017, along junction of Toa Payoh East & Toa Payoh Lor 6

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing :

NO	PARTS REPLACEMENT	QTY	LIST PRICE
1	Front Bumper <i>Defect</i>	1pc	S 3,085.40
2	Front Bumper Reinforcement <i>Defect</i>	1pc	S 2,100.85
3	Front Bumper Centre Grille <i>Defect</i>	1pc	S 250.00
4	Front Bumper Fog Lamp LH / RH <i>Defect</i>	2pcs	S 754.10
5	Front Bumper Fog Lamp Cover LH / RH <i>Defect</i>	2pcs	S 462.86
6	Front Bonnet <i>Defect</i>	1pc	S 5,656.58
7	Front Grille <i>Defect</i>	1pc	S 875.48
8	Front Mudguard - LH <i>Defect</i>	1pc	S 3,054.03
9	Front Headlight - LH / RH <i>Defect</i>	2pcs	S 3,640.16
10	Headlight Casing - LH / RH <i>Defect</i>	2pcs	S 662.20
11	Day Light LH / RH <i>Defect</i>	2pcs	S 356.70
12	Radiator <i>Defect</i>	1pc	S 1,032.90
13	Condenser <i>Defect</i>	1pc	S 1,578.15
14	Turbo Intercooler <i>Defect</i>	1pc	S 8,779.63
15	Drive Shaft - LH <i>Defect</i>	1pc	S 2,885.95
16	Lower Arm - LH <i>Defect</i>	1pc	S 1,121.25
17	Linkage - LH <i>Defect</i>	1pc	S 141.18
18	Bearing Hub & Knuckle Set <i>Defect</i>	1 Set	S 1,278.63
19	Sport Rim - Front LH <i>Defect</i>	1pc	S 1,735.58
20	Tyre - Front LH <i>Defect</i>	1pc	S 400.00
21	Mudguard Cowling - LH / RH <i>Defect</i>	2pcs	S 222.63
22	Stabilizer Bar <i>Defect</i>	1pc	S 901.90

23	Front Engine Under Cover - LH/ RH <i>for</i>	1Set	\$ 607.70
24	Engine Under Cover - Centre <i>for</i>	1pc	\$ 607.70
25	Wiper Nozzle & Cover <i>missing</i>	1 Set	\$ 103.05
TOTAL LIST PRICE			\$ 42,294.61
LESS - 20%			\$ 8,458.92
TOTAL AMOUNT			\$ 33,835.69
LABOUR CHARGES			
26	TO DISMANTLE / REPLACE UNDER CARRIAGE PARTS	\$	500.00 <i>350</i>
27	KNOCKING CHARGES & REPLACE OF BODY PARTS	\$	900.00 <i>800</i>
28	SPRAY PAINTING CHARGES.	\$	750.00 <i>700</i>
TOTAL AMOUNT			\$ 35,985.69
7% GST			\$ 2,519.00
NET AMOUNT			\$ 38,504.69

Please contact 6765-2616 for the survey arrangement at:

Location of the vehicle ;

38 Woodlands Industrial Park E1, #03-14
Singapore 757700

From :

Christine Chen

WP
Kalvin (CRM)
19/1/17
12 Repair Parts
After Repair photo.
Lang Sun Repair.

Kalvin - 96719399



Twin Wheels Auto Trading Enterprise

20th February 2017

Attn : MOTOR CLAIMS DEPARTMENT

India International Insurance Pte Ltd

64 Cecil Street
#04-#05 IOB Building
Singapore 049711

Dear Sirs / Madam,

Quotation 3rd Party Claims for your insured vehicle no. SHD 4203 P with our Vehicle No.
SKL 107 H, Accident on 17.01.2017, along junction of Toa Payoh East & Toa Payoh Lor 6

With reference to the above vehicle. We hereby submit a list of parts required
to be changed and append below the charges for changing and repairing :

Supplementary Labour charge :

NO	LABOUR CHARGES	PRICE	
1	LABOUR FOR FOCUS HEADLIGHT WIRING	S 60.00	50
2	WHEEL ALIGNMENT	S 120.00	100
3	TO DISMANTLE / RE-FIX AIR CON ASSEMBLY, FILL IN AIR CON GAS	S 180.00	150
4	TO APPLY RUST-PROOFING.	S 150.00	100
TOTAL AMOUNT		S 510.00	
7% GST		S 35.70	
NET AMOUNT		S 545.70	

Please contact 6765-2616 for the survey arrangement at:

Location of the vehicle :

38 Woodlands Industrial Park E1, #03-14
Singapore 757700

From :

Christine Chen

Handwritten signature and date:
K. L. L. L. L.
20/2/17
Resmy

Addendum Sheet

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: NA01419003059 Vehicle Registration No: SK210TH
 Name(as shown in NRIC): Mr Lim Joo Joo, Joo Joo
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 NRIC/Passport No: 894457532
 Address: Blk 241 Kim Keat Lnk #07-184 (S) 310241
 Contact (Tel): (H/P): 9043994
 (Email): Jojo_Nurhanda@gmail.com.sg
 Date of Accident: 17-7-2017 Time of Accident: 13:15
 Place of Accident: Intersection of Tanjong Pagar East & Tanjong Pagar Lr 6
 Insurance Company: China Insurance

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

1. Driver should be children of the insured instead of spouse
 2. Circumstance of accident Type 4 (Karma) should be too Pajoh
 instead of too Pajoh

Signature of Vehicle Owner / Driver

Date: 17-7-2017

30 Robinson Road #10-05 International Plaza Singapore 049903 Phone: Tel: 65 6724 0010 Fax: +65 6724 0010
 Operating Hours: Monday to Friday 9am to 5pm

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jan 2017 Edit Reg		19 Jan 2017 00:00 Edit Adj Rpt	\$18,350.00 Edit Estimates	\$18,350.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Main Claimant:	MT SINGAPORE CAR RENTAL PTE LTD , Co. Reg. No.: 201630785W		
Vehicle Reg. No.:	SKL107H	Date of Loss:	17/01/2017 11:00 - :59 [72 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT17010661	Policy/Cover Note No.:	MC0M0016 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	SHD4203P	Policy No. (Claimant):	DMHCSN1688911600
		Excess:	
Repairer:	Twin Wheels Auto Trading Enterprise (HQ) 38 Woodlands Industrial Park E1 #01-14, Admiralty Industrial Park, 757700 Woodlands - Tel: 6765 2616		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 14/03/2018]		
Driver/Custodian (Insured):	TEO SAY BENG PETER (), NRIC: S1813110B		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (11/04/2018): Alert - Adj Mandate Approved (\$10475.00) - SKL107H - Claim Handler: Sundari Nag...
- III_SG (10/04/2018): Alert - Adj Mandate Approved (\$10472.60) - SKL107H - Claim Handler: Sundari Nag...
- III_SG (14/07/2017): Alert - Adj Mandate Approved (\$0.00) - SKL107H - Claim Handler: Sundari Nagaraj...
- III_SG (22/03/2017): Alert - Adj Mandate Approved (\$0.00) - SKL107H - Claim Handler: Sundari Nagaraj...
- III_SG (16/03/2017): Alert - Adj Mandate Approved (\$0.00) - SKL107H - Claim Handler: Sundari Nagaraj...
- III_SG (09/02/2017): Alert - Adj Mandate Maintained - SKL107H - Claim Handler: Sundari Nagarajan
- III_SG (24/01/2017): Alert - Adj Mandate Approved (\$0.00) - SKL107H - Claim Handler: Sundari Nagaraj...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKL107H (MCT17010661)**
[SHD4203P]
TP
MT SINGAPORE CAR RENTAL PTE LTD
Jan 17 2017 11:00AM
[COMFORT TRANSPORTATION PTE LTD]
Twin Wheels Auto Trading Enterprise

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/01/17 16:51	General View	 Load JPG	✓
2	20/01/17 16:51	General View	 Load JPG	✓
3	20/01/17 16:51	General View	 Load JPG	✓
4	20/01/17 16:51	General View	 Load JPG	✓
5	20/01/17 16:51	General View	 Load JPG	✓
6	20/01/17 16:51	General View	 Load JPG	✓
7	20/01/17 16:51	General View	 Load JPG	✓
8	20/01/17 16:51	General View	 Load JPG	✓
9	20/01/17 16:51	General View	 Load JPG	✓
10	20/01/17 16:51	General View	 Load JPG	✓
11	20/01/17 16:51	General View	 Load JPG	✓
12	20/01/17 16:51	General View	 Load JPG	✓
13	20/01/17 16:51	General View	 Load JPG	✓
14	20/01/17 16:51	General View	 Load JPG	✓
15	20/01/17 16:51	General View	 Load JPG	✓
16	20/01/17 16:51	General View	 Load JPG	✓
17	20/01/17 16:51	General View	 Load JPG	✓
18	20/01/17 16:51	General View	 Load JPG	✓
19	20/01/17 16:51	General View	 Load JPG	✓
20	20/01/17 16:51	General View	 Load JPG	✓
21	20/01/17 16:51	General View	 Load JPG	✓
22	20/01/17 16:51	General View	 Load JPG	✓
23	20/01/17 16:51	General View	 Load JPG	✓
24	20/01/17 16:51	General View	 Load JPG	✓
25	20/01/17 16:51	General View	 Load JPG	✓
26	20/01/17 16:51	General View	 Load JPG	✓
27	20/01/17 16:51	General View	 Load JPG	✓
28	20/01/17 16:51	General View	 Load JPG	✓
29	20/01/17 16:51	General View	 Load JPG	✓
30	20/01/17 16:51	General View	 Load JPG	✓
31	20/01/17 16:51	General View	 Load JPG	✓
32	20/01/17 16:51	General View	 Load JPG	✓
33	20/01/17 16:51	General View	 Load JPG	✓
34	20/01/17 16:51	General View	 Load JPG	✓
35	20/01/17 16:51	General View	 Load JPG	✓

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	20/01/17 16:51	General View	 Load JPG	☒
37	20/01/17 16:51	General View	 Load JPG	☒
38	20/01/17 16:51	General View	 Load JPG	☒
39	20/01/17 16:51	General View	 Load JPG	☒
40	20/01/17 16:51	General View	 Load JPG	☒
41	20/01/17 16:51	General View	 Load JPG	☒
42	20/01/17 16:51	General View	 Load JPG	☒
43	20/01/17 16:51	General View	 Load JPG	☒
44	20/01/17 16:51	General View	 Load JPG	☒
45	20/01/17 16:51	General View	 Load JPG	☒
46	20/01/17 16:51	General View	 Load JPG	☒
47	20/01/17 16:51	General View	 Load JPG	☒
48	20/01/17 16:51	General View	 Load JPG	☒
49	20/01/17 16:51	General View	 Load JPG	☒
50	20/01/17 16:51	General View	 Load JPG	☒
51	20/01/17 16:51	General View	 Load JPG	☒
52	20/01/17 16:51	General View	 Load JPG	☒
53	20/02/17 17:16	Reinspection Photo	 Load JPG	☒
54	20/02/17 17:16	Reinspection Photo	 Load JPG	☒
55	20/02/17 17:16	Reinspection Photo	 Load JPG	☒
56	20/02/17 17:16	Reinspection Photo	 Load JPG	☒
57	20/02/17 17:16	Reinspection Photo	 Load JPG	☒
58	20/02/17 17:16	Reinspection Photo	 Load JPG	☒
59	20/02/17 17:16	Reinspection Photo	 Load JPG	☒
60	20/02/17 17:16	Reinspection Photo	 Load JPG	☒
61	20/02/17 17:16	Reinspection Photo	 Load JPG	☒
62	20/02/17 17:16	Reinspection Photo	 Load JPG	☒
63	20/02/17 17:16	Reinspection Photo	 Load JPG	☒
64	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
65	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
66	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
67	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
68	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
69	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
70	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
71	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
72	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
73	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
74	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
75	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
76	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
77	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
78	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
79	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
80	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
81	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
82	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
83	11/05/17 10:39	Reinspection Photo	Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
85	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
86	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
87	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
88	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
89	11/05/17 10:39	Reinspection Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/01/17 16:01	TP ESTIMATE- MARKED	 Load PDF	
2	12/07/17 18:05	Email from TP repairer reject 50% offer	 Load PDF	
3	19/07/17 15:45	Email lto III TP had forwarded the case to their lawyer. 19.7.17	 Load PDF	
4	19/07/17 15:45	Email from wkshop reject offer, TP had forwarded the case to their lawyer	 Load PDF	
5	10/04/18 16:54	Towing Receipt	 Load PDF	
6	10/04/18 16:54	LTA Receipt	 Load PDF	
7	01/06/18 09:19	AUTHORISATION TO ACT	 Load PDF	
8	01/06/18 09:19	DISCHARGE VOUCHER	 Load PDF	
9	01/06/18 09:19	LOD	 Load PDF	
10	01/06/18 09:19	RENTAL RECEIPT	 Load PDF	
11	01/06/18 09:19	WORKSHOP INVOICE	 Load PDF	
12	01/06/18 09:24	INVOICE NO DATED 31.07.2017	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	20/01/17 15:34	Singapore Accident Statement-IV	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III17001339/K1WB3S2-1
Date: 01/06/2018

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MC0M0016
Claimant Vehicle No :	SKL107H	Insured Vehicle No :	SHD4203P
Date of Loss:	17/01/2017	Nature of Claim:	TP
		Claim No:	MCT17010661

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL107H	Engine No:	CCZ020579
Make & Model:	SKODA OCTAVIA, 2.0 VRS (1Z) (A)	Chassis No:	TMBEF61Z8A2014299
Reg. Date:	23/12/2010 (Man. Year: 2009)	Odometer:	109541 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40ZR18	Rear Tyre Size:	225/40ZR18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,835.69	20,729.69	13,106.00	38.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,660.00	2,250.00	410.00	15.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,495.69	22,979.69	13,516.00	37.03
Approved Total (Overridden) (S\$)		18,350.00		
(S\$)	36,495.69	18,350.00	18,145.69	49.72
+ GST 7.00/7.00% (S\$)	2,554.70	1,284.50	1,270.20	49.72
Nett Amount (S\$)	39,050.39	19,634.50	19,415.89	49.72
+ Loss of Use (12.0 x S\$100.00/day) (S\$)		1,200.00		
(S\$)		20,834.50		
Liabe Amount (50.00%) (S\$)		10,417.25		
+ Doc/Search Fee (S\$)		5.35		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		10,472.60		
Global Sum Settlement (S\$)		10,475.00		

INSPECTION

Date of Assignment: 19/01/2017

6/1/2018

Adjuster Report

Date Inspected:

19/01/2017 Inspected At:

Estimated Period of Repair:

12.0 days

Twin Wheels Auto Trading Enterprise (HQ)
38 Woodlands Industrial Park E1 #01-14, Admiralty
Industrial Park
Singapore 757700

Adjuster: KALVIN ANG WEI KUN

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 May 2018)
Parts:	143	SKODA OCTAVIA 2.0 VRS (1Z) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL107H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	3,085.40 FL	*2,200.86 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	2,100.85 FL	*1,179.56 FL
3	1		*FRONT BUMPER CENTRE GRILLE	Cracked	250.00 FL	*250.00 FL
4	2		*FRONT BUMPER FOG LAMP LH / RH	Cracked	754.10 FL	*754.10 FL
5	2		*FRONT BUMPER FOG LAMP COVER LH / RH	Cracked	462.86 FL	*462.86 FL
6	1		*FRONT BONNET	Dented	5,656.58 FL	*2,209.66 FL
7	1		*FRONT GRILLE	Cracked	875.48 FL	*875.48 FL
8	1		*FRONT MUDGUARD - LH	Dented	3,054.03 FL	*1,123.44 FL
9	2		*FRONT HEADLIGHT - LH / RH	Cracked	3,640.16 FL	*3,640.16 FL
10	2		*HEADLIGHT CASING - LH / RH	Cracked	662.20 FL	*662.20 FL
11	2		*DAY LIGHT LH / RH	Cracked	356.70 FL	*356.70 FL
12	1		*RADIATOR	Bent	1,032.90 FL	*1,032.90 FL
13	1		*CONDENSER	Bent	1,578.15 FL	*1,578.15 FL
14	1		*TURBO INTERCOOLER	Bent	8,779.63 FL	*1,600.66 FL
15	1		*DRIVE SHAFT - LH	Broken	2,885.95 FL	*2,400.55 FL
16	1		*LOWER ARM - LH	Bent	1,121.25 FL	*700.67 FL
17	1		*LINKAGE - LH	Broken	141.18 FL	*141.18 FL
18	1		*SET BEARING HUB & KNUCKLE	Bent	1,278.63 FL	*1,100.00 FL
19	1		*SPORT RIM - FRONT LH	Grazed	1,735.58 FL	*1,200.00 FL
20	1		*TYRE - FRONT LH	Serviceable	400.00 FL	*- FL
21	1		*MUDGUARD COWLING - LH / RH	Torn	222.63 FL	*222.63 FL
		2pcs				
22	1		*STABILIZER BAR	Bent	901.90 FL	*901.90 FL
23	1		*SET FRONT ENGINE UNDER COVER - LH / RH	Torn	607.70 FL	*607.70 FL
24	1		*ENGINE UNDER COVER - CENTRE	Torn	607.70 FL	*607.70 FL
25	1		*SET WIPER NOZZLE & COVER	Missing	103.05 FL	*103.05 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	42,294.61	25,912.11
- List Item Discount on L Items 20.00/20.00% (\$\$)	8,458.92	5,182.42
Total Parts (\$\$)	33,835.69	20,729.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE / REPLACE UNDER CARRIAGE PARTS.	New	500.00	350.00
2	KNOCKING CHARGES & REPLACE OF BODY PARTS.	New	900.00	800.00
3	SPRAY PAINTING CHARGES.	New	750.00	700.00
4	LABOUR FOR FOCUS HEADLIGHT WIRING.	New	60.00	50.00
5	WHEEL ALIGNMENT.	New	120.00	100.00
6	TO DISMANTLE / RE-FIX AIR CON ASSEMBLY, FILL IN AIR CON GAS.	New	180.00	150.00
7	TO APPLY RUST-PROOFING.	New	150.00	100.00
Gross Labour Cost (\$\$)			2,660.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >